

CANZINCO MINES LTD.

NANISIVIK MINE, NUNAVUT

2021 ANNUAL GEOTECHNICAL INSPECTION

PROJECT NO.: 0255033

DATE: March 4, 2022

March 4, 2022
Project No.: 0255033

Zied Tebaibi, P. Geo.
Langlois Mines
c/o CanZinco Mines Ltd.
C.P. 6000, Route 1000, Km. 42
Lebel-sur-Quévillon, Québec J0Y 1X0
Canada

Dear Zied,

Re: Nanisivik Mine 2021 Annual Geotechnical Inspection

Please find attached our above captioned report on the 2021 Annual Geotechnical Inspection undertaken at Nanisivik Mine. If there are any questions or comments regarding this report, please contact the undersigned at your convenience.

Yours sincerely,

BGC ENGINEERING INC.
per:



Scott Garrison, M.Eng., P.Eng.
Geological Engineer

EXECUTIVE SUMMARY

The Annual Geotechnical Inspection was undertaken at the Nanisivik Mine site in 2021. The program involved the following:

- Completion of a site inspection by a professional geotechnical engineer. The site inspection included visual observations of all reclamation measures undertaken at the Nanisivik Mine site since 2004.
- Collection of geotechnical monitoring data from various instruments located around the mine site.
- Review of the geotechnical monitoring data to assess the performance of various reclamation measures with respect to the original design intent.

The following paragraphs provide a summary of the significant observations, conclusions, and recommendations based on the results of the 2021 Geotechnical Inspection Program undertaken at the Nanisivik Mine site.

Embankments

The West Twin Dyke and Test Cell Dyke were physically stable with no signs of erosion or seepage. The breaches constructed in the remnant dykes at the East Adit Treatment Facility continue to permit natural drainage of the area with only limited ponding in the Retention Pond.

Hydraulic Structures

The West Twin Dyke Spillway continues to effectively drain water from the Surface Cell cover into the Reservoir and is generally functioning as intended. Limited erosion was observed in 2021, although it is possible that additional maintenance will be required in the future. The spillway should continue to be inspected for additional erosion and maintenance should be undertaken as necessary.

As observed during previous inspections, a small head pond developed on the Surface Cell cover at the spillway inlet. The presence of the shallow head pond is not considered to negatively impact the overall cover performance; hence the elimination of the head pond is not considered necessary.

Despite continued seepage at the West Twin Outlet Wall, instrumentation data continues to support visual observations that the water level upstream of the outlet wall is maintained at or above the invert during the open water season. Continued deformation of the perimeter slopes of the upstream Polishing Pond was observed in 2021. As noted in previous inspections, the area of instability was further removed from the outlet wall compared to previous years. Hence there are no concerns associated with this instability with respect to the performance of the outlet wall. Based on the water quality measurements collected since the East Twin Lake access road was breached in 2008, the seepage losses from the Polishing Pond do not appear to be affecting the overall performance of the West Twin Area reclamation measures. The seepage losses should

continue to be monitored. Additional seepage control measures could be considered, if necessary.

Previous inspections made recommendations to repair left bank armouring material following observations of erosion along a section of the East Twin Creek Diversion Channel. In response to these observations, maintenance was undertaken at the diversion dyke in 2018. The maintenance included re-sloping of the affected area and addition of locally available armour materials. The maintained areas were visually assessed during the 2021 inspection and appeared to have performed favourably. Seepage discharge observed at the toe of the left bank of the dyke during previous inspections was observed again in 2021. The seepage water is likely originating in the Polishing Pond and likely only flows when the active layer thickness is near its maximum depth. The seepage was visually estimated to be similar in comparison to the 2020 inspection. The seepage flow was observed to be clear and free of sediment. No further maintenance of the diversion dyke is recommended at this time but should continue to be monitored for additional erosion and seepage flows.

Thermal Covers

Based on monitoring data collected from various frost gauges and thermistors, the thermal covers performed adequately throughout 2021. In general, the active layer thaw in 2021 was observed to be similar or slightly less than was measured in 2019 and 2020. The 2021 weather was variable: in general, the 2020/2021 winter and 2021 spring were warmer than average but the 2021 summer was cooler than average. Since the active layer thaw depths tend to closely reflect the summer and fall temperatures, less than average thaw depths were observed in 2021.

The minor erosion, cracking, and thermokarsting/settlement observed on the Surface Cell and Test Cell cover systems that has been noted in previous inspections was not observed to have visually changed in several years. However, the cracks and heaving in an oval pattern near the central-southern portion of the cover continued to grow since 2020. The heaving is likely due to the freeze-back of the pore water in the underlying tailings. The heaving/cracking is not considered to negatively impact the stability of the West Twin Dyke, thermal performance of the cover system, nor the water quality in the surrounding areas at this time. The water quality observed at the final discharge point for the West Twin Disposal Area was observed to remain well below the discharge criteria throughout the open water season in 2021. This is an indication that the cover systems continue to perform as intended.

Several instruments to monitor the performance of the thermal covers on site have ceased functioning in the past few years. This is expected, as most instruments were installed nearly 20 years ago. Replacement of the failed instruments is not considered necessary at this time, given generally positive performance monitoring results since installation.

No maintenance is required for the thermal covers at this time; however, visual monitoring is recommended to monitor for additional surface deformation and erosion, specifically the heave feature.

Talik and Mine Waste Freeze-back

Overall freeze-back of the talik in the Surface Cell and Test Cell appears to be proceeding faster than anticipated. However, since 2020, the downward migration of the freezing front and continued cooling of ground temperatures below approximately 15 m bgs has slowed. Shallow ground temperature at depths above approximately 15 m bgs generally showed warming since 2020, reflective of the warmer than average temperatures in the past few years. Despite these warmer air temperatures, mine waste remained frozen through 2021. All piezometers within the Surface Cell, and three out of five piezometers within the Test Cell, have frozen back due to continued downward migration of the freezing front. The piezometers have been observed to freeze back at lower temperatures when the piezometer tip is at a lower elevation, as well as when it is further away from the edge of the original lake bed. These relationships are likely related to the increasing solute concentrations in the unfrozen pore water contained within the remnant talik.

In areas where no talik exists (e.g., landfill, open pits), freeze-back of the materials underlying the cover systems has occurred and the rate of cooling has generally slowed over recent years, suggesting ground conditions are approaching thermal equilibrium at depth.

Mine Openings, Crown Pillars and Raises

The covers constructed over the mine openings generally appear to be physically stable. Cracking at the East Open Pit crown pillar does not appear to have progressed in many years. No maintenance is recommended, but continued visual inspection is warranted.

Shale and Armour Borrow Areas

In general, the shale and armour borrow areas appear to be physically stable and are not causing any significant ponding to occur. No maintenance was recommended at any of the borrow areas.

TABLE OF CONTENTS

| | |
|--|-----------|
| EXECUTIVE SUMMARY | i |
| 1.0 INTRODUCTION | 1 |
| 2.0 SCOPE OF SERVICES | 4 |
| 3.0 MINE RECLAMATION ACTIVITIES | 5 |
| 4.0 CLIMATE REVIEW | 6 |
| 5.0 MINE DESCRIPTION | 7 |
| 6.0 2021 SITE INSPECTION..... | 8 |
| 6.1. Embankments and Containment Structures | 8 |
| 6.1.1. East Adit Treatment Facility Dykes | 8 |
| 6.2. Water Conveyance Structures | 9 |
| 6.2.1. West Twin Dyke Spillway | 9 |
| 6.2.2. West Twin Lake Outlet Channel | 11 |
| 6.2.3. East Twin Creek Diversion Dyke and Channel | 13 |
| 6.3. Thermal Covers | 14 |
| 6.3.1. Surface Cell Tailings Cover | 14 |
| 6.3.2. West Twin Dyke | 17 |
| 6.3.3. Test Cell Area | 18 |
| 6.3.4. Toe of West Twin Dyke Tailings Cover | 21 |
| 6.3.5. Landfill Cover | 22 |
| 6.3.6. West Open Pit..... | 24 |
| 6.3.7. East Open Pit..... | 25 |
| 6.3.8. East Trench Waste Rock Cover..... | 26 |
| 6.3.9. Oceanview Open Pit Waste Rock Cover | 27 |
| 6.3.10. Area 14 Waste Rock Cover | 28 |
| 6.3.11. Upper Dump Pond Tailings Cover | 29 |
| 6.3.12. Industrial Complex Foundation Cover | 30 |
| 6.4. Mine Openings..... | 31 |
| 6.4.1. 00/01 Portals and Crown Pillar | 31 |
| 6.4.2. 17 North Portal | 32 |
| 6.4.3. Oceanview Portal | 33 |
| 6.4.4. K-Baseline Portal | 34 |
| 6.4.5. Area 14 Portal | 34 |
| 6.4.6. 09 South Portal | 35 |
| 6.4.7. Lower Adit | 36 |
| 6.4.8. Portal to Mill Foundation | 36 |
| 6.4.9. Shale Hill Raise..... | 37 |
| 6.4.10. Oceanview East Raise | 37 |
| 6.4.11. Oceanview West Raise | 38 |
| 6.4.12. Area 14 Raise | 38 |
| 6.5. Shale and Armour Borrow Areas..... | 39 |

| | |
|--|-----------|
| 6.5.1. Shale Borrow Areas | 39 |
| 6.5.2. Armour Borrow Areas | 40 |
| 6.6. Summary of 2021 Maintenance Recommendations..... | 41 |
| 6.7. 2020-2029 Monitoring Schedule..... | 42 |
| 7.0 CONCLUSIONS AND RECOMMENDATIONS..... | 43 |
| 8.0 CLOSURE | 46 |
| REFERENCES | 47 |

LIST OF TABLES

| | |
|--|----|
| Table 1-1. Summary of inspection items. | 2 |
| Table 6-1. Recommended maintenance and action items for 2021. | 41 |

LIST OF FIGURES

| | |
|-----------|---|
| Figure 01 | Climate Data |
| Figure 02 | Site Plan of the West Twin Disposal Area |
| Figure 03 | Polishing Pond Water Level Data |
| Figure 04 | Surface Cell Tailings Cover Geotechnical Monitoring Data 1 |
| Figure 05 | Surface Cell Tailings Cover Geotechnical Monitoring Data 2 |
| Figure 06 | Surface Cell Tailings Cover Geotechnical Monitoring Data 3 |
| Figure 07 | Surface Cell Tailings Cover Geotechnical Monitoring Data 4 |
| Figure 08 | Surface Cell Tailings Cover Geotechnical Monitoring Data 5 |
| Figure 09 | Surface Cell Run-off Water Quality Data |
| Figure 10 | West Twin Dyke Geotechnical Monitoring Data |
| Figure 11 | Test Cell Tailings Cover Geotechnical Monitoring Data 1 |
| Figure 12 | Test Cell Tailings Cover Geotechnical Monitoring Data 2 |
| Figure 13 | Test Cell Dyke Geotechnical Monitoring Data |
| Figure 14 | Toe of Test Cell Dyke Tailings Cover Geotechnical Monitoring Data |
| Figure 15 | Toe of West Twin Dyke Tailings Cover Geotechnical Monitoring Data |
| Figure 16 | West Twin Disposal Area Water Quality Data |
| Figure 17 | Landfill Cover Geotechnical Monitoring Data |
| Figure 18 | East Open Pit Waste Rock Cover Geotechnical Monitoring Data |
| Figure 19 | Oceanview Open Pit Waste Rock Cover Geotechnical Monitoring Data |
| Figure 20 | Area 14 Waste Rock Cover Monitoring Data |

| | |
|-----------|---|
| Figure 21 | Upper Dump Pond Tailings Cover Monitoring Data |
| Figure 22 | Industrial Complex Cover Geotechnical Monitoring Data |

LIST OF DRAWINGS

| | |
|------------|-------------------------------------|
| Drawing 01 | Site Location Plan |
| Drawing 02 | Surface Cell Tailings Cover |
| Drawing 03 | Test Cell Tailings Cover |
| Drawing 04 | Landfill Cover |
| Drawing 05 | West Open Pit Waste Rock Cover |
| Drawing 06 | East Open Pit Waste Rock Cover |
| Drawing 07 | Oceanview Open Pit Waste Rock Cover |
| Drawing 08 | Area 14 Waste Rock Cover |
| Drawing 09 | Upper Dump Pond Tailings Cover |
| Drawing 10 | Industrial Complex Cover |

LIST OF APPENDICES

| | |
|--------------|--|
| APPENDIX I | INSPECTION PHOTOS |
| APPENDIX II | 2021 GEOTECHNICAL MONITORING EVENTS |
| APPENDIX III | 2020-2029 GEOTECHNICAL MONITORING PROGRAM SCHEDULE |

LIMITATIONS

BGC Engineering Inc. (BGC) prepared this document for the account of CanZinco Mines Ltd. The material in it reflects the judgment of BGC staff in light of the information available to BGC at the time of document preparation. Any use which a third party makes of this document or any reliance on decisions to be based on it is the responsibility of such third parties. BGC accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this document.

As a mutual protection to our client, the public, and ourselves all documents and drawings are submitted for the confidential information of our client for a specific project. Authorization for any use and/or publication of this document or any data, statements, conclusions or abstracts from or regarding our documents and drawings, through any form of print or electronic media, including without limitation, posting or reproduction of same on any website, is reserved pending BGC's written approval. A record copy of this document is on file at BGC. That copy takes precedence over any other copy or reproduction of this document.

1.0 INTRODUCTION

Nanisivik Mine is located on the Borden Peninsula on northern Baffin Island, just south of Strathcona Sound, as shown on Drawing 01.

Mining operations at Nanisivik ceased in September 2002. The geotechnical site inspection in 2021 was conducted under Nunavut Water Board Licence 1AR-NAN2030 (the Licence), effective from January 9, 2020, through January 8, 2030.

The Licence authorizes CanZinco Mines Ltd. (the Licensee) to conduct post-closure monitoring and maintenance activities at the former Nanisivik Mine. Part H, Item 4 of the Licence states the following:

“The Licensee shall undertake a geotechnical inspection during the years set out in Schedule H, Table 1. The inspection shall be carried out annually by a Geotechnical Engineer and the results of the inspection shall be documented in a report. The inspection shall be conducted in accordance with the Canadian Dam Safety Guidelines (2007) where applicable and be consistent with the previous Annual Geotechnical Inspection reports submitted by BGC Engineering Inc. for the project, and shall taking into account all major earthworks and any changes to the project.”

In fulfillment of these regulatory requirements, Mr. Zied Tebaibi, Site Manager Langlois Mine, requested that BGC Engineering Inc. (BGC), conduct an inspection visit. The current report provides a summary of the conditions observed and any resulting recommendations and maintenance issues. The report also provides a comprehensive review of geotechnical monitoring data collected on site during the 2021 site inspection. Table 1-1 provides a list of the structures that were included within the inspection.

Table 1-1. Summary of inspection items.

| Facility Type | Inspection Item |
|---|----------------------------------|
| Embankments and Containment Structures | West Twin Dyke |
| | Test Cell Dyke |
| | East Twin Creek Diversion Dyke |
| | East Adit Treatment Facility |
| | Day Tank Farm Area |
| | West Twin Outlet Channel |
| Thermal Covers | Surface Cell |
| | Test Cell |
| | Toe of Test Cell Dyke |
| | Toe of West Twin Dyke |
| | Landfill |
| | West Open Pit |
| | East Open Pit |
| | Oceanview Open Pit |
| | Upper Dump Pond |
| | Industrial Complex |
| Mine Openings, Crown Pillars and Raises | 00/01 Portals and crown pillar |
| | 17 N Portal |
| | Oceanview Portal |
| | K-Baseline Portal |
| | 9S Portal |
| | Former Portal to Mill Foundation |
| | Lower Adit |
| | Shale Hill Raise |
| | Oceanview East and West Raises |

| Facility Type | Inspection Item |
|-------------------------------|-------------------------------------|
| Shale and Armour Borrow Areas | Mt. Fuji Shale Borrow Area |
| | West Twin Shale Borrow Area |
| | East Twin Shale Borrow Area |
| | Area 14 Shale Borrow Area |
| | Townsite Shale Borrow Area |
| | Shale Hill Shale Borrow Area |
| | Twin Lakes Delta Armour Borrow Area |
| | Kuhulu Lake Road Borrow Area |
| | 09S/17N Armour Borrow Area |
| | Chris Creek Armour Borrow Area |

2.0 SCOPE OF SERVICES

BGC Engineering Inc. (BGC) has provided geotechnical engineering, mine waste and mine closure support to the Nanisivik Mine since 2000, including the development and implementation of the reclamation plan for tailings deposits, waste rock piles, portals and open pits. BGC has overseen the implementation of the post-closure geotechnical and geothermal performance monitoring plan since completion of the bulk of the reclamation measures in 2004/2005.

At CanZinco's request, BGC provided a proposal on June 29, 2021, that outlined BGC's scope of work for the 2021 monitoring season. Included within the scope of work is the following:

- Project management.
- A site visit in August 2021 to complete the annual geotechnical site inspection, including collection of geotechnical instrumentation readings, and collection of water quality samples required by the Licence.
- Issuance of a geotechnical inspection summary report, including review and interpretation of geotechnical instrumentation. The results of water quality monitoring, including third-party laboratory analysis, are discussed in a separate BGC report titled "2021 Annual Water Quality Monitoring Report, Nanisivik Mine, Nunavut" dated March 2022.

Direction to proceed with the proposal, including a signed consultancy agreement, was provided on July 7, 2021.

3.0 MINE RECLAMATION ACTIVITIES

The Final Closure and Reclamation Plan (FCRP) was submitted to the Nunavut Water Board for review and approval in March 2004. The review process included a technical meeting in Yellowknife in May 2004 and a public hearing in Arctic Bay in June 2004. The Board conveyed its approval of the plan in a letter to Breakwater dated July 6, 2004.

The reclamation of the mine site began in August 2004, with the bulk of reclamation completed between 2004 and 2008. The reclamation activities are summarized in the project completion report (BGC, September 28, 2009) and documented in detail in various as-built reports referred to throughout this document. Post closure monitoring of the site is on-going and has been conducted in many areas of the site since 2006.

4.0 CLIMATE REVIEW

Climatic data was collected at the Nanisivik Airport by Environment Canada from 1976 to 2010, which was located approximately 10 km south of the West Twin Disposal Area (WTDA) and approximately 250 m higher in elevation. The recorded climate data were previously analyzed by Golder (October 1998) to provide a basis for deriving the existing climate parameters such as precipitation, air temperatures, and lake evaporation at the project site. The following list is a summary of the main climatic parameters provided by Golder (October 1998):

- Mean Annual Air Temperature (MAAT) was estimated to be -15.2°C
- Mean annual precipitation total was estimated to be 240 mm
- Twenty-four-hour Probable Maximum Precipitation (PMP) value was estimated to range from 140 to 210 mm
- Mean annual lake evaporation value, as measured at the Nanisivik site, was approximately 200 mm.

Climate monitoring was discontinued at the Nanisivik Airport in January 2011. Currently, the nearest available climate monitoring station is located at Arctic Bay, approximately 30 km from Nanisivik. Data collected from Arctic Bay since 2011 is provided on Figure 01. The MAAT recorded at the Arctic Bay weather station in 2021 was approximately -10.4°C . This is 1.6°C warmer than 2020 and 2.2°C warmer than the Arctic Bay 2011 to 2021 MAAT. In general, temperatures in 2021 were sporadic. The MAAT in January, April, and May were nearly the warmest recorded since 2011; MAATs in February, March, June, and August were approximately average; while the MAAT in July was one of the coolest on record. The Air Thaw Index calculated for 2021 was approximately 411-degree Celsius days ($^{\circ}\text{C}\cdot\text{d}$). This value is less than that of 2020 ($567^{\circ}\text{C}\cdot\text{d}$), and the 2011 to 2021 average of $479^{\circ}\text{C}\cdot\text{d}$.

Due to the approximately 630 m difference in elevation and the proximity to the coastline, the climate data sets from Arctic Bay and the historical data collected from the Nanisivik airport station are not directly comparable. To put the climate data collected from Arctic Bay since 2011 in historical context, a correction factor is required. A correction factor of -2°C has been estimated (Nanisivik airport 2°C cooler than Arctic Bay) based on the overlap of data sets while monitoring data was collected from both sites in 2010 and 2011, the air temperature data collected sporadically on site since 2013, and the available historical mean annual air temperature at both Arctic Bay and Nanisivik. This correction factor was applied to the climate data collected from Arctic Bay between 2011 and 2021 to create a hybrid climate data set for the Nanisivik mine site of 1977 to 2021 data.

Compared to the corrected hybrid climate data set since 1977, site conditions during the fall (September through November 2020), winter (December 2020 to February 2021), and spring (March through May 2021), were warmer. The corrected MAAT in 2021 was approximately -12.4°C , 2.1°C warmer than the 1977-2010 MAAT of -14.5°C . The corrected Air Thaw Index (ATI) calculated in 2021 was approximately 207-degree Celsius days ($^{\circ}\text{C}\cdot\text{d}$), which is lower than in 2020 ($363^{\circ}\text{C}\cdot\text{d}$) and lower than the 1977 to 2010 mean of $304^{\circ}\text{C}\cdot\text{d}$. So, despite higher-than-normal MAAT, the corrected ATI remained below average in 2021.

5.0 MINE DESCRIPTION

Mining was conducted at Nanisivik Mine between 1976 and 2002. During that time, mining was conducted at four small open pits (West Open Pit, East Open Pit, East Trench, and Oceanview Open Pit) and underground (Main Lens, Area 14, Oceanview, and K-Baseline). The locations of each mining area are illustrated on Drawing 01. The ore was processed at the mill and the tailings were transported to the WTDA, located at West Twin Lake.

The WTDA is comprised of an upper, solids retention pond, named the Surface Cell, and a lower, water retention pond, called the Reservoir, as shown on Figure 02. The Surface Cell and Reservoir are separated by the West Twin Dyke, a frozen-core, rockfill dyke. Prior to construction of the West Twin Dyke, tailings were deposited throughout the original West Twin Lake. After construction of the dyke, tailings were primarily deposited into the Surface Cell. Excess water was then siphoned or pumped from the Surface Cell into the Reservoir from where it was reclaimed for use in the mill. The Reservoir was subsequently further separated by constructing the Test Cell Dyke, creating additional tailings disposal capacity in what was known as the Test Cell.

The Reservoir and a final Polishing Pond were separated by a rockfill causeway and stop log structure. Water from the Polishing Pond was then discharged to Twin Lakes Creek at the decant structure located at the outlet from the pond. The decant structure was replaced in 2005 by the West Twin Outlet Channel. In September 2008, the stop log structure was removed and the rockfill causeway was breached allowing the Reservoir and Polishing Pond to behave as a flow-through hydraulic system.

6.0 2021 SITE INSPECTION

Mr. Scott Garrison, P.Eng., and Ms. Christy Rouault, P.Eng. (AB), conducted the geotechnical site inspection between August 19 and 23, 2021. The following site activities were conducted:

- Each of the elements from Table 1-1 was inspected on foot. Pertinent observations concerning the physical condition of each element were recorded by photograph.
- Instrument readings were collected.
- Aerial drone imagery was collected where time and weather conditions permitted.
- Water samples were collected and forwarded to a third-party laboratory for analysis (Water Quality report provided under separate cover).

Select photos are provided in Appendix I. The following sections review the results of the geotechnical inspection and geotechnical instrumentation monitoring program at the various site facilities.

6.1. Embankments and Containment Structures

Several embankments and containment structures were constructed at Nanisivik Mine throughout its history for various purposes. These include the following:

- West Twin Dyke
- Test Cell Dyke
- East Adit Treatment Pond Dyke
- East Adit Retention Pond Dyke
- Day Tank Farm Spill Containment Berm
- Main Tank Farm Spill Containment Berm.

The following sections provide a summary of the inspection conditions at each of the structures mentioned above. It should be noted that since the West Twin Dyke and Test Cell Dyke have been incorporated into the Surface Cell and Test Cell tailings covers, respectively, the inspection conditions for these structures are reviewed in Section 6.3 (Thermal Covers). Additionally, no inspection of the Day Tank Farm or Main Tank Farm areas was completed as both facilities have been fully decommissioned and berms have been removed.

6.1.1. East Adit Treatment Facility Dykes

Construction Details

The East Adit Treatment Facility was located approximately 3 km east of the mill, downslope from the East Adit area, as shown on Drawing 01. The facility was comprised of a Treatment Pond and a Retention Pond, both of which employed earthen dykes to retain surface water flow. Water that flows through this area is runoff water from the surrounding drainage basin, where the water quality is affected and/or impacted by natural mineralized soil and rock.

Both dykes are shale rockfill structures mixed with a combination of one or more of the following: regional talus, glacial till, marine clay, and/or bentonitic clay. The Treatment Pond Dyke is approximately 5 m above the surrounding ground surface. The Retention Pond Dyke is approximately 3 m above the surrounding ground surface.

Commitments were made in the 2004 Reclamation and Closure Plan (CanZinco, March 2004) to restore natural drainage by breaching/removing any man-made diversions or catchments. As such, both dykes were breached in late 2006. The breaches are approximately 5 m wide at the base and are sloped back to the remnant crest of the dykes at an angle of approximately 3(H):1(V).

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 1 & 2). The main observations made during the inspection are summarized by the following:

- Both the breach of the East Adit Retention Pond and the breach of the East Adit Treatment Pond promote drainage of the former pond areas as intended.
- As observed during previous inspections, a small remnant pond was observed in the East Adit Retention Pond area which has been present since breaching. The ponding has been reduced in areal extent over time due to continued natural backfilling of the area by sediments, mostly weathered shale, being transported and deposited in this area from natural deposits upslope.
- Some channelization of remnant sediments was observed in the bottom of the East Adit Treatment Pond.

As expected, natural sedimentation has steadily been reducing the areal extent of remnant ponding in the East Adit Retention Pond. As such, additional remedial actions at the East Adit Treatment Facility are not considered necessary.

6.2. Water Conveyance Structures

Several water conveyance structures were constructed at Nanisivik Mine, both prior to, and during the reclamation process. These include the following structures:

- West Twin Dyke Spillway
- West Twin Outlet Channel
- East Twin Creek Diversion Berm and Channel.

The following sections provide a summary of the inspection conditions at each of the structures mentioned above.

6.2.1. West Twin Dyke Spillway

Construction Details

The West Twin Dyke Spillway is located at the south end of the Surface Cell, as shown on Figure 02. The spillway conveys water from the Surface Cell to the Reservoir. The physical details of the spillway are summarized by the following:

- The spillway is approximately 550 m long
- The bottom of the spillway is approximately 6 m wide
- The grade of the spillway bottom varies from 0% at the inlet to 7% near the middle of the spillway and 2% at the outlet
- The bottom of the spillway is founded on rock from the inlet to 100 m down gradient of the access ramp. The remainder of the spillway bottom is comprised of rockfill
- The side slopes of the spillway vary from near vertical in rock to approximately 3(H):1(V) in soil side slopes
- Side slopes are composed of poor-quality rock or soil are armoured with riprap.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 3 through 9). The main observations are summarized by the following:

- A small pond was observed at the spillway inlet on the Surface Cell cover (Photo 3). The maximum depth of the pond was estimated to be approximately 20 cm, similar to previous years.
- The upper portion of the spillway (upstream of the access ramp) showed signs of further erosion of the armour material compared to 2020 but remained in satisfactory condition (Photos 5 and 6).
- Maintenance activities were undertaken in 2018 to address erosion along the left bank, downstream of the access ramp. The maintenance activities are described in detail in a memorandum appended to BGC's *Nanisivik Mine 2018 Annual Geotechnical Inspection Report (March 11, 2019)*. Minor erosion of the maintained area was noted in 2021, as it has been in inspections since 2019 (Photos 7 and 8).
- During 2018 maintenance activities, transported armour material that was deposited at the base of the spillway was removed or compacted in-place. No new deposition of armour material in the base of the spillway was observed during the 2019 to 2021 inspections (Photo 9).
- As noted in previous inspections, surface flow was observed to travel down the spillway before going subsurface into the rockfill approximately 150 m upstream of the spillway outlet. This is not considered to have an adverse impact on spillway performance at this time.

While the spillway is effective in directing and confining flow from the Surface Cell to the Reservoir, additional maintenance may be required in the future. It is recommended that the spillway and side slopes continue to be visually monitored for additional erosion and maintenance be undertaken as necessary.

6.2.2. West Twin Lake Outlet Channel

Construction Details

The West Twin Lake Outlet Channel is located in the northeast corner of the WTDA, as shown on Figure 02. The channel conveys water from the Reservoir into Twin Lakes Creek. The channel replaces the former decant station located in the same area. The main design feature of the channel is a steel-reinforced, concrete wall which provides water retention and elevation control for the water level in the Reservoir. The physical details of the channel are summarized by the following:

- The concrete wall is approximately 17 m long and 0.3 m thick
- The central portion of the wall where the flow occurs is 7 m wide and has an invert elevation of approximately 370.2 m
- The wall contains sloping side walls (4(H):1(V)) and the elevation of the top of the side walls is approximately 370.8 m
- The concrete wall is founded into the underlying bedrock via a steel-reinforced, concrete footing
- The channel is armoured to approximately 370.8 m elevation, upstream and downstream of the wall
- A plunge pool is located downstream of the wall to provide energy dissipation during flooding events.

In 2007, a geosynthetic clay liner (GCL) was installed upstream of the concrete wall, as recommended in the 2006 inspection report. This was completed in response to observations of declining water levels upstream of the wall during periods of low inflows. The declining water levels were inferred to suggest seepage losses through the foundation of the wall. As such, the GCL approach was suggested as a way to limit the potential for these seepage losses.

In September 2008, the culverts in the East Twin access road that had previously impeded the flow from the Reservoir to the Polishing Pond were removed and the Reservoir is now considered to be a flow-through hydraulic system at the normal water level. Due to the limited depth of the breach, the former East Twin access road restricts flow into the former Polishing Pond area at lower water levels.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 10 through 14). The main observations are summarized by the following:

- During the inspection, the water level upstream of the wall was noted to be flowing approximately 1 cm above the elevation of the wall invert (Photos 10 through 12).
- Slumping and settlement of the perimeter slopes of the upstream Polishing Pond continued to degrade since the 2020 inspection (Photos 13 and 14). The area of active instability remains away from the outlet wall area. As such, there is limited concern with respect to the instability and its potential impact on the effectiveness of the outlet wall to function as intended, but it should continue to be visually inspected for changes.

A water level logger was installed in the remnant Polishing Pond during the 2020 inspection trip and left in place until it was downloaded during the 2021 inspection. No water level data is available for the Reservoir from the 2020-2021 monitoring season due to freezing damage sustained by the logger. Water level logger data for the Polishing Pond is shown with site air temperature data on Figure 03. As observed in previous years, the data suggests that as freezing air temperatures cause icing of the Reservoir, inflows into the remnant Polishing Pond are reduced and water levels in the remnant Polishing Pond drop. During August/September 2020, the drop in the water level of the Polishing Pond was 66 cm, comparable to recent years, where 60-70 cm drops have been observed. Although no water level data was collected from the Reservoir this year, data from recent years has shown a typical drop in Reservoir level of 12-13 cm. These observations support the concept that water cover in the Reservoir is maintained despite seepage losses from the remnant Polishing Pond typically observed at the end of the monitoring season. The logger in the polishing pond was maintained and re-deployed during the inspection. The logger in the Reservoir that was damaged due to freezing during the winter of 2019-2020 was replaced with a new logger.

The observed seepage losses and stability issues along the edge of the remnant Polishing Pond are thought to be related to the excavation of sediments from the Polishing Pond during site reclamation activities in 2005. Excavation of these sediments created a deeper pocket of water upstream of the wall, measured to be between 3 and 4 m in the deepest parts of the pond. This provides a heat source which has likely resulted in thawing of the ground beneath the pond.

Based on the water quality measurements collected since the East Twin Access Road was breached in 2008, the seepage losses through the foundation of the wall do not appear to be influencing the overall performance of the West Twin Area reclamation measures. As suggested by the water level data discussed previously, the impact of seepage losses on the main water level in the Reservoir is minimized by the various breaches creating flow restrictions between the Reservoir and the remnant Polishing Pond. Additionally, the seepage losses from the remnant Polishing Pond do not appear to be increasing with time, as demonstrated by the water level measurements collected since closure. In previous inspection reports, it has been suggested that additional mitigation measures be considered to reduce the seepage losses, pending additional monitoring data and inspection observations. Given the recent observations, additional mitigation measures are not considered to be required at this time but monitoring of the water levels in the Reservoir and remnant Polishing Pond should continue.

6.2.3. East Twin Creek Diversion Dyke and Channel

Construction Details

The East Twin Creek Diversion Dyke is located along Twin Lakes Creek between East Twin Lake and the West Twin Outlet Channel, as shown on Figure 02. The diversion dyke and channel re-directs flow from East Twin Lake away from its previous drainage course, which drained directly into West Twin Lake (the Reservoir). The flow from the diversion channel combines with the flow from the Reservoir downstream of the West Twin Outlet Channel.

The diversion dyke is approximately 2 m above the adjacent ground level and is comprised of sand, gravel, and cobbles derived from the nearby Twin Lakes sand and gravel deposit. A portion of the dyke was re-graded during reclamation construction to be less susceptible to erosion. Additionally, the re-graded portion of the dyke was armoured with riprap to prevent future erosion from occurring.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 15 through 17).

Previous inspections made recommendations to repair the left bank armouring material following observations of erosion along a section of the East Twin Creek Diversion Channel. In response to these recommendations, maintenance was undertaken during in 2018. The maintenance consisted of re-shaping the in-situ material and placement of additional locally available armour materials. The maintenance activities are described in detail in a separate memorandum appended to BGC's *Nanisivik Mine 2018 Annual Geotechnical Inspection Report (March 11, 2019)*. During the 2021 annual inspection, the maintenance work was visually observed to have performed suitably since 2018 (Photos 16 and 17). It is recommended that the diversion dyke continue to be inspected for additional erosion of the side slopes and maintenance be undertaken as necessary.

The seepage discharge observed at the toe of the left bank during previous inspections appeared similar in 2021. The seepage water is likely originating in the Polishing Pond and flowing within the active layer of the East Twin Creek Diversion Dyke. The seepage flow in 2021 was observed to be clear and free of sediment. The seepage may be exacerbating the previously observed erosion impacts at this location. No mitigation efforts to address the observed seepage are recommended at this time, but the discharge point should continue to be visually monitored, along with associated impacts.

6.3. Thermal Covers

The following sections provide a summary of each of the thermal covers constructed at site, including construction details, a summary of the observations made during the 2021 inspection, and reviews the monitoring data collected in 2021. A table documenting the instrumentation monitoring undertaken in 2021 is provided in Appendix III. No additional data collection is planned prior to August 2022, in-line with the monitoring schedule defined within the Water Licence.

An additional note on the interpretation of the geothermal monitoring data; for the purposes of interpretations made in this report, the following assumptions were made:

- In the active layer, ground conditions are considered “thawed” when ground temperatures of 0°C and warmer are observed.
- In the taliks, ground conditions are considered “thawed” when ground temperatures of warmer than -0.5°C are observed. This temperature adjustment accounts for freezing point depression effects which have been noted in the tailings talik at the site. As the freezing front progresses deeper within the taliks, a cooler freezing point depression can be expected as the solute concentrations increase in the remnant pore water.

6.3.1. Surface Cell Tailings Cover

Construction Details

A thermal cover was constructed over the tailings in the Surface Cell in 2004 and 2005. The thermal cover consists of a 1 m thick layer (minimum thickness) of granular shale overlain by a 0.25 m thick layer (minimum thickness) of armour material comprised of sand, gravel, and cobbles. It should be noted that, due to surface grade considerations, significantly increased shale thicknesses (greater than 2 m thick) were applied to approximately 30% of the Surface Cell. Additionally, due to practical construction considerations related to the grain size distribution of the armour materials, the armour layer thickness regularly exceeded 0.25 m. The shale was sourced from the Mt. Fuji and Area 14 borrow areas (Drawing 01). The armour material was sourced from the Twin Lakes Delta deposit (Drawing 01). The Surface Cell tailings cover is drained by a series of swales which convey surface water to the spillway inlet located at the south end of the Surface Cell. The spillway transfers water draining off the Surface Cell cover system into the Reservoir. It should be noted that surface flow is not regularly observed on the Surface Cell and that the majority of the water flow occurs sub-surface due to the coarse nature of the cover materials.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 18 through 23). The main observations are summarized by the following:

- The head pond at the entrance to the spillway at the south end of the cover was observed to be similar in size compared to previous years.
- As has been observed in previous inspections, some minor thermokarst features were noted along the south shoreline, along the east edge of the main drainage swale and just north of the E/W trench (Photo 18). These localized thermokarsts are not considered to

be negatively impacting the overall performance of the cover system. Additionally, the same thermokarst features have been observed in past inspections and do not appear to be changing with time, suggesting they are physically stable.

- No erosion of the cover materials was noted, but some minor settlement deformation in the bottom of the main drainage swale was observed closer to the spillway entrance, similar to observations made during previous inspections.
- The cracking noted in the northeast and southwest quadrants of the cover system in 2016 did not visually appear to change in width or extent since 2016 (Drawing 02). The cause of this cracking is uncertain but is likely related to thermal effects within the cover materials or continued freeze-back of pore water in the underlying tailings.
- Cracks and heaving in an oval pattern were observed near the central-southern portion of the cover (Drawing 02, Photos 20 through 22). The cracks are likely due to heaving of the underlying tailings material due to freeze-back. The cracks are up to approximately 60 cm wide and 30 cm deep. The heave appears to have grown in height since the 2020 inspection. At this time, the cracks are not considered to be negatively impacting the performance of the cover system. Options to monitor the rate of growth of the heave may be evaluated prior to future inspections.

No maintenance is recommended for the Surface Cell cover system, though the surface of the cover should continue to be visually inspected for additional deformation and thermal cracking.

Monitoring Data

The Surface Cell is instrumented with 10 thermistors, seven vibrating wire piezometers, six frost gauges and two monitoring wells. The location of each of these instruments is provided on Drawing 02. Select plots providing the results of the monitoring are provided, for interpretation purposes, on Figures 04 through 08.

The instrumentation has two main purposes; monitor the depth of the active layer thaw in the cover and monitor the ground temperatures and pore pressures in the talik during freeze-back. Monitoring wells originally installed in the Surface Cell and Test Cell taliks to monitor pore water quality during freeze-back are no longer functional due to freeze-back of the tailings and are no longer monitored in accordance with the approved geotechnical and geothermal monitoring program.

Figure 04 provides data from thermistors installed throughout the Surface Cell talik. The graphs illustrate the following:

- The ground thermal profile in the upper approximately 15 m is warmer than 2020, reflective of warmer air temperatures at site in 2020 and 2021.
- The upper 20 to 25 m of the ground profile appears to be frozen, as illustrated by data recorded from Thermistors BGC03-07, BGC03-09, BGC03-10, BGC03-11, BGC03-15, and BGC05-05.
- At depths greater than approximately 15 to 20 m, the tailings continue to freeze back, as illustrated by data recorded from Thermistors BGC03-09, BGC03-10, BGC03-11, and

BGC05-05, although the rate of freeze-back has slowed over the past several years, as expected.

Figure 05 illustrates the downward progression of the freezing front over time in the Surface Cell. The depth of the -0.5°C isotherm from various thermistors is plotted against the distance from the crest of the West Twin Dyke. The data suggests the -0.5°C isotherm has migrated downwards to a depth of 22 to 26 m bgs since the cover system was completed in 2005. The data also illustrates how the thickness of frozen ground increases with proximity to the West Twin Dyke.

Figure 05 also illustrates that the freeze-back of the Surface Cell talik continues to proceed quicker than anticipated, compared to the results of the geothermal analysis documented in BGC (February 6, 2004a). This is illustrated by comparing the observed depth of the -0.2°C isotherm with the freeze-back envelope predicted by the original geothermal modeling. The -0.2°C isotherm was used for this comparison as it was the freezing point depression assumed during the original geothermal modelling completed as part of the talik freeze-back assessment (BGC, February 6, 2004a).

Figure 06 provides data collected from the piezometers installed in the Surface Cell talik. The graphs indicate that all of the piezometers in the Surface Cell talik have frozen back in response to continued downward migration of the freezing front in the tailings. These piezometers were installed at depths ranging from 15 to 24 m bgs. The temperature readings within piezometer BGC05-13 have not been obtainable since 2012, and thus, only piezometric elevation has been plotted since this time.

Figure 07 illustrates the relationship between piezometer tip depth and the freeze-back temperature of the piezometers in the Surface Cell cover system. The freeze-back of the piezometer tips occurred at temperatures ranging from -0.5°C to -1.3°C , and the freeze-back temperatures appear to decrease with depth. For the purposes of this assessment, freeze-back of the piezometer tip is taken to be the time at which a significant drop or increase in erratic nature of the recorded pore pressure is observed. The deeper the piezometer tip, the lower the temperature before freeze-back occurred.

The closed system nature of the Surface Cell also creates a dimension of freezing which is related to the distance from the edge of the original lakebed. The further the piezometer is at lateral distance from the edge of the original lakebed, the lower the freeze-back temperature was recorded within the piezometer.

These relationships are likely related to the increasing solute concentration in the remnant talik as it becomes smaller and cryo-concentration occurs. The freezing point of the water becomes lower with a higher solute concentration near the centre of the talik.

Figure 08 shows the data collected from select Surface Cell frost gauges. The data suggests that the active layer thaw in 2021 was approximately 10 cm shallower than in 2020. With the exception of Frost Gauge 3, which shows an active layer extending approximately 10 cm into tailings, the active layer thaw remained within the cover material. Since construction of the closure works in 2004, the maximum annual active layer thickness has generally decreased, indicating improved

overall thermal performance, believed to be largely due to increased thickness of the ice-saturated layer at the base of the cover. In recent years the depth of thaw appears to be stabilizing near the top of the inferred ice-saturated layer.

The results of water quality testing undertaken on samples collected at the inlet of the West Twin Dyke Spillway are provided on Figure 09. The sample collected in late August 2021 exhibited a total zinc concentration of 0.02 mg/L. This total zinc concentration is a decrease from the concentrations measured in 2019 (0.04 mg/L) and 2020 (0.03 mg/L). For comparison, since 2008, the measured annual maximum has varied from below the detection limit (<0.01 mg/L) to 0.04 mg/L. The water quality monitoring data suggests that the cover system continues to perform as intended.

6.3.2. West Twin Dyke

Construction Details

The West Twin Dyke is a frozen core, upstream constructed, earth fill dyke that separates the Surface Cell and the Reservoir (Drawing 03). The dyke is constructed of frozen, compacted shale and founded on frozen, settled tailings. The dyke is approximately 14 m high and the downstream face slopes at an angle of approximately 15°. The downstream face of the dyke was surfaced with a 0.25 m thick layer (minimum thickness) of sand, gravel and cobbles sourced from the Twin Lakes Delta.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 24 through 27). The main observations made during the inspection are summarized by the following:

- No settlement or cracking of the crest and immediate upstream area was noted
- The downstream face of the dyke shows no indications of erosion or settlement
- No seepage was noted on the face of the dyke or at the toe of the dyke.

In general, the dyke appeared to be in a satisfactory condition and no maintenance is recommended.

Monitoring Data

The West Twin Dyke was instrumented with five thermocouple cables installed within the dyke, as well as four thermistors and one vibrating wire piezometer installed from the crest of the dyke. The location of each of these instruments is provided on Drawings 02 (thermistors and piezometers) and Drawing 03 (thermocouple cables). Select plots providing the results of the monitoring, for interpretation purposes, are provided on Figure 10.

Figure 10 provides data from Thermistor BGC03-34, which provides a geothermal monitoring profile from 5 m below the crest of the dyke to approximately 14 m bgs. It also provides data from an additional thermistor installed from the crest of the dyke (BGC05-15), as well as one vibrating wire piezometer (BGC05-17). The 2021 thermistor data indicates the following:

- The profile at the crest of the dyke, within Thermistor BGC05-15, is colder than -3°C to at least 30 m bgs, approximately 14 m below base of dyke.
- The upper approximately 15 m, as observed in BGC03-34 and BGC05-15, has warmed slightly compared to 2019 and 2020, reflecting warmer than average air temperatures at site in the past few years.
- Below approximately 15 m depth the cooling trend observed since the installation of the instruments has continued, as observed in BGC05-15.
- The vibrating wire piezometer BGC05-17 was malfunctioning in August 2021. Therefore, no pore water temperature or piezometric elevation data was recorded in August 2021. This piezometer froze back in 2016 at a temperature of approximately -1.2°C, and was recorded to be -3°C in 2020.

6.3.3. Test Cell Area

Construction Details

The Test Cell area consists of the Test Cell, former Test Cell Dyke, and Toe of Test Cell Dyke. A thermal cover was constructed over the Test Cell area in 2004 and 2005. The thermal cover consists of a 1 m thick layer (minimum thickness) of granular shale overlain by a 0.25 m thick layer (minimum thickness) of armour material comprised of sand, gravel and cobbles. It should be noted that, due to surface grade considerations, significantly increased shale thicknesses (greater than 2 m) were applied to approximately 20% of the Test Cell. Additionally, due to practical construction considerations related to the grain size distribution of the armour materials, the armour layer thickness regularly exceeded 0.25 m. The shale was sourced from the Mt. Fuji, East Twin, and Area 14 borrow areas (Drawing 01). The armour material was sourced from the Twin Lakes Delta deposit (Drawing 01). The Test Cell tailings cover is drained by a main swale which conveys surface water directly into the Reservoir.

The Test Cell Dyke is an earth fill dyke that separates the Test Cell and the Reservoir (Figure 02). The dyke is constructed of frozen, compacted shale and founded on frozen, settled tailings. The dyke was approximately 4 m high. During reclamation, the top 2 m of shale material in the dyke was removed and placed in the Test Cell as cover material. The remnant dyke was surfaced with a layer of armour material, approximately 0.25 m thick. As such, the dyke is now essentially integrated into the Test Cell cover.

A thermal cover was constructed over the tailings at the toe of the Test Cell Dyke in 2005. The thermal cover consists of a 1 m thick (minimal thickness) layer of granular shale overlain by a 0.25 m thick layer (minimal thickness) of armour material comprised of sand, gravel and cobbles. It should be noted that, due to surface grade considerations, shale fill thickness in excess of the 1 m minimum thickness was applied to the tailings beach at the toe of Test Cell Dyke, especially immediately adjacent to the remnant Test Cell dyke. The shale was sourced from the Mt. Fuji and Area 14 borrow areas (Drawing 01). The armour material was sourced from the Twin Lakes Delta deposit (Drawing 01). The riprap was sourced from the dolostone outcrop at the south end of the West Twin Dyke.

Inspection Conditions

Select photos from the inspection of the Test Cell and Test Cell Dyke are provided in Appendix I (Photos 28 through 34). The main observations are summarized by the following:

- No erosion or ponding was observed.
- Similar to previous inspection observations, the north-south arm of the Test Cell Dyke and the Test Cell Cover just inside of the dyke remains undulating, suggesting some amount of settlement of the cover materials has occurred (Photos 29 and 30). This undulating nature of the cover in this area has not noticeably changed in the last several years and the cover is overbuilt in this area due to grade requirements. The undulating nature is not considered to negatively impact drainage or the thermal performance of the cover and, as such, this area is not of concern.

Thermal cracks (<20 cm wide and <20 cm deep) and minor thermokarsting were observed in some areas of the cover system but are not considered to be negatively impacting the performance of the cover. Photo 31 shows an example of minor thermokarsting. Photo 32 is a composite aerial UAV image showing the overall surface of the cover system.

Selected photos from the inspection of the cover along the toe of the Test Cell Dyke and through the Test Cell outlet is provided in Appendix I (Photos 33 through 36). The main observations are summarized by the following:

- No erosion of the cover was observed
- No disturbance due to ice plucking of the riprap was observed.

In general, the tailings cover in the Test Cell area appears to be in satisfactory condition. As such, no maintenance is recommended.

Monitoring Data

The Test Cell area is instrumented with seven thermistors, five vibrating wire piezometers, and four frost gauges. As previously noted in the Surface Cell monitoring review, the monitoring wells installed in the Test Cell talik are frozen to the bottom due to talik freeze-back and are no longer monitored in accordance with the approved monitoring program. The location of each of these instruments is provided on Drawing 03. Select plots providing the results of the monitoring are provided on Figures 11 through 14.

Figures 11 and 12 respectively provide geothermal and piezometric monitoring data collected from the Test Cell Cover in 2021. The data indicates the following:

- The active layer thaw was confined within the cover materials throughout 2021. Frost gauges FG-7 and FG-8 indicate that the active layer was approximately 1.1 to 1.2 m thick (approximately 0.2 to 0.3 m above the base of the cover). The 2021 active layer thickness measurements are smaller than 2019 and 2020, likely reflective of the below average Thaw-Degree-Days at site in 2021.
- The subsurface profile between 1.5 and 15 m depth in the Test Cell at the base of the West Twin Dyke (BGC05-04) is colder than -0.5°C and is presumed to be frozen. At 15 m

depth, temperatures of below -7°C are measured. The rate of cooling has slowed in recent years, indicating that the geothermal profile is approaching thermal equilibrium.

- The pore pressures and ground temperatures measured at Piezometer BGC05-18 (19 m depth) have decreased considerably since 2016. This suggests the piezometer has obtained freeze-back at approximately -0.7°C , with a current temperature of approximately -5.2°C .
- Similarly, as above, the pore pressures and ground temperatures measured at Piezometer BGC05-22 (23 m depth) have also decreased considerably since the 2016 inspection. This suggests the piezometer has obtained freeze-back at approximately -0.8°C , with a current temperature of approximately -1.7°C .
- The monitoring data from Piezometer BGC05-20 shows that pore water temperature measured at the piezometer tip, installed at approximately 18 m bgs, has remained relatively stable since 2013 at between -0.3°C and -0.5°C . The pore pressure continued a gradual increasing trend observed since 2013 that may be an indication of increasing hydraulic isolation between the reservoir and the test cell talik, as anticipated.

Select plots providing the results of the monitoring of the Test Cell Dyke are provided on Figure 13. The monitoring data indicates the following:

- Data from thermistors BGC03-22 and BGC05-29 suggest that the dyke and foundation beneath the dyke is frozen to approximately 25-28 m bgs. The geothermal profile above approximately 18 m is warmer than 2020, but the 2021 geothermal profile below 18 m is comparable to, or slightly cooler than, 2020.
- In thermistor BGC03-22, the node at 27 m cooled slightly in 2021 after remaining fixed near the freezing point for nearly a decade. This freezing time lag near the freezing point is expected, as a result of latent heat effects. This suggests that unfrozen tailings remain below 27 m but the tailings continue to slowly freeze back.
- The vibrating wire piezometer BC05-24, installed approximately 20 m bgs beneath the dyke, has frozen back as indicated by the tip temperature around -5.3°C and the corresponding variability in pore pressures. The recorded pore pressure is considered to be localized and associated with the freeze-back of the piezometer tip and is not considered to be representative of pore water pressures throughout the Test Cell talik.

Select plots providing the results of the monitoring of the tailings cover at the toe of the Test Cell Dyke are provided on Figure 14. The graphs indicate the following:

- The subsurface profile at the toe of the Test Cell Dyke (BGC05-27) between 3 and 22 m bgs is colder than -0.5°C and is presumed to be frozen. As observed elsewhere on site, the upper 17 m of the geothermal profile has warmed since 2020, reflective of warmer than average ambient temperatures in 2020 and 2021. The monitoring data demonstrates that the upper 22 m of the subsurface profile is frozen, despite being along a shoreline which was periodically submerged in water during operations of the tailings disposal area. The fact that permafrost exists at this location, to the extent it does, is considered beneficial to the overall Test Cell talik freeze-back. This is because it exceeds expectations and assumptions made in the contaminant loading model (CanZinco, March 2004) which assumed a completely thawed tailings profile adjacent to the water.

- The monitoring data from Piezometer BGC05-28, installed approximately 19 m bgs, indicates a piezometric elevation of about 370 metres above sea level (m asl). This is consistent with the elevation of the water level in the Reservoir and suggests hydraulic connectivity between the tailings at depth and the Reservoir. The pore water temperature at the piezometer tip remained at -1.8°C in 2021, as in 2019 and 2020.

Figure 07 illustrates the relationship between piezometer tip depth and the freeze-back temperature of the piezometers in the Surface Cell and Test Cell cover systems. In contrast to the Surface Cell, the hydraulic connectivity that is present between the Test Cell and the Reservoir creates a cooler temperature needed to obtain freeze-back closer to the reservoir. Two more piezometers (BGC05-20 and BGC05-28) have yet to freeze back in the Test Cell. The data obtained when these piezometers freeze back will provide more context for the rate of freeze-back within the Test Cell.

6.3.4. Toe of West Twin Dyke Tailings Cover

Construction Details

A thermal cover was constructed over the tailings at the toe of the West Twin Dyke in 2005. The thermal cover consists of a 1 m thick layer (minimum thickness) of granular shale overlain by a 0.25 m thick layer (minimum thickness) of armour material comprised of sand, gravel, and cobbles. The shale was sourced from the Mt. Fuji and Area 14 borrow areas (Drawing 01). The armour material was sourced from the Twin Lakes Delta deposit (Drawing 01). The riprap was sourced from the dolostone outcrop at the south end of the West Twin Dyke.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 37 through 39). The main observations are summarized by the following:

- No erosion of the cover was observed.
- As observed during previous inspections, some minor thermokarst features were present, but was not seen to be negatively impacting the overall performance of the cover system. No visual changes in the appearance of these thermokarst features have been noted in recent years, suggesting the area is generally physically stable.
- No erosion or ice plucking of the riprap along the shoreline was observed.

No additional maintenance items were recommended.

Monitoring Data

The tailings cover at the toe of the West Twin Dyke is instrumented with two thermistors. The location of each of these instruments is provided on Drawing 03. Select plots providing the results of the monitoring are provided on Figure 15. The graphs indicate the following:

- In 2021, no data below 4 m could be collected from Thermistor BGC05-26. Since 2010, the subsurface profile below 3 m at this location, as illustrated by the data collected from Thermistor BGC05-26, has remained colder than -5°C and has been frozen to at least 24 m bgs, the depth of the bottom of the instrument. The bottom 15 m of the instrument is

measuring ground temperatures in the bedrock, demonstrating the frozen nature of the bedrock near the base of the West Twin Dyke. Since recent performance has been positive, the active layer portion remains functional, and nearby thermistor 03-19 remains functional, replacement of this instrument is not considered necessary at this time.

- The monitoring data collected from Thermistor BGC03-19 indicates slightly warmer temperatures than 2020, reflective of warmer surface temperatures in 2021. The ground profile remains frozen from approximately 3 m depth to at least the bottom of the instrument at 11 m depth.

West Twin Disposal Area Water Quality

As required in Water Licence 1AR-NAN2030, a single water quality sampling event was undertaken at the West Twin Outlet Channel in August 2021. This channel is considered the final discharge point for water from the WTDA before entering the environment in Twin Lakes Creek. The sample was collected and forwarded to a laboratory for analysis. The sample was tested for pH, conductivity, Total Suspended Solids (TSS), sulphate, total metal concentrations, and ammonia (NH₃). The total zinc, total lead, total cadmium, sulphate and TSS concentrations observed at the West Twin Outlet Channel in 2021 are illustrated on Figure 16. The total zinc, lead, and cadmium concentrations observed in the 2021 sample met discharge criteria, as samples have since the covers were completed in 2005. The maximum total zinc concentration was observed to be 0.05 mg/L, well below the discharge criteria of 0.25 mg/L. The low metals and sulphate concentrations suggest that the thermal covers and the water cover in the Reservoir are effective in limiting metal loading to the water in the Reservoir.

BGC's report titled "2021 Annual Water Quality Monitoring Report, Nanisivik Mine, Nunavut," dated March 2022, should be referenced for a detailed review of the results of the water quality monitoring program undertaken in 2021.

6.3.5. Landfill Cover

Construction Details

A thermal cover was constructed over the Nanisivik Landfill in 2005. The thermal cover consists of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.25 m thick layer (minimum thickness) of armour material comprised of sand, gravel, and cobbles. The shale was sourced from the Townsite Shale borrow area. The armour material was sourced from the Twin Lakes Delta deposit. The face of the landfill is sloped at approximately 3(H):1(V).

It should be noted that the thermal cover constructed at the Landfill was built over an existing surficial shale cover that was continuously placed and maintained during operations as part of the on-going landfill operating procedures (for pest control and protection against wind transport). No attempts were made during construction of the thermal cover in 2005 to verify the existing cover thickness and thereby, reduce the fill requirements. Therefore, it can be assumed that the thermal cover is thicker than just the material placed in 2005.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 40 through 44). The main observations are summarized by the following:

- No erosion of the cover was observed, either on the upper flatter portion of the cover or on the sloping face of the Landfill.
- No seepage directly from the landfill cover was observed. However, because of rainfall shortly before the 2021 inspection, some flow was observed adjacent to the toe of the cover at the Northeast corner of the landfill cover, a portion of which likely flows along the ice-saturated layer within the landfill cover.
- Some exposed shale has previously been observed on the lower portion of the west face, but no changes were noted during this inspection. The exposed shale is due to an insufficient amount of armour material available for covering during construction and is not related to erosion. Previous attempts undertaken to spread the armour over the exposed shale were determined to be impractical from a construction standpoint. Considering the observed stability of the area since construction, additional maintenance is not considered necessary.
- Some minor cracking and thermokarst features have been observed along the upslope water deflection berm and in the area southwest of the cover in past inspections. This has resulted in a minor amount of surface water running along the west edge of the cover system. This water deflection berm was not a design element, and pre-dates the reclamation of the facility. Recent progression of the cracking and thermokarsting in this area was observed during the 2021 inspection, resulting in increased surface water flow along the western margin of the cover. This flow is not considered to be negatively impacting the performance of the adjacent landfill cover system and no maintenance is considered necessary at this time.
- No areas of settlement or thermokarst features were observed on the surface of the landfill cover system.

No maintenance items were recommended.

Monitoring Data

The Landfill cover is instrumented with one thermistor and one frost gauge. The location of each of these instruments is provided on Drawing 04. Select plots providing the results of the monitoring are provided on Figure 17. The graphs indicate the following:

- The active layer thaw did not penetrate the underlying waste material throughout 2021. The depth of active layer thaw recorded in 2021 was comparable to measurements collected in 2020.
- The overall geothermal performance of the landfill cover in 2021 was observed to be similar compared to recent years. The geothermal profile between 3 and 15 m bgs was slightly warmer in 2021 compared to 2020, remaining between -3°C and -11°C, reflective of the warmer than average ambient temperatures in recent years, as noted elsewhere. However, at the base of the instrument, near 15 m bgs, the temperature has remained

relatively stable in recent years, suggesting ground conditions are approaching thermal equilibrium at depth.

- The maximum temperature recorded at the thermistor node located at 2.3 m bgs, near the cover/landfill debris interface, was approximately -2.9°C.
- The landfill debris underlying the cover remained frozen throughout the year.

6.3.6. West Open Pit

Construction Details

A thermal cover was constructed over the West Open Pit in 2006. The thermal cover consists of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.35 m thick layer (minimum thickness) of armour material comprised of sand, gravel and cobbles. The shale was sourced from the Townsite Shale borrow area. The armour material was sourced from the local borrow source located along the road between the 09S portal and the 17 North Portal. The face of the West Open Pit cover is sloped at a maximum angle of approximately 3(H):1(V).

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 45 through 48). The main observations are summarized by the following:

- No erosion of the armour surface was noted
- No areas of settlement or thermokarst features were observed
- No advancement in the crack width or length in the crown pillar has been observed in at least 10 years
- No seepage water was observed at the toe of the cover.

Based on the observations noted above, the West Open Pit waste rock cover is considered to be physically stable. As such, no maintenance is recommended.

Monitoring Data

The West Open Pit cover is instrumented with one thermistor (BGC08-01), but this instrument was non-functional and unable to be read during the 2020 and 2021 inspections. The location of this instrument is provided on Drawing 05. It is suspected that this instrument has reached the end of its useful lifespan, and it is unlikely that it will resume functionality. Although this is the only instrument installed in the West Open Pit cover system, the performance of the cover has been satisfactory since the cover was built, and previous data suggests that the waste rock used to backfill the open pit has frozen back. As such, replacement of this instrument is not considered necessary at this time. It remains recommended that the West Open Pit continue to be visually monitored during annual inspections.

6.3.7. East Open Pit

Construction Details

A thermal cover was constructed over the East Open Pit in 2005. The thermal cover consists of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.35 m thick layer (minimum thickness) of armour material comprised of sand, gravel, and cobbles. The shale was sourced from the Shale Hill borrow area. The armour material was sourced from the local borrow source located along the road between the K-Baseline Portal and Kuhulu Lake. The face of the East Open Pit cover is sloped at a maximum angle of approximately 3(H):1(V). A remnant highwall exists along the south edge of the pit area. The remnant highwall ranges from 1 to 5 m high and is sloped back at an angle of approximately 60°. A bench exists between a portion of the remnant highwall and the main portion of the cover system.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 49 through 53). The main observations are summarized by the following:

- Some surface (rill) erosion was noted on the surface of the cover in 2021, as it has been during previous inspections (Photo 49). No advancement of the erosion has been noted in recent years.
- Some cracking of the cover materials was observed, in similar condition to previous inspections. This cracking is thought to be related to thermal expansion and contraction of the cover materials and settlement of the underlying backfill materials.
- Some cracking was noted on the crown pillar of the cover (Photos 50 through 52). No advancement in the crack width or length in the crown pillar has been observed in at least 10 years.
- No areas of settlement or thermokarst features were observed on the surface of the cover.

The minor erosion noted on the surface of the cover was anticipated. The armour material at this location contains a fine-grained fraction that was expected to wash away with time leaving behind the coarse-grained fraction, a process known as self-armouring. As such, the armour thickness at this location, and many others where alternative armour materials were used, was increased to 0.35 m. The coarse-grained fraction of the armour material is expected to limit the amount of erosion that can occur, without negatively impacting the geothermal performance of the cover.

As mentioned, the cracking in the crown pillar at the East Open Pit was not observed to have progressed. The cracking coincides with the mined-out rib pillar and the area of the 39 Portal. No opening to the underground has been observed during any inspection undertaken since reclamation of the East Pit in 2005. As such, the cracking was not seen to be of immediate concern especially given the lack of progression over the past decade. Accordingly, no maintenance is recommended, but the crown pillar should continue to be visually monitored for additional deformation.

Monitoring Data

The East Open Pit Waste Rock cover is instrumented with two thermistors and two frost gauges. The location of each of these instruments is provided on Drawing 06. One of the frost gauges (FG-14) ceased functioning in 2018. Select plots providing the results of the monitoring are provided on Figure 18, which indicate the following:

- Data from Thermistor BGC05-02, installed in the area with a thin layer of waste rock backfill (approximately 3 m thick), indicates that the waste rock remains frozen back. The geothermal profile is comparable to what was observed in 2020.
- Data from Thermistor BGC05-03, installed in the area with a thicker layer of waste rock backfill (approximately 9 m thick), indicates the waste rock, and hydrocarbon contaminated soil buried at depth, remains frozen back. The geothermal profile is comparable to what was observed in 2020.
- The rate of cooling of ground temperatures recorded in both BGC05-02 and BGC05-03 suggest that ground conditions are approaching thermal equilibrium at depth.
- The active layer monitoring data from Thermistor BGC05-02 and BGC05-03 indicates that the active layer was confined within the cover materials throughout 2021. Thawing remained confined to the cover material, with an approximate active layer thickness of 1.2 to 1.5 m, approximately 0.8 m to 1.2 m above the base of the cover system.
- Frost gauge FG-13 indicates that the active layer was approximately 1.6 m thick, which is approximately 0.8 m above the base of the cover, shown on Figure 18. The active layer thickness was slightly less than 2020.

6.3.8. East Trench Waste Rock Cover

Construction Details

A thermal cover was constructed over the East Trench in 2005. The thermal cover consists of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.35 m thick layer (minimum thickness) of armour material comprised of sand, gravel, and cobbles. The shale was sourced from the Shale Hill shale borrow area. The armour material was sourced from the local borrow source located along the road between the K-Baseline Portal and Kuhulu Lake. The face of the East Trench cover is sloped at an angle ranging between 4(H):1(V) and 6(H):1(V).

Inspection Conditions

An aerial UAV photo from the inspection is provided in Appendix I (Photo 54). The main observations are summarized by the following:

- As noted in previous inspections, minor surface (rill) erosion was observed near the upslope edge of the cover where seepage water periodically discharges from natural rock outcrops onto the surface of the cover. The coarse-grained fraction of the surface armour layer in this area is limiting the progression of the erosion. No advancement of this erosion was noted in 2021.
- No seepage was observed at the toe of the cover.

In general, the East Trench cover appears to be physically stable. As such, no maintenance is recommended.

6.3.9. Oceanview Open Pit Waste Rock Cover

Construction Details

A thermal cover was constructed over the Oceanview Open Pit in 2005. The thermal cover consists of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.35 m thick layer (minimum thickness) of armour material comprised of sand, gravel, and cobbles. The shale was sourced from the Shale Hill borrow area (Drawing 01). The armour material was sourced from the Chris Creek "A" borrow area (Drawing 01). The face of the Oceanview Open Pit cover is sloped at a maximum angle of approximately 3(H):1(V). The surface of the cover in the bottom of the pit slopes to the north at a grade of approximately 3%.

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 55 through 58). The main observations are summarized by the following:

- The upslope water deflection berm appeared to be effective in directing surface water away from the cover, although no flow was observed during the inspection.
- Minor surface erosion (<10 cm deep) was noted along the backslope at the south end of the cover, as has been noted during previous inspections (Photo 55). Some minor ponding of water was observed at the upstream end of the erosion (Photos 56 and 57). The erosion appears to be slowly progressing, based on visual observations, but is not expected to impact the overall performance of the cover system. Self armouring of the erosion areas is occurring as the coarser particles within the armour layer are exposed and concentrated at surface, as anticipated.
- Some seepage was observed at the toe of the cover.

- Some acid rock drainage staining was observed on the east edge of the cover, as it has been during previous inspections (Photo 58). The stained area originates upslope of the extent of the cover and appears to cover a similar extent to what has been observed in previous inspections.
- The minor sinkhole observed in the middle of the cover surface during the 2015 inspection did not appear to have grown since.
- In general, the Oceanview Open Pit cover appears to be in satisfactory condition. As such, no maintenance is recommended. The surficial erosion should continue to be visually monitored for additional progression.

As discussed previously, minor erosion of the surface of the cover was anticipated. Similar to the East Open Pit cover, the armour material at this location contains a fine-grained fraction that was expected to wash away with time. As such, the armour thickness was increased to 0.35 m. The coarse-grained fraction of the armour material is expected to limit the amount of erosion that can occur, without negatively affecting the geothermal performance of the cover.

Monitoring Data

The Oceanview Pit Waste Rock cover is instrumented with one thermistor and one frost gauge. The location of each of these instruments is provided on Drawing 07. Select plots providing the results of the monitoring are provided on Figure 19. The graphs indicate the following:

- The active layer was confined within the cover materials throughout 2021.
- The maximum active layer thaw depth indicated by Thermistor BGC05-01 was estimated to be approximately 1.0 m bgs, which is approximately 1.3 m above the base of the cover.
- The waste rock underlying the cover has frozen back and remained frozen throughout 2021.
- Thermistor BGC05-01 shows that the 2021 geothermal profile above 5 m depth is cooler than previous recent years. Below 5 m depth, the geothermal profile is comparable with recent years, suggesting ground conditions are approaching thermal equilibrium at depth.
- Frost gauge FG-16 indicates that the thaw depth was approximately 0.9 m thick in August, approximately 1.5 m above the base of the cover, which is much shallower than recent years, as shown on Figure 19.

6.3.10. Area 14 Waste Rock Cover

Construction Details

Area 14 is a satellite ore body situated on a west-facing slope, approximately 1 km to the east of East Twin Lake (Drawing 01). A waste rock pile was created outside the portal during mining operations. In 1988, the waste rock pile was flattened and a thermal cover was constructed over the top of the waste rock pile, but the face was left exposed.

In 2005, the thermal cover at the Area 14 waste rock pile was completed by constructing a cover over the exposed face and armouring the entire surface of the cover. The thermal cover consists of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.35 m thick layer (minimum thickness) of armour material comprised of sand, gravel, and cobbles. All shale was sourced from the Area 14 shale borrow area (Drawing 01). All armouring material was sourced from the hill side immediately north of the Area 14 portal.

Inspection Conditions

A photo from the inspection is provided in Appendix I (Photo 59). The main observations are summarized by the following:

- No erosion of the cover materials was observed
- No areas of settlement or thermokarst features were observed on the surface of the cover
- No seepage was noted at the toe of the cover.

In general, the Area 14 waste rock cover appears to be in a physically stable condition. As such, no maintenance is recommended.

Monitoring Data

The Area 14 Waste Rock cover is instrumented with one frost gauge, with the location provided on Drawing 08. Frost gauge FG-15 indicates that the active layer was approximately 1.1 m thick, which is 1.2 m above the base of the cover, as shown on Figure 20. The depth of the active layer has not changed greatly since 2006, suggesting the cover performance is generally stable.

6.3.11. Upper Dump Pond Tailings Cover

Construction Details

The upper dump pond was an emergency tailings storage containment cell located between the water tank and the West Twin Disposal Area, as shown on Drawing 01. A thermal cover was constructed over the tailings in the Upper Dump Pond in 2005. The thermal cover consists of a 2 m thick (minimal thickness) layer of granular shale overlain by a 0.25 m thick layer (minimal thickness) of armour material comprised of sand, gravel, and cobbles. The shale was sourced from the Townsite shale borrow area (Drawing 01). The armour material was sourced from the Twin Lakes Delta deposit (Drawing 01).

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photos 60 through 62). The main observations from the inspection are summarized by the following:

- No erosion of the surface of the cover was observed
- No seepage was noted at the toe of the cover
- No areas of settlement or thermokarst features were observed on the surface of the cover.

In general, the Upper Dump Pond tailings cover appears to be in a physically stable state. As such, no maintenance is recommended.

Monitoring Data

The Upper Dump Pond tailings cover is instrumented with one frost gauge. The location of this instrument is provided on Drawing 09. Frost gauge FG-17 indicates that the active layer was approximately 1.5 m thick, which is 0.85 m above the base of the cover, shown on Figure 21. The active layer thickness in 2021 falls within the range observed in recent years.

6.3.12. Industrial Complex Foundation Cover

Construction Details

The Industrial Complex is located approximately 1 km north of the town site (Drawing 01). The Industrial Complex housed the concentrator, DMS circuit, power plant, maintenance shops, warehouse, administration and technical offices, and associated facilities. The facility was built on bedrock and a reinforced concrete foundation.

The Industrial Complex was dismantled between 2005 and 2006 and the remnant foundation was backfilled with metals contaminated soils. In 2008, a thermal cover was constructed over the backfilled foundation. The thermal cover consists of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.35 m thick layer (minimum thickness) of armour material. The shale was sourced from the Mill Area deposit and the armour materials were locally sourced. The sloping face of the cover is approximately 3(H):1(V).

Inspection Conditions

Select photos from the inspection are provided in Appendix I (Photo 63 and 64). The main observations made during the inspection are summarized by the following:

- No erosion of the surface of the cover was observed
- No settlement or thermokarst features were observed on the surface of the cover
- No seepage was observed at the toe of the cover.

In general, the Industrial Complex cover appears to be physically stable. As such, no maintenance is recommended.

Monitoring Data

The Industrial Complex Foundation cover is instrumented with one thermistor. The location of this instrument is provided on Drawing 10. Select plots providing the results of the monitoring are provided on Figure 22. The graph indicates the following:

- The metals contaminated soils used to backfill the foundation footprint have frozen back.
- The active layer thaw (approximately 1.8 m) was confined within the cover materials throughout 2021, approximately 0.45 m above the base of the cover system, similar to 2019 and 2020.
- As expected, due to the shallow depth of the thermistor, the geothermal profile beneath the cover has warmed as a result of recent warm years but falls within the range observed in recent years.

6.4. Mine Openings

6.4.1. 00/01 Portals and Crown Pillar

Construction Details

00 Portal

The 00 Portal is located at the edge of the West Open Pit at the western end of the mine, as illustrated on Drawing 01. The 00 Portal was the principal access at the western extremity of the mine. The portal measured approximately 5 by 5 m in cross section. The brow immediately above the portal was approximately 4 to 5 m high.

In 2005, the portal was backfilled with waste rock. The backfill was placed approximately to within 1 m of the top of the portal and into the portal approximately 5 m from the entrance. The backfill extended outside the portal face and was sloped at an angle of approximately 3(H):1(V) and graded into the overall backfill of the West Open Pit. A thermal cover was subsequently constructed over the waste rock as part of the West Open Pit thermal cover.

01 Portal

The 01 Portal was located at the western end of the mine, as shown on Drawing 01. The 01 Portal housed the main ventilation fans during mining operations which were mounted in a plate steel bulkhead. The portal opening was approximately 22 m wide and 4 m high. The brow immediately above the portal was approximately 4 to 5 m high.

In 2005, the portal was backfilled with waste rock. The backfill was placed approximately to within 1 m of the top of the portal and into the portal up to the face of the bulkhead. The backfill extended outside the portal face and was sloped at an angle of approximately 3(H):1(V) and graded into the overall backfill of the West Open Pit. A thermal cover was subsequently constructed over the waste rock as part of the West Open Pit thermal cover.

00/01 Crown Pillar

A stope connecting the 00 and 01 portals was located approximately 5 m behind the West Open Pit highwall. A portion of the rock between the 00 and 01 portals, known as the 00/01 rib pillar, was removed during later stages of mine development as part of the pillar recovery program. After the recovery of a portion of the rib pillar, a crack developed in the crown pillar above the area that had been mined. In 2005, a fill pillar was constructed beneath the cracked portion of the crown pillar to provide additional support and prevent development of an opening into the mine workings if the pillar were to collapse. The pillar was constructed out of waste rock and was constructed approximately to within 1 m of the top of the opening.

Inspection Conditions

The area of the West Open Pit cover where the portals had existed was inspected in 2021. The observations are summarized by the following:

- No indications of surface deformation were observed
- No indications of seepage from the mine workings were observed.

No maintenance of the portal plugs or the cover over the portal plugs is recommended.

The crown pillar was also inspected from surface. The observations are summarized by the following:

- Similar to previous inspection observations, a small crack (1 - 3 cm wide) was observed in the crown pillar area (Photos 45 and 46). Based on visual observations, the size of the crack has not changed relative to previous years, and no additional cracking has occurred.
- No visually distinguishable deformation was observed in the crown pillar.
- Overall, no significant changes have been observed in the West Open Pit crown pillar since the fill pillar was constructed in 2005.

In general, the portal plugs constructed for the 00 and 01 portals and the 00/01 crown pillar appear to be in satisfactory condition. It is recommended that the crown pillar area continue to be visually monitored to check for further propagation of the cracking.

6.4.2. 17 North Portal

Construction Details

The 17 North Portal was a culverted portal giving access to the Main Ore Zone. The location of the portal is illustrated on Drawing 01. The 17 North Decline was approximately 5 m by 5 m in cross section and the culvert was half round with a diameter of 5 m and a length of 28 m. The culvert was supported by a 0.25 m thick by 2 m high concrete wall on either side and it extended 5 m inside the dolostone bedrock of the drift.

In 2005, the culvert was removed, and the portal was backfilled with granular shale derived from the Shale Hill borrow area. The backfill was placed to within 1 m of the top of the portal and extended into the portal for approximately 4 m. The backfill extended outside the portal face and was sloped at an angle ranging between 4(H):1(V) and 7H:1V and graded into the surrounding topography. A 0.35 m thick layer of armour material, derived from the Kuhulu Lake borrow area, was then applied to the surface of the shale backfill.

Inspection Conditions

A select photo from the inspection is provided in Appendix I (Photo 65). The main observations are summarized by the following:

- No erosion of the surface of the cover was observed
- No seepage was observed at the toe of the cover
- The small amount of water flowing along the east edge of the portal cover during the 2017 inspection was not observed in 2021.

In general, the 17 North Portal cover appears to be physically stable and in satisfactory condition. As such, no maintenance is recommended.

6.4.3. Oceanview Portal

Construction Details

The Oceanview Portal was a bare rock entrance into the north side of the Oceanview underground workings. The location of the portal is illustrated on Drawing 01. The Oceanview decline had a cross section of approximately 5 by 5 m. The brow of the portal was approximately 5 m in height.

Prior to 2004, the portal had been backfilled with waste rock and covered over with locally derived overburden materials. In 2005, a thermal cover was constructed over the existing portal plug. The cover consisted of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.35 m thick layer of armour material consisting of sand, gravel, and cobbles. The shale was derived from the Shale Hill borrow area. The armour material was derived from the Chris Creek "A" deposit. The thermal cover was extended to the east and north of the portal entrance in an old ore stockpile area. Additionally, a water deflection berm was constructed upslope of the cover extension to prevent concentrated surface water from flowing over the cover area.

Inspection Conditions

A select photo from the inspection is provided in Appendix I (Photo 66). The main observations from the inspection are summarized by the following:

- A small area of surficial settlement was observed near the southwest corner of the portal cover. The settlement area appears to have stabilized as it has not changed significantly since it was first observed in 2006.
- Some minor cracking was noted along the east edge of the portal cover, as has been noticed in previous inspections. The condition of the cracking does not appear to have changed in several years.
- No seepage was observed at the toe of the cover.
- The surface water deflection berm appeared to be effective in diverting water around the cover extension.

In general, the Oceanview Portal cover appears to be physically stable. As such, no maintenance is recommended.

6.4.4. K-Baseline Portal

Construction Details

The K-Baseline portal was a culverted entry used to access the K-Baseline ore body. The location of the portal is illustrated on Drawing 01. The K-Baseline decline was approximately 5 m by 5 m in cross section and the culvert was half round with a diameter of 5 m and a length of 28 m. The culvert was supported by two concrete pony walls, 1 m wide by 2.4 m high, on both sides. The concrete pony walls extended 3 m inside the dolostone bedrock of the drift.

In 2004, the culvert was removed, and the portal was backfilled with waste rock. In 2005, a thermal cover was constructed over the waste rock portal plug. The cover consisted of a 2 m thick layer (minimum thickness) of granular shale overlain by a 0.35 m thick layer of armour material consisting of sand, gravel, and cobbles. The shale was derived from the Shale Hill borrow area. The armour material was derived from the Chris Creek "A" deposit. An additional thermal cover was constructed over the area below the road immediately outside the portal where mineralized soils and additional waste rock were located. A surficial cover of shale was also constructed adjacent to the thermal cover to improve drainage conditions.

Inspection Conditions

A select photo from the inspection is provided in Appendix I (Photo 67). The main observations are summarized by the following:

- No erosion of the cover was observed
- No seepage was noted at the toe of the cover
- No areas of significant settlement were observed in the cover
- Some minor cracking was noted on the surface of the cover, likely related to thermal expansion and contraction of the cover materials.

In general, the K-Baseline portal appears to be physically stable. As such, no maintenance is recommended.

6.4.5. Area 14 Portal

Construction Details

The Area 14 Portal was a bare rock portal that provided access to the Area 14 underground workings. The location of the portal is illustrated on Drawing 01. Mining ceased in this area around 1987 and the portal was backfilled with waste. The waste was covered and contoured with shale in 1987 and 1988.

In 2005, locally derived armour material was stockpiled adjacent to the portal cover for construction of the final armour layer. In late 2006, the stockpiled armour materials were spread over the portal area.

Inspection Conditions

The main observations are summarized by the following:

- No erosion of the cover was observed
- No seepage was noted at the toe of the cover.

In general, the Area 14 Portal cover appears to be physically stable. As such, no maintenance is recommended.

6.4.6. 09 South Portal

Construction Details

The 09 South (09S) Portal is located at the western end of the mine, as shown on Drawing 01. The 09S Portal is a culverted entry giving access to the Main Ore Zone. The 09 South drift is approximately 5 m by 5 m in cross section. The culvert is round with a diameter of 5 m and a length of 28 m. The bottom of the culvert is filled with rockfill to provide a smooth floor. The culvert extends approximately 13 m inside the shale bedrock of 09 south drift, leaving 15 m exposed on surface, a portion of which is covered with talus from the slope above.

The 09 South Portal remained open until the fall of 2008 to provide access to the underground workings during the underground waste disposal program. Once the underground waste disposal program was complete in September 2008, work on permanent closure of the 09 South Portal began.

In 2008, the culvert was removed, and the portal was backfilled with granular shale derived from the Mill Area deposit. The backfill was placed to within 0.5 m of the top of the portal and extended into the portal for approximately 5 m. The backfill extended outside the portal face and was sloped at an angle of approximately 4(H):1(V) and graded into the surrounding topography. A 0.25 m (minimum thickness) layer of locally derived armour material was then applied to the surface of the shale backfill.

Inspection Conditions

A photo from the inspection is provided in Appendix I (Photo 68). The main observations are summarized by the following:

- No erosion of the cover was observed
- No seepage was noted at the toe of the cover
- Some minor cracking and deformation of the cover was noted, in a similar condition as was observed in previous inspections. The area appears to have stabilized since the cracking was first noted in 2009
- Some shale from rock outcrops upslope was deposited on the surface of the portal cover.

In general, the 09 South Portal cover appears to be physically stable. As such, no maintenance is recommended.

6.4.7. Lower Adit

Construction Details

The Lower Adit is located at the western end of the mine near the Industrial Complex, as illustrated on Drawing 01. The Lower Adit provided the main access into the underground crusher and fine ore bin, as well as secondary access to the Main Ore Zone.

The Lower Adit Portal remained open until the fall of 2008 to provide ventilation to the underground workings during the underground waste disposal program. Once the underground waste disposal program was complete in September 2008, work on permanent closure of the Lower Adit Portal began.

In 2008, the portal was backfilled with granular shale derived from the Mill Area deposit. The backfill was placed to within 0.5 m of the top of the portal and extended into the portal for approximately 5 m. The backfill extended outside the portal face and was sloped at an angle of approximately 4(H):1(V) and graded into the surrounding topography. A 0.25 m (minimum thickness) layer of locally derived armour material was then applied to the surface of the shale backfill.

Inspection Conditions

A photo from the inspection is provided in Appendix I (Photo 69). The main observations are summarized by the following:

- No erosion of the cover was observed
- No seepage was noted at the toe of the cover
- No cracking or deformation of the cover was noted.

In general, the Lower Adit portal plug appears to be physically stable. As such, no maintenance is recommended.

6.4.8. Portal to Mill Foundation

Construction Details

A portal was driven beneath the Mill building in 1980 as part of emergency repair operations for the Mill. The portal is located approximately 70 m south of the Mill, adjacent to Twin Lakes Creek. The portal provided access to an ice lens which was present beneath the mill building. As part of the repair operations, the ice lens was mined out and concrete pillars were constructed to provide additional support for the Mill. After the repair operations were complete, the portal was plugged with shale rock fill.

Inspection Conditions

A photo from the inspection is provided in Appendix I (Photo 70). The main inspection observations for the Portal to Mill Foundation are summarized by the following:

- No erosion of the armoured portal plug was observed
- No seepage was noted at the toe of the portal plug.

In general, the portal plug appears to be physically stable. No maintenance is recommended.

6.4.9. Shale Hill Raise

Construction Details

The Shale Hill Raise provided ventilation for the underground workings in the Shale Hill area. The location of the raise (E582524, N8107427, UTM NAD 83 Zone 16) is illustrated on Drawing 01. The 3 m diameter raise was approximately 47 m deep. During mining operations, the raise was sealed with a 3 m diameter steel tank with the bottom cut out and with two adaptors in the top for 36-inch ventilation fans. The tank was fixed to a cemented collar at the top of the raise.

Prior to 2005, the surface structure was removed and, according to mine site records, the Shale Hill raise was backfilled with waste rock. A mound of shale was constructed at surface with side slopes of approximately 3(H):1(V). In 2005, a 0.35 m thick layer of locally derived armour material was applied to the surface of the mound to complete the remediation of this raise.

Inspection Conditions

During the inspection, the armour surface appeared to be stable with no visual indications of erosion or surface deformation. As such, no maintenance is recommended.

6.4.10. Oceanview East Raise

Construction Details

The Oceanview East Raise was situated at the extreme east end of the Oceanview underground workings. The location of the raise (E585123, N8107506, UTM NAD 83 Zone 16) is illustrated on Drawing 01. The 4 m by 4 m raise was approximately 10 m deep and provided ventilation for the underground workings in the Oceanview area. During mining operations, the raise was covered with a wooden wind deflector with a locked door.

In 2002, the wooden deflector was removed and, according to mine site records, the raise was backfilled with waste rock. During backfilling, it was noted that an ice plug was present in the raise at a depth of approximately 1.5 m below ground surface. As such, waste rock was placed only to this depth. A 3 m high mound was placed on top of the raise to accommodate for possible future settlement of the ice plug. The mound was constructed of shale and surfaced with coarse rock.

Inspection Conditions

A photo from the inspection is provided in Appendix I (Photo 71). During the inspection, the armour surface appeared to be stable with no visual indications of erosion or surface deformation. As such, no maintenance was recommended.

It was noted that periodic flows of groundwater seepage from upslope of the raise has caused acid rock drainage (ARD) staining of the ground surface around the raise. The source of the ARD is not known but is likely related to near surface exposure of sulphidic soils and/or bedrock. This water is collecting in a disturbed area downslope of the raise. This low spot could be backfilled to prevent collection of this water.

6.4.11. Oceanview West Raise

Construction Details

The Oceanview West raise was located near the west end of the Oceanview underground workings (E584851, N8107466, UTM NAD 83 Zone 16), as shown on Drawing 01. The 3 m diameter raise is approximately 26 m deep and provided ventilation for the underground workings. The raise was covered by a steel enclosure with a locked wooden cover.

In 2002, the steel enclosure was removed and, according to mine site records, the raise was backfilled with waste rock as part of the progressive reclamation of the mine site. During backfilling, it was noted that an ice plug was present in the raise at a depth of approximately 1.5 m below ground surface. As such, waste rock was placed only to this depth. A 3 m mound was placed on top of the raise to accommodate for possible future settlement of the ice plug. The mound was constructed of shale and surfaced with coarse rock.

Inspection Conditions

A photo from the inspection is provided in Appendix I (Photo 72). During the inspection, the armour surface appeared to be stable with no visual indications of erosion or surface deformation. As such, no maintenance is recommended.

6.4.12. Area 14 Raise

Construction Details

The location of the Area 14 Raise (E584187, N8105663, UTM NAD 83 Zone 16) is illustrated on Drawing 01. The raise had a cross section of 5 by 5 m and an approximate depth of 8 m. Mining ceased in this area around 1987 and the raise was completely backfilled to the floor of the underground workings. Backfilling was completed with waste rock and the surface was then covered and contoured with shale in the summer of 1987 and 1988.

Inspection Conditions

During the inspection, no settlement of the area surrounding the former raise was observed. As such, no maintenance is recommended.

6.5. Shale and Armour Borrow Areas

6.5.1. Shale Borrow Areas

Several shale borrow areas were developed during the reclamation process to provide material for construction of the thermal covers. The borrow areas include the following:

- Mt. Fuji
- Area 14
- West Twin
- East Twin
- Shale Hill
- Townsite.

The borrow areas were reclaimed when no longer required. The reclamation efforts included re-grading of slopes for stability and sufficient grading of the floor of each borrow area to provide for positive drainage of surface water.

Select photos from the inspection are provided in Appendix I (Photos 73 and 74). The main observations are summarized by the following:

Mt. Fuji

- The benches are continuing to slowly fill in from the raveling of the remaining bench faces and are expected to eventually form a stable slope at the natural angle of repose.
- The floor had no significant areas of ponded water and is considered generally well drained.
- No issues requiring maintenance were observed.

Area 14

- The re-graded pit walls appear to be stable.
- One area of erosion has occurred at the north end of the borrow area where natural surface water periodically discharges into the pit, typically during freshet. At this location, the overburden material has been eroded down to the top of the bedrock and has been deposited into the floor of the pit. This area was observed to have stabilized during recent inspections as down-cutting of these materials no longer appears to be occurring.
- The pit was mostly covered in snow, and no ponding of water was observed at the time of the inspection, but there has been significant thermokarst development at the entrance to the pit. As such, it is likely that this impedes drainage at some point in the year. The material is sufficiently fractured that any ponded water likely drains when the ground thaws.

West Twin

- Was not visited during the 2021 inspection.
- No issues requiring maintenance have been identified in recent years.

East Twin

- Was not visited during the 2021 inspection.
- No issues requiring maintenance have been identified in recent years.

Shale Hill

- In general, the re-graded pit walls appear to be stable.
- No ponding was observed in the floor of the pit.
- No issues requiring maintenance were observed.

Townsite

- In general, the re-graded pit walls appear to be stable.
- No ponding was observed in the floor of the pit.
- No issues requiring maintenance were observed.

6.5.2. Armour Borrow Areas

Several armour borrow areas were developed during the reclamation process to provide material for construction of the thermal covers. The borrow areas include the following:

- Twin Lakes Delta deposit
- Chris Creek "A" and "B" deposits
- Kuhulu Lake Road deposit
- 09S/17N Road deposit
- Area 14 deposit.

The borrow areas were reclaimed once no longer required. The reclamation efforts included sufficient grading of the floor of each borrow area to provide for positive drainage of surface water.

The main observations are summarized by the following:

Twin Lakes Delta deposit

- The floor of the quarry was, in general, well drained. The surface water flows to the north edge of the borrow area and then proceeds to flow west to the Reservoir.
- Only isolated thermokarst features were observed in the floor of the quarry.
- No issues requiring maintenance were observed.

Chris Creek "A" and "B" deposits

- Some minor ponding was observed on the floor of the quarry, likely associated with the thermokarst features that have been observed in previous inspections.
- No issues requiring maintenance were observed.

Kuhulu Lake Road deposit

- The Kuhulu Lake Road deposit was not observed during the 2021 inspection.

- No issues requiring maintenance have been identified in recent years.

09S/17N Road deposit

- The face of the borrow area did not exhibit any indications of erosion or thermokarst development.
- No issues requiring maintenance were observed.

Area 14 deposit

- The re-graded pit walls appear to be stable.
- Significant thermokarsting was noted at the east end entrance of the pit and minor thermokarsting was noted throughout the pit. It is likely that the thermokarsting impedes drainage during freshet, but the material is sufficiently fractured that any ponded water likely drains when the ground thaws.
- No ponding of water was observed at the time of the inspection.

6.6. Summary of 2021 Maintenance Recommendations

The maintenance items recommended throughout Section 5.0 are summarized in Table 6-1.

Table 6-1. Recommended maintenance and action items for 2021.

| Inspection Item | Recommended Maintenance and Action Items |
|--|--|
| West Twin Dyke Spillway | The area should continue to be visually monitored for any signs of erosion or permafrost degradation induced deformation of the side slopes and channel bottom. |
| West Twin Outlet Channel | Monitor the water elevation in the Reservoir and Polishing Pond. Monitor slopes along perimeter of Polishing Pond for stability considerations. |
| East Twin Creek Diversion Channel | The diversion dyke should continue to be monitored for seepage through the East Twin Creek Diversion Dyke and for erosion along the East Twin Creek Diversion Channel. |
| Surface Cell Tailings Cover | Continue to monitor thermokarst areas for additional deformation. Monitor the heave feature that has been observed. |
| East Open Pit/ East Trench Waste Rock Cover | Continue to visually monitor cracking in EOP crown pillar and minor surficial cracking and erosion of EOP and East Trench covers. |
| Oceanview Pit Waste Rock Cover | Continue to visually monitor surficial erosion along backslope. |
| 00/01 Portals and Crown Pillar | Continue to visually monitor cracking in WOP crown pillar. |
| Instrumentation/ Monitoring | Download the water level loggers installed in the Reservoir and Polishing Pond during the 2022 inspection. |

No maintenance or action items are recommended for other areas not specifically noted in Table 6-1.

6.7. 2020-2029 Monitoring Schedule

As part of the Water Licence renewal process in 2019/2020, BGC undertook a review of the geotechnical monitoring requirements for the Nanisivik Mine site, with the intent to develop a reduced monitoring schedule for the term of the 1AR-NAN2030 Water Licence. The results of this review are documented in a project memorandum (BGC, April 24, 2019). As part of the Water Licence, the monitoring frequency of geotechnical instrumentation (thermistors, piezometers, frost gauges) was reduced to a single monitoring event per year, provided that current performance trends and general site stability continue to be observed. In addition to a reduction in per-annuum monitoring, the Water Licence allows a further reduction in the monitoring frequency to omit monitoring years in a tapered fashion such that annual inspections are gradually spaced farther apart. Annual inspections are intended to be performed concurrent with monitoring events.

The 2020-2029 monitoring schedule incorporated within the Water Licence is provided in Appendix III. The next site inspection and instrumentation monitoring event is planned for August 2022.

7.0 CONCLUSIONS AND RECOMMENDATIONS

The following paragraphs provide a summary of the significant observations, conclusions, and recommendations based on the results of the 2021 Geotechnical Inspection Program undertaken at the Nanisivik Mine site.

Embankments

The West Twin Dyke and Test Cell Dyke were physically stable with no signs of erosion or seepage. The breaches constructed in the remnant dykes at the East Adit Treatment Facility continue to permit natural drainage of the area with only limited ponding in the Retention Pond.

Hydraulic Structures

The West Twin Dyke Spillway continues to effectively drain water from the Surface Cell cover into the Reservoir and is generally functioning as intended. Limited erosion was observed in 2021, although it is possible that additional maintenance will be required in the future. The spillway should continue to be inspected for additional erosion and maintenance should be undertaken as necessary.

As observed during previous inspections, a small head pond developed on the Surface Cell cover at the spillway inlet. The presence of the shallow head pond is not considered to negatively impact the overall cover performance; hence the elimination of the head pond is not considered necessary.

Despite continued seepage at the West Twin Outlet Wall, instrumentation data continues to support visual observations that the water level upstream of the outlet wall is maintained at or above the invert during the open water season. Continued deformation of the perimeter slopes of the upstream Polishing Pond was observed in 2021. As noted in previous inspections, the area of instability was further removed from the outlet wall compared to previous years. Hence there are no concerns associated with this instability with respect to the performance of the outlet wall. Based on the water quality measurements collected since the East Twin Lake access road was breached in 2008, the seepage losses from the Polishing Pond do not appear to be affecting the overall performance of the West Twin Area reclamation measures. The seepage losses should continue to be monitored. Additional seepage control measures could be considered, if necessary.

Previous inspections made recommendations to repair left bank armouring material following observations of erosion along a section of the East Twin Creek Diversion Channel. In response to these observations, maintenance was undertaken at the diversion dyke in 2018. The maintenance included re-sloping of the affected area and addition of locally available armour materials. The maintained areas were visually assessed during the 2021 inspection and appeared to have performed favourably. Seepage discharge observed at the toe of the left bank of the dyke during previous inspections was observed again in 2021. The seepage water is likely originating in the Polishing Pond and likely only flows when the active layer thickness is near its maximum depth. The seepage was visually estimated to be similar in comparison to the 2020 inspection.

The seepage flow was observed to be clear and free of sediment. No further maintenance of the diversion dyke is recommended at this time but should continue to be monitored for additional erosion and seepage flows.

Thermal Covers

Based on monitoring data collected from various frost gauges and thermistors, the thermal covers performed adequately throughout 2021. In general, the active layer thaw in 2021 was observed to be similar or slightly less than was measured in 2019 and 2020. The 2021 weather was variable: in general, the 2020/2021 winter and 2021 spring were warmer than average but the 2021 summer was cooler than average. Since the active layer thaw depths tend to closely reflect the summer and fall temperatures, less than average thaw depths were observed in 2021.

The minor erosion, cracking, and thermokarsting/settlement observed on the Surface Cell and Test Cell cover systems that has been noted in previous inspections was not observed to have visually changed in several years. However, the cracks and heaving in an oval pattern near the central-southern portion of the cover continued to grow since 2020. The heaving is likely due to the freeze-back of the pore water in the underlying tailings. The heaving/cracking is not considered to negatively impact the stability of the West Twin Dyke, thermal performance of the cover system, nor the water quality in the surrounding areas at this time. The water quality observed at the final discharge point for the West Twin Disposal Area was observed to remain well below the discharge criteria throughout the open water season in 2021. This is an indication that the cover systems continue to perform as intended.

Several instruments to monitor the performance of the thermal covers on site have ceased functioning in the past few years. This is expected, as most instruments were installed nearly 20 years ago. Replacement of the failed instruments is not considered necessary at this time, given generally positive performance monitoring results since installation.

No maintenance is required for the thermal covers at this time; however, visual monitoring is recommended to monitor for additional surface deformation and erosion, specifically the heave feature.

Talik and Mine Waste Freeze-back

Overall freeze-back of the talik in the Surface Cell and Test Cell appears to be proceeding faster than anticipated. However, since 2020, the downward migration of the freezing front and continued cooling of ground temperatures below approximately 15 m bgs has slowed. Shallow ground temperature at depths above approximately 15 m bgs generally showed warming since 2020, reflective of the warmer than average temperatures in the past few years. Despite these warmer air temperatures, mine waste remained frozen through 2021. All piezometers within the Surface Cell, and three out of five piezometers within the Test Cell, have frozen back due to continued downward migration of the freezing front. The piezometers have been observed to freeze back at lower temperatures when the piezometer tip is at a lower elevation, as well as when it is further away from the edge of the original lake bed. These relationships are likely related

to the increasing solute concentrations in the unfrozen pore water contained within the remnant talik.

In areas where no talik exists (e.g., landfill, open pits), freeze-back of the materials underlying the cover systems has occurred and the rate of cooling has generally slowed over recent years, suggesting ground conditions are approaching thermal equilibrium at depth.

Mine Openings, Crown Pillars and Raises

The covers constructed over the mine openings generally appear to be physically stable. Cracking at the East Open Pit crown pillar does not appear to have progressed in many years. No maintenance is recommended, but continued visual inspection is warranted.

Shale and Armour Borrow Areas

In general, the shale and armour borrow areas appear to be physically stable and are not causing any significant ponding to occur. No maintenance was recommended at any of the borrow areas.

8.0 CLOSURE

We trust the above satisfies your requirements at this time. Should you have any questions or comments, please do not hesitate to contact us.

Yours sincerely,

BGC ENGINEERING INC.
per:




Scott Garrison, M.Eng., P.Eng.
Geological Engineer

Reviewed by:

Geoff Claypool, M.Eng., P.Eng.
Principal Geological Engineer

SG/GC/sf/js



REFERENCES

(Not all cited in text)

- BGC Engineering Inc. (2004a, February 6). *Assessment of Surface Cell and Test Cell Taliks* [Report]. Prepared for CanZinco Ltd.
- BGC Engineering Inc. (2004b, February 6). *Engineering Design of Surface Reclamation Covers* [Report]. Prepared for CanZinco Ltd.
- BGC Engineering Inc. (2009, September 28). *Nanisivik Mine Reclamation – Project Completion Report. Submitted to Breakwater Resources Ltd* [Report]. Prepared for Breakwater Resources Ltd.
- BGC Engineering Inc. (2014, February 27). *2013 Annual Geotechnical Inspection – Nanisivik Mine, Nunavut* [Report]. Prepared for Nyrstar.
- BGC Engineering Inc. (2015, February 28). *2014 Annual Geotechnical Inspection – Nanisivik Mine, Nunavut* [Report]. Prepared for Nyrstar.
- BGC Engineering Inc. (2016, March 30). *2015 Annual Geotechnical Inspection – Nanisivik Mine, Nunavut* [Report]. Prepared for Nyrstar.
- BGC Engineering Inc. (2017, March 7). *2016 Annual Geotechnical Inspection – Nanisivik Mine, Nunavut* [Report]. Prepared for Nyrstar.
- BGC Engineering Inc. (2018, February 23). *2017 Annual Geotechnical Inspection – Nanisivik Mine, Nunavut* [Report]. Prepared for Nyrstar.
- BGC Engineering Inc. (2019, March 11). *2018 Annual Geotechnical Inspection – Nanisivik Mine, Nunavut* [Report]. Prepared for Nyrstar.
- BGC Engineering Inc. (2019, April 24). *Geotechnical Monitoring Beyond 2019 – Nanisivik Mine, NU* [Project Memorandum]. Prepared for Nyrstar.
- BGC Engineering Inc. (2020, February 24). *2019 Annual Geotechnical Inspection – Nanisivik Mine, Nunavut* [Report]. Prepared for Nyrstar.
- BGC Engineering Inc. (2020, March 13). *Nanisivik Mine, Nunavut – 2020 Updated to Post Closure Geotechnical Monitoring Contingency Plan* [Report]. Prepared for Nyrstar
- BGC Engineering Inc. (2021, March 24). *2020 Annual Water Quality Monitoring – Nanisivik Mine, Nunavut* [Report]. Prepared for Nyrstar.
- CanZinco Ltd. (2004, March). 2004 Reclamation and Closure Plan. Submitted to Nunavut Water Board.
- Gartner Lee Ltd. (2004, February). *Nanisivik Mine Reclamation and Closure Monitoring Plan* [Report]. Prepared for Nanisivik Mine, a Division of CanZinco Ltd.

Golder Associates Ltd. (1998, October). *1998 Geotechnical Inspection of Waste Containment Dykes, Nanisivik Mine, Baffin Island, NWT* [Report]. Prepared for Nanisivik Mine, a Division of CanZinco Ltd.



Jacques Whitford Stantec Limited. (2009, October). *Abandonment and Reclamation Plan, Fuel Tank Farm, Former Nanisivik Mine Site, Nunavut* [Report]. Prepared for Breakwater Resources Ltd.

Nunavut Water Board. (2004, July 6). *Nunavut Water Board's Letter of Approval for Terms and Conditions Applying to the Nanisivik Mine 2004 Reclamation Plan and Closure Plan* [Memorandum]. Prepared for Breakwater Resources Ltd.


Nunavut Water Board. (2020). *Nunavut Water Board licence 1AR-NAN2030 Type "A"* [Report]. January 9, 2020.

SRK Consulting (Canada) Inc. (2009, January). *Nanisivik Mine, Summary of Contaminated Soil Remediation Progress – September 10, 2008* [Report]. Prepared for CanZinco Ltd.



FIGURES




*Historical average taken from 1977-2010 when data was available at the Nanisivik Airport
*2011-2021 temperature corrected by -2 °C to adjust for new weather station location (Arctic Bay).



*Historical average taken from 1977-2010 when data was available at the Nanisivik Airport
*Temperature corrected by -2 °C to adjust for new weather station location (Arctic Bay).



*Historical average taken from 1977-2010 when data was available at the Nanisivik Airport
*2011-2021 Air Thawing Index corrected by -2 °C per day to adjust for new weather station location (Arctic Bay).



*Historical average taken from 1977-2010 when data was available at the Nanisivik Airport
*2011-2021- Air Thawing Index corrected by -2 °C to adjust for new weather station location (Arctic Bay).

NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|--------------------------------|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Climate Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: N/A | PROJECT NO: 0255-033 | FIGURE NO: 01 |



NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection", dated March 2022.
2. Photo derived from Google Earth, imagery date July 28, 2015

PREPARED BY:

EK

FIGURE TITLE:

Site Plan of the West Twin Disposal Area

CHECKED BY:

GKC

CLIENT:

CanZinco Mines Ltd.

APPROVED BY:

SDG

SCALE:

1:10,000

PROJECT NO:


0255-033

FIGURE NO:

02

0 5 10 mm in ANSI A sized paper

Polishing Pond Water Level Data (Aug 2020 - Aug 2021)




NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.
2. Air temperatures were recorded at the Surface Cell.

| | | | |
|---------------------|--|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Polishing Pond Water Level Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: NOT TO SCALE | PROJECT NO: 0255-033 | FIGURE NO: 03 |


0 5 10 mm in ANSI B sized paper




NOTES
1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|--|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Surface Cell Tailings Cover Geotechnical Monitoring Data 1 | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 04 |

0 5 10 mm in ANSI B sized paper




*Since 2005, the -0.5°C Isotherm for BGC05-15 is extrapolated using linear extrapolation of nodes at 20 to 30 m depth.



NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.


| | | | |
|---------------------|--|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Surface Cell Tailings Cover Geotechnical Monitoring Data 2 | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 05 |



NOTES
1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|--|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Surface Cell Tailings Cover Geotechnical Monitoring Data 3 | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 06 |

0 5 10 mm in ANSI B sized paper



NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection", dated March 2022.

PREPARED BY:

EK

FIGURE TITLE:

**Surface Cell Tailings Cover
Geotechnical Monitoring Data 4**

CHECKED BY:

GKC

CLIENT:

CanZinco Mines Ltd.

APPROVED BY:

SDG


SCALE:

PROJECT NO:



0255-033

FIGURE NO:

07




| | | | | |
|--|---------------------|--------|---|------------------|
| <div>NOTES</div> <div>1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.</div> | PREPARED BY: EK | | FIGURE TITLE: Surface Cell Tailings Cover Geotechnical Monitoring Data 5 | |
| | CHECKED BY: GKC | | CLIENT: CanZinco Mines Ltd. | |
| | APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 08 |




NOTES
1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|---|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Surface Cell Run-Off Water Quality Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 09 |






| | | | | |
|---|---------------------|--------|---|------------------|
| NOTES 1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022. | PREPARED BY: EK | | FIGURE TITLE: West Twin Dyke Geotechnical Monitoring Data | |
| | CHECKED BY: GKC | | CLIENT: CanZinco Mines Ltd. | |
| | APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 10 |



NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.


| | | | |
|---------------------|---|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Test Cell Tailings Cover Geotechnical Monitoring Data 1 | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 11 |




NOTES
1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|---|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Test Cell Tailings Cover Geotechnical Monitoring Data 2 | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 12 |





0 5 10 mm in ANSI B sized paper



| | | | | |
|---|---------------------|--------|---|------------------|
| NOTES 1. This Figure should be read in conjunction with BGC’s report titled “Nanisivik Mine 2021 Annual Geotechnical Inspection” and dated March 2022. | PREPARED BY: EK | | FIGURE TITLE: Test Cell Dyke Geotechnical Monitoring Data | |
| | CHECKED BY: GKC | | CLIENT: CanZinco Mines Ltd. | |
| | APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 13 |



| | | | | |
|--|-----------------------------|--------|--|--------------------------|
| <div>NOTES</div> <div>1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.</div> | PREPARED BY: <div>EK</div> | | FIGURE TITLE: <div>Toe of Test Cell Dyke Tailings Cover Geotechnical Monitoring Data</div> | |
| | CHECKED BY: <div>GKC</div> | | CLIENT: <div>CanZinco Mines Ltd.</div> | |
| | APPROVED BY: <div>SDG</div> | SCALE: | PROJECT NO: <div>0255-033</div> | FIGURE NO: <div>14</div> |









NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|---|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Toe of West Twin Dyke Tailings Cover Geotechnical Monitoring Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 15 |





0 5 10 mm in ANSI B sized paper



NOTES


1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.
2. Data points represent individual water samples and may not be representative of the true annual maximum concentrations.
3. Maximum authorized concentrations according to Part D of Water Licence 1AR-NAN2030 (NWB 2020).

| | | | |
|---------------------|--|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: West Twin Disposal Area Water Quality Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 16 |






NOTES
1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|---|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Landfill Cover Geotechnical Monitoring Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 17 |



NOTES
1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|---|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: East Open Pit Waste Rock Cover Geotechnical Monitoring Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 18 |




NOTES
1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|---|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Oceanview Pit Waste Rock Cover Geotechnical Monitoring Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 19 |

0 5 10 mm in ANSI B sized paper

Active Layer Monitoring
Area 14 Waste Rock Cover
Frost Gauge 15

2006 Data 2010 Data
 2013 Data 2016 Data
 2018 Data 2019 Data
 2020 Data 2021 Data



NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection", dated March 2022.

PREPARED BY:

EK

FIGURE TITLE:

**Area 14 Waste Rock Cover
Monitoring Data**

CHECKED BY:

GKC

CLIENT:

CanZinco Mines Ltd.

APPROVED BY:

SDG


SCALE:

PROJECT NO:

0255-033

FIGURE NO:

20



NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection", dated March 2022.

PREPARED BY:

EK

FIGURE TITLE:

Upper Dump Pond Tailing Cover
Monitoring Data

CHECKED BY:

GKC

CLIENT:

CanZinco Mines Ltd.

APPROVED BY:

SDG




SCALE:

PROJECT NO:

0255-033

FIGURE NO:

21




NOTES

1. This Figure should be read in conjunction with BGC's report titled "Nanisivik Mine 2021 Annual Geotechnical Inspection" and dated March 2022.

| | | | |
|---------------------|---|-------------------------|------------------|
| PREPARED BY: EK | FIGURE TITLE: Industrial Complex Cover Geotechnical Monitoring Data | | |
| CHECKED BY: GKC | CLIENT: CanZinco Mines Ltd. | | |
| APPROVED BY: SDG | SCALE: | PROJECT NO: 0255-033 | FIGURE NO: 22 |

DRAWINGS



X:\Projects\0255028\CAD\PRODUCTION\REPORT\20180123 NANASIVIK MINE 2017 ANNUAL GEOTECHNICAL INSPECTION01.dwg Layout: RM-B-SIZE Plot Date Feb 14 22 Time: 11:49 AM

NOTES:

1. ALL DIMENSIONS ARE IN METRES UNLESS OTHERWISE NOTED.
2. THIS DRAWING MUST BE READ IN CONJUNCTION WITH BGC'S REPORT TITLED "NANASIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION" AND DATED MARCH 2022.
3. PROJECTION IS UTM NAD 83 Z16N.
4. UNLESS BGC AGREES OTHERWISE IN WRITING, THIS DRAWING SHALL NOT BE MODIFIED OR USED FOR ANY PURPOSE OTHER THAN THE PURPOSE FOR WHICH BGC GENERATED IT. BGC SHALL HAVE NO LIABILITY FOR ANY DAMAGES OR LOSS ARISING IN ANY WAY FROM ANY USE OR MODIFICATION OF THIS DOCUMENT NOT AUTHORIZED BY BGC. ANY USE OF OR RELIANCE UPON THIS DOCUMENT OR ITS CONTENT BY THIRD PARTIES SHALL BE AT SUCH THIRD PARTIES' SOLE RISK.

| | |
|-----------|----------|
| SCALE: | AS SHOWN |
| DATE: | MAR 2022 |
| DRAWN: | KB |
| CHECKED: | GKC |
| APPROVED: | SDG |

BGC

BGC ENGINEERING INC.

AN APPLIED EARTH SCIENCES COMPANY

CLIENT:


CanZinco Mines Ltd.

| | |
|--|----------------|
| PROJECT: NANASIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION | |
| TITLE: SITE LOCATION PLAN | |
| PROJECT No.: 0255-033 | DWG No.: 01 |



NOTES:

- ALL DIMENSIONS ARE IN METRES UNLESS OTHERWISE NOTED.
- THIS DRAWING MUST BE READ IN CONJUNCTION WITH BGC'S REPORT TITLED "NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION" AND DATED MARCH 2022.
- CONTOUR INTERVAL IS 1 m.
- PROJECTION IS UTM NAD 83, Z16N.
- UNLESS BGC AGREES OTHERWISE IN WRITING, THIS DRAWING SHALL NOT BE MODIFIED OR USED FOR ANY PURPOSE OTHER THAN THE PURPOSE FOR WHICH BGC GENERATED IT. BGC SHALL HAVE NO LIABILITY FOR ANY DAMAGES OR LOSS ARISING IN ANY WAY FROM ANY USE OR MODIFICATION OF THIS DOCUMENT NOT AUTHORIZED BY BGC. ANY USE OF OR RELIANCE UPON THIS DOCUMENT OR ITS CONTENT BY THIRD PARTIES SHALL BE AT SUCH THIRD PARTIES' SOLE RISK.

| | | | | |
|-----------|----------|--|--|--|
| SCALE: | 1:2,500 |  BGC ENGINEERING INC. <small>AN APPLIED EARTH SCIENCES COMPANY</small> | PROJECT: NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION | |
| DATE: | MAR 2022 | | TITLE: TEST CELL TAILINGS COVER | |
| DRAWN: | KB | | PROJECT No.: 0255-033 | |
| CHECKED: | GKC | | DWG No.: 03 | |
| APPROVED: | SDG | | CanZinco Mines Ltd. | |



NOTES:

1. ALL DIMENSIONS ARE IN METRES UNLESS OTHERWISE NOTED.
2. THIS DRAWING MUST BE READ IN CONJUNCTION WITH BGC'S REPORT TITLED "NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION", AND DATED MARCH 2022.
3. CONTOUR INTERVAL IS 1 m.
4. PROJECTION IS UTM NAD 83 ZONE 16N.
5. UNLESS BGC AGREES OTHERWISE IN WRITING, THIS DRAWING SHALL NOT BE MODIFIED OR USED FOR ANY PURPOSE OTHER THAN THE PURPOSE FOR WHICH BGC GENERATED IT. BGC SHALL HAVE NO LIABILITY FOR ANY DAMAGES OR LOSS ARISING IN ANY WAY FROM ANY USE OR MODIFICATION OF THIS DOCUMENT NOT AUTHORIZED BY BGC. ANY USE OF OR RELIANCE UPON THIS DOCUMENT OR ITS CONTENT BY THIRD PARTIES SHALL BE AT SUCH THIRD PARTIES' SOLE RISK.


| | |
|-----------|----------|
| SCALE: | 1:1,000 |
| DATE: | MAR 2022 |
| DRAWN: | KB |
| CHECKED: | GKC |
| APPROVED: | SDG |

BGC

BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY

CLIENT:
CanZinco Mines Ltd.

| | |
|--|----------------|
| PROJECT: NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION | |
| TITLE: LANDFILL COVER | |
| PROJECT No.: 0255-033 | DWG No.: 04 |



NOTES:

1. ALL DIMENSIONS ARE IN METRES UNLESS OTHERWISE NOTED.
2. THIS DRAWING MUST BE READ IN CONJUNCTION WITH BGC'S REPORT TITLED "NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION" AND DATED MARCH 2022.
3. CONTOUR INTERVAL IS 1 m.
4. PROJECTION IS UTM NAD 83, Z16N.
5. UNLESS BGC AGREES OTHERWISE IN WRITING, THIS DRAWING SHALL NOT BE MODIFIED OR USED FOR ANY PURPOSE OTHER THAN THE PURPOSE FOR WHICH BGC GENERATED IT. BGC SHALL HAVE NO LIABILITY FOR ANY DAMAGES OR LOSS ARISING IN ANY WAY FROM ANY USE OR MODIFICATION OF THIS DOCUMENT NOT AUTHORIZED BY BGC. ANY USE OF OR RELIANCE UPON THIS DOCUMENT OR ITS CONTENT BY THIRD PARTIES SHALL BE AT SUCH THIRD PARTIES' SOLE RISK.

| | |
|-----------|----------|
| SCALE: | 1:1,000 |
| DATE: | MAR 2022 |
| DRAWN: | KB |
| CHECKED: | GKC |
| APPROVED: | SDG |

BGC


BGC ENGINEERING INC.

AN APPLIED EARTH SCIENCES COMPANY

CLIENT:

CanZinco Mines Ltd.


| | |
|--|----------------|
| PROJECT: NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION | |
| TITLE: WEST OPEN PIT WASTE ROCK COVER | |
| PROJECT No.: 0255-033 | DWG No.: 05 |



NOTES:

- ALL DIMENSIONS ARE IN METRES UNLESS OTHERWISE NOTED.
- THIS DRAWING MUST BE READ IN CONJUNCTION WITH BGC'S REPORT TITLED "NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION" AND DATED MARCH 2022.
- CONTOUR INTERVAL IS 1 m.
- PROJECTION IS UTM NAD 83, Z16N.
- UNLESS BGC AGREES OTHERWISE IN WRITING, THIS DRAWING SHALL NOT BE MODIFIED OR USED FOR ANY PURPOSE OTHER THAN THE PURPOSE FOR WHICH BGC GENERATED IT. BGC SHALL HAVE NO LIABILITY FOR ANY DAMAGES OR LOSS ARISING IN ANY WAY FROM ANY USE OR MODIFICATION OF THIS DOCUMENT NOT AUTHORIZED BY BGC. ANY USE OF OR RELIANCE UPON THIS DOCUMENT OR ITS CONTENT BY THIRD PARTIES SHALL BE AT SUCH THIRD PARTIES' SOLE RISK.

| | | | | |
|-----------|----------|---|--|----------------|
| SCALE: | 1:2,000 | <div><div><div></div><div></div><div></div></div><div>BGC ENGINEERING INC. AN APPLIED EARTH SCIENCES COMPANY</div></div> <div>CLIENT: <div>CanZinco Mines Ltd.</div></div> | PROJECT: NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION | |
| DATE: | MAR 2022 | | TITLE: EAST OPEN PIT WASTE ROCK COVER | |
| DRAWN: | KB | | | |
| CHECKED: | GKC | | | |
| APPROVED: | SDG | | PROJECT No.: 0255-033 | DWG No.: 06 |



X:\Projects\0255\028\CAD\PRODUCTION\REPORT\2018\0123 NANASIVIK MINE 2017 ANNUAL GEOTECHNICAL INSPECTION\08.dwg | Layout: 08 Plot Date Feb 14 22 Time: 12:15 PM

THIS DRAWING MAY HAVE BEEN REDUCED OR ENLARGED.
ALL SCALE NOTATIONS INDICATED ARE BASED ON
ORIGINAL FORMAT DRAWINGS.

LEGEND

THERMISTOR/THERMOCOUPLE

FROST GAUGE

- NOTES:
- ALL DIMENSIONS ARE IN METRES UNLESS OTHERWISE NOTED.
 - THIS DRAWING MUST BE READ IN CONJUNCTION WITH BGC'S REPORT TITLED "NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION" AND DATED MARCH 2022.
 - CONTOUR INTERVAL IS 1 m.
 - PROJECTION IS UTM NAD 83, Z16N.
 - UNLESS BGC AGREES OTHERWISE IN WRITING, THIS DRAWING SHALL NOT BE MODIFIED OR USED FOR ANY PURPOSE OTHER THAN THE PURPOSE FOR WHICH BGC GENERATED IT. BGC SHALL HAVE NO LIABILITY FOR ANY DAMAGES OR LOSS ARISING IN ANY WAY FROM ANY USE OR MODIFICATION OF THIS DOCUMENT NOT AUTHORIZED BY BGC. ANY USE OF OR RELIANCE UPON THIS DOCUMENT OR ITS CONTENT BY THIRD PARTIES SHALL BE AT SUCH THIRD PARTIES' SOLE RISK.

| | |
|-----------|----------|
| SCALE: | 1:500 |
| DATE: | MAR 2022 |
| DRAWN: | KB |
| CHECKED: | GKC |
| APPROVED: | SDG |


BGC ENGINEERING INC.

AN APPLIED EARTH SCIENCES COMPANY

CLIENT:

CanZinco Mines Ltd.

| | |
|--|----------------|
| PROJECT: NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION | |
| TITLE: AREA 14 WASTE ROCK COVER | |
| PROJECT No.: 0255-033 | DWG No.: 08 |



NOTES:

1. ALL DIMENSIONS ARE IN METRES UNLESS OTHERWISE NOTED.

2. THIS DRAWING MUST BE READ IN CONJUNCTION WITH BGC'S REPORT TITLED "NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION" AND DATED MARCH 2022.

3. CONTOUR INTERVAL IS 0.2 m.

4. PROJECTION IS UTM NAD 83, Z16N.

5. UNLESS BGC AGREES OTHERWISE IN WRITING, THIS DRAWING SHALL NOT BE MODIFIED OR USED FOR ANY PURPOSE OTHER THAN THE PURPOSE FOR WHICH BGC GENERATED IT. BGC SHALL HAVE NO LIABILITY FOR ANY DAMAGES OR LOSS ARISING IN ANY WAY FROM ANY USE OR MODIFICATION OF THIS DOCUMENT NOT AUTHORIZED BY BGC. ANY USE OF OR RELIANCE UPON THIS DOCUMENT OR ITS CONTENT BY THIRD PARTIES SHALL BE AT SUCH THIRD PARTIES' SOLE RISK.

| | |
|-----------|----------|
| SCALE: | 1:500 |
| DATE: | MAR 2022 |
| DRAWN: | KB |
| CHECKED: | GKC |
| APPROVED: | SDG |

BGC


BGC ENGINEERING INC.

AN APPLIED EARTH SCIENCES COMPANY

CLIENT:

CanZinco Mines Ltd.

| | |
|--|----------------|
| PROJECT: NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION | |
| TITLE: UPPER DUMP POND TAILINGS COVER | |
| PROJECT No.: 0255-033 | DWG No.: 09 |



NOTES:

- ALL DIMENSIONS ARE IN METRES UNLESS OTHERWISE NOTED.
- THIS DRAWING MUST BE READ IN CONJUNCTION WITH BGC'S REPORT TITLED "NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION" AND DATED MARCH 2022.
- CONTOUR INTERVAL IS 1 m.
- PROJECTION IS UTM NAD 83, Z16N.
- UNLESS BGC AGREES OTHERWISE IN WRITING, THIS DRAWING SHALL NOT BE MODIFIED OR USED FOR ANY PURPOSE OTHER THAN THE PURPOSE FOR WHICH BGC GENERATED IT. BGC SHALL HAVE NO LIABILITY FOR ANY DAMAGES OR LOSS ARISING IN ANY WAY FROM ANY USE OR MODIFICATION OF THIS DOCUMENT NOT AUTHORIZED BY BGC. ANY USE OF OR RELIANCE UPON THIS DOCUMENT OR ITS CONTENT BY THIRD PARTIES SHALL BE AT SUCH THIRD PARTIES' SOLE RISK.

| | |
|-----------|----------|
| SCALE: | 1:1,000 |
| DATE: | MAR 2022 |
| DRAWN: | KB |
| CHECKED: | GKC |
| APPROVED: | SDG |

BGC

BGC ENGINEERING INC.

AN APPLIED EARTH SCIENCES COMPANY

CLIENT:

CanZinco Mines Ltd.

| | |
|--|----------------|
| PROJECT: NANISIVIK MINE 2021 ANNUAL GEOTECHNICAL INSPECTION | |
| TITLE: INDUSTRIAL COMPLEX COVER | |
| PROJECT No.: 0255-033 | DWG No.: 10 |

APPENDIX I INSPECTION PHOTOS

LIST OF APPENDIX I INSPECTION PHOTOS

| | |
|---------------|-----------------------------------|
| Photo 1 – 2 | East Adit Treatment Facility |
| Photo 3 – 9 | West Twin Dyke Spillway |
| Photo 10 – 12 | West Twin Lake Outlet Wall |
| Photo 13 – 14 | Polishing Pond |
| Photo 15 – 17 | East Twin Creek Diversion Channel |
| Photo 18 – 23 | Surface Cell |
| Photo 24 – 27 | West Twin Dyke |
| Photo 28 – 36 | Test Cell |
| Photo 37 – 39 | Toe of West Twin Dyke |
| Photo 40 – 44 | Landfill |
| Photo 45 – 48 | West Open Pit |
| Photo 49 – 53 | East Open Pit |
| Photo 54 | East Trench |
| Photo 55 – 58 | Oceanview Open Pit |
| Photo 59 | Area 14 |
| Photo 60 – 62 | Upper Dump Pond |
| Photo 63 – 64 | Industrial Complex Cover |
| Photo 65 | 17N Portal |
| Photo 66 | Oceanview Portal |
| Photo 67 | K-Baseline Portal |
| Photo 68 | 09S Portal |
| Photo 69 | Lower Adit |
| Photo 70 | Mill Portal |
| Photo 71 | Oceanview East Raise |
| Photo 72 | Oceanview West Raise |
| Photo 73 | Mt. Fuji Shale Quarry |
| Photo 74 | Shale Hill Borrow Area |



Photo 1. East Adit Treatment Facility - Retention Pond as seen from UAV.




Photo 3. West Twin Dyke Spillway – Small headpond at spillway inlet as seen from UAV.




Photo 2. East Adit Treatment Facility - Breach in treatment pond as seen from UAV.




Photo 4. West Twin Dyke Spillway – Upper spillway, looking upstream from UAV. Note minor left bank erosion.




Photo 5. West Twin Dyke Spillway – Spillway access ramp, looking upstream from UAV.




Photo 7. West Twin Dyke Spillway – Primary area where 2018 left bank maintenance was performed, as seen from UAV.




Photo 6. West Twin Dyke Spillway – Area approximately 100 metres downstream of the access ramp, as seen from UAV. Note secondary area of 2018 left bank maintenance.



Photo 8. West Twin Dyke Spillway – On right bank looking downstream along location of 2018 left bank maintenance.



Photo 9. West Twin Dyke Spillway – Looking downstream at spillway outlet where 2018 maintenance was performed.



Photo 11. West Twin Outlet Wall – As seen from left bank.



Photo 10. West Twin Outlet Wall – As seen from downstream.




Photo 12. West Twin Outlet Wall – Overview, as seen from UAV.




Photo 13. Polishing Pond – Thermokarsting around Polishing Pond, as seen from UAV.



Photo 15. East Twin Creek Diversion – Overview, looking downstream from UAV. Note minor erosion near upper right.



Photo 14. Polishing Pond – Thermokarsting around Polishing Pond.




Photo 16. East Twin Creek Diversion – Looking upstream from UAV at area where 2018 left bank maintenance was performed.



Photo 17. East Twin Creek Diversion – Looking downstream at area where 2018 left bank maintenance was performed.



Photo 19. Surface Cell Cover System – Minor thermokarsting along main E-W drainage swale.



Photo 18. Surface Cell Cover System – Minor thermokarsting along main N-S drainage swale.




Photo 20. Surface Cell Cover System – Overview from UAV, looking Northeast. Note heave feature in bottom left.



Photo 21. Surface Cell Cover System – Heave feature in the southwest quadrant of the Surface Cell cover system, as seen looking Southwest



Photo 23. Surface Cell Cover System – Western portion of the cover system, as seen from UAV near right abutment of the West Twin Dyke.



Photo 22. Surface Cell Cover System – Heave feature in the southwest quadrant of the Surface Cell cover system, as seen looking Northeast from UAV.




Photo 24. West Twin Dyke – Overview, as seen from UAV near the left abutment.



Photo 25. West Twin Dyke - Overview, as seen from UAV near the right abutment.



Photo 26. West Twin Dyke - Composite orthographic photo from UAV, Southwestern half.




Photo 27. West Twin Dyke - Composite orthographic photo from UAV, Northeastern half.



Photo 28. Test Cell Cover System - Looking Southwest across the cover system from UAV near the left abutment of the West Twin Dyke.



Photo 30. Test Cell Cover System – N/S arm of Test Cell Dyke, as seen from UAV. Note minor settlement trough.



Photo 29. Test Cell Cover System – Minor settlement trough along N/S arm of Test Cell Dyke.



Photo 31. Test Cell Cover System – Flat surface of cover system, looking North. Note minor thermokarsting.



Photo 32. Test Cell Cover System – Composite overview of cover system as seen from UAV.



Photo 34. Test Cell Cover System – Outlet of breach in Test Cell Dyke.



Photo 33. Test Cell Cover System – Toe of the test cell dyke.




Photo 35. Test Cell Cover System - UAV overview of erosion protection along E-W arm.



Photo 36. Test Cell Cover System – UAV overview of erosion protection along the toe of the Test Cell Dyke, view looking north.



Photo 38. Toe of West Twin Dyke Tailings Cover – Note minor thermokarsting.



Photo 37. Toe of West Twin Dyke Tailings Cover – As seen from UAV.



Photo 39. Toe of West Twin Dyke Tailings Cover – Note minor thermokarsting.



Photo 40. Landfill – Flat surface of cover system.




Photo 42. Landfill – Note flow along diversion berm upstream of the landfill (near bottom of photo).



Photo 41. Landfill – Diverted water flowing around north side of cover system.




Photo 43. Landfill – Northern toe of cover system as seen from UAV.




Photo 44. Landfill – Western toe of cover system as seen from UAV.




Photo 46. West Open Pit – Crack behind remnant highwall, as seen from above.



Photo 45. West Open Pit – Crack behind remnant highwall, as seen from above.



Photo 47. West Open Pit – Overview looking Northwest from UAV.



Photo 48. West Open Pit – Overview looking Northeast from UAV.



Photo 50. East Open Pit - Uppermost portion of cover and cracking in crown pillar, as seen from UAV.



Photo 49. East Open Pit - Looking upslope at rilling on upper portion of cover. Note self-armouring.



Photo 51. East Open Pit – Cracking in crown pillar.



Photo 52. East Open Pit - Remnant highwall, as seen from UAV.



Photo 54. East Trench – Overview as seen from UAV.



Photo 53. East Open Pit – Overview as seen from UAV.



Photo 55. Oceanview Pit – Rilling on the south end of the cover system. Note self-armouring.



Photo 56. Oceanview Pit – Minor seepage flowing into the cover system from upslope, as seen from the ground.



Photo 58. Oceanview Pit – Overview of cover system as seen from UAV.




Photo 57. Oceanview Pit – Minor seepage flowing into the cover system from upstream, as seen from UAV.



Photo 59. Area 14 - Overview as seen from UAV.



Photo 60. Upper Dump Pond – Flat surface of thermal cover system.



Photo 62. Upper Dump Pond – Constructed breach in road to mill site.



Photo 61. Upper Dump Pond - Looking upstream at constructed breach in road to Townsite.



Photo 63. Industrial Complex – Overview, as seen from UAV.



Photo 64. Industrial Complex – Sloping face of cover system.



Photo 66. Oceanview Portal Cover – Overview of cover as seen from UAV.



Photo 65. 17N Portal – As seen from road.



Photo 67. K-Baseline – As seen from UAV.



Photo 68. 09S Portal – Looking upslope at plug.



Photo 70. Mill Portal - As seen from UAV.




Photo 69. Lower Adit – Sloping face of cover system as seen from UAV.




Photo 71. Oceanview East Raise – Surface plug as seen from UAV, view looking north.



Photo 72. Oceanview West Raise – Surface plug as seen from UAV.



Photo 74. Shale Hill Borrow Area – As seen from road.



Photo 73. Mt. Fuji Shale Quarry – As seen from road.

APPENDIX II

2021 GEOTECHNICAL MONITORING

Annual Reading


| | | 01-Jan | 01-Feb | 01-Mar | 01-Apr | 15-Apr | 01-May | 11-May | 21-May | 01-Jun | 07-Jun | 14-Jun | 21-Jun | 01-Jul | 07-Jul | 14-Jul | 21-Jul | 01-Aug | 07-Aug | 14-Aug | 21-Aug | 01-Sep | 07-Sep | 14-Sep | 21-Sep | 01-Oct | 11-Oct | 21-Oct | 01-Nov | 01-Dec | 08-Dec | 15-Dec | 22-Dec | 29-Dec |
|------------------------|-----------------|-----------------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| Toe of West Twin Dyke | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC03-18 | Thermocouple | Not functioning | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC03-19 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-26 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Test Cell | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-04 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-18 | VW Piezo. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-19 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-20 | VW Piezo. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-21 | Monitoring Well | Not functioning | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-22 | VW Piezo. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-23 | Monitoring Well | Not functioning | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-24 | VW Piezo. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-25 | Contingency | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-7 | Frost Gauge | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-8 | Frost Gauge | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Test Cell Dyke | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC02-09 | Thermistor | Not functioning | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC03-22 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-29 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Toe of Test Cell Dyke | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-27 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-28 | VW Piezo. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-9 | Frost Gauge | Not functioning | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-10 | Frost Gauge | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Oceanview Pit | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-01 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-16 | Frost Gauge | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| East Open Pit | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-02 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-03 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-13 | Frost Gauge | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-14 | Frost Gauge | Not functioning | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Landfill | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC05-30 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-11 | Frost Gauge | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Area 14 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| TC7 | Thermocouple | Not functioning | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-15 | Frost Gauge | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Upper Dump Road | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FG-17 | Frost Gauge | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| West Open Pit | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC08-01 | Thermistor | Not functioning | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Mill Cover | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| BGC08-02 | Thermistor | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Water Quality / Levels | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 159-4 | Water Level | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 159-4 | Water Quality | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Spillway Inlet | Water Quality | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

| |
|-------------------|
| Weekly Reading |
| Monthly Reading |
| Bi-Weekly Reading |

APPENDIX III

2020-2029 GEOTECHNICAL MONITORING PROGRAM SCHEDULE

| Status of Instrument | | | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 |
|----------------------|-----------------|-----------------------|------|------|------|------|------|------|------|------|------|------|
| West Twin Dyke | | | | | | | | | | | | |
| TC12 | Thermocouple | Not functioning | | | | | | | | | | |
| TC13A | Thermocouple | Not functioning | | | | | | | | | | |
| TC31 | Thermocouple | Not functioning | | | | | | | | | | |
| TC32 | Thermocouple | Not functioning | | | | | | | | | | |
| TC33 | Thermocouple | Not functioning | | | | | | | | | | |
| BGC03-33 | Thermistor | | | | | | | | | | | |
| BGC03-34 | Thermistor | | | | | | | | | | | |
| BGC05-09 | Thermistor | | | | | | | | | | | |
| BGC05-15 | Thermistor | | | | | | | | | | | |
| BGC05-17 | VW Piezo. | | | | | | | | | | | |
| Surface Cell | | | | | | | | | | | | |
| BGC02-03 | Thermistor | Not functioning | | | | | | | | | | |
| BGC03-07 | Thermistor | | | | | | | | | | | |
| BGC03-09 | Thermistor | | | | | | | | | | | |
| BGC03-10 | Thermistor | | | | | | | | | | | |
| BGC03-11 | Thermistor | | | | | | | | | | | |
| BGC03-12 | Vibrating Wire | | | | | | | | | | | |
| BGC03-14 | Vibrating Wire | | | | | | | | | | | |
| BGC03-15 | Thermistor | | | | | | | | | | | |
| BGC03-20 | Thermistor | | | | | | | | | | | |
| BGC03-21 | Thermistor | Not functioning | | | | | | | | | | |
| BGC03-32 | Vibrating Wire | | | | | | | | | | | |
| BGC03-35 | Vibrating Wire | | | | | | | | | | | |
| BGC03-36 | Thermocouple | Not functioning | | | | | | | | | | |
| BGC03-37 | Thermistor | Not functioning | | | | | | | | | | |
| BGC05-05 | Thermistor | | | | | | | | | | | |
| BGC05-06 | VW Piezo. | | | | | | | | | | | |
| BGC05-07 | VW Piezo. | | | | | | | | | | | |
| BGC05-08 | Contingency | | | | | | | | | | | |
| BGC05-10 | VW Piezo. | | | | | | | | | | | |
| BGC05-11 | Monitoring Well | Not functioning | | | | | | | | | | |
| BGC05-12 | Monitoring Well | Not functioning | | | | | | | | | | |
| BGC05-13 | VW Piezo. | Partially functioning | | | | | | | | | | |
| BGC05-14 | Contingency | | | | | | | | | | | |
| BGC05-16 | Contingency | | | | | | | | | | | |
| FG-1 | Frost Gauge | | | | | | | | | | | |
| FG-2 | Frost Gauge | | | | | | | | | | | |
| FG-3 | Frost Gauge | | | | | | | | | | | |
| FG-4 | Frost Gauge | | | | | | | | | | | |
| FG-5 | Frost Gauge | | | | | | | | | | | |
| FG-6 | Frost Gauge | | | | | | | | | | | |

 Instruments to be read

| | | Status of Instrument | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | |
|------------------------|-----------------|----------------------|------|------|------|------|------|------|------|------|------|------|--|
| Toe of West Twin Dyke | | | | | | | | | | | | | |
| BGC03-18 | Thermocouple | Not functioning | | | | | | | | | | | |
| BGC03-19 | Thermistor | | | | | | | | | | | | |
| BGC05-26 | Thermistor | | | | | | | | | | | | |
| Test Cell | | | | | | | | | | | | | |
| BGC05-04 | Thermistor | | | | | | | | | | | | |
| BGC05-18 | VW Piezo. | | | | | | | | | | | | |
| BGC05-19 | Thermistor | | | | | | | | | | | | |
| BGC05-20 | VW Piezo. | | | | | | | | | | | | |
| BGC05-21 | Monitoring Well | Not functioning | | | | | | | | | | | |
| BGC05-22 | VW Piezo. | | | | | | | | | | | | |
| BGC05-23 | Monitoring Well | Not functioning | | | | | | | | | | | |
| BGC05-24 | VW Piezo. | | | | | | | | | | | | |
| BGC05-25 | Contingency | | | | | | | | | | | | |
| FG-7 | Frost Gauge | | | | | | | | | | | | |
| FG-8 | Frost Gauge | | | | | | | | | | | | |
| Test Cell Dyke | | | | | | | | | | | | | |
| BGC05-09 | Thermistor | Not functioning | | | | | | | | | | | |
| BGC03-22 | Thermistor | | | | | | | | | | | | |
| BGC05-29 | Thermistor | | | | | | | | | | | | |
| Toe of Test Cell Dyke | | | | | | | | | | | | | |
| BGC05-27 | Thermistor | | | | | | | | | | | | |
| BGC05-28 | VW Piezo. | | | | | | | | | | | | |
| FG-9 | Frost Gauge | Not functioning | | | | | | | | | | | |
| FG-10 | Frost Gauge | | | | | | | | | | | | |
| Oceanview Pit | | | | | | | | | | | | | |
| BGC05-01 | Thermistor | | | | | | | | | | | | |
| FG-16 | Frost Gauge | | | | | | | | | | | | |
| East Open Pit | | | | | | | | | | | | | |
| BGC05-02 | Thermistor | | | | | | | | | | | | |
| BGC05-03 | Thermistor | | | | | | | | | | | | |
| FG-13 | Frost Gauge | | | | | | | | | | | | |
| FG-14 | Frost Gauge | Not functioning | | | | | | | | | | | |
| Landfill | | | | | | | | | | | | | |
| BGC05-30 | Thermistor | | | | | | | | | | | | |
| FG-11 | Frost Gauge | | | | | | | | | | | | |
| Area 14 | | | | | | | | | | | | | |
| TC7 | Thermocouple | Not functioning | | | | | | | | | | | |
| FG-15 | Frost Gauge | | | | | | | | | | | | |
| Upper Dump Road | | | | | | | | | | | | | |
| FG-17 | Frost Gauge | | | | | | | | | | | | |
| West Open Pit | | | | | | | | | | | | | |
| BGC08-01 | Thermistor | | | | | | | | | | | | |
| Mill Cover | | | | | | | | | | | | | |
| BGC08-02 | Thermistor | | | | | | | | | | | | |
| Water Quality / Levels | | | | | | | | | | | | | |
| 159-4 | Water Level | | | | | | | | | | | | |
| 159-4 | Water Quality | | | | | | | | | | | | |
| Spillway Inlet | Water Quality | | | | | | | | | | | | |

 Instruments to be read