

SHEAR DIAMONDS (NUNAVUT) CORP.

## 2011 ANNUAL SEEPAGE SURVEY REPORT JERICHO DIAMOND MINE, NUNAVUT



### REPORT

NOVEMBER 2011  
ISSUED FOR USE  
EBA FILE: E14101140



---

## LIMITATIONS OF REPORT

This report and its contents are intended for the sole use of Shear Diamonds (Nunavut) Corp. and their agents. EBA, A Tetra Tech Company, does not accept any responsibility for the accuracy of any of the data, the analysis, or the recommendations contained or referenced in the report when the report is used or relied upon by any Party other than Shear Diamonds (Nunavut) Corp, or for any Project other than the proposed development at the subject site. Any such unauthorized use of this report is at the sole risk of the user.

## TABLE OF CONTENTS

<b>1.0 INTRODUCTION.....</b>	<b>1</b>
1.1 General .....	1
1.2 Background Information.....	1
1.3 Objective and Scope.....	2
<b>2.0 SEEPAGE QUALITY GUIDELINES .....</b>	<b>2</b>
<b>3.0 METHODS .....</b>	<b>2</b>
3.1 Routine Seepage Monitoring.....	2
3.2 Seepage Identification and Collection .....	2
3.3 Sample Preparation and Analysis .....	3
<b>4.0 FIELD ACTIVITIES AND OBSERVATIONS .....</b>	<b>3</b>
4.1 Site Conditions .....	3
4.2 Field Observations.....	4
<b>5.0 RESULTS AND DISCUSSION .....</b>	<b>6</b>
5.1 Data Quality Review .....	6
5.1.1 Duplicate Samples .....	6
5.1.2 Blank Samples .....	6
5.1.3 Field and Laboratory Measured Parameters .....	7
5.2 Laboratory Results Interpretation .....	7
5.2.1 Waste Rock Dump 1 and 2.....	7
5.2.2 Low Grade Ore Stockpile .....	8
<b>6.0 CONCLUSION AND RECOMMENDATIONS.....</b>	<b>8</b>
<b>7.0 CLOSURE.....</b>	<b>10</b>
<b>REFERENCES.....</b>	<b>11</b>

## TABLES

Table 2	Field Measurement and Laboratory Analytical Results
Table 3	RPD Calculation for Duplication Samples
Table 4	Comparison with the 2006 Seepage Survey Results

## FIGURES

Figure 1	Catchment Areas and Sample Locations
----------	--------------------------------------

## APPENDICES

Appendix A	Weekly Geotechnical Inspection Records
------------	--

## ACRONYMS & ABBREVIATIONS

CPK	Coarse Processed Kimberlite
DO	Dissolved Oxygen
EC	Electrical Conductivity
FPK	Fine Processed Kimberlite
GMP	General Monitoring Plan
NWB	Nunavut Water Board
MAC	Jericho Water Licence PKCA Discharge Criteria for Maximum Average Concentration
MGC	Jericho Water Licence PKCA Discharge Criteria for Maximum Grab Concentration
Ponding	Topographic low area that accumulated surface runoff and/or precipitation
PHC	Petroleum Hydrocarbons
PKCA	Processed Kimberlite Containment Area
PKMP	PKCA Management Plan
RPD	Relative Percent Difference
Seepage	Any water that drains through or escapes from any structure designed to contain, withhold, divert or retain water or waste. Seepage also includes any flows that have emerged from the toe, or as a result of runoff from overburden storage areas, waste rock storage facilities, coarse kimberlite reject areas and ore stockpile areas
Shear	Shear Diamonds (Nunavut) Corp.
SWMP	Site Water Management Plan
TDC	Tahera Diamonds Corporation
TDS	Total Dissolved Solids
TSS	Total Suspended Solids



## 1.0 INTRODUCTION

### 1.1 General

The Annual Seepage Survey for Jericho Diamond Mine, described herein, has been conducted to assess any leakage from the dams around the perimeter of the processed kimberlite containment area (PKCA) dams, and to monitor the changes in the chemistry of seeps from the waste rock dumps, ore stock piles, coarse processed kimberlite (CPK) stockpile, and explosives area.

This investigation fulfills requirements in the Jericho Water Licence (2AM-JER0410), Schedule L, Part 3:

- a) *"To include routine monitoring of all surface storage facilities identified in Table 3;*
- b) *To include the explosives storage and emulsion plant areas;*
- c) *To include seepage chemistry results from any sumps in the plant area;*
- d) *An annual seepage survey from the toe of the recovery plant rejects stockpile should be submitted to the Nunavut Water Board, along with the annual seepage survey results for all other waste and low grade ore stockpile; and*
- e) *To include any seepage at the base of the West Dam and all other dams around the perimeter of the Processed Kimberlite Containment Area (PKCA)."*

### 1.2 Background Information

The Jericho Diamond Mine is located approximately 260 km southeast of Kugluktuk, NU, and 30 km north of Lupin Mine. It was constructed and operated between 2005 and 2008 by Tahera Diamond Corporation (TDC). The mining activities were suspended in February 2008; and the ore processing activities were suspended in April 2008. After the cessation of the operation, the site was placed under care and maintenance. In August 2010, Shear Diamonds (Nunavut) Corp. (Shear) purchased the Jericho Mine and its assets, and assumed the responsibility for the site. Presently, the mine remains under temporary shutdown as Shear evaluates the mineral resources.

Under the previous ownership, formal annual seepage surveys were conducted in 2006 and 2007. According to the 2006 Seepage Survey Report (SRK 2006), seeps were identified and sampled at the northwest side of Low Grade Ore Stockpile (Seep-13) and the north side of Waste Rock Dump 2 (Seep-05). According to the 2007 Seepage Survey Report (TDC 2007), the two seeps identified in 2006 were dry; two additional seeps were identified and sampled at the south side of Waste Rock Dump 2 (Seep-2 and Seep-3). No annual seepage survey reports were submitted for the year 2008, 2009 and 2010. Recently, Shear has recovered a number of analytical results from old site computers, which indicates that additional seepage sampling was conducted in 2007 and 2008. This data does not correspond to the annual seepage reports filed by TDC. There is no reference map or coordinates provided, making it impossible to confirm the locations of these sampling events. Therefore, these additional analytical results are not reviewed. In July 2011, Shear's on-site environmental technicians collected a number of seepage and water ponding samples at the site.

### 1.3 Objective and Scope

The objectives of the annual seepage survey are to monitor any water that drains through or escapes from any structure designed to contain, withhold, divert or retain water or waste, and to monitor the water qualities of any flows that have emerged from the toe, or as a result of runoff from overburden storage areas, waste rock storage facilities, coarse kimberlite reject areas and ore stockpile areas.

The scope of the 2011 annual seepage survey program includes:

- Visual inspections for seepage from the water retention structures;
- Identifying and sampling of potential seepage exiting from the toe of Waste Rock Dumps, and Ore and CPK Stockpiles;
- Identifying and sampling of potential seepage flowing from the ammonium nitrate storage and emulsion plant area; and
- Prepare the 2011 annual seepage survey report in accordance with the Jericho Water Licence, Schedule L, Part 3.

## 2.0 SEEPAGE QUALITY GUIDELINES

The Jericho Water Licence Part F, Item 4(d) specifies “*any runoff accumulated and/or seepage that does not meet the effluent quality criteria Part G, Item 6(a) shall be collected and directed to the PKCA (...)*”. Therefore, the analytical results of the seepage samples are compared with the criteria for Maximum Average Concentration (MAC) and Maximum Grab Concentration (MGC) listed in Part G, Item 6(a) of the water licence.

## 3.0 METHODS

### 3.1 Routine Seepage Monitoring

As part of the Weekly Operational Geotechnical Inspections, Shear is responsible for conducting the routine seepage monitoring and reporting any observed seepages from the water retention structures. Appendix A includes a copy of Shear’s Weekly Geotechnical Monitoring Records from June 2 through September 6, 2011. The inspection records are maintained on-site, and are available for review upon request by the inspector.

### 3.2 Seepage Identification and Collection

As specified in the Jericho Water Licence, Schedule A, seepage is defined as “*any water that drains through or escapes from any structure designed to contain, withhold, divert or retain water or waste. Seepage also includes any flows that have emerged from the toe, or as a result of runoff from overburden storage areas, waste rock storage facilities, coarse kimberlite reject areas and ore stockpile areas*”.

Mr. William Liu of EBA and Mr. Mathieu Charbonneau of Shear conducted seepage surveying and sampling on September 14 and 15, 2011. The survey included:

- Conducting reconnaissance along the perimeters of waste rock dumps, CPK and ore stockpiles, waste rock pads for the low grade ore stockpiles and the plant site, explosives area, and PKCA dams;
- Documenting any seeps (actively flowing water emerging from the toe of waste rock dumps and pad, and CPK and ore stockpiles) and water pondings (topographic low area that tend to accumulate surface runoff and/or precipitation); and
- Collecting a grab sample from each identified seep that was actively flowing from the toe of the waste rock dumps/pads and the ore/CPK stockpiles.

The quality of the water adjacent or in close proximity to the rock piles can be largely influenced by overland runoff or precipitation, and may not represent the true seepage water quality. Therefore, the ponded water at the site was not sampled.

All identified seeps and ponded water were photographed, and the locations were recorded using a hand-held GPS. Seeps were sampled using laboratory supplied sample containers. Field parameters including temperature, pH, dissolved oxygen (DO), and electric conductivity (EC) for each sample were measured using an YSI 556 multi-parameter meter. This meter was calibrated weekly, as indicated by Shear's environmental technician.

One set of duplicate samples was collected at sample location JER-SPG-01C. One set of field blank samples was prepared in the field on September 14, 2011. One set of trip blank samples was prepared in and delivered from the laboratory, and was placed in the cooler with other water samples during the fieldwork and shipment to the laboratory.

### 3.3 Sample Preparation and Analysis

All sample bottles, filters, preservatives and coolers were supplied by ALS Laboratory in Yellowknife, NT. During the field sampling program, dissolved metal samples were filtered through 0.45 µm Millipore syringe filters and preserved with nitric acid; total metal samples were preserved with nitric acid; and nutrients samples were preserved with sulphuric acid.

Water bottles containing samples from the same station were placed in a clean plastic bag to avoid cross-contamination with samples from other sample stations, and were stored in a designated fridge or coolers to keep the samples below 4°C before shipment to the laboratory on September 17, 2011. Chain of custody forms were used to track samples. The seepage samples were submitted to ALS Laboratory in Yellowknife, NT, for the analysis of routine water parameters, nutrients, total metals, and dissolved metals.

## 4.0 FIELD ACTIVITIES AND OBSERVATIONS

### 4.1 Site Conditions

The *Supplemental Climate and Hydrology Report* (SRK 2003) described the climate at Jericho as having a short and cool summer and cold winter. The mean annual temperature at the nearby Lupin Airport is -11.1°C. July is the warmest month with a mean temperature of 11.5 °C; and January is the coolest month with a mean temperature of -30.4 °C. The mean annual precipitation at Jericho is approximately 330 mm,

with the majority of the precipitation occurring in August and September. The mean annual runoff at Jericho was estimated to be 225 mm, with the peak runoff occurring during freshet in June.

Shear recorded a light snow fall event approximately one week prior to the seepage survey, but there was no snow cover at the site during the survey. There was a light rain on the morning of September 14, 2011. The temperature during the two-day survey was approximately between 5 and 10 °C. Ice was observed at a number of locations near rock pile toes. Shear's Environment Technician indicated that seepage flows during the survey were noticeably greater than those observed in August.

## **4.2 Field Observations**

During the seepage survey, approximately 20 flowing streams and accumulated water ponding were observed at or in close proximity to the assessed areas. EBA field personnel and the Shear environmental technician collected water samples from seven identified active seeps and one stream flowing into the Waste Rock Dump 1. The site plan and sample locations are shown in Figure 1. The physical location and descriptions of the stations where samples were collected are present in Table 1.

### **Waste Rock Dumps 1 and 2**

The Waste Rock Dumps 1 and 2 spanned from the northeast to the southeast of the open pit. Based on the local topography and field observation, seeps that emerge from the waste rock dump generally flow northwest or west towards the pit or Carat Lake. During the survey, three active seeps (JER-SPG-01A, B, and C, see Photos 1 to 3) were identified at the northwest side of the Waste Rock Dump 1, which were flowing towards Carat Lake. Two smaller active seeps (JER-SPG-01D and 02A, see Photos 4 and 5) at the west side of the Waste Rock Dump 1 and the northwest side of the Waste Rock Dump 2 were flowing on, and eventually infiltrating into, the road between the waste rock dumps and the pit. The seepage water is anticipated to either feed into the pit sump or exit from the northwest side of the Waste Rock Dump 1 (approximate location of JER-SPG-01C). A small stream (JER-SPG-INFLOW01, see Photo 6) was also found to flow into Waste Rock Dump 1 from the Ditch C4 Catchment Area (See Figure 1).

In addition, six water pondings were observed along the perimeter of the waste rock dump, of which two relatively large water pondings had accumulated at the south and east side of Waste Rock Dump 2 (see Figure 1, and Photos 7 and 8). These two pondings were isolated at the time of the survey. Based on the observed moisture at the flow path between the ponding at the south side of Waste Rock Dump 2 and Key Lake, excessive water from this pond had flowed towards Key Lake in the past.

### **Low Grade Ore Pile**

The low grade ore piles were placed on a waste rock pad. The approximate perimeter of the waste rock pad is shown in Figure 1. Based on the local topography and field observations, potential seeps emerging from the low grade ore piles and the waste rock pad would flow northwest or north towards Lake C1 or the open pit. During the survey, two active seeps (JER-SPG-08A and 08B, see Photos 9 and 10) were observed at the west side of the waste rock pad flowing towards Lake C1. Six small water pondings near the west and north side of the waste rock pad were also identified. No active seeps or ponded water were observed at the east or south side of the waste rock pad.

## Ore and CPK Stockpiles and Plant Site

No seeps were observed the perimeters of the Ore Stockpile, CPK Stockpile or Waste Rock Pad for the Plant Site. One relatively large water ponding was found at the south side of the Ore Stockpile (see Photo 12). The ponded water is anticipated to originate from precipitation and surface runoff.

## Ammonium Nitrate Storage Pad, Emulsion Plant and Explosives Magazine

The Ammonium Nitrate Storage Pad is located in close proximity to a wetland area. Ponded water was observed at the east and west side of the pad (see Photos 13 and 14). The ponded water at the west of the pad feed into a small stream flowing in the direction to Lynne Lake. Active flowing water was observed at the time of the survey. As no ammonium nitrate was stored at the pad, no samples were collected during the site visit.

The Emulsion Plant was constructed on a waste rock pad. No seepage or ponded water was observed along the pad during the survey.

The explosives magazine area consists of a number of intermodal containers on sleds. No seepage or ponded water was observed in this area.

## West Dam, Southeast Dam and East Dam

The field personnel conducted visual reconnaissance at the toe of West Dam, Southeast Dam and East Dam of the PKCA (see Photo 15 to 18). No seepage was observed at the time of the survey. This is consistent with the Annual Geotechnical Inspection conducted in July 2011 (EBA 2011a) and the routine seepage monitoring conducted by Shear's on-site personnel.

**Table 1: Descriptions of Seepage Sample Stations and Flow Characteristics**

Station	Location	Flow Direction and Destination	Sample Collection
JER-SPG-01A	Toe at northwest side of Waste Rock Dump 1	West into Carat Lake	Collected one set of samples <sup>(1)</sup>
JER-SPG-01B	Toe at northwest side of Waste Rock Dump 1	West into Carat Lake	Collected one set of samples <sup>(1)</sup>
JER-SPG-01C	Toe at west side of Waste Rock Dump 1 and northeast side of the pit	North into Carat Lake	Collected one set of samples and one set of duplicate samples <sup>(1)</sup>
JER-SPG-01D	Toe at Southwest side of Waste Rock Dump 1	North on the Haul Road and infiltrate into the road	Collected one set of samples <sup>(1)</sup>
JER-SPG-02A	Toe of northwest side of Waste Rock Dump 2	North on the Haul Road and into a small ponding at the side of the road	Collected one set of samples <sup>(1)</sup>
JER-SPG-08A	Toe of west side of Low Grade Ore Stockpile	Northwest into Lake C1	Collected one set of samples <sup>(1)</sup>
JER-SPG-08B	Near southwest side of Low Grade Ore Stockpile	Northwest into Lake C1	Collected one set of samples <sup>(1)</sup>

**Table 1: Descriptions of Seepage Sample Stations and Flow Characteristics**

Station	Location	Flow Direction and Destination	Sample Collection
JER-SPG-INFLOW01	Northeast side of Waste Rock Dump 1	From Ditch C4 Catchment Area at the east and entering the northeast side of Waste Rock Dump 1	Collected one set of samples <sup>(2)</sup>
<b>Note:</b> 1. Detailed analytical parameters are presented in Appendix B. 2. Flow was too shallow to be measured. 3. Seep sample was collected on September 14, 2011, but the flow ceased at the time of flow measurement on September 15, 2011.			

## 5.0 RESULTS AND DISCUSSION

Eight water samples along with one duplicate sample and two blank samples were submitted to the laboratory for the analysis of routine parameters, nutrients, and total and dissolved metals. The analytical results that exceeded the Water Licence MAC and MGC criteria are highlighted in Table 2.

### 5.1 Data Quality Review

As a part of the quality assurance and quality control process, the quality of the data is reviewed before being used for data interpretation. This includes comparing the duplicate sample results, reviewing the field and trip blanks sample results, and comparing the field and laboratory measured parameters.

#### 5.1.1 Duplicate Samples

The purpose of the duplicate sampling is to verify the precision of the field sampler and the sampling procedure. One sequential duplicate sample for sample JER-SPG-01C was collected and submitted to the laboratory for the same analysis as the host sample. The relative percent difference (RPD)<sup>1</sup> of each parameter between the sample and its duplicate is calculated and presented in Table 3. Nineteen of 102 analyzed parameters have calculated RPD greater than 15%. Most of the parameters with large RPD values are within the total metals group, where the heterogeneity of the suspended particles in the water may play a major role in causing large RPD values. The sampling procedure of the seepage sampling program is deemed to be accurate and precise.

#### 5.1.2 Blank Samples

Generally, the field blank sample reflect the ambient conditions during the sampling program and are used to measure potential sampling contamination, while the trip blank sample reflect the potential contamination that may occur during the transportation of the samples.

The pH values in the field and trip blank samples are 5.81 and 5.69, below the Water Licence criteria of pH 6. Total and dissolved zinc in both samples are about 30 times of the detection limit, and are higher than

<sup>1</sup> Relative Percent Difference =  $\frac{|a-b|}{(a+b)/2}$



the zinc concentration in a number of the seepage samples. As described in Section 3.0, the trip blank sample was prepared in the laboratory, and was placed in a Ziploc plastic bag during shipment. Thus, the potential for cross-contamination during shipment is minimal. An email correspondence from ALS Laboratory indicated *“Over the 6-week period of 15-Aug-2011 thru 29-Sep-2011, de-ionized water supplied through our Yellowknife office for purposes of Trip and Field Blanks may have contained background levels of some trace metals. (...) To date, only zinc appears to have been definitely affected (observed at between 0.0025 and 0.0030 mg/L), but some instances of barium, copper, manganese, molybdenum and sodium have also been noted, albeit at much lower levels (...). pH of stored DIW is typically between 5 and 6, owing to absorption of ambient carbon dioxide, but it would not be considered corrosive since the actual acidity is so low”*.

### 5.1.3 Field and Laboratory Measured Parameters

The field measurement, including temperature, pH, DO, and EC, can provide the true value of the crucial water chemistry parameters, which cannot be obtained or may be altered due to a change in ambient environment.

In comparing field and laboratory pH in the eight samples in Table 2, field pH is, in general, lower than the laboratory pH. This is likely due to reduced carbon dioxide concentration at higher ambient temperature in the laboratory setting. Therefore, the field pH may represent the true pH value in the seepage water.

In comparing, field and laboratory ECs in the eight samples in Table 2, field EC values are generally half of the laboratory EC values, with the exception of sample JER-SPG-08B. As changed ambient temperature and sample shipment cannot significantly alter the EC of the water, the laboratory measured EC is likely to represent the true EC value of the seepage water. The EC calibration of the multi-parameter meter should be checked.

## 5.2 Laboratory Results Interpretation

### 5.2.1 Waste Rock Dump 1 and 2

#### Total Suspended Solids (TSS)

As presented in Table 2, TSS in samples JER-SPG-01A, 01C, and 01D are between 40 mg/L and 45 mg/L; and TSS in sample JER-SPG-02A is 237 mg/L. These values exceeded the Water Licence MGC criterion of 25 mg/L. Due to the snow melt and rainfall event that occurred during the day of the survey, sudden water flows through the rock piles may have disturbed the settled particles along the flow paths and increased the TSS in the seeps.

Seeps JER-SPG-01D and 02A infiltrated into the road along the pit, and may further seep into the pit or exit from the toe at the northwest side of Waste Rock Dump 1. Seeps JER-SPG-01A and 01C flowed through a vegetated area before entering Carat Lake; therefore, TSS concentrations in these two seeps are anticipated to be reduced before reaching Carat Lake.

Visual observations suggest the turbidity of seep JER-SPG-02A would be similar to other seeps; however, the laboratory results indicated the TSS is approximately five times that of other samples. EBA requested that the laboratory retest the sample; however, the laboratory indicated sample retesting cannot be performed due to limited sample remains.

## **Nitrate**

Nitrate concentrations in samples JER-SPG-01D and 02A were 125 mg/L and 58 mg/L, which exceeded the Water Licence MGC criterion of 56 mg/L. These two seeps infiltrated the road. Based on the topography of the original ground, they may further seep into the pit or exit from the toe at the northwest side of Waste Rock Dump 1.

Nitrate in sample JER-SPG-01C was 53.2 mg/L, which was below the Water Licence MGC criterion of 56 mg/L, but exceeded the Water Licence MAC criterion of 28 mg/L. This seep flowed through a vegetated area towards Carat Lake. The water quality monitoring data showed that nitrate at the outlet of Carat Lake (JER-AEM-16) had an increasing trend from 0.05 mg/L to 0.185 mg/L between 2005 and 2009, and decreased to below detection in August 2011. Additional study is required to assess if the elevated nitrate concentration in the seepage water would contribute to the increased nitrate concentration in Carat Lake.

Nitrate in sample JER-SPG-INFLOW01 was 0.347 mg/L. This indicates that the majority of the nitrate in the seeps is from dissolved blast residual (ammonium nitrate) carried by the waste rock. Sample Seep-5 in the 2006 Seepage Survey Report has nitrate concentration (65.9 mg/L) similar to sample JER-SPG-01D and 02A. Comparison of the two sets of results in Table 4 shows, after five years of flushing, that a large quantity of blast residual remains in the waste rock dumps.

### **5.2.2 Low Grade Ore Stockpile**

## **TSS**

TSS in sample JER-SPG-08A and 08B were 7 mg/L and <0.3 mg/L, which were both below the water licence MSC criterion of 25 mg/L.

## **Nitrate**

Nitrate in sample JER-SPG-08A and 08B were 12 mg/L and 3.26 mg/L, which are all below the water licence MSC criterion of 56 mg/L.

## **6.0 CONCLUSION AND RECOMMENDATIONS**

During the 2011 seepage survey, EBA field personnel and Shear's environmental technician conducted visual reconnaissance around the perimeter of Waste Rock Dump 1 and 2, Low Grade Ore Stockpiles, Coarse PK Stockpile, Plant Site Area, Explosives Area, and PKCA dams.

Seven active seeps and one inflow were observed and sampled. These included five seeps and one inflow at Waste Rock Dump 1 and 2, and two seeps from Low Grade Ore Piles. No seeps were observed at the Coarse PK Stockpile or the Plant Site area. One stream was observed from a wet land at the ammonium nitrate storage area. As no ammonium nitrate is currently stored at the site, no sample was collected. No seeps were observed from West Dam, East Dam or Southeast Dam at the time of the site visit.

TSS in four seepage samples from the waste rock dump exceeded the Water Licence MGC criterion. As discussed in Section 5.2.1, elevated TSS in the seepage samples may be attributed to the snow melt and rain event that occurred on the day of the seepage survey.



Nitrate in the two samples flowing between the open pit and waste rock dump exceeded the Water Licence MGC criterion. By the time that the analytical results from the laboratory were received, freeze up had occurred at the site therefore additional samples could not be collected to verify the results or determine the exact fate of the water.

Based the observation made on-site and the laboratory analysis, EBA recommends as the following:

- Implementation of a more detailed seepage survey program in 2012 including:
  - Conducting seasonal seepage surveys starting at freshet to monitor the seasonal variation of the seepage quality and flow rate;
  - Establishing sampling stations in Carat Lake and Lake C1 near the seep inflows to verify the dispersion of the constituents from the seepage water;
  - Collecting water samples from the established stations on a seasonal basis; and
  - Identifying the sources and fates of the identified seeps
- Conducting surface water dispersion models in Carat Lake to predict the potential impact from the seeps during production and at closure; and
- Analyzing and pumping ponded water from the south and east side of Waste Rock Dump 2 to the PKCA (refer to Figure 1) to prevent overflowing into the receiving environment.

## 7.0 CLOSURE

EBA, A Tetra Tech Company




William Liu, M.Eng., E.I.T.  
Environmental Scientist  
Environment Practice  
Direct Line: 780.451.2130 x257  
wliu@eba.ca



Reviewed by  
Natalie Lippa, M.Sc.  
Environmental Scientist  
Environment Practice  
Direct Line: 780.451.2130 x504  
nlippa@eba.ca



Reviewed by:  
Allison Rippin Armstrong  
Regulatory & Compliance Specialist  
Direct Line: 780.451.2130 x512  
aarmstrong@eba.ca



Reviewed by:  
K.W. Jones, P.Eng.  
Vice President of Arctic Development  
Direct Line: 780.451.2130 x271  
kjones@eba.ca

**Reviewed by Shear Diamonds Ltd.**

Julie Lassonde  
Executive Chairman and Chief Executive Officer

## REFERENCES

- EBA, A Tetra Tech Company (EBA), 2011a. 2011 Annual Geotechnical Inspection, Jericho Diamond Mine, Nunavut. Prepared for Shear Diamonds Ltd., September 2011.
- EBA, A Tetra Tech Company (EBA), 2011b. General Monitoring Plan, Jericho Diamond Mine, Nunavut. Prepared for Shear Diamonds Ltd., February 2011.
- EBA, A Tetra Tech Company (EBA), 2011c. Site Water Management Plan, Jericho Diamond Mine, Nunavut. Prepared for Shear Diamonds Ltd., February 2011.
- SRK Consulting Inc. (SRK), 2003. Technical Memorandum C: Supplemental Climate and Hydrology, Jericho Project, Nunavut. Prepared for Tahera Corporation, October 2003.
- SRK Consulting Inc. (SRK), 2004. Technical Memorandum O: Proposed Discharge Limits for the Jericho Project, Nunavut. Prepared for Tahera Corporation, August 2004.
- SRK Consulting Inc. (SRK), 2006. Jericho Diamond Mine 2006 Waste Rock Seepage Monitoring Report. Prepared for Tahera Diamond Corporation, October 2006.
- Tahera Diamond Corporation (TDC), 2007. 2007 Waste Rock Seepage Monitoring Report. Prepared by Jericho Diamond Mine Environment Department.

## TABLES

---

Table 2	Field Measurement and Laboratory Analytical Results
Table 3	RPD Calculation for Duplication Samples
Table 4	Comparison with the 2006 Seepage Survey Results

Table 2: Field Measurement and Laboratory Analytical Results

Analyte	Unit	Sample ID			JER-SPG-01A	JER-SPG-01B	JER-SPG-01C	JER-SPG-01D	JER-SPG-02A	JER-SPG-08A	JER-SPG-08B	JER-SPG-INFLOW01	JER-SPG-DUP01	JER-SPG-FB	JER-SPG-TB
		Laboratory ID			L1059935-1	L1059935-2	L1059935-3	L1059935-5	L1059935-6	L1059935-7	L1059935-8	L1059935-9	L1059935-4	L1059935-12	L1059935-13
		Date Sampled			9/14/2011	9/14/2011	9/14/2011	9/14/2011	9/14/2011	9/14/2011	9/14/2011	9/15/2011	9/14/2011	9/14/2011	9/14/2011
		LOR <sup>(1)</sup>	NWB-WL <sup>(2)</sup> Max. Avg	NWB-WL <sup>(2)</sup> Max. Grab											
Coordinates (NAD 27, Zone 12W)															
Northing			-	-	7320042	7319967	7319737	7319301	7319217	7319028	7319112	7319861	Same as JER-SPG-01C	-	-
Easting			-	-	478773	478777	478393	478465	478363	477618	477720	479136		-	-
Field Measurement															
pH (Field)	-		-	-	7.17	7.55	7.70	7.78	8.23	7.41	7.60	7.30	-	-	-
Conductivity (EC, Field)	µS/cm		-	-	191.5	93.0	384.5	824.0	406.6	164.7	219.9	23.5	-	-	-
Dissolved Oxygen (Field)	mg/L		-	-	7.8	11.8	13.3	12.8	12.4	10.2	13.0	13.4	-	-	-
Temperature (Field)	°C		-	-	1.8	1.1	0.3	4.8	7.0	5.3	3.2	2.0	-	-	-
Physical Parameter															
pH (Lab)	pH	0.1	6 - 8.8	6 - 8.8	7.59	7.76	7.93	8.05	8.12	8.03	8.06	7.34	7.94	5.81	5.69
Conductivity (EC)	uS/cm	0.2	-	-	310	159	658	1240	793	349	251	38.7	645	1.07	0.91
Total Dissolved Solids (Calculated)	mg/L	n/a	2,000	4,000	157	96.4	441	911	529	213	139	18.1	408	<1.0	<1.0
Total Suspended Solids	mg/L	3	15	25	40	5	40	45	237	7	<3.0	<3.0	56	<3.0	<3.0
Turbidity	NTU	0.1	-	-	24.8	2.65	5.04	33.4	231	3.62	0.72	3.2	19.6	<0.10	<0.10
Hardness (as CaCO3)	mg/L	1.3	-	-	116	60	265	513	331	130	104	16.3	259	<1.3	<1.3
Ion Balance (Calculated)	%	n/a	-	-	124	97.1	95.4	90	95.4	95.8	105	Low EC	100	Low TDS	Low TDS
Anions and Nutrients															
Acidity (as CaCO3)	mg/L	5	-	-	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	-	<5.0
Alkalinity, Total (as CaCO3)	mg/L	5	-	-	38.5	30.4	78.9	73.4	117	67.3	85.9	14.2	81.7	<5.0	<5.0
Bicarbonate (HCO3)	mg/L	5	-	-	47	37.1	96.3	89.5	143	82.1	105	17.3	99.7	<5.0	<5.0
Carbonate (CO3)	mg/L	5	-	-	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0
Hydroxide (OH)	mg/L	5	-	-	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0
Chloride (Cl)	mg/L	0.5	500	1,000	5.92	1.88	7.03	7.17	10.5	8.38	4.52	<0.50	6.44	<0.50	<0.50
Fluoride (F)	mg/L	0.05	-	-	<0.050	<0.050	0.091	0.088	<0.050	0.057	0.104	<0.050	0.093	<0.050	<0.050
Total Ammonia (as N)	mg/L	0.005	6	12	0.76	0.157	0.489	2.25	0.205	0.306	<0.0050	<0.0050	0.463	<0.0050	<0.0050
Nitrate and Nitrite (as N)	mg/L	0.006	-	-	14.9	9.84	54	126	58	12	3.26	0.347	46.6	<0.0060	<0.0060
Nitrate (as N)	mg/L	0.006	28	56	14.8	9.84	53.2	125	58	12	3.26	0.347	46	<0.0060	<0.0060
Nitrite (as N)	mg/L	0.002	2.5	5.0	0.099	<0.050	0.722	0.669	0.054	0.056	<0.0020	<0.0020	0.625	<0.0020	<0.0020
Orthophosphate-Dissolved (as P)	mg/L	0.001	-	-	0.0033	<0.0010	<0.0010	<0.0010	0.0656	0.0018	<0.0010	<0.0010	<0.0010	<0.0010	<0.0010
Phosphorus (P)-Total	mg/L	0.001	0.2	0.4	0.0503	0.0102	0.0361	0.0115	0.176	0.0473	0.008	0.0049	0.0443	<0.0010	<0.0010
Sulfate (SO4)	mg/L	0.05	-	-	12.5	6.48	38.6	102	54.6	50.2	18.9	1.36	39.3	0.065	<0.050
Organic/Inorganic Carbon															
Total Inorganic Carbon	mg/L	1	-	-	11	7.8	20.7	18.4	29.8	16.7	22.3	4.3	21.1	<1.0	<1.0
Total Organic Carbon	mg/L	1	-	-	7.4	6.3	7	3.4	10.5	13.5	6	6.3	7.5	2.8	<1.0
Total Metals															
Aluminum (Al)-Total	mg/L	0.0002	1.5	3.0	0.0743	0.0901	0.122	0.0277	0.128	0.136	0.037	0.195	0.0791	<0.00020	<0.00020
Antimony (Sb)-Total	mg/L	0.000005	-	-	0.0000821	0.0000727	0.000146	0.000161	0.000348	0.000167	0.000833	0.0000128	0.000165	<0.0000050	<0.0000050
Arsenic (As)-Total	mg/L	0.00002	0.05	0.10	0.00029	0.000322	0.000907	0.000716	0.00108	0.000631	0.000376	0.000186	0.000775	<0.000020	<0.000020
Barium (Ba)-Total	mg/L	0.00002	-	-	0.0434	0.0171	0.0772	0.0647	0.102	0.0443	0.0261	0.0071	0.0777	<0.000020	<0.000020
Beryllium (Be)-Total	mg/L	0.000002	-	-	0.0000181	0.0000161	0.0000127	0.0000025	0.0000105	0.0000146	0.0000054	0.0000405	0.0000084	<0.0000020	<0.0000020
Bismuth (Bi)-Total	mg/L	0.000001	-	-	0.0000014	0.0000021	0.0000045	0.0000012	0.0000075	0.0000032	<0.0000010	0.0000021	0.0000028	<0.0000010	<0.0000010
Boron (B)-Total	mg/L	0.005	-	-	0.0579	0.0449	0.102	0.111	0.0556	0.0483	0.0355	0.0051	0.103	<0.0050	<0.0050
Cadmium (Cd)-Total	mg/L	0.000005	0.0012	0.0024	0.0000094	<0.0000050	<0.000010	<0.000010	0.000111	<0.0000050	<0.0000050	<0.0000050	<0.000010	<0.0000050	<0.0000050
Calcium (Ca)-Total	mg/L	0.03	-	-	26.3	13.5	63.6	130	83.7	29.4	24.7	3.94	62.4	<0.030	<0.030
Cesium (Cs)-Total	mg/L	0.000005	-	-	0.0000819	0.0000471	0.000043	0.000247	0.0000689	0.0000461	0.0000172	0.0000309	0.0000336	<0.0000050	<0.0000050
Chromium (Cr)-Total	mg/L	0.00005	0.087	0.17	0.00029	0.000289	0.000382	0.000104	0.000427	0.000909	0.000241	0.00037	0.000234	<0.000050	<0.000050
Cobalt (Co)-Total	mg/L	0.000005	-	-	0.00145	0.000262	0.00448	0.00149	0.00234	0.0012	0.000185	0.000135	0.00491	<0.0000050	<0.0000050
Copper (Cu)-Total	mg/L	0.00005	0.02	0.04	0.00486	0.00456	0.00442	0.00863	0.0135	0.00549	0.00581	0.00289	0.00446	<0.000050	<0.000050
Gallium (Ga)-Total	mg/L	0.00005	-	-	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050
Iron (Fe)-Total	mg/L	0.01	-	-	0.303	0.119	0.365	0.05	0.209	0.257	0.069	0.17	0.303	<0.010	<0.010
Lead (Pb)-Total	mg/L	0.000005	0.01	0.02	0.000143	0.000228	0.000324	0.0000234	0.000767	0.00046	0.0000966	0.000185	0.000259	<0.0000050	<0.0000050
Lithium (Li)-Total	mg/L	0.0002	-	-	0.00404	0.0031	0.00804	0.011	0.00383	0.00412	0.00278	0.00078	0.00767	<0.00020	<0.00020
Magnesium (Mg)-Total	mg/L	0.03	-	-	13	6.88	29.3	56	34.5	15.6	10	1.65	28.7	<0.030	<0.030
Manganese (Mn)-Total	mg/L	0.000005	-	-	0.253	0.0331	0.935	0.718	0.337	0.481	0.00261	0.00321	1.06	0.0000223	0.000017
Mercury (Hg)-Total	mg/L	0.00005	-	-	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050	<0.000050
Molybdenum (Mo)-Total	mg/L	0.00001	0.73	1.50	0.00332	0.00318	0.01	0.00592	0.00293	0.00695	0.00405	0.000111	0.00954	0.000012	0.000013
Nickel (Ni)-Total	mg/L	0.00005	0.05	0.10	0.00684	0.00263	0.00823	0.00828	0.0314	0.0121	0.00246	0.000788	0.00849	<0.000050	<0.000050
Phosphorus (P)-Total	mg/L	0.05	-												

Table 3: RPD Calculation for Duplication Samples

Analyte	Unit		JER-SPG-01C	JER-SPG-DUP01	RPD
			L1059935-3	L1059935-4	
			9/14/2011	9/14/2011	
Physical Parameter		LOR <sup>(1)</sup>			
pH (Lab)	pH	0.1	7.93	7.94	0.1%
Conductivity (EC)	uS/cm	0.2	658	645	2.0%
Total Dissolved Solids (Calculated)	mg/L	n/a	441	408	7.8%
Total Suspended Solids	mg/L	3	40	56	33.3%
Turbidity	NTU	0.1	5.04	19.6	118.2%
Hardness (as CaCO3)	mg/L	1.3	265	259	2.3%
Anions and Nutrients					
Acidity (as CaCO3)	mg/L	5	<5.0	<5.0	< 5x of LOR
Alkalinity, Total (as CaCO3)	mg/L	5	78.9	81.7	3.5%
Bicarbonate (HCO3)	mg/L	5	96.3	99.7	3.5%
Carbonate (CO3)	mg/L	5	<5.0	<5.0	< 5x of LOR
Hydroxide (OH)	mg/L	5	<5.0	<5.0	< 5x of LOR
Chloride (Cl)	mg/L	0.5	7.03	6.44	8.8%
Fluoride (F)	mg/L	0.05	0.091	0.093	2.2%
Total Ammonia (as N)	mg/L	0.005	0.489	0.463	5.5%
Nitrate and Nitrite (as N)	mg/L	0.006	54	46.6	14.7%
Nitrate (as N)	mg/L	0.006	53.2	46	14.5%
Nitrite (as N)	mg/L	0.002	0.722	0.625	14.4%
Orthophosphate-Dissolved (as P)	mg/L	0.001	<0.0010	<0.0010	< 5x of LOR
Phosphorus (P)-Total	mg/L	0.001	0.0361	0.0443	20.4%
Sulfate (SO4)	mg/L	0.05	38.6	39.3	1.8%
Organic/Inoragnic Carbon					
Total Inorganic Carbon	mg/L	1	20.7	21.1	1.9%
Total Organic Carbon	mg/L	1	7	7.5	6.9%
Total Metals					
Aluminum (Al)-Total	mg/L	0.0002	0.122	0.0791	42.7%
Antimony (Sb)-Total	mg/L	0.000005	0.000146	0.000165	12.2%
Arsenic (As)-Total	mg/L	0.00002	0.000907	0.000775	15.7%
Barium (Ba)-Total	mg/L	0.00002	0.0772	0.0777	0.6%
Beryllium (Be)-Total	mg/L	0.000002	0.0000127	0.0000084	40.8%
Bismuth (Bi)-Total	mg/L	0.000001	0.0000045	0.0000028	46.6%
Boron (B)-Total	mg/L	0.005	0.102	0.103	1.0%
Cadmium (Cd)-Total	mg/L	0.000005	<0.000010	<0.000010	< 5x of LOR
Calcium (Ca)-Total	mg/L	0.03	63.6	62.4	1.9%
Cesium (Cs)-Total	mg/L	0.000005	0.000043	0.0000336	24.5%
Chromium (Cr)-Total	mg/L	0.00005	0.000382	0.000234	48.1%
Cobalt (Co)-Total	mg/L	0.000005	0.00448	0.00491	9.2%
Copper (Cu)-Total	mg/L	0.00005	0.00442	0.00446	0.9%
Gallium (Ga)-Total	mg/L	0.00005	<0.000050	<0.000050	< 5x of LOR
Iron (Fe)-Total	mg/L	0.01	0.365	0.303	18.6%
Lead (Pb)-Total	mg/L	0.000005	0.000324	0.000259	22.3%
Lithium (Li)-Total	mg/L	0.0002	0.00804	0.00767	4.7%
Magnesium (Mg)-Total	mg/L	0.03	29.3	28.7	2.1%
Manganese (Mn)-Total	mg/L	0.000005	0.935	1.06	12.5%
Mercury (Hg)-Total	mg/L	0.00005	<0.000050	<0.000050	< 5x of LOR
Molybdenum (Mo)-Total	mg/L	0.00001	0.01	0.00954	4.7%
Nickel (Ni)-Total	mg/L	0.00005	0.00823	0.00849	3.1%
Phosphorus (P)-Total	mg/L	0.05	<0.050	<0.050	< 5x of LOR
Potassium (K)-Total	mg/L	0.05	7.11	7.02	1.3%
Rhenium (Re)-Total	mg/L	0.000005	0.0000161	0.0000153	5.1%
Rubidium (Rb)-Total	mg/L	0.000005	0.00597	0.00579	3.1%
Selenium (Se)-Total	mg/L	0.00004	0.000513	0.000453	12.4%
Silicon (Si)-Total	mg/L	0.05	5.46	5.26	3.7%
Silver (Ag)-Total	mg/L	0.000005	<0.0000050	<0.0000050	< 5x of LOR
Sodium (Na)-Total	mg/L	0.2	14.5	14	3.5%
Strontium (Sr)-Total	mg/L	0.00001	0.325	0.319	1.9%
Tellurium (Te)-Total	mg/L	0.00001	<0.000010	<0.000010	< 5x of LOR
Thallium (Tl)-Total	mg/L	0.000001	0.0000174	0.0000163	6.5%
Thorium (Th)-Total	mg/L	0.000005	0.0000674	0.0000364	59.7%
Tin (Sn)-Total	mg/L	0.00001	<0.000010	<0.000010	< 5x of LOR
Titanium (Ti)-Total	mg/L	0.00005	0.00432	0.00233	59.8%
Tungsten (W)-Total	mg/L	0.00001	0.000199	0.000191	4.1%
Uranium (U)-Total	mg/L	0.000001	0.183	0.168	8.5%
Vanadium (V)-Total	mg/L	0.00001	0.000637	0.000584	8.7%
Yttrium (Y)-Total	mg/L	0.000005	0.000465	0.000304	41.9%
Zinc (Zn)-Total	mg/L	0.0001	0.00271	0.00324	17.8%
Zirconium (Zr)-Total	mg/L	0.00001	0.000265	0.000211	22.7%
Dissolved Metals					
Aluminum (Al)-Dissolved	mg/L	0.0002	0.0193	0.0238	20.9%
Antimony (Sb)-Dissolved	mg/L	0.000005	0.000149	0.000144	3.4%
Arsenic (As)-Dissolved	mg/L	0.00002	0.000775	0.000778	0.4%
Barium (Ba)-Dissolved	mg/L	0.00002	0.0783	0.0759	3.1%
Beryllium (Be)-Dissolved	mg/L	0.000002	0.0000056	0.0000061	8.5%
Bismuth (Bi)-Dissolved	mg/L	0.000001	<0.0000010	0.0000011	< 5x of LOR
Boron (B)-Dissolved	mg/L	0.005	0.102	0.105	2.9%
Cadmium (Cd)-Dissolved	mg/L	0.000005	<0.000010	<0.000010	< 5x of LOR
Calcium (Ca)-Dissolved	mg/L	0.03	63.6	63.2	0.6%
Cesium (Cs)-Dissolved	mg/L	0.000005	0.0000244	0.0000245	0.4%
Chromium (Cr)-Dissolved	mg/L	0.00005	0.00013	0.000151	14.9%
Cobalt (Co)-Dissolved	mg/L	0.000005	0.00405	0.00419	3.4%
Copper (Cu)-Dissolved	mg/L	0.00005	0.00359	0.00364	1.4%
Gallium (Ga)-Dissolved	mg/L	0.00005	<0.000050	<0.000050	< 5x of LOR
Iron (Fe)-Dissolved	mg/L	0.01	0.213	0.228	6.8%
Lead (Pb)-Dissolved	mg/L	0.000005	0.0000884	0.0000933	5.4%
Lithium (Li)-Dissolved	mg/L	0.0002	0.00782	0.00749	4.3%
Magnesium (Mg)-Dissolved	mg/L	0.03	29.2	28.5	2.4%
Manganese (Mn)-Dissolved	mg/L	0.000005	0.873	0.915	4.7%
Mercury (Hg)-Dissolved	mg/L	0.00005	<0.000050	<0.000050	< 5x of LOR
Molybdenum (Mo)-Dissolved	mg/L	0.00001	0.0102	0.00944	7.7%
Nickel (Ni)-Dissolved	mg/L	0.00005	0.00707	0.00729	3.1%
Phosphorus (P)-Dissolved	mg/L	0.05	<0.050	<0.050	< 5x of LOR
Potassium (K)-Dissolved	mg/L	0.05	7.01	7.03	0.3%
Rhenium (Re)-Dissolved	mg/L	0.000005	0.0000159	0.0000153	3.8%
Rubidium (Rb)-Dissolved	mg/L	0.000005	0.00561	0.00556	0.9%
Selenium (Se)-Dissolved	mg/L	0.00004	0.000389	0.000461	16.9%
Silicon (Si)-Dissolved	mg/L	0.05	5.09	5.09	0.0%
Silver (Ag)-Dissolved	mg/L	0.000005	<0.0000050	<0.0000050	< 5x of LOR
Sodium (Na)-Dissolved	mg/L	0.2	14.3	14.1	1.4%
Strontium (Sr)-Dissolved	mg/L	0.00001	0.321	0.31	3.5%
Tellurium (Te)-Dissolved	mg/L	0.00001	<0.000010	<0.000010	< 5x of LOR
Thallium (Tl)-Dissolved	mg/L	0.000001	0.0000162	0.0000163	0.6%
Thorium (Th)-Dissolved	mg/L	0.000005	0.0000289	0.000029	0.3%
Tin (Sn)-Dissolved	mg/L	0.00001	<0.000010	<0.000010	< 5x of LOR
Titanium (Ti)-Dissolved	mg/L	0.00005	0.000432	0.000425	1.6%
Tungsten (W)-Dissolved	mg/L	0.00001	0.000204	0.000192	6.1%
Uranium (U)-Dissolved	mg/L	0.000001	0.182	0.166	9.2%
Vanadium (V)-Dissolved	mg/L	0.00001	0.0004	0.000415	3.7%
Yttrium (Y)-Dissolved	mg/L	0.000005	0.000215	0.000227	5.4%
Zinc (Zn)-Dissolved	mg/L	0.0001	0.00264	0.00311	16.3%
Zirconium (Zr)-Dissolved	mg/L	0.00001	0.000132	0.00015	12.8%
Note:					
1. LOR - Limit of Reporting					
2. Relative Percent Difference is highlighted in yellow if the value is larger than 15%					






# FIGURES

---

Figure 1 Catchment Areas and Sample Locations






NOTES:

1. LAYOUTS ARE APPROXIMATE, AND MAY NOT REFLECT ACTUAL SIZE AND LOCATIONS
2. FOOTPRINT OF CURRENT WASTE ROCK DUMP ARE PLOTTED BASED ON SURVEY DATA AND HANDHELD GPS TRACKS IN 2011

MONITORING LOCATIONS:

■ - 2011 SEEPAGE SURVEY SAMPLE LOCATION



STATUS  
ISSUED FOR USE

CLIENT



2011 ANNUAL SEEPAGE SURVEY  
JERICO DIAMOND MINE, NUNAVUT

CATCHMENT AREAS AND SAMPLE  
LOCATIONS

PROJECT NO. E14101140	DWN DBD/TK	CKD WL	REV 0
OFFICE EBA-EDM	DATE October 2011		

Figure 1



# PHOTOGRAPHS

---



**Photo 1:** Seep JER-SPG-1A Flowing into Carat Lake  
Western aspect  
Photo taken on September 14, 2011



**Photo 2:** Seep JER-SPG-1B Emerging from West Side of Waste Rock Dump 1  
Southern aspect  
Photo taken on September 14, 2011





**Photo 3:** Seep JER-SPG-1C Flowing North into Carat Lake  
Northern aspect  
Photo taken on September 14, 2011



**Photo 4:** Seep JER-SPG-01D Flowing North on Haul Road  
Northern aspect  
Photo taken on September 14, 2011





**Photo 5:** Seep JER-SPG-02A Flowing into a Small Pond on Side of Haul Road  
Southeastern aspect  
Photo taken on September 14, 2011



**Photo 6:** Stream JER-SPG-INFLOW01 Flowing West into Waste Rock Dump 1  
Western aspect  
Photo taken on September 15, 2011





**Photo 7:** Ponding South of Waste Rock Dump 2  
Eastern aspect  
Photo taken on September 15, 2011



**Photo 8:** Ponding East of Waste Rock Dump 2  
Northwestern aspect  
Photo taken on September 15, 2011






**Photo 9:** Seep JER-SPG-08A Emerging from West Side of Low Grade Ore Stockpile  
Eastern aspect  
Photo taken on September 14, 2011



**Photo 10:** Seep JER-SPG-08B at Southwest Side of Low Grade Ore Stockpile  
Southeastern aspect  
Photo taken on September 14, 2011





**Photo 11:** Northwest Side of Coarse PK Stockpile  
Southeastern aspect  
Photo taken on September 15, 2011



**Photo 12:** Water Ponding at South Side of Ore Stockpile  
Western aspect  
Photo taken on September 15, 2011





**Photo 13:** Water Ponding and Wetland at East Side of Ammonia Nitrate Storage Pad  
Northeastern aspect  
Photo taken on September 15, 2011



**Photo 14:** Water Ponding at West Side of Ammonia Nitrate Storage Pad  
Western aspect  
Photo taken on September 15, 2011





**Photo 15:** North Portion of the West Face of West Dam  
Northern aspect  
Photo taken on September 15, 2011



**Photo 16:** South Portion of the West Face of West Dam  
Southern aspect  
Photo taken on September 15, 2011





**Photo 17:** Southeast Face of Southeast Dam  
Northeastern aspect  
Photo taken on September 15, 2011



**Photo 18:** East Face of East Dam  
Western aspect  
Photo taken on September 15, 2011

# APPENDIX A

## APPENDIX A WEEKLY GEOTECHNICAL INSPECTION RECORDS

---



Ⓟ = Photo taken.

## WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: THURSDAY JUNE 2ND 2011 Weather: overcast, N/W wind, ~-5°C  
Time (Start/Finish): 8:35 - 18:00 Inspected by: CJP / RAK

### West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read (June 1/11)  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment Thermister casing @ #1916 damaged.

Notes: (Location/description, extent, dimensions of feature)

- trace seepage - frozen - probably meltwater
- minor slope erosion (~5m) on S side of transition zone on DIS side Ⓟ
- snow on DIS side of toe.
- water @ UP side flow.

☒ Require Inspection by Engineer RAK (EBS) present.

### East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read (May 31/11)  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

- UP side ~~minor~~ erosion typically near T-joints Ⓟ - particularly at most S/E end.
- ponding DIS side - likely meltwater. - liner should be adjusted under pipe?

☒ Require Inspection by Engineer RAK onsite.

### South Dam

☒ Seepage NO. ☒ Cracking ☒ Erosion ☒ Instruments Read (June 2/11)  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

- erosion as at East Dam. should be fixed. - Crack forming beside erosion @ SE end.
- HDPE liner under SE outflow T-joint should be fixed.
- DIS snow limiting inspection

☒ Require Inspection by Engineer RAK onsite.

### Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment n/a m

Notes: (Location/description, extent, dimensions of feature)

- cell B/C side frozen + snow covered. Ⓟ
- visible surfaces look good.

☒ Require Inspection by Engineer RAK onsite.

### Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

- small amount of settlement on N side/outside wall - minor.
- S side top of berm slightly damaged by equipment - should be fixed.
- S side discoloration + evidence of spill.

☒ Require Inspection by Engineer RAK onsite

**Generator Containment Area**

*Minor on top of E side*

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

**Notes:** (Location/description, extent, dimensions of feature)

- elevation of berm on W side should be improved.
- water should be pumped out to facilitate volume for potential spill.

☒ Require Inspection by Engineer

**Airstrip Containment Area**

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

**Notes:** (Location/description, extent, dimensions of feature)

- small depressions on E side holding ponded water. Discolouration and evidence of spill. Liner needs to be investigated when thawed to assess why its showing there.
- HOLES should be filled if okay

☒ Require Inspection by Engineer

**Landfill**

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

**Notes:** (Location/description, extent, dimensions of feature)

- landfill mostly covered and inactive.

☒ Require Inspection by Engineer

**Waste Transfer Area**

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

**Notes:** (Location/description, extent, dimensions of feature)

- In process of pumping out ponded water - analytical results available.
- Many issues with liner in W cell - must be fixed - on ALL sides.
- Some damage in E cell - must be fixed - mostly N + W sides.
- Holes, breaks likely by equipment.

☒ Require Inspection by Engineer

**C1 Diversion Channel**

☒ Water Flowing ☒ Cracking ☒ Erosion/Sloughing ☒ Culverts Open  
☒ Settlement or Slumping ☒ Ponded Water ☒ Free of Snow

**Notes:** (Location/description, extent, dimensions of feature)

- rock in UPS side of culvert deemed minor by RK. ~300mm stone.
- most of trib is snow covered.

☒ Require Inspection by Engineer



### East Sump

☒ Seepage/Over topping    ☒ Cracking    ☒ Damage by equipment    Pond water level  
☒ Settlement or Slumping    ☒ Erosion    N/A m

Notes: (Location/description, extent, dimensions of feature)

• ice covered.  
 • ~~no~~ v. minor erosion along PK - No action necessary.

☒ Require Inspection by Engineer

### Collector Ditches and Culverts - surveyed 7 culverts along airport Rd. See below.

☒ Water Flowing    ☒ Cracking    ☒ Erosion    ☒ Culverts Open  
☒ Settlement or Slumping    ☒ Ponded Water    ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Culverts #1d from N to S. starting with culvert nearest HwTA.  
(all ephemeral)

☐ Require Inspection by Engineer

### Additional Notes:

- ① perched culvert on O/S side.  
flowing.
- ② not flowing, blocked.  
(ephemeral)
- ③ flowing, this system should  
be improved for blue herons
- ④ flowing
- ⑤ blocked - cemently  
actually pumping  
vs ponded water.
- ⑥ is there supposed to  
be a culvert at this  
marker?
- ⑦ v. small flow -

### Photo List:

Ⓟ = indicate photos  
taken @ site.



# WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: 12-June-11 Weather: A bit of rain / snow  
 Time (Start/Finish): 15:00-17:30 Inspected by: Carolyn & Tatiana

## West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment NA

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

## East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* minor upstream side

☒ Require Inspection by Engineer

## Southeast Dam

☐ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

## Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion ☐ Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment ☐ m

Notes: (Location/description, extent, dimensions of feature)

\*abit in cell A  
There seems to be a flow from cell A to cell B-C  
Pictures taken (see daily)

☒ Require Inspection by Engineer

## Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment historical

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer



### Generator Containment Area

☒ Y/N Seepage ☒ Y/N Cracking ☒ Y/N Erosion ☒ Y/N Evidence of Spillage  
☒ Y/N Settlement or Slumping ☒ Y/N Ponded Water ☒ Y/N Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Y/N Require Inspection by Engineer

### Airstrip Containment Area

☒ Y/N Seepage ☒ Y/N Cracking ☒ Y/N Erosion ☒ Y/N Evidence of Spillage  
☒ Y/N Settlement or Slumping ☒ Y/N Ponded Water ☒ Y/N Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☐ Y/N Require Inspection by Engineer

### Landfill

☒ Y/N Seepage ☒ Y/N Cracking ☒ Y/N Erosion  
☒ Y/N Settlement or Slumping ☒ Y/N Ponded Water ☒ Y/N Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☐ Y/N Require Inspection by Engineer

### Waste Transfer Area (Area 1 + HUSTA)

☒ Y/N Seepage ☒ Y/N Cracking ☒ Y/N Erosion  
☒ Y/N Settlement or Slumping ☒ Y/N Ponded Water ☒ Y/N Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Y/N Require Inspection by Engineer

### C1 Diversion Channel

☒ Y/N Water Flowing ☒ Y/N Cracking ☒ Y/N Erosion/Sloughing ☒ Y/N Culverts Open  
☒ Y/N Settlement or Slumping ☒ Y/N Ponded Water ☒ Y/N Free of Snow

Notes: (Location/description, extent, dimensions of feature)

☒ Y/N Require Inspection by Engineer

## East Sump

☒ Y/N Seepage/Over topping ☒ Y/N Cracking

☒ Y/N Cracking

☒ Y/N Damage by equipment

Pond water level

☒ Y/N Settlement or Slumping      ☒ Y/N Erosion

☒ Y/N Erosion

**Notes:** (Location/description, extent, dimensions of feature)

m

NOT ESTABLISHED YET

☒ Y/N Require Inspection by Engineer

### Collector Ditches and Culverts

☒ Y/N Water Flowing

☒ Y/N Cracking

+ a bit

☒ Y/N Erosion

☐ Y/N Culverts Open

☒ Y/N Settlement or Slumping ☒ Y/N Ponded Water

☒ Y/N Ponded Water

☒ Y/N Damage by equipment

**Notes:** (Location/description, extent, dimensions of feature)

\* Culvert work needed on Airport Road

☒ Y/N Require Inspection by Engineer

**Additional Notes:**

### Photo List:

# WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: 18 June 2011 Weather: Cloudy & windy. No rain.  
 Time (Start/Finish): \_\_\_\_\_ Inspected by: TATIANA LELLERC, JIM KANE

## West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

DONE MAY 31.

Notes: (Location/description, extent, dimensions of feature)

There is a small depression at the top of the dam (pond BC) (P)  
 confirmed: it is there for a season.

☒ Require Inspection by Engineer

## East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* minor upstream side (P)  
 \* AC fine downstream (historical.)

☒ Require Inspection by Engineer

## South East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* minor erosion upstream  
 \* T joint, HDPE liner has to be fixed (P)

☒ Require Inspection by Engineer

## Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment  m

Notes: (Location/description, extent, dimensions of feature)

\* lots of dirt downstream side  
 \* ice melted on shore  
 \* No flow side BC, still a flow side A

☒ Require Inspection by Engineer

## Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* Lots of water has has to be cleaned prior to discharge. Algae.  
 \* historical large spill.

☒ Require Inspection by Engineer

1 of 4





### Generator Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* Sand missing on the rims. liner exposed. (P)  
\* Ponded water historical.

☐ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* Ponded water contaminated (P)  
\* Erosion at the bottom (exterior) due to melted snow.

☐ Require Inspection by Engineer

### Landfill

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☐ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* Liner exposed to the rims  
\* ponded water contaminated.  
\* tarp was to be put back on W. cell.

☐ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing ☒ Cracking ☒ Erosion/Sloughing ☒ Culverts Open  
☒ Settlement or Slumping ☒ Ponded Water ☒ Free of Snow

Notes: (Location/description, extent, dimensions of feature)

☐ Require Inspection by Engineer

### East Sump

☒ Seepage/Over topping      ☒ Cracking      ☒ Damage by equipment      Pond water level  m  
☒ Settlement or Slumping      ☒ Erosion

**Notes:** (Location/description, extent, dimensions of feature)

WA

☒ Y/N Require Inspection by Engineer

## Collector Ditches and Culverts

being taken care of

☒ Y/N Water Flowing     
 ☒ Y/N Cracking     
 ☒ Y/N Erosion     
 ☒ Y/N Culverts Open  
☒ Y/N Settlement or Slumping     
☒ Y/N Ponded Water     
☒ Y/N Damage by equipment     
*one has*

**Notes:** (Location/description, extent, dimensions of feature)

one has to be  
deconstructed.  
Need info approval.

Y/N	Require Inspection by Engineer
-----	--------------------------------

**Additional Notes:**

Emerson paul

No sep page

no element

No cracking

UFS pender weler

Yes sports.

**Photo List:**This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

# WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: 24-June-2011 Weather: Sunny. Windy.

Time (Start/Finish): 4:00 PM - 5:30 PM Inspected by: TATIANA CECLERC

8:00 PM - 9:00 PM

## West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read

☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

READ MAY 31

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

## East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read

☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* minor erosion down upstream  
\* PKCA downstream

☒ Require Inspection by Engineer

## Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read

☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* HDPE liner has to be fixed.

☒ Require Inspection by Engineer

## Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion ☒ Cell B/C water level

☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* a bit upstream

From water to pin = 47.5cm.  
(.475m)

☒ Require Inspection by Engineer

## Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage

☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

historical

☒ Require Inspection by Engineer





### Generator Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* liner a lot exposed on rims.

☒ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment *historical*

Notes: (Location/description, extent, dimensions of feature)

\* Erosion: at the bottom.

\* liner exposed.

☐ Require Inspection by Engineer

### Landfill

☐ Seepage ☐ Cracking ☐ Erosion  
☐ Settlement or Slumping ☐ Ponded Water ☐ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Landfill is inactive.  
operations working

☐ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

\* Ponded water dried.

\* liner exposed and damaged by equipment

\* tarp ~~was~~ positioned on west cell but not permanent

☒ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing ☒ Cracking ☒ Erosion/Sloughing ☒ Culverts Open  
☒ Settlement or Slumping ☒ Ponded Water ☒ Free of Snow *almost*

Notes: (Location/description, extent, dimensions of feature)

\* some snow left down south.

\* a rock into the culvert but doesn't keep water from flowing

☒ Require Inspection by Engineer





# WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: July 6 / 2011 Weather: clear, no wind, clouds / sun.  
 Time (Start/Finish): 14:00 17:45 Inspected by: CIP / CS

## West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature) as was found originally on westside historic. see notes

☒ Require Inspection by Engineer

## East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature) historic - downstream

☒ Require Inspection by Engineer

## Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature) as reported

liner repair as previously reported.

☒ Require Inspection by Engineer

## Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion ☐ Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment 0.591 m

Notes: (Location/description, extent, dimensions of feature) minor upstr

☒ Require Inspection by Engineer

## Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature) as historic

evidence of 'DRIP' from joint from pipe to tank and spill ponds down be r Chris Investigate

☒ Require Inspection by Engineer follow up

### Generator Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☐ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

*→ should be pumped once remed unit in place*

☒ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

*some - not extreme.  
as usual  
- liner exposed - on list to be fixed.*

☐ Require Inspection by Engineer

### Landfill

*INACTIVE - LANDFILL HAS BEEN COVERED*

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☐ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

*- Problems has inspected & reported historically.  
- No new issues  
- laid down spill pad @ one drum.  
- ongoing*

☒ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing ☒ Cracking ☒ Erosion/Sloughing ☒ Culverts Open  
☒ Settlement or Slumping ☒ Ponded Water ☒ Free of Snow

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### East Sump

☒ Y/N Seepage/Over topping ☒ Y/N Cracking

Y/N	Damage by equipment	Pond water level
-----	---------------------	------------------

☐ Y/N Settlement or Slumping ☐ Y/N Erosion

MA m

**Notes:** (Location/description, extent, dimensions of feature)

☒ Y/N Require Inspection by Engineer

## Collector Ditches and Culverts

☒ Y/N Water Flowing

☒ Y/N Cracking

☒ Y/N Erosion

☒ Y/N Culverts Open

☐ Y/N Settlement or Slumping ☐ Y/N Ponded Water

☒ Y/N Damage by equipment

**Notes:** (Location/description, extent, dimensions of feature)

- will be rebuilt with DFO guidance
- biologists in next week.

Y/N

 Require In

☒ Y/N Require Inspection by Engineer

**Additional Notes:**

### Photo List:



# WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: JULY 14 2011 Weather: Sunny Clear Light Winds ~16°C  
 Time (Start/Finish): 13:00 - 16:30 Inspected by: CJP / TL

## West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

@ SE side - historic and appears stable.

Happening this week! BARY COOP.

☒ Require Inspection by Engineer

! Data forwarded to Geotech.

## East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

- erosion typically near 'T-joints'  
 - Liner should be adjusted under pipe.

☒ Require Inspection by Engineer

## Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

- erosion issues as @ east dam.  
 - HDPE liner under SE outflow should be fixed.

☒ Require Inspection by Engineer

## Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Cell B/C water level  m

Notes: (Location/description, extent, dimensions of feature)

SAS 05 = 33 in = 83.8 cm.  
 SAS 04 = 43/4 = 12 cm.

☒ Require Inspection by Engineer

05  
 517.66  
 - 83.80  
 433.86  
 04  
 517.01  
 - 12.00  
 505.01  
 ?

## Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

• small amount of ~~erosion~~ settled on N side / outside wall  
 • S side - top of berm slightly damaged by equipment.  
 • S side historical spill

☒ Require Inspection by Engineer

• ponded water in S cell being remediated w new unit.



### Generator Containment Area

☒ Seepage      ☒ Cracking      ☒ Erosion <sup>v. minor</sup>      ☒ Evidence of Spillage  
☒ Settlement or Slumping      ☒ Ponded Water      ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

- water to be pumped.

☒ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage      ☒ Cracking      ☒ Erosion <sup>v. minor</sup>      ☒ Evidence of Spillage <sup>historic</sup>  
☒ Settlement or Slumping      ☒ Ponded Water <sup>v. minor</sup>      ☒ Damage by equipment <sup>inside ~~the~~ floor</sup>

Notes: (Location/description, extent, dimensions of feature)

small depressions on E side floor of containment to be filled. Should investigate liner prior to assure integrity on floor.

☒ Require Inspection by Engineer

### Landfill

☒ Seepage      ☒ Cracking      ☒ Erosion  
☒ Settlement or Slumping      ☒ Ponded Water      ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Landfill closed.

☒ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage      ☒ Cracking      ☒ Erosion  
☒ Settlement or Slumping      ☒ Ponded Water      ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

As noted on previous inspections these cells require major repair - however no current water or evidence of contaminants leaving containment.

☒ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing      ☒ Cracking      ☒ Erosion/Sloughing      ☒ Culverts Open  
☒ Settlement or Slumping      ☒ Ponded Water      ☒ Free of Snow

Notes: (Location/description, extent, dimensions of feature)

rock in upstrm side of culvert -

☒ Require Inspection by Engineer





# WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: FRIDAY JULY 22/11 Weather: overcast, mod wind.  
Time (Start/Finish): 15:00 Inspected by: C Paterson

## West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

*Leak in upper part of discharge hose creating small pool of water in middle bench on west side of dam.  
Some siltation, but remedied immediately.  
NO FURTHER ACTION.*

☒ Require Inspection by Engineer

## East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

*minor on West side.  
-erosion typically near 'T' joints  
-Liner should be adjusted under discharge pipes before any discharge happens.*

☒ Require Inspection by Engineer

## Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

## Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment 0.33 m SAS-04

Notes: (Location/description, extent, dimensions of feature)

*very small ant upstrm side - and evaporating quickly.*

☒ Require Inspection by Engineer

## Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment *HISTORIC / nothing new.*

Notes: (Location/description, extent, dimensions of feature)

*minor - mostly from walking over banks.  
on south side - historic  
• some settlement on N side, outside wall not serious  
• South side - historical spill  
• ponded water in S cell being pumped to OZEE*

☒ Require Inspection by Engineer



### Generator Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

- water slated to be pumped to OZREC.

☒ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

↳ very small and - evaporating quickly.

☒ Require Inspection by Engineer

### Landfill (OLD LANDFILL)

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

HMTA in process of investigation and repair this weekend.

☒ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing ☒ Cracking ☒ Erosion/Sloughing ☒ Culverts Open  
☒ Settlement or Slumping ☒ Ponded Water ☒ Free of Snow

Notes: (Location/description, extent, dimensions of feature)

↳ but very low flow -

☒ Require Inspection by Engineer

### East Sump

☒ Seepage/Over topping    ☒ Cracking    ☒ Damage by equipment    Pond water level N/A m  
☒ Settlement or Slumping    ☒ Erosion

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### Collector Ditches and Culverts

*in C-2 only.*  
☒ Water Flowing    ☒ Cracking    *evidence from freshet*    ☒ Erosion    *yes and no on some.*    ☒ Culverts Open  
☒ Settlement or Slumping    ☒ Ponded Water    ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

*minor at some culverts - slated for repair*  
*EB A & DFO was here this week*

☐ Require Inspection by Engineer

### Additional Notes:

### Photo List:

*[Handwritten signature]*

## WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: 08-AUGUST-11 Weather: Sunny, calm  
 Time (Start/Finish): 18:00 - 19:30 Inspected by: JATANA

### West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

→ Erosion, T-joints, liner under pipes need adjustment  
 → PK fine on East side (historical)

☒ Require Inspection by Engineer

### Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

→ Erosion, liner unadjusted under T joints

☒ Require Inspection by Engineer

### Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment  m

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

→ Spill historical  
 → ponded water being remediated via OZTEC  
 →

☒ Require Inspection by Engineer



### Generator Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

→ H<sub>2</sub>O will be treated prior to discharge.  
→ liner a bit visible.

☒ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

a bit at bottom/north side

↳ hidden

Notes: (Location/description, extent, dimensions of feature)

→ ponded water dry (evaporation)

☒ Require Inspection by Engineer

### Landfill

\* SAMPLED  
JULY 15

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

→ liners broken & exposed ⇒ pictures & field notes sent to E&A

☒ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing ☒ Cracking ☒ Erosion/Sloughing ☒ Culverts Open  
☒ Settlement or Slumping ☒ Ponded Water ☒ Free of Snow

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer



# WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: 16 - AUGUST - 2011 Weather: Windy (East) Rainy, Cool <10°C  
 Time (Start/Finish): 13:00 Inspected by: CJP + MC

## West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

→ photo - slump area noted - photo taken, not new - has been there since May, but may be deeper now? will compare with photo taken today in later inspections

☒ Require Inspection by Engineer

## East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

only slight on downstream side as noted in previous inspect.

☒ Require Inspection by Engineer

## Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

erosion under T joints & discharge pipes - as noted previously

☒ Require Inspection by Engineer

## Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment 0.21 m below SASO4

Notes: (Location/description, extent, dimensions of feature)

very little water on upstrm side.

☒ Require Inspection by Engineer

## Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

still a lot of ponded water on N section

evidence present, but from old spills/leaks previously recorded.

☒ Require Inspection by Engineer





### Generator Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Covers most of the base of the secondary containment.

☒ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

ponded water at under tank on the S side of fuel tank #20

slight smell & appearance of hydrocarbon in ponded water (appears old)

☒ Require Inspection by Engineer

### Landfill N/A - CLOSED

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Cracks in lining, not on berms. slight pools in tire tracks (fairly deep)

☒ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

slight pooling present

☒ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing ☒ Cracking ☒ Erosion/Sloughing ☒ Culverts Open  
☒ Settlement or Slumping ☒ Ponded Water ☒ Free of Snow bit damaged.

Notes: (Location/description, extent, dimensions of feature)

- at base of culvert  
- culvert appears damaged

☒ Require Inspection by Engineer

### East Sump

☒ Seepage/Over topping    ☒ Cracking    ☒ Damage by equipment    Pond water level  
☒ Settlement or Slumping    ☒ Erosion    n/a m

Notes: (Location/description, extent, dimensions of feature)

(no markers)

☒ Require Inspection by Engineer

### Collector Ditches and Culverts

☒ Water Flowing    ☒ Cracking    ☒ Erosion    ☒ Culverts Open  
☒ Settlement or Slumping    ☒ Ponded Water    ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

some culverts appear fairly damaged & should be replaced  
still has water flowing

very damaged towards  
airport road. slight damage @

☒ Require Inspection by Engineer

Additional Notes: 1 diversion stream

### Photo List:

- ① Slump @ West Dam
- ② " " "



# WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: Aug 23<sup>rd</sup>, 2011 Weather: Slight E wind, Cool (~9°C) no rain  
 Time (Start/Finish): (10:55 am) Inspected by: MC.

## West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

slight slump on west side of Dam.

☒ Require Inspection by Engineer

## East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

0

☒ Require Inspection by Engineer

## Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

## Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion ☒ Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment ☒ 516.65 m

Notes: (Location/description, extent, dimensions of feature)

no significant water on East side of Dyke.

(ASL)

☒ Require Inspection by Engineer

## Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

still a lot of ponded water in S section of Farm  
 (Down significantly from the previous week)

☒ Require Inspection by Engineer



### Generator Containment Area

☒ Seepage      ☒ Cracking      ☒ Erosion      ☒ Evidence of Spillage  
☒ Settlement or Slumping      ☒ Ponded Water      ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

lots of water present due to continuous rain. will need to be drained & cleaned in Oztec

☒ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage      ☒ Cracking      ☒ Erosion      ☒ Evidence of Spillage  
☒ Settlement or Slumping      ☒ Ponded Water      ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

pooling near fuel tank #2

old spill present, no new incidents found.

☐ Require Inspection by Engineer

### Landfill

N/A  
☒ Seepage      ☐ Cracking      ☐ Erosion  
☒ Settlement or Slumping      ☐ Ponded Water      ☐ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Land fill is closed.

☐ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage      ☒ Cracking      ☒ Erosion  
☒ Settlement or Slumping      ☒ Ponded Water      ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

slight pooling in tracks  
on N end of N section

☒ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing      ☒ Cracking      ☒ Erosion/Sloughing      ☒ Culverts Open  
☒ Settlement or Slumping      ☒ Ponded Water      ☒ Free of Snow      (slight damage)

Notes: (Location/description, extent, dimensions of feature)

at base of culvert  
(culvert is slightly above  
water level)

☒ Require Inspection by Engineer



## WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: Aug 30, 2011 Weather: Sunny, no clouds, 11°C  
Time (Start/Finish): 9:00 am - 12:00 pm Inspected by: MC/WA

### West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Slight slump noted previously

☒ Require Inspection by Engineer

### East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

outside of dam covered in FPK

☒ Require Inspection by Engineer

### Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment  m

Notes: (Location/description, extent, dimensions of feature)

East side of Dam  
(in PKCA)

☒ Require Inspection by Engineer

### Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer



### Generator Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### Airstrip Containment Area

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

minimal  
(no action required)

- past spill  
- slight diesel in  
ponded water

☒ Require Inspection by Engineer

### Landfill

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

NOT OPEN

☒ Require Inspection by Engineer

### Waste Transfer Area

☒ Seepage ☒ Cracking ☒ Erosion  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Settled waste in N section  
(near fire rts)

lots of exposed / damaged liner.

☒ Require Inspection by Engineer

### C1 Diversion Channel

☒ Water Flowing ☒ Cracking ☒ Erosion/Sloughing ☒ Culverts Open  
☒ Settlement or Slumping ☒ Ponded Water ☒ Free of Snow

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer



## WEEKLY GEOTECHNICAL INSPECTION SUMMARY

Observation Date: 06 Sept 2011

Weather: foggy, mild, ~9°C

Time (Start/Finish): 9-11 am

Inspected by: WA

### West Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

slumping previously notes

☒ Require Inspection by Engineer

### East Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

outside of wall covered in FPK

☒ Require Inspection by Engineer

### Southeast Dam

☒ Seepage ☒ Cracking ☒ Erosion ☒ Instruments Read  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

erosion at drainage troughs  
one trough out of place

☒ Require Inspection by Engineer

### Divider Dyke A

☒ Downstream Turbidity ☒ Cracking ☒ Erosion Cell B/C water level  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment 516.42 m

Notes: (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

### Fuel Tank Farm

☒ Seepage ☒ Cracking ☒ Erosion ☒ Evidence of Spillage  
☒ Settlement or Slumping ☒ Ponded Water ☒ Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

lots of ponded water  
depression of berm near tank #8

☒ Require Inspection by Engineer





### Generator Containment Area

☒ Y/N Seepage      ☒ Y/N Cracking      ☒ Y/N Erosion      ☒ Y/N Evidence of Spillage  
☒ Y/N Settlement or Slumping      ☒ Y/N Ponded Water      ☒ Y/N Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Y/N Require Inspection by Engineer

### Airstrip Containment Area

☒ Y/N Seepage      ☒ Y/N Cracking      ☒ Y/N Erosion      ☒ Y/N Evidence of Spillage  
☒ Y/N Settlement or Slumping      ☒ Y/N Ponded Water      ☒ Y/N Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

☒ Y/N Require Inspection by Engineer

### Landfill

☒ Y/N Seepage      ☒ Y/N Cracking      ☒ Y/N Erosion  
☒ Y/N Settlement or Slumping      ☒ Y/N Ponded Water      ☒ Y/N Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

N/A - not in use

☒ Y/N Require Inspection by Engineer

### Waste Transfer Area

☒ Y/N Seepage      ☒ Y/N Cracking      ☒ Y/N Erosion  
☒ Y/N Settlement or Slumping      ☒ Y/N Ponded Water      ☒ Y/N Damage by equipment

Notes: (Location/description, extent, dimensions of feature)

Exposed term

☒ Y/N Require Inspection by Engineer

### C1 Diversion Channel

☒ Y/N Water Flowing      ☒ Y/N Cracking      ☒ Y/N Erosion/Sloughing      ☒ Y/N Culverts Open  
☒ Y/N Settlement or Slumping      ☒ Y/N Ponded Water      ☒ Y/N Free of Snow

Notes: (Location/description, extent, dimensions of feature)

☒ Y/N Require Inspection by Engineer

## East Sump

☒ Seepage/Over topping      ☒ Cracking      ☒ Damage by equipment      Pond water level  
☒ Settlement or Slumping      ☒ Erosion       m

**Notes:** (Location/description, extent, dimensions of feature)

m  
no benchmarks

☒ Y/N Require Inspection by Engineer

## Collector Ditches and Culverts

☒ N Water Flowing     
 ☐ Y ☒ N Cracking     
 ☐ Y ☒ N Erosion     
 ☒ Y ☒ N Culverts Open  
☐ Y ☒ N Settlement or Slumping     
 ☐ Y ☒ N Ponded Water     
 ☐ Y ☒ N Damage by equipment

**Notes:** (Location/description, extent, dimensions of feature)

☒ Require Inspection by Engineer

**Additional Notes:**

### Photo List:

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.