

APPENDIX 1

SITE INSPECTION MEMO



BGC ENGINEERING INC.

AN APPLIED EARTH SCIENCES COMPANY

#1605 - 840 7th Avenue S.W., Calgary, Alberta, Canada. T2P 3G2
Phone (403) 250-5185 Fax (403) 250-5330

PROJECT MEMORANDUM

To:	Kinross Gold Corp., Lupin Operation	Fax No.:	provided at site
Attention:	Mr. Dave Hohnstein	CC:	none
From:	Mr. Jim Cassie, P.Eng.	Date:	July 30, 2003
Subject:	2003 Annual Inspection of Tailings Dams and Miscellaneous Dikes Maintenance Recommendations		

No. of Pages (including this page): 3 Pages

Project No: 0256-007-01

The following memo provides some comments on required maintenance, following the inspection of the tailings dams and waste containment dikes on July 29th and 30th, 2003.

External Tailings Dams

Dam 1A

- Some minor cracking is occurring adjacent to the siphon pipes at the downstream access road berm.
- No maintenance is suggested.

Dam 1B

- No maintenance suggested.

Dam 1C

- Grade minor erosional gullies on the downstream face.

Dam 2

- Minor erosional scarp, approximately 2.5 m below the crest on the upstream slope, should be backfilled with rip rap.

Dam 3

- Minor tension cracks were noted along the toe of the eastern arm of the dam and at the toe of the northwestern portion of the dam (where Dam 3 contacts Boomerang Lake). Some minor grading or slope flattening may be required.

This communication is intended for the use of the above named recipient. Any unauthorized use, copying, review or disclosure of the contents by other than the recipient is prohibited.

Dam 4

- Dozer /construction activity on the upstream side has disturbed the rip rap placement. Consideration should be given to regrading the materials to an overall consistent slope to prevent the concentration of surface runoff.
- Erosional gullies on the downstream face, approximately 10 m west of Thermistor 4-1, should be backfilled.

Dam 5

- Backfill numerous erosional gullies on the downstream slope.

Dam 6

- Backfill numerous erosional gullies on the downstream slope.

Internal Tailings Dams

J-Dam

- High water level has resulted in erosion of the upstream face of the dam. The vertical scarp created is quite extensive and cracking of the upstream side has resulted. Consideration should be given to regrading or protecting these eroded faces.
- One 0.5 m diameter sinkhole noted near the upstream side of the crest and this should be backfilled.

K-Dam

- The tailings beach on the upstream side has left very little "freeboard" to the dam crest should a significant precipitation event occurs. If pond drainage overtops the dam crest, significant erosion and possible failure of the dam could result. Measures should be taken to ensure that extreme precipitation events can be retained by the dam.
- Significant erosional scarps have formed at the toe of the downstream slope, due to the previous and current water levels of Pond #2. Regrading of this eroded toe and/or placement of protective rip rap should be undertaken to prevent further erosion leading to progressive slumping of the face.

L-Dam

- The tailings beach on the upstream side has left very little "freeboard" to the dam crest (within the northern portion of the dam) should a significant precipitation event occurs. If pond drainage overtops the dam crest, significant erosion and possible failure of the dam could result. Measures should be taken to ensure that extreme precipitation events can be retained by the dam.
- Three transverse cracks were noted on the crest. The cracks and the associated settlement troughs should be backfilled to prevent the infiltration of water.
- Numerous sloughs and settled areas are occurring on the downstream face, generally due to scarps formed at the toe. A significant crack has formed in the northern portion of the crest, directly proximal to the tailings line. The crack should be backfilled and the downstream slope flattened to prevent further movement.

M-Dam

- Significant cracking and settlement of the outer portion of the upstream face of the dam has occurred. The upstream slope needs to be flattened so that the cracking does not progress any further.

Dam 3D

- No maintenance is required.

Other Waste Retaining Dams/Dikes

Upper Sewage Retention Dike

- Backfill and/or grade over longitudinal cracks located on both the upstream and downstream edges of the crest (some proximal to tailings line). Flatten slope on the upstream side to prevent further cracking.

Lower Sewage Retention Dike

- No maintenance is required.

Dump Pond #1 (closest to Mill) Retention Dike

- Grade over longitudinal cracks located on the upstream face of the dike.

Dump Pond #2 (closer to TCA) Retention Dike

- Grade over longitudinal cracks on the upstream face of the dike.

All of the noted work is relatively minor but should be undertaken in the near future before snowfall occurs to prevent potential further damage from occurring next Spring.

Respectfully submitted,

BGC Engineering Inc.

per:





James W. Cassie, M.Sc., P.Eng.
Specialist Geotechnical Engineer

APPENDIX 2


THERMISTOR PLOTS FOR VARIOUS DAMS

Long Term Plot for Deep Nodes in D1A-00-01
(Crest of Dam 1A, South End)







Long Term Plot for Deep Nodes in D2-00-2
(Downstream side of crest of Dam 2, north end)





Long Term Plot for Deep Nodes on D2-00-3
(Crest of Dam 2, mid to north end of dam)







Long Term Plot for TD4-2
(Crest of Dam 4, East End, West of TD4-1)






Long Term Plot for TD4-4
(Crest of Dam 4, Far West End)









Trumpet Curve for Thermistor BGC03-03

Dam 6

(Installed May 20, 2003)





APPENDIX 3

DAM INSPECTION FORM



Dam Inspection Form

Date (Yr/Mn/Dy): _____ Inspector: _____

Dam No: _____ Weather: _____

1. Upstream face:

- ☐ Location of water level relative to crest? _____
- ☐ Location of beach (tailings) level relative to crest? _____
- ☐ Any cracks or erosional features? _____
- ☐ Displaced or eroded rip rap? _____
- ☐ Sinkholes or settlement of the slope or nearby beach? _____
- ☐ Water entering into the upstream face? _____

2. Crest (access road):

- ☐ Erosional features? _____
- ☐ Sinkholes, settlement or depressed areas? _____
- ☐ Visible cracks? _____
- ☐ If Yes, note length, width and direction: _____

3. Downstream face and toe area:

- ☐ Cracks or erosional features? _____
- ☐ Bulging or deformation along the slope or the toe? _____
- ☐ Visible seepage? _____
- ☐ If Yes, note location, quantity and if any sediment within the seepage water: _____

4. Any other comments indicating different or atypical conditions?

- ☐ _____

5. Record thermistor (where installed) readings at least monthly on separate recording sheet.

Sketches / Diagrams – provide more detail on any issues noted above