

Photo shows a small pond which is being retained on the upstream side at the south abutment of this dam.



Photo shows two longitudinal cracks at the downstream toe. These cracks may have been due to drying and shrinkage.



Photo shows the upstream side of the crest looking towards the north abutment.



Photo shows another erosional gully at the toe which needs to be repaired.

CLIENT:



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

	-	-	-	-	-
-	-	-	-	-	-
-	-	-	-	-	-
REV.	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED

SCALE:	N/A	
SEPTEMBER 2	005	
DRAWN:	SLF	
DESIGNED:	WC	
CHECKED:	WC	
APPROVED:	WC	

PROJECT ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS						
TITLE						
DAM 6 INSPECTION PHOTOS						
PROJECT No.	FIGURE No.	REV.				
0256-011-01	12	0				



BGC Engineering Inc. AN APPLIED EARTH SCIENCES COMPANY

Calgary Alberta Phone: (403) 250-5185