

February 2nd, 2026

Kyle Amsel
Resource Management Officer
Kivalliq Region, Field Operations Unit
Crown-Indigenous Relations and Northern Affairs Canada
Rankin Inlet, NU
X0C 0G0

Sent via email: kyle.amsel@rcaanc-circnac.gc.ca

Re: Follow-up Report Spill #2026-004 – Release of 80 L of Sewage at the Meliadine Gold Project

On January 8th, 2026, the Nunavut Spill Line was notified by Agnico Eagle personnel via email (spills@gov.nt.ca) of a spill of approximately 80 L of sewage at the Meliadine Gold Mine (spill location coordinates: 63°2'24.42"N, 92°13'42.96"W). This follow-up report provides supplemental information based on the results of the incident assessment and is being provided in accordance with:

- Nunavut Water Board 2AM-MEL1631 Water Licence (the Licence), Part H, Item 8c.

Description of Incident

On January 8th, 2026, at 09:00, approximately 80 L of sewage spilled onto the industrial pad outside the Wing 2 lift station. Upon inspection, it was discovered the lift station pump impeller was obstructed by non-compliant material, which led to the pump's failure and caused the lift station to overflow.

The spill occurred within the site's water management infrastructure, and as such, no waterbodies were impacted by the spill. The closest water body (Lake G2) is approximately 235 meters northwest, as seen in Figure 1.



AGNICO EAGLE
MELIADINE



Figure 1: Location of the spill and proximity to waterbodies.

Response and Remediation

Upon discovering the spill, a vacuum truck and a plumber were dispatched to respond to the spill. The vacuum truck was utilized to empty the contents within the secondary containment. The contaminated material was recovered and transported to Landfarm A in accordance with the Spill Contingency Plan.



Root Cause and Corrective Measures

An assessment was conducted soon after the incident to determine the root cause and contributing factors. The assessment concluded with the following:

- Non-compliant material was flushed down a toilet in Wing 2. This resulted in the pump's impeller being obstructed and clogged, which led to the pump's failure and the lift station overflow.

The following corrective and preventative actions have been implemented to address the root cause and to reduce the likelihood of recurrence.

- A verification was done to ensure that the instructional signs for non-compliant material were posted in every bathroom in wing 2.
- A Meliadine Minute regarding what cannot be flushed down the toilet was distributed to the entire site.

Should you have any questions or require further information, please do not hesitate to contact the undersigned.



Randy Schwandt | Supervisor, Environment
randy.schwandt@agnicoeagle.com | Direct 819.759.3555 x4603996 |
Agnico Eagle Mines Limited - Meliadine Mine, Suite 879 - Rankin Inlet, Nunavut,
Canada X0C 0G0
agnicoeagle.com



Appendix A – Photos



AGNICO EAGLE
MELIADINE



Photo 1: Spill location



AGNICO EAGLE
MELIADINE



Photo 2: Spill location post remediation