

Jonathan Mesher
Water Resources Officer, CIRNAC
Nunavut District, Nunavut Region
P.O. Box 100
Iqaluit, NU X0A 0H0

RE: Water Licence 2AM-MRY1325 September 2021 Inspection – Follow Up

The following submission from Baffinland Iron Mines Corporation (Baffinland) is a follow up in response to the Water Licence Inspection¹ conducted on September 16-17, 2021, at Baffinland's Mary River Project (the Project) by Crown-Indigenous Relations Northern Affairs Canada (CIRNAC) Water Resource Officer. The attached Table 1 provides a summary of the Inspector's key observations and concerns. Baffinland has detailed responses to these items in Table 1.

Should you have any additional concerns or questions regarding the attached responses, please do not hesitate to contact the undersigned at your convenience.

Regards,

A handwritten signature in black ink, appearing to read "K. Button".

Kendra Button
Environmental Superintendent

Cc: Francois Gaudreau, Martin Beausejour, Megan Lord-Hoyle, Lou Kamermans, Tim Sewell, Connor Devereaux (Baffinland)

Attachments

Attachment 1 - 2021-QIK-JKM012 2AM-MRY1325 Inspection Report

Attachment 2 - Table 1: Baffinland Responses to CIRNAC 2021 September Inspection Report

Attachment 3 - Photos

¹ CIRNAC (2021) Re: 2021-QIK-JKM012 2AM-MRY1325 Inspection Report - CIRNAC Baffinland Iron Mines Water Licence Inspection Form. Inspection form dated October 18, 2021.

Attachment 1

2021-QIK-JKM012 2AM-MRY1325 Inspection Report

WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Baffinland Iron Mines	Connor Devereaux
Licence No. / Expiry	Representative's Title
2AM-MRY	Environmental superintendent
Land / Other Authorizations	Land / Other Authorizations
	--
Date of Inspection	Inspector
September 16-17, 2021	Jonathan MESHER
Activities Inspected	
<div><div><input type="checkbox"/> Camp</div><div><input checked="" type="checkbox"/> Roads/Hauling</div><div><input type="checkbox"/> Drilling</div><div><input type="checkbox"/> Other:</div><div><input checked="" type="checkbox"/> Mining</div><div><input type="checkbox"/> Construction</div><div><input type="checkbox"/> Other:</div><div><input type="checkbox"/> Reclamation</div><div><input type="checkbox"/> Fuel Storage</div></div>	

Conditions: **A - Acceptable** **C - Concern** **U - Unacceptable** **NA – Not Applicable** **NI – Not Inspected**

Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	NA		Water Management Structures	NA		Storage	NA	
Flow Measure. Device	NA		Culverts / Bridges	NA		Spills	NA	
Source:	NA		Drainage	NA		Spill Plan	NI	
Water Use:	NA		Erosion / Sediment	NA				
Recirculation (y /n)	NA		Mitigation Measures	A		Administrative		
			Reclamation Activities	NA		Records	NI	
			Materials Storage	NA		Reports	NI	
Waste Disposal			Signage			Plans	NI	
Waste Water	NA					Notifications	A	
Solid Waste	NA		Monitoring			Other		
Hazardous Waste	NA		Sample Collection / Analysis	A		Follow-up from previous inspection	NI	
*The number in the comments field will correspond with specific comments provided below.								
Samples taken by Inspector:			Location(s):					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No								

SECTION 1 ☒ Comments ☐ Non-Compliance with Act or Licence ☐ Action Required

Background

On September 16-17, 2021 I Jonathan Mesher Resource Management Officer of CIRNAC conducted a Water licence inspection at the Mary River Project, Tote Road and Milne port site.

Inspection

A) Tote Road;

1-60 Crown Land- multiple spills of unknown substance(potentially motor oil) on the ground near the parking area. See photo 3 for the spills.

1-154A/ Spill 21247- there was visible erosion on the road near the culvert, upstream of the culvert and down stream of the culvert. See photos 4 &5 for erosion.

1-115/ spill 21247- no concerns near the culvert.

1-112/spill 21247- potentially non-engineered ditches upstream of the culvert could be causing increased TSS. See Photo # 1 for the mentioned ditches.

1-093/spill 21247- potentially non-engineered ditches upstream of the culvert could be causing increased TSS. See photo 6 for the potentially non-engineered ditches. See photo 7 for the potentially, non-engineered ditches.

1-24/spill 21247- significant erosion on both sides of culvert. See photos 8-9 for the erosion.

1-001/spill 21247- damaged culvert and erosion on down stream side of culvert. See photo 10 for the photos of the

naged culvert.

B) Milne Inlet

- 1)MP-05- The inspector noted rips on the liner at the inflow after the culvert, the pond appeared to be appropriately pumped down. See photo 11 for pictures of the rips.
- 2)MP-06- There was erosion noted on the East inflow of the pond, the pond appeared appropriately pumped down. See photo 12 for the erosion noted.
- 3)Pond 3- Pond 3 is unable to passively drain into MP-06 and the ditch connecting the two ponds is leaking. The surface water on the South West side of the ore pad is unable to drain into Pond 3. See photo 13 for a picture of the hoses used to pump the water from pond 3 into mp-06 and the area leaking.
- 4)Snow dumps- The snow dumps appear to be contaminated with litter scooped up during the winter season. see photos 14 and 15 for waste in the snow dumps.
- 5) HWB 03 and 04- the is no defined berm where waste is being stored it appears if a spill did occur the waste would flow outside of this facility. See photo 16 for a picture of this facility.
- 6)western globe fuel module- there is no visible berm, this pumping station does not appear to be properly contained, if a spill was or occur or if rain was to pool and become contaminated it appears to be able to flow outside of containment. See photo 17 for the lack of defined berms.

C) Mine site

- 1) The inspector noted erosion North of the camp lake intake, is appears surface water from the runway and surrounding area has no water management structure to manage it. This surface water has previously caused erosion near the camp lake tributary and now is eroding the sandy hills north of the water intake. See photo 18 and 19 for pictures of this erosion.
- 2) Aircraft Fuel berm- The inspector noted erosion on the outside of this berm. See photo 20 for the erosion noted.
- 3) Landfill- While inspecting the landfill the following items were noted; food waste, fuel filters two generators, break fluid and a automotive fuel tank. See photo 21 for a photo of some of the items mentioned.
- 4) Mine site snow dump- the mine site snow dump also has significant waste. See photo 22 for the waste in the snow dump
- 5) Waste Rock Stockpile pond- this waste rock stockpile and the surrounding area was snow covered at the time of the inspection making it difficult to identify any concerns, no concerns were noted.
- 6) MS-07/spill 21268- This facility is currently dealing with a seepage issue potentially due to gradient of the ditch and the type of fill used. See Photo 23 for the ditch with the unresolved seepage.
- 7) Crusher Pad and pond- The Crusher pad is currently dealing with a unresolved seepage as well, the ditch that is designed to divert surface water to the containment pond is not operational due to a leak. The licensee currently has a sump installed and is pumping water from the sump into the containment pond. See photo 24 for a photo of the sump and berms installed to keep the surface water out o the ditches.
- 8) Km 104 laydown- during the inspection the inspector noted the following concerns at the 104 laydown;
 - Lubricants and hazardous material outside of containment, in damaged containment and staining which smelled strongly of fuel. See photo 25 for the area with staining and hazardous material outside of containment.
 - Open containers with dirty absorbent rags nearing capacity, see photo 26 and 27 for the containers.
 - Heavy equipment actively leaking on the ground with no drip tray, see photos 28 and 29 for photos of fluid under heavy equipment at laydown 104.

Section 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
The licensee is to provide a plan to with the following concerns by November 25, 2021.			
1) The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2. The following items in Part C of the license 2AM-MRY1325 require the licensee to prevent erosion and maintain erosion control measures;			
7 . The Licensee shall not cause erosion to the banks of any body of water and shall provide necessary controls to prevent such erosion.			

8. The Licensee shall implement sediment and erosion control measures prior to and maintain such measures during the undertaking to prevent entry of sediment into Water.
- 2) The licensee is to ensure the following waste/water management structures are operating as intended and consistent with the design in the plans approved by the Nunavut Water Board ; Ore stockpile ditches and gradient, Crusher pad ditches, MP-07 ditches, Western Globe Fuel Module, HWB 03, HWB 04.
- 3) The licensee is to remove all waste from the snow dumps and provide a monitoring schedule to ensure the snow dumps are not contaminating the surrounding water bodies.
- 4) The licensee is to remediate all spills noted in this report.


Inspector's Name	
Jonathan MESHER	
Signature	
Date	
October 18, 2020	

Water Resource Officer, Nunavut Region
Crown Indigenous Relations and Northern Affairs Canada – CIRNAC
Jonathan.mesher@canada.ca
Office #: 867-975-4296
Fax: 867 979-6445


Date	Camera	Inspector	Authorization
	Sony Cyber-shot	J.Mesher	2AM-MRY


Photo Log


Photo 1





Description: damaged drip tray at km 97

Date	Camera	Inspector	Authorization
	Sony Cyber-shot	J.Mesher	2AM-MRY
Photo Log			
Photo 2			
			
Description: damaged drip tray at km 97			

Date	Camera	Inspector	Authorization
	Sony Cyber-shot	J.Mesher	2AM-MRY
Photo Log			
Photo 3			
			
Description: km 60 spill.			

Date	Camera	Inspector	Authorization
	Sony Cyber-shot	J.Mesher	2AM-MRY
Photo Log			
Photo 4			
			
Description: Cv-154 erosion upstream			

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY
Photo Log			
Photo 5			
			
Description: Cv-154 erosion down stream.			

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY
Photo Log			
Photo 6			
			
Description: Cv-112, potential cause of TSS.			

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY
Photo Log			
Photo 7			
			
Description: Cv-093, potential cause of TSS.			

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 8



Description: BG-24, erosion on down stream side of culvert/ damaged culvert.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 9



Description: BG-24, erosion on down stream side of culvert/ damaged culvert.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log

Photo 10



Description: Cv-001 damaged culvert.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log

Photo 11



Description: damaged liner at MP-05

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 12



Description: erosion on the East inflow of MP-06

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 13



Description: hoses required for pumping and leaking area of the ditch.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 14



Description: current snow dump containing waste.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 15



Description: previous snow dump still containing plastic, metal and wood waste

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 16



Description: standing outside the HWB’s looking in, you can clearly see there is no defined berm.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 17



Description: lack of defined berms at fuel module.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 18



Description: Erosion near water intake, standing on runway perimeter road looking towards camp lake.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 19



Description: Erosion near water intake, standing near intake looing at the hillside.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 20



Description: Erosion on outside of aircraft fuel berm.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 21



Description: Erosion near water intake, standing on runway perimeter road looking towards camp lake.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 22



Description: Mine site snow dump.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 23



Description: MS-07 ditch with ongoing seepage issue.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log

Photo 24



Description: Berm and sump installed.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log

Photo 25



Description: hazardous material outside of containment, in damaged containment and staining in the area.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log

Photo 26



Description: dirty spill rags and unknown waste in open container outside of containment

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log

Photo 27



Description: dirty spill rags and unknown waste in open container outside of containment

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 28



Description: fluid leaking from heavy equipment.

Date	Camera	Inspector	Authorization
September,16-17 2021			
	Sony Cyber-shot	J.Mesher	2AM-MRY

Photo Log
Photo 29



Description: fluid leaking from heavy equipment.

Attachment 2

Baffinland Response to CIRNAC 2021 September Inspection Report

Table 1 – Baffinland Responses to CIRNAC 2021 September Inspection Report

Number	Project Location	Description of Concern or Finding	Response
A) Tote Road			
1)	KM-60 Crown Land	Multiple spills of unknown substance (potentially motor oil) on the ground near the parking area. See photo 3 for the spills. The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2. The licensee is to remediate all spills noted in this report.	The KM60 Laydown is regularly inspected for surficial staining, and follow-up inspections since the September Water License inspection have confirmed no further staining has been present and no vehicles or stationary equipment were found to be leaking. Surficial staining that is observed on the laydown is cleaned up and placed in appropriate secondary containment. Photo 1 in Attachment 2 show the current status of the KM60 Laydown.
2)	CV-154A	Spill 21247 - There was visible erosion on the road near the culvert, upstream of the culvert and down stream of the culvert. See photos 4 & 5 for erosion. The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2. The licensee is to remediate all spills noted in this report.	Following the elevated TSS conditions at CV-154A on June 1, 2021, an assessment was completed to identify potential erosion and sediment control measures around the culvert crossing. During July 2021, check dams were constructed within the ditch and armouring of the ditch upstream of the culvert inlet was completed. Photo 2 in Attachment 2 shows the completed check dams. Additional work will be completed at this culvert crossing prior to freshet 2022, including removing excess sediment from the culvert inlet and outlet banks, reshaping and re-armouring of the embankment slopes, and routine maintenance of the check dams.

3)	CV-115	Spill 21247- No concerns near the culvert. The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2. The licensee is to remediate all spills noted in this report.	Following the elevated TSS conditions at CV-115 on June 1, 2021, temporary ESC measures were installed and an assessment was completed to identify erosion and sediment control measures around the culvert crossing. During the summer 2021, rip rap was placed at the inlet and outlet of the culvert crossing embankments in accordance with the Surface Water Aquatic Effects Management Plan (SWAEMP). Photo 3 in Attachment 2 shows the rip rap placed at the outlet of the culvert crossing. Additional work will be completed at this culvert crossing prior to freshet 2022, including removing excess sediment from the culvert inlet and outlet banks, extending the culvert inlet/outlet, reshaping and re-armouring of the roadway embankment slope, and sediment clean out and armouring of the ditch draining to the culvert inlet.
4)	CV-112	Spill 21247- Potentially non-engineered ditches upstream of the culvert could be causing increased TSS. See Photo # 6 for the mentioned ditches. The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2. The licensee is to remediate all spills noted in this report.	Following the elevated TSS conditions at CV-112 on June 1, 2021, temporary ESC measures were installed and an assessment was completed to identify erosion and sediment control measures around the culvert crossing. Prior to freshet 2022, excess sediment will be removed from the culvert inlet and outlet banks, embankments will be reshaped and re-armoured, and the ditch on the inlet side will be cleaned out of sediment and armoured as per the approved Civil Design Criteria for the Project.
5)	CV-093	Spill 21247- Potentially non-engineered ditches upstream of the culvert could be causing increased TSS. See photo of potentially non-engineered ditches. See photo 7 for the potentially, non-engineered ditches. The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2. The licensee is to remediate all spills noted in this report.	Following the elevated TSS conditions at CV-093 on June 9, 2021, temporary ESC measures were installed and an assessment was completed to identify erosion and sediment control measures around the culvert crossing. During the summer 2021, rip rap was placed at the inlet and outlet of the culvert crossing embankments in accordance with the SWAEMP. Photo 4 in Attachment 2 shows the rip rap placed at the inlet of the culvert crossing. Additional work will be completed at this culvert crossing prior to freshet 2022, including the excavation of sediment build up from the ditch draining to the culvert inlet, and reshaping and armouring of the ditch as per the approved Civil Design Criteria for the Project.

6)	BG-24	Spill 21247- Significant erosion on both sides of culvert. See photos 8-9 for the erosion. The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2. The licensee is to remediate all spills noted in this report.	Following the elevated TSS conditions at BG-24 on June 8, 2021, an assessment was completed to identify erosion and sediment control measures around the culvert crossing. Prior to freshet 2022, excess sediment will be removed from the culvert inlet and outlet banks, culvert extensions will be installed and road embankments will be re-armoured.
7)	CV-001	Spill 21247- Damaged culvert and erosion on down stream side of culvert. See photo 10 for the photos of the damaged culvert. The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2. The licensee is to remediate all spills noted in this report.	Following the elevated TSS conditions at CV-112 on June 1, 2021, an assessment was completed to identify erosion and sediment control measures around the culvert crossing. Prior to freshet 2022, excess sediment will be removed from the culvert inlet and outlet banks, culvert extensions installed to repair the damaged end, and road embankments will be re-armoured.
	KM97	Damaged drip trays were identified in CIRNAC inspection report supporting Photo 1 and Photo 2 beneath fuel drums at KM97.	The fuel drums at KM97 were removed from the area and placed in appropriate secondary containment. Photo 5 in Attachment 2 shows the area at KM97 with the fuel drums and damaged spill trays removed.
B) Milne Port			
1)	MP-05	The inspector noted rips on the liner at the inflow after the culvert, the pond appeared to be appropriately pumped down. See photo 11 for pictures of the rips.	Surface Water Management Pond MP-05 and associated ditches are routinely inspected as per Baffinland's Type A Water License. A geotechnical inspection of MP-05 was completed in September 2021, and the 2021 Geotechnical Report No. 2 noted that the pond was in excellent condition with stable, well-maintained berms and intact liner. The minor liner damage observed by CIRNAC near the crest of the southern inlet channel to the pond was also identified during the September geotechnical inspection. Baffinland is assessing suitable controls to prevent this liner damage, and will repair the minor rips identified above the water line during Q2 2022.

2)	MP-06	There was erosion noted on the East inflow of the pond, the pond appeared appropriately pumped down. See photo 12 for the erosion noted.	Surface Water Management Pond MP-06 and associated ditches are routinely inspected as per Baffinland's Type A Water License. A geotechnical inspection of MP-06 was completed in September 2021, and the 2021 Geotechnical Report No. 2 noted that the pond was in excellent condition with stable, well-maintained berms and intact liner. To prevent the erosion observed during the September Water Licence inspection, a berm will be constructed to ensure runoff from the Ore pad enters the appropriate ditches for conveyance to MP-06. Baffinland will conduct routine monitoring and maintenance activities prior to Freshet 2022, which includes the regrading and stabilization of berm slopes and crests, and ensuring runoff from the ore pad enters the appropriate ditches.
3)	Pond 3	Pond 3 is unable to passively drain into MP-06 and the ditch connecting the two ponds is leaking. The surface water on the South West side of the ore pad is unable to drain into Pond 3. See photo 13 for a picture of the hoses used to pump the water from pond 3 into mp-06 and the area leaking. The licensee is to ensure the following waste/water management structures are operating as intended and consistent with the design in the plans approved by the Nunavut Water Board; Ore stockpile ditches and gradient, Crusher pad ditches, MP-07 ditches, Western Globe Fuel Module, HWB 03, HWB 04.	The west ore pad ditch normally collected a low volume of runoff water from the ore pad intermittently, however, a temporary diversion berm was constructed to prevent this runoff from reporting to the ditch until the ditch is repaired. In the interim, ore pad runoff water is being redirected to the surface water management ponds. The temporary diversion berm is inspected on a regular basis and is functioning as intended and diverting water away from the affected ditch and to the surface water management ponds. Pond 3 water is pumped directly into MP-06 whenever necessary. Corrective actions to address the seepage are under investigation and runoff water from the ore pad will continue to be diverted to the surface water management ponds via the interim measures until permanent corrective actions are identified and implemented.

4)	Snow Dumps	<p>The snow dumps appear to be contaminated with litter scooped up during the winter season. See photos 14 and 15 for waste in the snow dumps.</p> <p>The licensee is to remove all waste from the snow dumps and provide a monitoring schedule to ensure the snow dumps are not contaminating the surrounding water bodies.</p>	<p>As per Baffinland's Snow Management Plan (SMP), clean up and removal of debris is an ongoing task as snow melts throughout the year and debris surfaces (see Photo 6 in Attachment 2). This remains a priority for Baffinland on an annual basis. Water quality monitoring of snowmelt and surface water runoff is monitored via the Surveillance Network Program (SNP), the Tote Road Monitoring Program (TRMP), and additional monitoring locations to support the SNP and TRMP for areas down gradient of snow stockpile locations. Monitoring results of the SNP, TRMP and temporary freshet monitoring stations are reported annually in the QIA & NWB Annual Report for Operations. Results of the SNP are also reported monthly as required by the Project's Type 'A' Water Licence. Regular inspections of the snow stockpiles are completed as per Baffinland's Snow Management Plan (SMP) and include stockpile assessment for the presence of debris.</p>
5)	HWB 03 and 04	<p>There is no defined berm where waste is being stored it appears as if a spill did occur the waste would flow outside of this facility. See photo 16 for a picture of this facility.</p> <p>The licensee is to ensure the following waste/water management structures are operating as intended and consistent with the design in the plans approved by the Nunavut Water Board; Ore stockpile ditches and gradient, Crusher pad ditches, MP-07 ditches, Western Globe Fuel Module, HWB 03, HWB 04.</p>	<p>Baffinland will regrade the area at the entrance of twin-cell HWB-3/HWB-4 prior to freshet 2022 to re-establish the gradient normally present within the cells. Routine inspections of HWB-3/ HWB-4 are completed regularly as part of the inspections of structures designed to contain, withhold, divert or retain waters or wastes during periods of flow; conducted in accordance with Part E Item 11 of the Water Licence.</p>

6)	Western Globe Fuel Module	<p>There is no visible berm, this pumping station does not appear to be properly contained, if a spill was or occur or if rain was to pool and become contaminated it appears to be able to flow outside of containment. See photo 17 for the lack of defined berms.</p> <p>The licensee is to ensure the following waste/water management structures are operating as intended and consistent with the design in the plans approved by the Nunavut Water Board; Ore stockpile ditches and gradient, Crusher pad ditches, MP-07 ditches, Western Globe Fuel Module, HWB 03, HWB 04.</p>	<p>The Western Global Fuel Module is a lined facility equipped with spill response supplies. There should be a small gravel berm around the fuel module to contain any possible spills, and Baffinland will re-construct this berm by December 31, 2021. Baffinland's Environmental Protection Plan (EPP) outlines additional protection measures for fuel dispensing activities to prevent fuel releases during refueling. These measures include supervision of fuel transfer points at all times during refueling and daily inspections of permanent fuel dispensing facilities. Photo 8 and Photo 9 in Attachment 2 show the condition of the OHT refuelling facility and spill kit.</p>
C) Mine Site			
1)	North of Camp Lake Intake	<p>The inspector noted erosion North of the camp lake intake, it appears surface water from the runway and surrounding area has no water management structure to manage it. This surface water has previously caused erosion near the camp lake tributary and now is eroding the sandy hills north of the water intake. See photo 18 and 19 for pictures of this erosion.</p> <p>The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2.</p>	<p>Baffinland will implement additional erosion and sediment control measures in accordance with the SWAEMP to address the erosion north of the Camp Lake Intake prior to Freshet 2022, which was identified during the September Water Licence inspection. Water management measures for runoff in this area is being addressed as part of the ongoing implementation of Baffinland's Long Term Water Management Plan (LTWMP).</p>

2)	Aircraft Fuel Berm	The inspector noted erosion on the outside of this berm. See photo 20 for the erosion noted. The licensee is to install the appropriate erosion control measures to prevent continued erosion identified in comments A1-A7, C1 and C2.	The Jet A Fuel Tank Berm, located at the aerodrome, is routinely inspected as per Baffinland's Type A Water License. A geotechnical inspection of the facility was completed in September 2021, and the 2021 Geotechnical Report No. 2 noted that the facility is surrounded by a stable perimeter berm and that a second berm, constructed from crushed rock fill, provides additional protection at two (2) sides (Tote Road and airport parking sides) of the facility. Baffinland will conduct routine maintenance activities prior to Freshet 2022 to address the minor berm erosion, including regrading of berm slopes and crests and runoff diversion away from the berm slopes to prevent future erosion.
3)	Landfill	While inspecting the landfill the following items were noted; food waste, fuel filters, two generators, break fluid and an automotive fuel tank. See photo 21 for a photo of some of the items mentioned.	The debris observed during the September Water Licence inspection was removed from the Landfill Facility as shown in Photo 7 and Photo 8 in Attachment 2. Baffinland continues to improve upon housekeeping and debris management, as demonstrated by Photo 9 and Photo 10 in Attachment 2, and is committed to adhering to the current Waste Management Plan. In addition to ongoing employee education, routine inspections of the Landfill Facility are completed with a focus on waste volume, composition and overall conformance to the Project's Waste Sorting Guidelines.
4)	Mine Site Snow Dump	The mine site snow dump also has significant waste. See photo 22 for the waste in the snow dump. The licensee is to remove all waste from the snow dumps and provide a monitoring schedule to ensure the snow dumps are not contaminating the surrounding water bodies.	As per Baffinland's Snow Management Plan (SMP), clean up and removal of debris is an ongoing task as snow melts throughout the year and debris surfaces (see Photo 6 in Attachment 2). Water quality monitoring of snowmelt and surface water runoff is monitored via the Surveillance Network Program (SNP), the Tote Road Monitoring Program (TRMP), and additional monitoring locations to support the SNP and TRMP for areas down gradient of snow stockpile locations. Monitoring results of the SNP, TRMP and temporary freshet monitoring stations are reported annually in the QIA & NWB Annual Report for Operations. Results of the SNP are also reported monthly as required by the Project's Type 'A' Water Licence. Regular inspections of the snow stockpiles are completed as per Baffinland's SMP and include stockpile assessment for the presence of debris.

5)	MS-07	Spill 21268- This facility is currently dealing with a seepage issue potentially due to gradient of the ditch and the type of fill used. See Photo 23 for the ditch with the unresolved seepage. The licensee is to remediate all spills noted in this report.	Interim ground work measures including temporary diversion swales and a sump, constructed in accordance with Baffinland's MDMER Emergency Response Plan, continue to be inspected on a regular basis and are functioning as intended to convey all seepage water into the KM106 Ore Stockpile Facility Pond (MS-07). Baffinland has retained a third party consulting firm to investigate the KM106 diversion berm to determine appropriate corrective actions to ensure the berm functions as per design criteria. All contact water will continue to be captured and conveyed to the surface water management pond via the interim measures until permanent corrective actions are identified and implemented.
6)	Crusher Pad and Pond	The Crusher pad is currently dealing with an unresolved seepage as well, the ditch that is designed to divert surface water to the containment pond is not operational due to a leak. The licensee currently has a sump installed and is pumping water from the sump into the containment pond. See photo 24 for a photo of the sump and berms installed to keep the surface water out of the ditches. The licensee is to ensure the following waste/water management structures are operating as intended and consistent with the design in the plans approved by the Nunavut Water Board; Ore stockpile ditches and gradient, Crusher pad ditches, MP-07 ditches, Western Globe Fuel Module, HWB 03, HWB 04.	Interim contingency measures to manage water at the Crusher Facility which includes a diversion berm and sumps, constructed in accordance with Baffinland's MDMER Emergency Response Plan, continue to be inspected on a regular basis and are functioning as intended to convey all seepage water into Crusher Facility surface water management pond MS-06. MS-06 is routinely inspected as per Baffinland's Type A Water License. A geotechnical inspection of MS-06 was completed in September 2021, and the 2021 Geotechnical Report No. 2 indicated that the liner within the pond and on the upstream slopes of the berm appears to be intact. There was no evidence of seepage from the pond at the time of the inspection. Baffinland continues to implement the Ore Crusher pad Regrading Strategy to prevent the pooling of water on and around the Crusher Facility pad. All contact water will continue to be captured and conveyed to the surface water management pond via the interim measures until permanent corrective actions are identified and implemented. Water management measures for the Crusher Facility are being addressed as part of the ongoing implementation of Baffinland's LTWMP.

7)	KM 104 Laydown	<p>During the inspection the inspector noted the following concerns at the 104 laydown:</p> <ul style="list-style-type: none">• Lubricants and hazardous material outside of containment, in damaged containment and staining which smelled strongly of fuel. See photo 25 for the area with staining and hazardous material outside of containment.• Open containers with dirty absorbent rags nearing capacity, see photo 26 and 27 for the containers.• Heavy equipment actively leaking on the ground with no drip tray, see photos 28 and 29 for photos of fluid under heavy equipment at laydown 104.	<p>Containers that were observed to be located outside of secondary containment are in progress of being removed from the area and placed within appropriate secondary containment. Surficial staining observed beneath heavy equipment at the KM104 Laydown was cleaned up and placed in appropriate secondary containment. Spill trays were subsequently placed underneath dripping equipment and equipment in mid-term and long-term storage, in accordance with the EPP, to provide secondary containment to prevent spills due to product leaks. Photo 11 and Photo 12 in Attachment 2 show examples of these corrective actions. Baffinland is committed to ensuring that spill trays are placed beneath dripping equipment and equipment that is not being used for more than five (5) days, and beneath all stationary equipment that is regularly refueled. Operational areas are inspected for proper use of secondary containment during routine compliance inspections and any issues are addressed as they are identified.</p>
----	----------------	---	---

Attachment 3

Photos



Photo 1 – Current Status of the KM60 Laydown – November 2021



Photo 2 – Check Dams Constructed in Ditch Upstream of Culvert CV-154A – August 2021



Photo 3 – Rip Rap Placed at CV-115 Outlet to Stabilize Embankment – August 2021



Photo 4 – Rip Rap Placed at CV-093 Inlet to Stabilize Embankment – August 2021



Photo 5 – KM97 Following Removal of Fuel Drums –November 2021



Photo 6 – Snow Stockpile Clean Up Activities to Remove Debris – July 2021



Photo 7 – Mine Site Landfill Facility Following Debris Removal – October 2021



Photo 8 – Mine Site Landfill Facility Following Debris Removal – October 2021



Photo 9 – Site Waste Clean Up Activities – July 2021



Photo 10 – Site Waste Clean Up Activities – July 2021



Photo 11 – Spill Trays beneath Heavy Equipment at the KM104 Laydown – September 2021



Photo 12 – Spill Trays beneath Heavy Equipment at the KM104 Laydown – September 2021