



BHM Project No. 15-97

# BAFFINLAND IRON MINES CORPORATION

ANNUAL GEOTECHNICAL INSPECTIONS

MARY RIVER PROJECT

SECOND INSPECTION OF TWO

September 2015



## Prepared for:

Mr. Jeff Bush

Site Services Superintendent

Baffinland Iron Mines Corporation

2275 Upper Middle Road East, Suite 300

Oakville, Ontario L6H 0C3



***Barry H. Martin, P. Eng., MRAIC, Consulting Engineer and Architect***

1499 Kraft Creek Road

Timmins, Ontario P4N 7C5

Tel: 705-268-5621

[Barrymartin1499@gmail.com](mailto:Barrymartin1499@gmail.com)

# INDEX

## **1.0 INTRODUCTION**

- 1.01 Mary River Site
- 1.02 Milne Inlet Site

## **2.0 METHODOLOGY FOR INSPECTION**

## **3.0 MARY RIVER SITE**

- 3.01 General
- 3.02 Bulk Fuel Storage Facility
- 3.03 Generator Fuel Storage Containment
- 3.04 Polishing/Waste Stabilization Pond #1
- 3.05 Polishing/Waste Stabilization Ponds #2 and #3
- 3.06 Helicopter Fuel Tank Containment
- 3.07 Barrel Fuel Containment (MS-HWB-3 and MS-HWB-4)
- 3.08 Hazardous Waste Storage (MS-HWB-2)
- 3.09 Enviro Tank Storage (MS-HWB-5)
- 3.10 Stove Oil Storage (MS-HWB-1)
- 3.11 Jet Fuel Tank and Pump Containment
- 3.12 Solid Waste Disposal Site
- 3.13 Minesite Steel Fuel Tank Farm Containment
- 3.14 Quarry
- 3.15 Crusher Pad Drainage Containment
- 3.16 Waste Pile Drainage Containment
- 3.17 Jet “A” Fuel Containment
- 3.18 Hazardous Waste Containment (MS-HWB-6)
- 3.19 Overview

Mary River Photos  
Mary River Drawing

## **4.0 MILNE INLET**

- 4.01 General
- 4.02 Hazardous Waste Storage (WP-HWB-3, and MP-HWB-4, and MP-HWB-5)
- 4.03 Fuel Tank Farm
- 4.04 New Sewage Effluent Pond (PWSP)
- 4.05 Landfarm Containment
- 4.06 Contaminated Snow Containment
- 4.07 Sediment Pond East
- 4.08 Sediment Pond West
- 4.09 Quarry
- 4.10 Loading Area Contaminated Storage (MP-HWB-1)
- 4.11 Fuelling Facility Containment
- 4.12 Overview

Milne Inlet Photos  
Milne Inlet Drawing

September 30, 2015

Baffinland Iron Mines Corporation  
2275 Upper Middle Road East, Suite 300  
Oakville, Ontario  
L6H 0C3

Attention: Jeff Bush  
[jeff.bush@baffinland.com](mailto:jeff.bush@baffinland.com)

**RE: ANNUAL GEOTECHNICAL INSPECTIONS  
BAFFINLAND IRON MINES CORPORATION  
OUR REFERENCE NO. 15-097**

## **1.0 INTRODUCTION**

Barry H. Martin, P. Eng., Consulting Engineer, completed the eighth annual water licence geotechnical inspection of the following on-site engineered facilities as required by Licence No. 2AM-MRY 1325 of the Nunavut Water Board:

Pit Walls  
Quarries  
Landfills  
Land Farms  
Bulk Fuel Storage Facilities  
Sediment Ponds  
Collection Ponds  
Polishing and Waste Stabilization Ponds

The inspection that took place September 25<sup>th</sup> to September 29<sup>th</sup> is the second phase of a biannual inspection to be carried out within the open water shipping season at the two Baffinland sites, in Mary River at the mine site, and at Milne Inlet at the port facility.

The inspections were carried out in accordance with the guidelines set out in "Dam Safety Guidelines 2007" as published by the Canadian Dam Association.

The inspections were completed by Mr. Barry H. Martin, P. Eng., the design Engineer for the initial containment facilities both at Mary River and Milne Inlet, the runway extension, initial bridges on the connecting road, the solid waste disposal site as well as continuing construction of select mine infrastructure.

The seven previous annual water licences geotechnical inspections were completed by Mr. Martin. You shall note that Hazardous Waste Containment Structures have been assigned new designations in the report as compared to previous years.

The facilities inspected are as per the following:

### **Mary River Site**

Bulk Fuel Storage Containment  
Generator Fuel Storage Facility Containment  
Polishing/Waste Stabilization Pond No. 1  
Polishing/Waste Stabilization Ponds Nos. 2 and 3 (constructed as a two-cell structure)  
Helicopter Fuel Cell Containment  
Barrel Fuel Containment (constructed as a two-cell structure)(MS-HWB-3 and MS-HWB-4)  
Hazardous Waste Storage (MS-HWB-2)  
Enviro-Tank Storage (constructed contiguous with hazardous waste storage and stove oil storage) (MS-HWB-1)  
Stove Oil Storage (MS-HWB-5)  
Jet Fuel Tank and Pump Containment  
Solid Waste Disposal Site  
Minesite Steel Fuel Tank Farm Containment  
Quarry  
Crusher Pad Drainage Containment  
Waste Pile Drainage Containment  
Jet "A" Aircraft Containment  
Hazardous Waste Containment (MS-HWB-6)

A site plan for the Mary River site showing most structures reviewed is attached.

### **Milne Inlet Site**

Hazardous Waste Storage (constructed as a two-cell structure) (MP-HWB-3, and MP-HWB-4,)  
Fuel Tank Farm  
New Sewage Effluent Pond (PWSP)  
Land Farm  
Contaminated Snow Containment  
Sediment Ponds East and West  
Quarry  
Loading Area Contaminated Storage (MP-HWB-1)  
Fuelling Facility Containment

A site plan for the Milne Inlet site showing most structures reviewed is attached.

## **2.0 METHODOLOGY FOR INSPECTION**

The geotechnical inspector was Barry H. Martin, P. Eng., who also reviewed the two sites for the first of the biannual inspections on July 30<sup>th</sup>, 2015 to August 3<sup>rd</sup>, 2015 just as the annual shipping season commenced with the arrival of the first ship into port. This inspection was planned to take place at the end of the shipping season.

The inspections primarily focused on the following aspects:

1. The structures were inspected for conformance with the design basis as presented in “as constructed” and “as-built” drawings (provided in the first and subsequent reports).
2. The structures were specifically inspected for settlement, cracking, and seepage through the berms.
3. The areas around the structures were examined for evidence of seepage.
4. Quarry walls were reviewed for relative stability. I note that the quarries are active removal areas and long term stability was not yet established.
5. New structures under construction were reviewed for conformity with design drawings.
6. Photographs were taken to document observations made during the inspection and are attached.

## **3.0 MARY RIVER CAMP**

### **3.01 General**

As with other years, there had been some rainfall at Mary River preceding the second inspection and it was expected that there would be some water in the containment dykes.

A monitoring program is in place to test storm water that does accumulate within the containment structures. As reviewed, the water that does not meet the water licence effluent requirements is treated on site prior to release.

At the Bulk Fuel Storage Facility Containment, the water that collects within the dyke is treated at the end of the containment structure.

We report on the new Jet “A” Fuelling Containment Structure and Hazardous Waste Containment for the first time.

As with the August report of this year there are new code names assigned to hazardous waste structures.

The Bulk Fuel Storage Containment (Exploration Phase Bladder Farm) is coming due for decommissioning and is currently used to store barrels of fuel, lubricant cubes, and a large fuel tank at this time.

### **3.02 Bulk Fuel Storage Facility (Exploration Phase Bladder Farm)**

#### **General Conditions**

The Bulk Fuel Storage Facility still exists but it is no longer utilized as a bulk fuel storage facility. There are a number of full fuel barrels and lubricant cubes now stored within the berms, as well as a large fuel tank.

The granular cover over the geotextile and liner is still in place within the containment structure awaiting land farming and a fair amount of water at one end awaiting treatment.

## **Stability**

At the time of this initial review, water had not been removed for a period from within the containment and water was ponding above the level of the gravel within the bottom of the containment at the north of the facility.

At the load-out end of the facility there was water ponding within the dykes.

The soil structure is considered stable in the present condition and is in conformance with the design basis for the facility.

The presence of water within the structure and at the load-out area is an indication of the integrity of the liner.

## **Recommendations**

We have no recommendations with respect to this containment structure as it awaits decommissioning.

### **3.03 Generator Fuel Storage Containment (Exploration Phase)**

This particular containment structure is currently being decommissioned. The fuel bladder that was contained within the dyke has been removed.

The granular fill over the geotextile and liner shall require landfarming with the material from the bulk fuel storage facility.

There is no indication that the liner is compromised and decommissioning should proceed when the granular cover is either moved to a land farm or other containment. There is water ponding within the structure.

### **3.04 Polishing/Waste Stabilization Pond #1**

#### **General Conditions**

PWSP No. 1 continues to be utilized as a holding facility for sewage plant effluent that does not meet water effluent quality criteria.

Currently the pond is being used primarily as a repository for off spec sewage and sewage sludge forming in lift stations.

The supernatant from PWSP No. 1 is periodically decanted to PWSPs Nos. 2 and 3 where it is tested and treated as required to meet Water Licence effluent requirements.

At the time of our visit there was approximately fifty percent of capacity to accommodate further sewage and the structure readily conforms to its design intent.

## **Stability**

Our review of this area around the pond at the base of the slopes showed no sign of seepage and hence we conclude that the liner has been effective in containing sewage and there are no tears or ruptures in

the membrane, excepting some minor tears from past activity at the top of the dyke well above the allowable effluent level in the structure in the horizontal portion of the membrane.

A review of the top of the dyke showed no indication of cracking or settlement which would indicate stresses within the structure.

Many of the tears that had occurred in the liner on the top of the dyke have been patched during the period between reviews in 2008 and 2009 and are holding well. As well, there are no signs of weather related deterioration of the liner where it is exposed.

There appears to be no sign of erosion of the dykes, even with the precipitation that has occurred over the lifetime of the facility.

The minor settlements have had little effect on the integrity of the structure.

## **Recommendations**

We have no recommendations with respect to this containment facility.

### **3.05 Polishing Ponds/Waste Stabilization Ponds #2 and #3**

#### **General Conditions**

The structure was designed and constructed as a two-cell structure.

The supernatant from PWSP #1 is currently discharged to PWSPs Nos. 2 and 3. The treated effluent is tested for Water Licence effluent requirements, treated if necessary, and discharged to the environment.

At the time of our visit there was considerable freeboard to accommodate further sewage and the structure readily conforms to its design intent. There was fifty-percent remaining capacity in one cell and the second cell was almost empty at the time of our inspection.

#### **Stability**

Our review of the area around the pond at the base of the slopes showed no sign of seepage and hence we conclude that the liner has been effective in containing the sewage and there are no tears or ruptures in the membrane.

Longitudinal cracking which appeared in the dykes of PWSP #3 due to the melt of permafrost wedges in 2009 has not reoccurred and we consider this structure to be stable in its present condition.

Monitoring points have been set upon the top of the dyke and have been monitored since 2009. Settlements have occurred since that time. These settlements have not led to any stress cracks in the structure. Monitoring was discontinued last year.

There appears to be no sign of erosion of the dykes and plants are continuing to seed themselves on the dykes. This growth is minimal, however.

There are three small bubbles formed by air trapped under the enviroliner that were present in the first review that are probably the result of wrinkles in the liner that should disappear if further liquid is added to the cell.

## **Recommendations**

We have no recommendations with respect to this containment facility.

### **3.06 Helicopter Fuel Tank Containment**

#### **General Conditions**

The structure was designed and constructed as a single cell structure that contains a 1000 gal fuel storage tank.

The structure currently conforms to its design intent.

In the past, a liner clad wood curb had been added to the top of the berm to prevent the erosion of gravel off the berm, caused by pulling the fuel hose from within the dyke out to the helicopters to provide them with fuel.

#### **Stability**

Our review of the area around the pond at the base of the slopes showed no sign of seepage. There is water in the bottom of the containment indicating the integrity of the liner.

A review of the exterior and the top of the berms showed no sign of cracking or settlement which would indicate stress within the structure.

The structure is considered to be stable in its present condition.

## **Recommendations**

We have no recommendations with respect to this structure.

### **3.07 Barrel Fuel Containment (Now MS-HWB-3 and MS-HWB-4)**

#### **General Conditions**

This particular structure which we called “Barrel Fuel Containment” in our previous inspection reports is a two-cell structure which is currently used to accommodate cubes of lubricant and barrels in the east cell and cubes of lubricant and antifreeze in the west cell.

#### **Stability**

Our review of the area around this containment structure showed no sign of seepage. This shows that there is reasonably little chance of tearing or rupture of the membrane having taken place.

A review of the exterior and top of the dyke showed no sign of cracking or settlement which would indicate stresses within the structure.

The structure is considered to be stable in its present condition.



## **Recommendations**

We have no recommendations at this time.

### **3.08 Hazardous Waste Storage (Now MS-HWB-2)**

#### **General Conditions**

This particular cell was constructed contiguous with an existing cell, which is referred to on site as the “Enviro Tank Storage”, from drawings by our office in 2010 and conforms to our drawings. It is also contiguous with the Stove Oil Storage cell.

This structure contains barrels and bags of hazardous waste.

#### **Stability**

Our review of the area around this cell at the base of the slopes, showed no sign of seepage. There is water ponding in this structure.

The structure appears to be stable in its present condition. The water confirms the integrity of the liner.

#### **Recommendations**

There are no recommendations at this time.

### **3.09 Enviro Tank Storage (Now MS-HWB-1)**

#### **General Conditions**

This particular structure is constructed contiguous with the Hazardous Waste Storage constructed in 2010 and the Stove Oil Storage cell. It was utilized as a wash down cell during the last season. It is currently in use storing cubes of lubricant and barrels.

#### **Stability**

Last year there was concern for the integrity of this cell as the cell was dry and the geotextile was exposed from heavy traffic during our initial inspection. During our second inspection, the cell was holding a small amount of water confirming limited integrity of the liner.

The cell is dry this year at both of the 2015 inspections raising concerns anew on the integrity of the liner.

#### **Recommendations**

We recommend that the geotextile over the liner be checked and the granular cover be made good prior to continuing use of this cell

### **3.10 Stove Oil Storage (Now MS-HWB-5)**

#### **General Conditions**

This particular structure had been used to store barrels of stove fuel in 2011.

The structure again contains barrels of stove oil and some Jet "A" fuel.

This structure was constructed in accordance with a standardized drawing provided by this office utilizing a one piece liner.

### **Stability**

Our review of the exterior at the base of the dyke showed no sign of seepage. This shows that there is reasonably little chance of tearing or rupture of the membrane having taken place.

A review of the exterior and the top of the dyke showed no sign of cracking or settlement which would indicate stresses with the structure.

There is water contained within the cell confirming the integrity of the liner.

The structure is considered to be stable in its present condition.

## **3.11 Jet Fuel Tank and Pump Containment**

### **General Conditions**

This particular structure was reconstructed based on our recommendation of the 2012 Geotechnical Inspection.

The construction was completed in accordance with our recommendations for such structures and the liner was constructed as a one piece liner with geotextile protection on both sides and gravel over the geotextile as protection.

The construction appears proper and the structure is in good condition.

Minor water ponding confirms the integrity of the liner.

At this time as in our earlier inspection report this year, the jet fuel tank and pump have been removed and the cell is empty.

### **Stability**

Our review of the area around the cell at the base of the slopes showed no sign of seepage and water is ponding within the cell.

.

The structure is stable in its present condition.

### **Recommendations**

There are no recommendations at this time.

## **3.12 Solid Waste Disposal Site**

Berms appear stable and no erosion appears to have taken place on the back and both sides of the site. Solid waste was being placed at the front edge of the site and was awaiting salvage of wood and lumber

prior to the placing of cover at the time of our site review. There is also separation of metals taking place.

The disposal was being conducted in conformity with plans prepared and applicable guidelines and operating plans set out for the disposal of solid waste.

The current footprint as established by the existing covered material and the “blow control” fence at the front of the immediate site has now reached capacity. It is our understanding that the footprint of the facility and blow fence shall be expanded in the near future in accordance with plans and guidelines set out for this solid waste disposal site.

### **3.13 Minesite Steel Fuel Tank Farm Containment**

#### **General Conditions**

All work appears to be complete excepting the installation of the sump pits that are on site awaiting installation and which shall be utilized to facilitate the removal of water that collects from precipitation.

There is water ponding in the bottom of the containment confirming the integrity of the liner. This ponding of water is now well above the cover on the bottom of the containment.

#### **Stability**

All work appears to have been completed in accordance with drawings and we have no concerns with the stability of this containment structure.

#### **Recommendations**

We recommend that at least one sump be installed as per the drawings prepared for this facility and that when weather permits, removal of water within the containment.

### **3.14 Quarry QMR2**

#### **General Conditions**

The quarry has well defined benches. The quarry faces at the benches are clean.

The current work site is undermining the road on the bench above it (see photo). However, it is recognized that the road area referred to is restricted access. The quarry is active, and the area of instability will soon be removed as part of ongoing quarry development.

#### **Stability**

The current work site is undermining road on the bench above it. (see photo)

### **3.15 Crusher Pad Drainage Containment**

#### **General Conditions**

There is a new containment being constructed to catch surface water flow from the crushing area and stockpile area at the minesite.

The ditch at the entry to the recessed inlet on the east and west side of the containment is now complete and the facility has now been completed.

### **Stability**

The structure has been completed in accordance with drawings included in our last report in a most satisfactory manner.

### **Recommendations**

We have no recommendations with respect to this containment structure.

## **3.16 Waste Stockpile Drainage Containment**

### **General Conditions**

This structure was in operation only for one summer as a temporary containment for waste rock runoff. It is our understanding that this structure will no longer be used in 2016 and will be replaced by a more permanent structure before freshet in 2016. The existing structure will be buried within the footprint of the expanding waste rock pile.

This pond is a collection pond wherein the front end of the pond is not lined with an eviroliner and only the end dykes are.

There are swales constructed to contain runoff from the waste pile and conduct it into the settlement pond where it can be tested and released when acceptable quality is found, by pumping it out.

There are other swales constructed to divert normal runoff away from this collection area to prevent it from mixing with the runoff from the waste pile where PAG (possibly acid generating) rock is encapsulated.

As there was snow windswept across this area at the time of our inspection, it was reviewed from aerial photography done prior to the snow.

### **Stability**

The area appears stable at this time.

## **3.17 Jet "A" Fuel Containment**

### **General Conditions**

This cell was constructed to replace the containment structure near the Weatherhaven Camp.

This cell now contains two double walled tanks and is located north of the air terminal buildings.

### **Stability**

The cell was constructed using a one piece enviroliner with geotextile and was constructed in accordance with standardized drawings prepared in the past for such construction by our office.

There is water ponding in the bottom of the cell confirming the integrity of the liner.

There were no signs of cracking of the dykes.

### **Recommendations**

We have no recommendations with respect to this structure.

## **3.18 Hazardous Waste Containment (MS-HW-6)**

### **General Conditions**

Although it was constructed in 2012, we have not reported on it in the past.

It is located near the incinerator and is utilized to store barrels of ash from the incinerator. It is, however, empty at this time.

### **Stability**

The cell was constructed utilizing a one piece enviroliner with geotextile and was constructed in accordance with standardized drawings prepared in the past for such construction by our office.

There is water ponding in the bottom of the cell confirming the integrity of the liner.

There were no signs of cracking of the dykes or seepage around the exterior of the dykes.

### **Recommendations**

We have no recommendations with respect to this structure.

## **3.19 Overview**

This report is the seventh annual Geotechnical Inspection at Mary River and Milne Inlet completed by this author on behalf of Baffinland Iron Mines Corporation and the second year of reporting covering the first of two inspections in one shipping season.

As set out in our past reports, there has been little or no erosion taken place from wind or rain and the dykes constructed of the sand/gravel soil have remained stable at slopes of 3:1 and 4:1.

As noted last year, there are only just now signs of settlement appearing at PSWP's 1, 2 and 3. The settlements are not differential settlements of the dykes but are minor overall settlements of the total structures with respect to the surrounding area.

These settlements appear to be settlements within the one metre  $\pm$  active layer above the permafrost and are of little concern as the PWSP's are temporary structures and the settlements have no effect on the dyke stability.

It is expected that many of the structures that form the basis for the inspections set out in the biannual Geotechnical inspections shall be decommissioned as the mine facilities are finalized.

# MARY RIVER PHOTOS



Generator Fuel Storage Containment



Helicopter Fuel Tank Containment





PWSP #2



PWSP #3



PWSP #1



Bulk Fuel Storage





Barrel Fuel Containment MS-HWB-4



Barrel Fuel Containment MS-HWB-3






Hazardous Waste Containment MS-HWB-2



Enviro Tank Containment MS-HWB-1



Stove Oil Storage MS-HWB-5



Jet "A" Fuel Containment from 2014





Jet "A" Fuelling Containment



Hazardous Waste Containment MS-HWB-6





Edge and Top of Solid Waste Disposal Site



Crusher Pad Drainage Pond and Swale





Mary River Tank Farm Containment



Mary River Quarry Bench Undermining





Waste Rock Containment  
(Verified via Aerial Photography)