



CERTIFICATE OF FINAL INSPECTION AND ACCEPTANCE

PROJECT NAME: Mary River Project "Sedimentation Pond stock pile East"
PROJECT NUMBER: CT000071 DATE: 17 Aug 2014
OWNER: Baffinland Iron Mine Corporation
LOCATION: Norwaut.

SCOPE OF INSTALLATION(S): THE WORK

LP 7 Geotextile underlay 7,500 m²
EL 60 mil Geomembrane 7,333 m² 100% tested "Air test and
Vac Box"

Part 1 – LAYFIELD ENVIRONMENTAL SYSTEMS LTD.

I, Yonatan Espindola, a duly appointed representative of Layfield Environmental Systems Ltd. (LES), have visually observed the installations (as outlined above), and have found the Work to be complete and free of defects and declare that the Work was completed in accordance with the project specifications, Layfield Environmental Systems' QC program and the terms and conditions of the contract.

Layfield Environmental Systems Representative:

Name: Yonatan Espindola
Title: Supervisor
Date: 17/Aug/2014 Signature: Yonatan Espindola

Part 2 – OWNER (or Representative)

I, Marlon Coakley, a duly appointed representative of Glatch
for Baffinland, do hereby take over and accept the installation(s)
described above, and confirm that the work has been completed in accordance with the project specifications and the terms of the conditions of the contract.

I have evaluated and measured the work together with the Layfield Environmental Systems representative, and agree that the measurements shown are both true and correct, and that the installation has met our approval.

Owners Representative:

Name: Marlon Coakley
Title: Construction Manager
Company: Glatch
Date: Aug 18/2014 Signature: Marlon Coakley

Comments: _____

LAYFIELD CANADA LTD.
Unit 2 – 117 Basaltic Road Vaughan, ON Canada

Phone: (905) 761 9123
Fax: (905) 761 -0035
Toll Free: 1 888 436 4273

Web: www.layfieldgroup.com
E-Mail: info@layfieldgroup.com

INSTALLATION WARRANTY

Layfield Reference No. : (Job #) **CT000071**

LAYFIELD CANADA LTD. (LAYFIELD) hereby warrants to Baffinland Iron Mine; (the Customer) that the work performed by LAYFIELD on the Installation described as **H349000/CC004 HDPE Liner Installation**, covering the Anmar Maintenance Pad, Ruskin Shop Pad, Landfarm (FBS 2.1.2), Snow Containment (FBS 2.1.2), Sediment Pond and Sediment Stockpile (FBS 2.1.4), Hazardous Waste Containment Areas North (FBS 2.1.1) and Hazardous Waste Containment South (FBS 2.1.3) will:

1. Meet the field seam specifications set out in the contract between LAYFIELD and the Customer (as amended by LAYFIELD's quotation), all workmanship to meet the requirements of LAYFIELD's Field Installation Quality Assurance program, and be free of defects at the time of completion of the Installation; and
2. Be free of installation defects from the date of the completion of the Installation (August 10, 2014), for a period of two (2) years so long as the completed Installation is used for the purposes and in the manner for which the Installation was designed.

Should damage or defects within the scope of the aforesaid warranties occur, LAYFIELD shall repair the damage or defects, PROVIDED THAT the area to be repaired must first be made ready by the Customer and be in a clean, dry, unencumbered condition, free from all water, soil, sludge, residuals, and liquids of any kind.

To enable LAYFIELD to investigate and determine the cause of any alleged damage or defect, notice and details of any claim hereunder must be presented in writing to LAYFIELD within thirty (30) days after the alleged damage or defect was first noticed or observed. Failure to provide such notice and details shall invalidate all warranties provided hereunder.

The liability of LAYFIELD under the aforesaid warranties are subject to the following conditions:

- a. LAYFIELD's only obligation shall be to repair or replace any defective workmanship and in no event shall LAYFIELD be liable for any amount in excess of the cost of the Installation;
- b. No allowance will be made for repairs, replacements or alterations made by the Customer unless with the prior written consent of LAYFIELD;
- c. The warranties hereunder extend only to the Customer and are not transferable;
- d. The warranties hereunder shall not apply to any damage or defects resulting from misuse, mechanical abuse by machinery, equipment or persons, excessive pressures or stresses, exposure of the completed Installation of harmful chemicals, unusual weather conditions, casualty catastrophe such as (but not limited to) earthquake, flood, hail, tornado, or any other act of God;
- e. Under no circumstances shall LAYFIELD be liable for any special, direct, indirect, or consequential damages including the loss of use of the Installation howsoever caused;
- f. The warranties hereunder are given in lieu of all other warranties, express, implied, statutory, or otherwise, and the Customer expressly waives all other warranties and claims whatsoever except those specifically given herein, and the Customer acknowledges that the warranties hereunder are accepted in preference to and to the exclusion of any or all other warranties; and
- g. An Installation Warranty will not be provided for lining projects unless the installation is completed by LAYFIELD personnel or designated LAYFIELD subcontractors.

LAYFIELD CANADA LTD.


Ryan Parish, Projects & Operations Manager

HATCH		VENDOR DATA REVIEW	
Doc Number	E349000-CC004-02-198-0001-010	Sub	01
Date Received			
Review Grade		Next Submittal Status	
<input type="checkbox"/> C1 – Proceed to next submission & status		<input type="checkbox"/> Internal Review <input type="checkbox"/> Certified Final <input type="checkbox"/> Final <input type="checkbox"/> Not Built	
<input type="checkbox"/> C2 – Proceed with exceptions as noted to next		Next Submittal Date:	
<input type="checkbox"/> C3 – Do not proceed, revise as noted & resubmit			
<input type="checkbox"/> C4 – No further submission required - Cancelled		<input type="checkbox"/> No further submission required - Complete <input type="checkbox"/> No further submission required - Superseded	
Package Coordinator: Name, signature and Date:			
<small>REVIEWED ONLY FOR GENERAL CONFORMITY WITH THE SPECIFICATIONS. ACCEPTANCE BY THE ENGINEER DOES NOT WARRANT OR REPRESENT THAT THE INFORMATION CONTAINED ON THIS DRAWING/DOCUMENT IS EITHER ACCURATE OR COMPLETE. THE SOLE RESPONSIBILITY FOR CORRECT DESIGN, DETAILS & DIMENSIONS SHALL REMAIN WITH THE PARTY SUBMITTING THE DRAWING/DOCUMENT.</small>			

Appendix B

As-Built Drawings

- A. H349000-2345-10-035-0001 Rev02: Milne Port Ore Stockpile Sedimentation Ponds
Earthworks & Drainage – Plan & Sections **[1 page]**



Appendix C

Survey Data

Stockpile Sedimentation Pond No. 1 As Built - 29Oct2014.asc

2001	7976361.	821837	503113.	930202	5.284	ZTOS
2002	7976362.	964593	503112.	688732	5.080	ZTOS
2003	7976369.	605654	503107.	239600	5.045	ZTOS
2004	7976375.	469479	503101.	475576	5.055	ZTOS
2005	7976370.	488117	503095.	387029	4.963	ZTOS
2006	7976367.	838124	503092.	712965	4.716	ZTOS
2007	7976365.	862243	503090.	267970	4.947	ZTOS
2008	7976357.	287503	503079.	628123	4.902	ZTOS
2009	7976348.	497887	503068.	325436	5.012	ZTOS
2010	7976339.	703820	503057.	511062	5.028	ZTOS
2011	7976331.	541651	503047.	486673	5.070	ZTOS
2012	7976323.	944067	503037.	760840	5.011	ZTOS
2013	7976314.	392485	503025.	595596	4.922	ZTOS
2014	7976302.	485594	503033.	935675	4.852	ZTOS
2015	7976294.	552930	503040.	184955	5.020	ZTOS
2016	7976304.	220702	503055.	430969	5.265	ZTOS
2017	7976314.	365353	503067.	633474	5.346	ZTOS
2018	7976325.	304926	503079.	368561	5.267	ZTOS
2019	7976336.	790409	503090.	909747	5.273	ZTOS
2020	7976349.	439483	503103.	095969	5.232	.TOS
2021	7976372.	517998	503094.	828693	4.914	ZTOS
2022	7976379.	436792	503101.	521568	5.037	ZTOS
2023	7976370.	995498	503108.	820032	5.023	ZTOS
2024	7976362.	542470	503117.	306870	5.100	ZTOS
2025	7976347.	460182	503104.	553244	5.311	ZTOS
2026	7976335.	300192	503092.	509945	5.343	ZTOS
2027	7976323.	481966	503080.	941900	5.287	ZTOS
2028	7976312.	794668	503069.	045578	5.341	ZTOS
2029	7976309.	670371	503066.	747765	5.229	ZTOS
2030	7976307.	659538	503066.	556089	5.363	ZTOS
2031	7976305.	813048	503067.	575916	5.317	XTOS
2032	7976304.	236672	503066.	290020	5.379	ZTOS
2033	7976305.	342334	503063.	588146	5.294	ZTOS
2034	7976305.	660449	503061.	126325	5.230	ZTOS
2035	7976303.	279468	503057.	752885	5.341	ZTOS
2036	7976299.	614090	503053.	289254	5.219	ZTOS
2037	7976297.	498939	503053.	686811	5.279	ZTOS
2038	7976294.	899471	503055.	634587	5.341	XTOS
2039	7976294.	063995	503054.	659194	5.340	ZTOS
2040	7976295.	751695	503050.	756966	5.170	ZTOS
2041	7976296.	187850	503048.	287825	5.215	ZTOS
2042	7976293.	546555	503043.	057460	5.281	ZTOS
2043	7976291.	351426	503039.	077257	5.305	ZTOS
2044	7976301.	249378	503032.	160070	4.955	ZTOS
2045	7976314.	710548	503023.	224621	4.937	ZTOS
2046	7976325.	969010	503036.	506266	4.993	ZTOS
2047	7976333.	248297	503046.	210186	4.985	ZTOS
2048	7976341.	761821	503055.	844696	5.032	ZTOS
2049	7976350.	158190	503066.	903241	5.037	ZTOS
2050	7976359.	138871	503078.	289064	4.939	ZTOS
2051	7976366.	192780	503087.	202817	4.877	XTOS
2052	7976378.	295301	503091.	872854	2.663	ZBOS
2053	7976378.	381597	503094.	974873	4.403	ZBOS
2054	7976381.	003816	503097.	146867	2.581	ZBOS
2055	7976384.	157966	503102.	342184	2.418	ZBOS
2056	7976375.	108064	503111.	868278	2.920	ZBOS
2057	7976369.	699428	503115.	785034	3.048	XBOS
2058	7976307.	070479	503065.	014558	5.234	ZDrn
2059	7976305.	214113	503066.	780389	5.221	ZDrn
2060	7976302.	800613	503069.	333211	5.466	ZDrn
2061	7976300.	624182	503070.	792534	5.997	ZDrn
2062	7976299.	893067	503071.	401058	6.175	ZDrn
2063	7976299.	924441	503073.	023663	6.459	ZDrn

Stockpile Sedimentation Pond No. 1 As Built - 29Oct2014.asc

2064	7976300.953720	503074.782529	6.789	ZDrn
2065	7976301.011278	503076.602976	7.127	ZDrn
2066	7976300.374019	503078.207621	7.335	ZDrn
2067	7976299.544107	503079.786552	7.950	XDrn
2068	7976261.223580	503041.163164	7.940	ZDrn
2069	7976265.566691	503042.553957	7.629	ZDrn
2070	7976269.983671	503044.036343	7.448	ZDrn
2071	7976272.920229	503045.078935	7.359	ZDrn
2072	7976274.965342	503046.703080	7.386	ZDrn
2073	7976277.243627	503050.704579	7.132	ZDrn
2074	7976279.024198	503054.568140	6.985	ZDrn
2075	7976281.054402	503057.623515	6.968	ZDrn
2076	7976284.825515	503058.536211	6.631	ZDrn
2077	7976288.827805	503059.878045	6.173	ZDrn
2078	7976290.778013	503060.095227	5.954	ZDrn
2079	7976292.340611	503057.708572	5.586	ZDrn
2080	7976294.292035	503055.371542	5.197	ZDrn
2081	7976295.916737	503053.560478	5.104	ZDrn
2082	7976297.675651	503051.571871	5.158	ZDrn
2083	7976298.709868	503050.899874	5.173	ZDrn
2084	7976291.751923	503026.104946	2.110	ZBOS
2085	7976296.354801	503031.545419	2.833	ZBOS
2086	7976302.868038	503026.782162	2.504	ZBOS
2087	7976315.258514	503017.465715	1.770	ZBOS
2088	7976323.570730	503026.053472	2.037	ZBOS
2089	7976331.304656	503036.279571	2.233	ZBOS
2090	7976339.293780	503046.489642	2.225	ZBOS
2091	7976342.971736	503050.538647	2.334	ZBOS
2092	7976346.051797	503052.461560	2.510	ZBOS
2093	7976347.777335	503056.158531	2.813	ZBOS
2094	7976351.077720	503060.741674	2.945	ZBOS
2095	7976355.133034	503066.398754	2.794	ZBOS
2096	7976357.793174	503069.264521	2.718	ZBOS
2097	7976367.349082	503081.360337	2.918	ZBOS
2098	7976369.541332	503081.538312	2.594	XBOS
RTCM-Ref 0000	7976079.473010	503925.887938	16.092	-----

Stockpile Sedimentation Pond No. 2 As Built - 29Oct2014.asc

1500	7976329.186054	503498.547608	11.753	ZTOS
1501	7976326.901960	503496.046876	11.851	ZTOS
1502	7976328.229853	503472.094282	12.014	ZTOS
1503	7976329.978647	503460.441566	11.823	ZTOS
1504	7976333.490317	503444.880624	11.697	ZTOS
1505	7976331.411874	503444.461312	11.693	XTOS
1506	7976336.952162	503430.542416	11.526	ZTOS
1507	7976338.772445	503430.304048	11.462	ZTOS
1508	7976344.433885	503412.887640	11.372	ZTOS
1509	7976347.657013	503407.222489	11.333	ZTOS
1510	7976351.477611	503405.259276	11.185	ZTOS
1511	7976359.621479	503406.943588	10.547	ZTOS
1512	7976359.541070	503404.662879	10.623	XTOS
1513	7976364.674655	503407.163028	10.295	ZTOS
1514	7976364.738572	503409.690175	10.167	ZTOS
1515	7976374.882897	503417.512024	9.270	ZTOS
1516	7976387.416349	503425.454951	8.631	ZTOS
1517	7976391.342613	503428.022569	8.438	ZTOS
1518	7976392.851538	503431.332089	8.165	ZTOS
1519	7976386.962923	503458.973378	8.327	ZTOS
1520	7976379.438174	503487.601633	8.332	ZTOS
1521	7976382.066042	503488.948586	8.421	XTOS
1522	7976379.333685	503497.176348	8.458	ZTOS
1523	7976377.040998	503496.421207	8.321	ZTOS
1524	7976374.786417	503499.763089	8.283	ZTOS
1525	7976371.210988	503503.364584	8.321	ZTOS
1526	7976365.185188	503506.505739	8.501	ZTOS
1527	7976347.555025	503505.560258	9.592	XTOS
1528	7976347.628531	503507.169095	9.643	ZTOS
1529	7976366.363025	503508.069116	8.625	ZTOS
1530	7976372.262424	503505.645318	8.375	ZTOS
1531	7976376.396875	503501.658105	8.277	ZTOS
1532	7976378.757272	503498.190525	8.379	ZTOS
1533	7976385.184412	503500.532642	7.540	XTOS
1534	7976385.530112	503499.201519	7.511	ZTOS
1535	7976379.184093	503497.017818	8.475	XTOS
1536	7976381.976403	503489.007789	8.415	ZTOS
1537	7976388.705548	503491.144598	7.620	XTOS
1538	7976389.079167	503490.277643	7.630	ZTOS
1539	7976382.687576	503488.014422	8.384	ZTOS
1540	7976382.108875	503486.347573	8.404	ZTOS
1541	7976382.620933	503483.907660	8.420	ZTOS
1542	7976389.120563	503459.369901	8.348	ZTOS
1543	7976395.219793	503430.768742	8.223	ZTOS
1544	7976394.646428	503427.084620	8.370	ZTOS
1545	7976392.705897	503425.805508	8.477	ZTOS
1546	7976388.686968	503423.204475	8.664	ZTOS
1547	7976375.883768	503415.532125	9.311	ZTOS
1548	7976364.641692	503407.126260	10.318	XTOS
1549	7976359.652910	503404.752167	10.641	ZTOS
1550	7976351.193469	503402.770962	11.247	ZTOS
1551	7976345.712277	503405.198129	11.296	ZTOS
1552	7976342.181867	503412.236795	11.383	ZTOS
1553	7976336.991317	503430.510512	11.561	XTOS
1554	7976331.415725	503444.598673	11.721	ZTOS
1555	7976328.292286	503460.399366	11.784	ZTOS
1556	7976326.354880	503472.227124	12.034	ZTOS
1557	7976324.631940	503494.200726	11.968	ZTOS
1558	7976324.890874	503498.414048	11.884	ZTOS
1559	7976327.554373	503500.744450	11.821	XTOS
2000	7976353.908806	503492.800608	7.221	Zgl n
2001	7976359.767434	503496.831924	7.097	Zgl n
2002	7976368.219616	503497.517458	6.864	Zgl n

Stockpile Sedimentation Pond No. 2 As Built - 29Oct2014.asc

2003	7976371.032201	503495.192280	6.902	Zgl n
2004	7976373.628466	503477.936449	6.905	Zgl n
2005	7976376.572200	503458.699164	6.878	Zgl n
2006	7976383.481207	503444.810281	6.894	Zgl n
2007	7976386.817990	503432.647960	6.981	Zgl n
2008	7976386.264858	503430.708968	6.971	Zgl n
2009	7976373.298680	503426.797243	6.948	Zgl n
2010	7976361.506792	503422.070714	6.845	Zgl n
2011	7976353.640579	503444.446804	6.964	Zgl n
2012	7976348.914062	503467.569243	6.939	Zgl n
2013	7976351.404208	503469.119440	7.003	Zgl n
2014	7976353.154300	503480.328275	7.069	Zgl n
2015	7976353.346245	503485.923037	7.145	.gl n
2016	7976364.778515	503489.799504	6.991	Node
2017	7976366.731666	503480.043655	6.962	Node
2018	7976368.671386	503469.779197	6.913	Node
2019	7976371.465413	503459.792849	6.931	Node
2020	7976374.951839	503449.510979	7.001	Node
2021	7976378.821051	503439.519074	6.971	Node
2022	7976371.443808	503436.973589	6.970	Node
2023	7976368.321852	503446.863403	6.944	Node
2024	7976365.331682	503456.592497	6.950	Node
2025	7976362.585784	503466.883404	7.009	Node
2026	7976360.208463	503476.620974	6.997	Node
2027	7976358.568355	503486.317892	7.080	Node
2028	7976353.178771	503467.206989	6.998	Node
2029	7976355.800245	503457.173956	6.972	Node
2030	7976357.998865	503447.143825	6.952	Node
2031	7976360.691049	503437.574088	6.952	Node
2032	7976364.403878	503429.119094	7.024	Node
2014P0006	7976064.316000	503642.649000	12.659	-----
RTCM-Ref 0000	7976079.473010	503925.887938	16.092	-----

Appendix D

Annual Geotechnical Inspection

- A. BHM 14-084: Annual Geotechnical Inspection Baffinland Iron Mines Corporation Mary River Project – 2014 Inspections **[59 pages]**



BHM Project No.: 14-084

BAFFINLAND IRON MINES CORPORATION

ANNUAL GEOTECHNICAL INVESTIGATION

MARY RIVER PROJECT

2014 INSPECTIONS



Prepared for:

Mr. Jeff Bush
Site Services Superintendent
Baffinland Iron Mines Corporation
2275 Upper Middle Road East, Suite 300
Oakville, Ontario L6H 0C3



Barry H. Martin P.Eng., MRAIC, Consulting Engineer and Architect

1499 Kraft Creek Rd,
Timmins, ON P4N 7C3
Tel : 705.268.5621
Contact: Barry Martin: barrymartin1499@gmail.com

INDEX

1.0 INTRODUCTION

Mary River Site

Milne Inlet Site

2.0 METHODOLOGY FOR INSPECTION

3.0 MARY RIVER SITE

3.01 General

3.02 Bulk Fuel Storage Facility

- General Conditions
- Stability
- Recommendations

3.03 Generator Fuel Storage Containment

- General Conditions
- Stability
- Recommendations

3.04 Polishing/Waste Stabilization Pond #1

- General Conditions
- Stability
- Recommendations

3.05 Polishing Ponds/Waste Stbilization Ponds #2 and #3

- General Conditions
- Stability
- Recommendations

3.06 Helicopter Fuel Tank Containment

- General Conditions
- Stability
- Recommendations

3.07 Barrel Fuel Containment

- General Conditions
- Stability
- Recommendations

3.08 Hazardous Waste Storage

- General Conditions
- Stability
- Recommendations

- 3.09 Enviro Tank Storage
 - General Conditions
 - Stability
 - Recommendations
- 3.10 Stove Oil Storage
 - General Conditions
 - Stability
 - Recommendations
- 3.11 Jet Fuel Tank and Pump Containment
 - General Conditions
 - Stability
 - Recommendations
- 3.12 Solid Waste Disposal Site
 - General Conditions
 - Stability
 - Recommendations
- 3.13 Waste Oil Storage Containment
- 3.14 Minesite Steel Fuel Tank Farm Containment
 - General Conditions
 - Stability
 - Recommendations
- 3.15 Quarry
 - General Conditions
 - Stability
 - Recommendations
- 3.16 Overview

PHOTOS

DRAWINGS

4.0 MILNE INLET

- 4.01 General
- 4.2 Bulk Fuel Containment Facility
- 4.03 Existing Polishing/Waste Stabilization pond
- 4.04 Barrel Fuel Storage

- 4.05 Hazardous Waste Storage
 - General Conditions
 - Stability
 - Recommendations
- 4.06 Oil And Antifreeze Containment
- 4.07 Jet “A” Pump Containment
- 4.08 Fuel Tank Farm
 - General Conditions
 - Stability
 - Recommendations
- 4.09 New Sewage Effluent Pond
 - General Conditions
 - Stability
 - Recommendations
- 4.10 Landfarm Containment
 - General Conditions
 - Stability
 - Recommendations
- 4.11 Contaminated Snow Containment
 - General Conditions
 - Stability
 - Recommendations
- 4.12 Sediment Pond East
 - General Conditions
 - Stability
 - Recommendations
- 4.13 Sediment Pond West
 - General Conditions
 - Stability
 - Recommendations
- 4.14 Quarry
 - General Conditions
 - Stability
 - Recommendations
- 4.15 Overview

PHOTOS

DRAWINGS



October 28, 2014

Baffinland Iron Mines Corporation
2275 Upper Middle Road East, Suite 300
Oakville, Ontario L6H 0C3

Attention: Jeff Bush
Jeff.bush@baffinland.com

**RE: ANNUAL GEOTECHNICAL INSPECTIONS
BAFFINLAND IRON MINES CORPORATION
OUR REFERENCE NO. 14-084**

1.0 INTRODUCTION

Barry H. Martin, P. Eng., Consulting Engineer completed the 7th annual water licence geotechnical inspection of the following on-site engineered facilities:

- Pit Walls
- Quarries
- Landfills
- Land farms
- Bulk Fuel Storage Facilities
- Sediment Ponds
- Collection Ponds
- Polishing and Waste Stabilization Ponds

The inspection that took place July 31st/August 5th is the first phase of a biannual inspection to be carried out within the open water shipping season at the two Baffinland sites in Mary River at the mine site and at Milne Inlet at the port facility. A second inspection took place September 25th/30th.

The inspections were carried out in accordance with the guidelines set out in "Dam Safety Guidelines 2007" as published by the Canadian Dam Association.

The inspections were completed by Mr. Barry H. Martin, P. Eng., the design Engineer for the initial containment facilities at both Mary River and Milne Inlet, the runway extension, initial bridges on the connecting road plus the solid waste disposal site.

The previous 6 annual water license geotechnical inspections were completed by Mr. Martin.

The facilities inspected are as per the following:

Mary River Site

1. Bulk Fuel Storage Containment
2. Generator Fuel Storage Facility Containment
3. Polishing/Waste Stabilization Pond No. 1
4. Polishing/Waste Stabilization Ponds No. 2 and No. 3 (Constructed as a 2 cell structure)
5. Helicopter Fuel Cell Containment
6. Barrel Fuel Containment (Constructed as a 2 cell structure)
7. Hazardous Waste Storage
8. Enviro-Tank Storage (Constructed contiguous with hazardous waste storage and stove oil storage)
9. Stove Oil Storage
10. Jet Fuel Tank and Pump Containment
11. Solid Waste Disposal Site
12. Waste Oil Storage Containment
13. Minesite Steel Fuel Tank Farm Containment
14. Quarry

A site plan for the Mary River site showing most structures reviewed is attached.

Milne Inlet Site

1. Bulk Fuel Containment Facility
2. Existing Polishing/Waste Stabilization Pond
3. Barrel Fuel Storage (Constructed as a 2 cell structure)
4. Hazardous Waste Storage (Constructed as a 2 cell structure)
5. Oil and Antifreeze Containment
6. Jet "A" Pump Containment

7. Fuel Tank Farm
8. New Sewage Effluent Pond
9. Land farm
10. Contaminated Snow Containment
11. Sediment Ponds East and West
12. Quarry

A site plan for the Milne Inlet site is attached.

2.0 METHODOLOGY FOR INSPECTION

The geotechnical inspector was Barry H. Martin, P. Eng., who reviewed the two sites for the first of the biannual inspections on July 31st, 2014 to August 4th, 201, just as the annual shipping season commenced and on Sept 25th, 2014 to Sept. 30th, 2014 for the second inspection, just as the shipping season ended.

The inspections primarily focused on the following aspects:

1. The structures were inspected for conformance with the design basis as presented in “as-constructed” and “as-built drawings (provided in the first and subsequent reports).
2. The structures were specifically inspected for settlement, cracking, and seepage through the berms.
3. The areas around the structures were examined for evidence of seepage.
4. Quarry walls were reviewed for relative stability. I note that the quarries were active removal areas and long term stability was not yet established.
5. New structures under construction were reviewed for conformity with design drawings.
6. Photographs were taken to document observations made during the inspection and are attached.

3.0 MARY RIVER CAMP

3.01 General

As with other years, there had been a fair amount of rainfall at Mary River preceding the first inspection and it was expected that there would be some water in the containment dykes. Such was the case. During the second inspection we found ice at the bottom of the containment areas.

A monitoring program is in place to test storm water that does accumulate within the containment structures. As reviewed, the water that does not meet the water license effluent requirements is treated on site prior to release.

At the Bulk Fuel Storage Facility Containment, the water that collects within the dyke is treated at the end of the containment structure.

We report on the quarry and the steel fuel tank containment structure for the first time.

The bulk fuel storage containment is coming due for decommissioning and shall only be in use to accommodate jet "A" fuel until the end of this summer/autumn season.

3.02 Bulk Fuel Storage Facility

General Conditions

A new steel tank storage facility has been constructed at the mine site and it is intended that this facility shall replace the bulk fuel storage facility during this summer season at which time the remaining bladders still containing product shall be emptied.

Only Jet A fuel shall be accommodate by this facility until November at the latest when the total use of this facility shall be discontinued and it shall be due for decommissioning and a final decision has been made on land farming of oil impacted granular cover within the structure.

Stability

At the time of our first review, water had not been removed for a period from within the containment and water was ponding above the level of the gravel within the bottom of the containment. There was still considerable factor of safety against failure of oil holding bladders within the dykes with the water level as it exists. Such was the case during the second inspection, but the water had frozen.

The structure was visually inspected for any signs of cracking or subsidence. There was no indication of any settlement, seepage, or cracking in the soil structures that formed the dykes. As well, there was no indication of seepage at the base of the structure around the exterior.

The soil structure is considered stable in the present condition and is in conformance with the design basis for the facility.

The presence of water within the structure is an indication of the integrity of the liner.

Recommendations

We have one recommendation. There is limited storage for spills at the load out end of the facility. Water currently ponds above the gravel in this area confirming the integrity of the liner but minimizing the capacity of the structure for spill containment.

We recommend that this water be removed on a regular basis. If the water proves to be oil impacted, it may be pumped to within the storage containment for treatment at a future date.