

Bridge No.	2017-2318-23.9	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-13
------------	----------------	-----------	----------------------	-----------------	------------



Figure 6: SE binwall and ballast wall gap (top)



Figure 8: South centre bearing, front face



Figure 5: SE binwall and ballast wall (base)



Figure 7: Soffit of bridge and temporary access platforms (looking south)

Bridge No.	2017-2318-23.9	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-13
------------	----------------	-----------	----------------------	-----------------	------------



Figure 10: Top of deck (looking south)



Figure 12: Typical back of bearing (NW top)



Figure 9: Spall in deck soffit, north centre girder (west side)



Figure 11: Typical back of bearing (NW bottom)

Bridge No.	2017-2318-23.9	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-13
------------	----------------	-----------	----------------------	-----------------	------------



Figure 14: Typical girder splice top (NW first splice, west girder)



Figure 16: West internal bracing and temporary access platforms (looking south)




Figure 13: Typical girder splice bottom (NW first splice, west girder)



Figure 15: West girder outside face (looking south)

Bridge Inspection Report Agnico Eagle

Bridge No.	2017-2318-23.9	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-13
------------	----------------	-----------	----------------------	-----------------	------------



Figure 18: East girder (looking north)



Figure 20: General (NW corner, looking south)



Figure 17: Deck level (looking from NW corner)



Figure 19: Front of south bin wall abutment (looking west)

Bridge No.	2017-2318-23.9	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-13
------------	----------------	-----------	----------------------	-----------------	------------



Figure 22: NE ballast wall and bin walls



Figure 24: NW abutment and bin walls




Figure 21: NE ballast wall and bin wall (side view)



Figure 23: NE ballast wall and deck edge (note evazote missing in joint)

Bridge Inspection Report

Agnico Eagle

Bridge No.	2017-2318-26.1	Road Name	Meadowbank to Amaruq					Inspection Date	2017-07-15						
STA.	Forest District					Access Notes									
26.1 km															
Bridge Length	Stream Crossing					Inspected By									
14.7 o/o m						R. Smertina									
UTM Zone	Easting					Northing									
No. Spans		Installation Date		Current Load Rating		Deck Width		Project No.		Anticipated Replacement					
1		2017				7900 mm									
Span / Length (m)	1	13.88	2		3		4		5		6		7		
Comments	single span. steel girders with precast concrete deck and integral abutments														
<p>Excellent: New or almost new condition and properly installed</p> <p>Good: Structurally sound, in good repair and have minimal wear</p> <p>Fair: Structurally sound, but show moderate wear or preliminary indications of rot or corrosion</p> <p>Poor: Structurally unsound, major items in need of repair or replacement, or bridge load rating should be reduced</p> <p>Abutment, spans, piers numbered from left bank, facing downstream / girders numbered from upstream to downstream.</p>															
Approaches															
Approach Road	Good		minor gaps in road embankment approaching deck edge												
Alignment	Good		Straight												
Visibility	Good		weather dependent												
Signage	N/A		temporary signage installed currently												
Delineators	N/A		none												
Overall	Good														
Deck - Span 1															
Running Surface	Good		Lifting lug pockets plugged with gravel (maintenance concern)												
Grout Pockets	Good		Drip grooves at CIP deck joints not installed (maintenance consideration)												
Curb Rails and Risers	Fair		Only 2 of 3 anchor bolts currently installed at each connection - fit-up problems during construction at some locations												
Hardware	Good														
Overall	Good														
Superstructure - Span 1															
Girders	Excellent														
Bracing	Good														
Diaphragms	Good														
Hardware	Excellent														
Overall	Good														

Bridge Inspection Report

Agnico Eagle

Bridge No.	2017-2318-26.1	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-15
Abutment - North					
Bearings	Poor	Guide plates are at the limit of allowed movement			
Bracing	Good				
Ballast Wall	Good	Some loose evazote under ballast wall and at joint with deck Some minor spalling evident at welded embedded plate locations Minor rotation out of plumb (bottom of ballast wall kicks in, opposite of other abutment)			
Corrosion Protection	N/A	weathering steel			
Caps or Sills	Good	footings installed level			
Fill	Good	Some minor gaps in approach grading at the ends of the deck			
Hardware	Excellent				
Riprap	Excellent				
Wingwall	Good				
Overall	Good				
Abutment - South					
Bearings	Poor	Guide plates are at the limit of allowed movement			
Bracing	Good				
Ballast Wall	Good	Some loose evazote under ballast wall and at joint with deck Some minor spalling evident at welded embedded plate locations Minor rotation out of plumb (top of ballast wall tips inwards)			
Corrosion Protection	Excellent	weathering steel			
Caps or Sills	Good	footings are installed with a minor nominal slope.			
Fill	Poor	Some minor gaps in approach grading at the ends of the deck			
Hardware	Excellent	weathering steel			
Riprap	Excellent				
Wingwall	Good				
Overall	Good				
Hazards					
High Water					
Scour					
Ice					
Debris					
Aggradation					
Channel					
Estimated Present Water Level Depth					
Estimated Present Water Level Width					
Estimated High Water Level Clearance					

Bridge Inspection Report

Agnico Eagle

Bridge No.	2017-2318-26.1	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-15
Repair Description and Cost Estimate					
No.	Description	Priority	Cost Estimate		
1	Cut bearing slots for guide plates to allow further movement - see report for recommended amount	Medium	\$0.00		
2	Confirm that all bracing and bolted connections are tightened according to project specifications	Low	\$0.00		
3	Install permanent signage at bridge approaches	Low	\$0.00		
4	Clean out and grout lifting lug pockets in deck to prevent damage from gravel and traffic	Low	\$0.00		
5	Install railings meeting facility requirements - ensure all anchor bolts are installed	Low	\$0.00		
6	Maintain road embankments to match bridge deck width or provide delineation at gap locations	Low	\$0.00		
7	Repair concrete spall areas where steel reinforcing is exposed	Low	\$0.00		
<p>High: Immediate, non-recurring repair to assure public safety</p> <p>Medium: Ongoing, regular maintenance items to protect capital investment</p> <p>Low: Minor maintenance items or improvements to extend service life</p> <p>The cost estimate for individual maintenance items reflects the cost of materials and labour for completing a task; it does not include any costs associated with mobilization, demobilization, delivery of materials, engineering or contract administration.</p>					
Monitoring Items					
No.	Description				
1	Monitor approach grading regularly to avoid traffic damaging the precast deck panel edges				
2	Monitor for loose or missing evazote at underside of ballast wall or joints and replace/repair as required				
3	Monitor ballast walls for further movement				
Comments				Seal	
Partial Inspection 12:00 pm Girder exterior face skin temperature varies from 8.9 to 12 degrees Celcius Load test conducted on July 15th - minor noise observed					

Bridge Inspection Report Agnico Eagle

Bridge No.	2017-2318-26.1	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-15
------------	----------------	-----------	----------------------	-----------------	------------



Figure 2: General west side, looking north



Figure 4: North abutment



Figure 1: Approach from south



Figure 3: Minor spall in deck soffit (SW corner)

Bridge No.	2017-2318-26.1	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-15
------------	----------------	-----------	----------------------	-----------------	------------



Figure 6: NW bearing - front west corner



Figure 8: SE deck and ballast wall end



Figure 5: NW bearing - back west corner



Figure 7: Railing bracket installation (SW end)

Bridge Inspection Report Agnico Eagle

Bridge No.	2017-2318-26.1	Road Name	Meadowbank to Amaruq	Inspection Date	2017-07-15
------------	----------------	-----------	----------------------	-----------------	------------



Figure 10: SW ballast wall and deck joint from above



Figure 12: SW bearing front face



Figure 9: Spall in dek panel corner (SE)



Figure 11: SW bearing back face