

WATER LICENCE INSPECTION FORM

Original	
Follow-Up	Report

Sabina Gold and Silver Corp. Representative Titles Representative Titles	Licensee			Licensee Represent	ative			
Site Superintendent	Sabina Gold and	Sabina Gold and Silver Corp. Rob Da			b Davidson			
Lack Obber Authoritations N2D1FCOO11				Representative's Title				
NZ01FC0016	2BE-GEO1520			Site Superintendent				
Inspector Insp	Land / Other Authorization	Land / Other Authorizations Land / Other Authorizations						
SARDA Conditions: A Acceptable U-Unacceptable C-Concern NI-Not Inspected Conditions: A Acceptable U-Unacceptable C-Concern NI-Not Inspected NA-Not applicable PART: Item No.* Condition Observation No.* A Condition Observation No.*	(1202), 0020							
Conditions: A Acceptable U-Unacceptable C-Concern Ni-Not inspected NA- Not applicable								
Conditions: A A Acceptable				Eva Paul				
PART: A: SCOPE, DEFINITIONS AND ENFORCEMENT A: SCOPE, DEFINITIONS AND ENFORCEMENT A: CONDITIONS A: CONDITIONS A: CONDITIONS A: CONDITIONS A: CONDITIONS APPLYING TO WATER USE A: A: CONDITIONS APPLYING TO WASTE DISPOSAL B: CONDITIONS APPLYING TO WASTE DISPOSAL A: CONDITIONS APPLYING TO ORILLING OPERATIONS C: CONDITIONS APPLYING TO DRILLING OPERATIONS C: CONDITIONS APPLYING TO DRILLING OPERATIONS A: CONDITIONS APPLYING TO MODIFICATIONS A: CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR C: CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR C: CONDITIONS APPLYING TO HE MONITORING PROGRAM A: CONDITIONS APPLYING TO THE MONITORING PROGRAM A: CONDITIONS APPLYING TO THE MONITORING PROGRAM A: CONDITIONS APPLYING TO THE MONITORING PROGRAM A: The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by Inspector: Ves	⊠ Camp		Mining					
SECTION 1 Comments (s.1) Non-Compliance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at Nebrasire Inserting was defined in the 2015 inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the dryll. 2. Sumplest of short geotechnical holes at Bathurst Inlet for the MLA. The site maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA has been established at Nebrasing was defined in the 2015 inspection and has not been open for several years. 4. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumpling was identified in the 2015 inspection and has not been open for several years. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet. The new emplored in the inspection, and found that some of the park of the previous order of the first previous order of the first previous order of the first previous order	Conditions:	A- Acceptable	U-Unacceptable	C-Concern				
B. GENERAL CONDITIONS A 1 C. CONDITIONS APPLYING TO WATER USE A 1 C. CONDITIONS APPLYING TO WATER USE A C. CONDITIONS APPLYING TO WATER USE C. CONDITIONS APPLYING TO BY A CONDITIONS C. CONDITIONS APPLYING TO DRILLING OPERATIONS A C. CONDITIONS APPLYING TO SILLING OPERATIONS A C. CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING C. CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR C. CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR TEMPORARY CLOSING J. CONDITIONS APPLYING TO THE MONITORING PROGRAM A The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by Inspector: Ves No Location(s): Ves No Location(s): Ves No Non-Compliance with Act or Licence (s.2) Action Required (s.3) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabira's Site Superintendent. The new camp for the MLA has been water licence. I was accompanied by Rob Davidson, Sabira's Site Superintendent. The new camp for the MLA has been established at N66'933'7" W107'94'19"; slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a prive, and a "Burnadette" style fluel-Fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. 3. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the Inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt	PART:				Item No.*	Condition	Observation No.*	
D: CONDITIONS APPLYING TO WASTE USE D: CONDITIONS APPLYING TO WASTE USEPOSAL A D: CONDITIONS APPLYING TO DRILLING OPERATIONS S: CONDITIONS APPLYING TO DRILLING OPERATIONS A B: CONDITIONS APPLYING TO DRILLING OPERATIONS A B: CONDITIONS APPLYING TO DRILLING OPERATIONS A B: CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING C: CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING B: CONDITIONS APPLYING TO A BANDONMENT AND RESTORATION OR C: CONDITIONS APPLYING TO THE MONITORING PROGRAM B: CONDITIONS APPLYING TO THE MONITORING PROGRAM The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by Inspector: Ves No SECTION 1 Comments [s:1] Non-Compilance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. It was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66*38'37" W107*41'37"; slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the Inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance	A: SCOPE, DEFINITIO	NS AND ENFORCEME	NT		00000	Α		
D. CONDITIONS FOR CAMPS, ACCESS INFRASTRUCTURES AND OPERATIONS 5 A 2 F. CONDITIONS FOR CAMPS, ACCESS INFRASTRUCTURES AND OPERATIONS 5 A 3 F. CONDITIONS APPLYING TO MODIFICATIONS A A 3 F. CONDITIONS APPLYING TO MODIFICATIONS A A 3 F. CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING 3 C 4 F. CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING 3 C 4 F. CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING 3 C 5 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO SENDING THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO SENDING THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO SENDING THE MONITORING PROGRAM A 1 F. CONDITIONS APPLYING TO SENDING THE MONITORING THE MONITOR	B: GENERAL CONDITI	ONS	***			Α		
E: CONDITIONS FOR CAMPS, ACCESS INFRASTRUCTURES AND OPERATIONS 5 A 2 F: CONDITIONS APPLYING TO DRILLING OPERATIONS A 3 G: CONDITIONS APPLYING TO MODIFICATIONS A 4 H: CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING 3 C 4 II: CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR C 5 TEMPORARY CLOSING J: CONDITIONS APPLYING TO THE MONITORING PROGRAM A 5 SECTION 1 CONDITIONS APPLYING TO THE MONITORING PROGRAM A 5 SECTION 1 CONDITIONS APPLYING TO THE MONITORING PROGRAM A 5 SECTION 1 COMMENT OF THE MONITORING PROGRAM A 5 SECTION 1 COMMENT OF THE MONITORING PROGRAM A 5 SECTION 1 COMMENT OF THE MONITORING PROGRAM A 6 SECTION 1 COMMENT OF THE MONITORING PROGRAM A 6 SECTION 1 COMMENT OF THE MONITORING PROGRAM A 6 SECTION 1 COMMENT OF THE MONITORING PROGRAM A 6 SECTION 1 COMMENT OF THE MONITORING PROGRAM A 6 SECTION 1 COMMENT OF THE MONITORING PROGRAM A 7 An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MILA has been established at 106-233 The MILA HAS DEED THE MONITORING PROGRAM A 7 An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MILA has been established at 106-233 The MILA HAS DEED THE MILA HAS DEE	C: CONDITIONS APPL	YING TO WATER US				Α	1	
F. CONDITIONS APPLYING TO DRILLING OPERATIONS G. CONDITIONS APPLYING TO MODIFICATIONS H. CONDITIONS APPLYING TO MODIFICATIONS J. C. 4 H. CONDITIONS APPLYING TO SPLIL CONTINGENCY PLANNING J. CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR C. 5 TEMPORARY CLOSING J. CONDITIONS APPLYING TO THE MONITORING PROGRAM A *The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by Inspector: Ves. No Comments provided below. SECTION 1 Comments (S:1) Non-Compliance with Act or Licence (S:2) Action Required (S:3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at Non-Regarday. Willy to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently sung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the padis of drill lubricant	D: CONDITIONS APP	LYING TO WASTE DI	SPOSAL			Α		
F. CONDITIONS APPLYING TO MODIFICATIONS A G. CONDITIONS APPLYING TO MODIFICATIONS A It: CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING 3	E: CONDITIONS FOR	CAMPS, ACCESS INFI	RASTRUCTURES AND OF	PERATIONS	5	A	2	
G: CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING H: CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING C S TEMPORARY CLOSING J: CONDITIONS APPLYING TO THE MONITORING PROGRAM The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by inspector: Ves No Comments (s.1) Non-Compilance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38'37" W107°41'37"; slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the Inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and slit fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The slit fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the palls of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the li					10	Α	3	
H: CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR C 5 TEMPORARY CLOSING J: CONDITIONS APPLYING TO THE MONITORING PROGRAM A The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by Inspector: Ves No SECTION 1 Comments (s.1) Non-Compliance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at Non69'38'37" W107'94'37", slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette' style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the lined berm area. A large quantity of	G: CONDITIONS APP	LYING TO MODIFICA	TIONS			Α		
I: CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR J: CONDITIONS APPLYING TO THE MONITORING PROGRAM A *The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by inspector: Ves No SECTION 1 Comments (s.1) Non-Compliance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabinar's Site Superintendent. The new camp for the MLA has been established at N66°98'37" W107°41'37"; slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a priv, and a "Burnadette" style feel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silf fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The slit fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the palls of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the line derm area. A large quantity of drill salt bags are p				1	3	С	4	
TEMPORARY CLOSING J: CONDITIONS APPLYING TO THE MONITORING PROGRAM *The Item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by inspector: Ves No SECTION 1 Comments (s.1) Non-Compilance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compilance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66-3813" Villowing 1.3 gillyly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compilance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the lined berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compro				ON OR		С	5	
#The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by Inspector:	''							
The Item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below. Samples taken by Inspector: Yes No	121111 0111 1111 022		ORING PROGRAM			A		
Samples taken by Inspector: Ves No Section 1 Comments (s.1) Non-Compilance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38'37" W107°41'37"; slightly to the north of the previous work that was done at Bathurst linet. The new camp consists of 7 weatherhaven tents, a privy, and a "Surnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the linend berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compromised resulting in dissolution of salts into the pad. 5. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. Section 2 Commen	3. CONDITIONS AND E							
Samples taken by Inspector: Ves No Section 1 Comments (s.1) Non-Compilance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38'37" W107°41'37"; slightly to the north of the previous work that was done at Bathurst linet. The new camp consists of 7 weatherhaven tents, a privy, and a "Surnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the linend berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compromised resulting in dissolution of salts into the pad. 5. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. Section 2 Commen	*The item number	r corresponds with se	ecific conditions within	the licence and	the observation num	nber corresp	onds with specific	
Section 1	ine item number	corresponds with sp			the observation has	iber corresp	ones musipedific	
SECTION 1 Comments (s.1) Non-Compliance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38'37" W107°41'37"; slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the lined berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compromised resulting in dissolution of salts into the pad. 5. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. SECTION 2 Comments Non-Compliance with Act or Licence			T	NOVIDEU DEIOW.				
SECTION 1 Comments (s.1) Non-Compliance with Act or Licence (s.2) Action Required (s.3) An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38'37" W107°41'37"; Slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the palls of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the lined berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compromised resulting in dissolution of salts into the pad. 5. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. SECTION 2 Comments Non-Compliance with Act or Licence		pector:	Location(s):					
An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38'37" W10°41'37'; glightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the lined berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compromised resulting in dissolution of salts into the pad. 5. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. SECTION 2 Comments Non-Compliance with Act or Licence Action Required E-5. With respect to access road, pad construction or other earthworks, t	Yes No			- Lander				
An inspection was conducted at George Camp and the Marine Laydown Area (MLA) to assess compliance with the above water licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38'37" W10°41'37'; glightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the lined berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compromised resulting in dissolution of salts into the pad. 5. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. SECTION 2 Comments Non-Compliance with Act or Licence Action Required E-5. With respect to access road, pad construction or other earthworks, t								
licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38'37" W10°04'37"; slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. 1. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. 2. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. 3. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. 4. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the lined berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compromised resulting in dissolution of salts into the pad. 5. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. 5. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. 6. Section 2 Comments Non-Compliance with Act or Licence Action Required 6. With respect to access road, pad const	SECTION 1	Comments (s.1)	Non-Comp	liance with Act	or Licence (s.2)	Action	n Required (s.3)	
E-5. With respect to access road, pad construction or other earthworks, the deposition of debris or sediment into or onto any water body is prohibited. H-3. The Licensee shall prevent any chemicals, petroleum products or wastes associated with the project from entering Water. [including ponds] I-12. The Licensee may store drill cores produced by the appurtenant undertaking in an appropriate manner and location at least	 licence. I was accompanied by Rob Davidson, Sabina's Site Superintendent. The new camp for the MLA has been established at N66°38′37″ W107°41′37″; slightly to the north of the previous work that was done at Bathurst Inlet. The new camp consists of 7 weatherhaven tents, a privy, and a "Burnadette" style fuel-fired incinerator. Matrix established and was operating the camp. A bear fence will be completed for camp shut-down later in August. George Camp was not in use at the time of the inspection and has not been open for several years. Water is currently slung from a nearby river for camp use, as the closest water is the saline Bathurst Inlet. Salt water from the inlet was being used for the drill. Slumping was identified in the 2015 inspection off of the fuel pad and silt fences were subsequently installed to prevent sediment from impacting the surrounding wetlands. The silt fence does not appear to have been maintained since that time. Drilling consisted of short geotechnical holes at Bathurst Inlet for the MLA. The site was found to be clean and operating in compliance with the licence. Workers at George Camp for the day were inspecting tarped berms of materials at the fuel storage pad at the time of the inspection, and found that some of the pails of drill lubricants stored there had been crushed over time, resulting in release of the lubricants within the berm but none to the environment. Similarly, some drums had leaked within the lined berm area. A large quantity of drill salt bags are palletized on the pad, but many bags were compromised resulting in dissolution of salts into the pad. Some core remains in proximity to the lake at George. It is understood that it is impractical to address this when the camp is not operational. 							
body is prohibited. H-3. The Licensee shall prevent any chemicals, petroleum products or wastes associated with the project from entering Water. [including ponds] I-12. The Licensee may store drill cores produced by the appurtenant undertaking in an appropriate manner and location at least	Contraction of the Contraction o		The state of the s					
H-3. The Licensee shall prevent any chemicals, petroleum products or wastes associated with the project from entering Water. [including ponds] I-12. The Licensee may store drill cores produced by the appurtenant undertaking in an appropriate manner and location at least								
[including ponds] I-12. The Licensee may store drill cores produced by the appurtenant undertaking in an appropriate manner and location at least								
I-12. The Licensee may store drill cores produced by the appurtenant undertaking in an appropriate manner and location at least		III prevent any chemi	cals, petroleum produc	ts or wastes ass	sociated with the pro	ject from en	itering Water.	
,						manner and	location at least	



Affaires autochtones et du Nord Canada

SECTION 8 Comments	Non-Compliance with Act or Licence	Action Required						
A. Maintenance of the silt fence off the Ge	A. Maintenance of the silt fence off the George fuel pad is required.							
	containment and protected from the elements. Steps are to be taken to ensure dissolved salts are not entering the nearby							
C. Please provide an update in writing on the George core relocation plan/program.								
Licensee or Representative	Inspector's Name							
Rob Davidson	Eva Paul	Eva Paul						
Signature Pur Dundson	Signature	-						
Date Aug- 20/17	20/Aug/ 17							
Office Use Only: Follow-up report to be issued by inspect	tor Yes 🛛 Y	No						



Licensing Department, NWB Erik Allain, Manager of Field Operations, INAC

