

## WATER LICENCE INSPECTION FORM

$\times$	Original
	Follow-Up Repor

Licensee			Licensee Representative		
Sabina Gold and S	Silver Corpora	ation	Rob Davidson		
Licence No. / Expiry			Representative's Title		
2BC-BRP1819, 2BE-GEO1520, 2BE-GOO1520		Site Manager			
Land / Other Authorizations Land / Other Authorizations					
Date of Inspection			Inspector		
October 10 2018			Jeremy Fraser		
Activities Inspected					
□ Camp     □ Roads/Hauling	☑ Drilling ☐ Other:	Mining	☐ Construction☐ Other:	Reclamation	∑ Fuel Storage

SECTION 1	Comments (s)	Non-Compliance with Act or Licence (s)	Action Required (s)	
Background				
The Sabina Back River Project in the Kitikmeot region of Nunavut is geographically located approximately 400km south				
west of Cambridge Bay, the project is focused on mining gold and is in possession of three water licenses and a land use permit for the purpose of constructing a winter ice road and hauling supplies/ material from the marine laydown area to				
the associated camps for use and operations.				
SECTION 2	<b>◯</b> Comments	Non-Compliance with Act or Licence	Action Required	
Inspector's Statement:				

On October 10, 2018 Water License inspections of the Marine Laydown Area (MLA), George Lake camp, and Goose Lake camp was conducted. Facilities inspected include all water management structures and deposits of waste. These facilities include but are not limited to fresh water intake facilities, fuel storage areas, and laydown areas.

## Marine Laydown Area (MLA) 2BC-BRP1819

- On October 10, 2018 at approximately 0905hrs CIRNAC inspectors Jeremy Fraser, Justin Hack and Candice Pedersen arrived at the MLA and conducted an inspection of the desalination unit, which is used to withdraw water from Bathurst Inlet to separate salt from water and fill the MLA potable water supply.
- The Bulk fuel storage area, incinerator, laydown areas, and camp pad including fuel supplies for all structures were inspected.
- The inspector noted no issues regarding water use or deposit of waste found on the MLA site (See figure#1).

## **George Lake Camp 2BE-GEO1520**

- On October 10, 2018 at approximately 1045hrs CIRNAC inspectors arrived at George Lake camp to conduct an inspection of water licence 2BE-GEO1520. The inspectors walked around the entire facility noting that the camp appears to be closed and not in use during the time of the inspection (see figure #2).
- It was noted that there was significant snow build-up within the insta-berms at this site. This snow should be managed prior to freshet to address possible over-topping of the facility (see figure #3).

## Goose Lake Camp 2BE-GOO1520

- On October 10, 2018 at approximately 1145hrs CIRNAC inspectors arrived at Goose Lake camp to conduct an inspection of Water License 2BE-GOO1520. The inspectors met with Rob Davidson and proceeded with orientation for Candice Pedersen and Justin Hack.
- At 1320hrs an inspection of operating drills 1563 and 1507 was conducted. The drills recirculate water (total 6964m³used) and deposit drill cuttings in a sump located east of Goose camp. No concerns were noted regarding drilling activity.
- During the inspection, it was noted that the original sump used to store drill cuttings was no longer being used. It was capped with gravel. A new sump was established parallel to it for all new cuttings. This sump was constructed as per condition Part H, Item 2 in the Water License whereas it was located 31m from the highwater mark, in which direct flow into a water body is not possible. (see figure #4,5)



	*	4	

Date

•	An inspection of the contractor's storage facility was conducted; all hydrocarbons were within containment. No
	concerns were found within this facility.

Records of camp water use were inspected, no concerns noted. As of October 10, 2018, 1406m³ has been used

for domestic purposes.				
<ul> <li>Hazardous</li> </ul>	Hazardous waste records were available to the inspector upon request.			
SECTION 3	Comments	Non-Compliance with Act or Licence	Action Required	
The following information is a summary of the Actions Required by the licensee to promote and ensure compliance:				
It is recommended that Sabina Gold and Silver perform preventative maintenance on insta-berms prior to				
freshet to ensure compliance with the water licence.				
Licensee or Representativ	e	Inspector's Name		
		Jeremy Fraser		
Signature		Signature		

Office Use Only:	Follow-up report to be issued by Inspector	☐ Yes ⊠ No

Date

CC: Licensing Department, NWB

Justin Hack, Manager of Field Operations, CIRNAC



















