



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee			Licensee Representative		
Adamera Minerals Corp.			None		
Licence No. / Expiry			Representative's Title		
2BE-MAL1116					
Land / Other Authorizations					
Date of Inspection			Inspector		
18/07/2014			Justin HACK		
Activities Inspected					
<input checked="" type="checkbox"/> Camp		<input checked="" type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction	<input type="checkbox"/> Reclamation
<input type="checkbox"/> Roads/Hauling		<input type="checkbox"/> Other:	<input type="checkbox"/> Other:	<input type="checkbox"/> Fuel Storage	
Conditions: A - Acceptable C - Concern U - Unacceptable NA – Not Applicable NI – Not Inspected					
Water Use		Condition	Comment	Site Conditions	
Intake/Screen		NA		Water Management Structures	
Flow Measure. Device		NA		Culverts / Bridges	
Source:		NA		Drainage	
Water Use:		NA		Erosion / Sediment	
Recirculation (y /n)		NA		Mitigation Measures	
				Reclamation Activities	
				Materials Storage	
Waste Disposal				Signage	
Waste Water		NA			
Solid Waste		NA		Monitoring	
Hazardous Waste		NA		Sample Collection / Analysis	
Administrative					
				Records	
				Reports	
				Plans	
				Notifications	
				Other	
				Drill Sites	
*The number in the comments field will correspond with specific comments provided below.					

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Background			
<p>In 2013, Uranium North Resources and Diamonds North Resources amalgamated to form Adamera Minerals Corp. According to documentation submitted on July, 8 2014 by Zoe Pratt, the GIS Manager, no exploration work has been done on the property since 2011, Abandonment and Reclamation activities were completed in 2013, and no future work is planned.</p> <p>Previous work on the property included 5 diamond drill holes, a camp facility, air strip, and fuel cache.</p>			
Observations on Site			
<p>1. At the camp location (63° 50' 30"N, 98° 19' 37"W):</p> <ul style="list-style-type: none">a. Wooden infrastructure appears to have been burned and there are remains small traces of ash on the ground;b. Four core boxes remain on site;c. No spills were observed on site;d. It appears that the ground has been contoured to a more natural state; ande. Reclamation of the camp appears to have been successfully implemented. <p>2. At the airstrip and fuel cache (63° 50' 01"N, 98° 18' 65"W):</p> <ul style="list-style-type: none">a. No rutting was evident on site.b. No contamination was evident near the location of the fuel cache. <p>3. Drill holes</p> <ul style="list-style-type: none">a. All 5 drill sites were inspected (DDH-ML-01, DDH-ML-02, DDH-ML-03, DDH-ML-04, DDH-ML-05).b. No concerns were noted.			
SECTION 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required

Inspector's Name
Justin Hack
Signature
Date
August 20, 2014