

## **APPENDIX E**

### **HEAT LOSS AND BOILER SYSTEMS**

# Heat Loss Calcs:

## Equations:

### Static Heat Loss

Rate of heat loss per unit length  $q$  (W/m):

$$q = (T_w - T_a) / R_T$$

pg 18 Rankin

where  $T_w$  is water temp (C) and  $T_a$  is exterior ambient temp (C) and  $R_T$  is total thermal resistance per length (Cm/W)

$R_T$  (total thermal resistance per length (Cm/W)) can be taken from TABLE 1 pg 19 Rankin  
 $q$  can be read from TABLE 2 page 20 Rankin

### Heat Loss & temp drop in a flowing pipe

Temperature at  $x$  location along water main:

$$T_x = (T_i - T_a) e^{-X/(m \cdot C \cdot R_T)} + T_a$$

where  $T_i$  is water temp (C) at input and  $T_a$  is exterior ambient temp (C) and  $R_T$  is total thermal resistance per length (Cm/W)  
 and  $X$  is length of pipe in m

and  $m$  is the mass flow rate  $m = (V \cdot \text{Area}) \cdot d$  where  
 area is  $m^2$  and  $V$  is velocity  $m/s$  and  $d$  is density of fluid  $1000 \text{ kg/m}^3$

$T_x$  can be read from TABLES 3-1 to 3-4 but must be calculated for 100 mm pipe.

### Freeze up time in pipe in permafrost with no flow

$$T_f = (\pi \cdot \text{Dip}^2 \cdot d \cdot C \cdot (T_x - T_f) \cdot R_T) / (2 \cdot (T_x - 2 \cdot T_a + T_f))$$

Time to drop to freezing temp

$$T_s = (\pi \cdot \text{Dip}^2 \cdot d \cdot H_f \cdot R_T) / (4 \cdot (T_i - T_a))$$

where  $H_f =$

$$334720 \text{ J/kg}$$

Time to freeze solid

### Knowns:

Dip Pipe inside diameter 4" (100 mm) (m):	0.092 m	
Flow Area 4" subtracting 1.5" heat pipe:	0.0055 $m^2$	
Pipe Length:	3400 m	
C Fluid Specific heat (J/KgC):	4190 J/KgC	
$T_i$ Input water temp:	1 C	
Rule:		Temp drop along pipe should be less than 2.5C
$H_f$ Heat of fusion of fluid (J/kg):	334720 J/kg	
$d$ density of fluid (kg/m <sup>3</sup> ):	1000 kg/m <sup>3</sup>	
$T_f$ Temp freezing:	0 C	
$T_a$ Ambient Soil Temp:	-10 C	
Insulation thickness:	50 mm	
Depth of Bury:	1 m	
Velocity 2004 to 2014 (ft/s):	1.88 ft/s	
Velocity 2004 to 2014 (m/s):	0.57 m/s	
Flow 2004 to 2014 (m <sup>3</sup> /s):	0.0032 m <sup>3</sup> /s	0.00315473 check
Velocity 2015 to 2024 (ft/s):	3.60 ft/s	
Velocity 2015 to 2024 (m/s):	1.10 m/s	
Flow 2015 to 2024 (m <sup>3</sup> /s):	0.0060 m <sup>3</sup> /s	

### Static Heat Loss

Rate of heat loss per unit length  $q$  (W/m):  $q = (T_w - T_a)/RT$  pg 18 Rankin

where  $T_w$  is water temp (C) and  $T_a$  is exterior ambient temp (C) and  $RT$  is total thermal resistance per length (Cm/W)

$RT$  (total thermal resistance per length (Cm/W)) can be taken from TABLE 1 pg 10 Rankin  
 $q$  can be read from TABLE 2 page 20 Rankin

**RT for 1 m bury, 50 mm insul, 100mm pipe:**

**4.38735 Cm/W** from TABLE 1

**Rate of heat loss per unit length  $q$  (W/m):**

**2.51 W/m**  $q = (T_w - T_a)/RT$

**Rate of heat loss for pipeline:**

**8524.51 W**

### Heat Loss & temp drop in a flowing pipe

Temperature at  $x$  location along watermain:

$$T_x = (T_i - T_a)e^{(-X/(m \cdot C \cdot R_t))} + T_a$$

where  $T_i$  is water temp (C) at input and  $T_a$  is exterior ambient temp (C) and  $RT$  is total thermal resistance per length (Cm/W)

and  $X$  is length of pipe in m

and  $m$  is the mass flow rate  $m = (V \cdot \text{Area}) \cdot d$  where area is  $m^2$  and  $V$  is velocity  $m/s$  and  $d$  is density of fluid  $1000 \text{ kg/m}^3$

$T_x$  can be read from TABLES 3-1 to 3-4 but must be calculated for 100 mm pipe.

#### 2004 to 2014

Velocity 2004 to 2014 (m/s):

0.57 m/s

Flow 2004 to 2014 (m<sup>3</sup>/s):

0.0032 m<sup>3</sup>/s

X Distance along pipe (m):	Tx Temp at point along pipe (C):		check using other equation
	0	1	
500	0.91		
1000	0.81		
1500	0.72		
2000	0.63		
2500	0.54		
3000	0.45		
3400	0.37		

#### 2015 to 2024

Velocity 2015 to 2024 (m/s):

1.10 m/s

Flow 2015 to 2024 (m<sup>3</sup>/s):

0.0060 m<sup>3</sup>/s

X Distance along pipe (m):	Tx Temp at point along pipe (C):	
	0	1
500	0.95	
1000	0.90	
1500	0.85	
2000	0.80	
2500	0.75	
3000	0.71	
3400	0.67	

Freeze up time in pipe in permafrost with no flow

$$t_f = (\pi \cdot \text{Dip}^2 \cdot d \cdot C \cdot (T_x - T_f) \cdot R) / (2 \cdot (T_x - 2 \cdot T_a + T_f))$$

or replace with actual flow area

$$t_f = (A \cdot d \cdot C \cdot (T_x - T_f) \cdot R) / (T_x - 2 \cdot T_a + T_f)$$

Time to drop to freezing temp

$$t_s = (\pi \cdot \text{Dip}^2 \cdot d \cdot H \cdot R) / (4 \cdot (T_f - T_a))$$

or replace with actual flow area

$$t_s = (A \cdot d \cdot H \cdot R) / (T_f - T_a)$$

Time to freeze solid

2004 to 2014

Tf Time to drop from Tx to freeze:

Tx=

0.37 C

Tf=

0.00 C

Time to drop to freeze from Tx:

3713.52 sec

1.03 hours

Time to freeze solid from Tx:

808797.66 sec

224.67 hours

2015 to 2024

Tf Time to drop from Tx to freeze:

Tx=

0.67 C

Tf=

0.00 C

Time to drop to freeze from Tx:

6545.86 sec


1.82 hours

Time to freeze solid from Tx:

808797.66 sec

224.67 hours

# GOA HAVEN - SUMMARY OF PRELIMINARY CALCULATIONS THE HE EXCHANGERS & COILERS WERE BASED ON.



$$V_c = .57 \text{ m/s} \quad \text{as per K's calc.}$$

$$A_c = .0055 \text{ m}^2 \quad \rho = 1000 \text{ kg/m}^3$$

$$\dot{m}_c = (.0055 \text{ m}^2 \times .57 \text{ m/s} \times 1000 \text{ kg/m}^3)$$

$$= 3.135 \text{ kg/s}$$

$$\dot{m}_c + \dot{m}_h = \dot{m}_e$$

$$\dot{m}_c = 2.71 \text{ kg/sec}$$

$$V_h = .6096 \text{ m/s} \quad (2 \text{ ft/s})$$

$$\text{using 4 mm wall thickness for 15" pipe}$$

$$A_h = .0007 \text{ m}^2$$

$$\dot{m}_h = (.0007 \times .6096 \times 1000)$$

$$= .427 \text{ kg/sec}$$

ENERGY NEEDED TO HEAT LAKE WATER TO 5°C

$$Q_c = \dot{m}_c C_p (T_c - T_e)$$

$$= 2.71 \text{ kg/sec} \cdot 4190 \text{ J/kg} \cdot (5 - 1)^\circ\text{C}$$

$$= 45420 \text{ W}$$

$$\text{or } 155000 \text{ BTU/hr}$$

$$v = 40.6 \text{ gal/min}$$

heat exchanger at WTP

$$Q = 45420 = \dot{m}_h C_p (T_{\text{hot}} - T_{\text{in}})$$

$$45420 = (.427)(4190)(T_{\text{hot}} - 4)$$

$$T_{\text{hot}} = 29.4^\circ\text{C}$$

$$30^\circ\text{C}$$

$$v = 410 \text{ gal/min} \quad T_p = 30^\circ\text{C} \quad T_e = 4^\circ\text{C}$$

Storage Tank

$$Q = 53000 \text{ BTU/hr}$$

$$\text{or } 15533 \text{ J/s}$$

say temp from tank = 3°C

$$V = 2 \text{ ft/s} \quad (6096 \text{ m/s}) \quad \text{using 1.5" pipe}$$

$$Q = \dot{m} C_p (T_f - T_i)$$

$$15533 = .427(4190)(T_f - 3)$$

$$T_f = 16.7^\circ\text{C}$$

$$v = 410 \text{ gal/min} \quad T_f = 16.7^\circ\text{C} \quad T_e = 3^\circ\text{C}$$

By \_\_\_\_\_

Date \_\_\_\_\_

Project Name GOA HAVEN

Checked \_\_\_\_\_

Date \_\_\_\_\_

Page \_\_\_\_\_

of \_\_\_\_\_

Project No. 020602

**DILLON**  
CONSULTING

## **APPENDIX F**

## **COST ESTIMATES**

**From:** Angela Saranchuk  
**To:** Strong, Gary  
**Date:** 10/17/02 3:11PM  
**Subject:** exchanger info

Afternoon, Gary.

Another quote for both the main and tank recirc lines is coming - original quote was on single walled, not double walled construction.

'main' recirculating line -

- 2 quotes - \$2,750 (shell & tube) - make - Armstrong
- \$3,650 (plate) - make - Alfa Laval
- all double-wall construction
- assumed 50% ethylene glycol solution

tank recirc line

- 1 quote - \$2,100 (shell & tube) - make - Armstrong
- waiting for a third to come in - forgot to ask them for this one as well as the 'main' one

boiler -

- 1 quote - \$11,400 - make - Bryant
- CSA approved burners
- \* 2nd quote still to be in this afternoon (doubt it as it's already 4), sent info, but not price ( make is Cleaver-Brooks)

I'll send off more info when I get it. I tried to get 3 quotes for all, but few boiler people listed in the yellow pages carry oil fired ones. Is there another brand you think I should be going for?

I'm faxing the calculations that I did to size the equipment. Please let me know if there are any errors. Thanks.

**From:** Angela Saranchuk  
**To:** Strong, Gary  
**Date:** 10/17/02 3:49PM  
**Subject:** Re: exchanger info

Heat exchangers for based on glycol inlet temperatures of 170/180 F  
main exchanger is for ~155,000 BTU/hr - come to think of it, I'll need to check into provisions for  
increasing this come 2014.  
tank exchanger is for ~55,000 BTU/hr

The boiler

450,000 BTU/hr input

360,000 BTU/hr output (too high only need ~200, 000 initially)

10 Boiler Hp

we can't get a CSA approval on a smaller burner in this type of unit - but this will leave us room for when  
we increase the pump for 2014 and beyond (then we'll require 265,000 BTU/hr for the main as opposed to  
155,000)

Hopefully this is what you meant.

>>> Gary Strong 10/17/02 04:15pm >>>

Can you also provide the info on what the unit sizes are so I can include them in the report.

thanks

g



Call to Norm Dei  
Vincent Tan  
List of quantities

- PW/S  
- PW/S

Pump house

\$300,000

100 mm Insulated pipe

\$300/m

40 mm Uninsulated pipe

\$100/m

Access vaults

\$25,000

Concrete foundations

2,000 /m<sup>3</sup>

Pre-engineered Building

240 /m<sup>2</sup>

YK

Steel Built Buildings

2,350 /m<sup>2</sup>

Steel tanks

vertical tanks - \$180/l

1 tank 280,000 l -

vert steel insulated (checked)  
- Kinghand on both

AKelvik - Earth Tech.

John Bernier 171-1254  
murphyson

Gjose Haven

Community factor

1.5

annual increase

over next 12 months

10%

Albertha

Slowing down - but there is

a back log

2006 might be the end of spike

By

Date

Project Name

Checked

Date

Page

of

Project No.

DILLON  
CONSULTING

From: <John\_Bulmer@gov.nt.ca>  
To: <gstrong@dillon.ca>  
Date: 10/21/02 2:25PM  
Subject: RE: Tank estimates

Gary

The "reliable" computer is working again.

Actual Details

AKLAVIK

1999 - supply and install water tank (minimum 110 000 l size)  
Total Cost: \$ 180 453.00 (included small pipeline and connections to water plant).  
Tank was insulated c/w metal cladding.  
Contractor: Dowland Contracting

\$ 1.64/l

2001 - supply only one water tank  
Total Cost: \$ 169 383.00 including shipping charges from Hay River to Aklavik.  
Tank Size: H = 6.1 m, R = 2.8 m. Approximate Volume = 150 000 litres.  
Foundation was already in place.  
Tank was insulated c/w metal cladding.  
Contractor: King Manufacturing

\$ 1.12/l.

no foundation

2001 - install second water tank and connections  
Total Cost: \$ 75 986.00  
Contractor: Dowland Contracting

FORT MCPHERSON

2000 - supply two water tanks  
Total Cost: \$ 404 275.40  
Tank Size: H = 7.0 m, R = 3.625 m. Approximate Volume = 290 000 litres (each).  
Tank was insulated c/w metal cladding.  
Foundation was already in place.  
Contractor: NTCL

\$ 1.37/l.

1.63/l foundation incl

2000 - construct Foundation  
Total Cost: \$ 67 800.00  
Contractor: Terwood Industries (Fort McPherson).

That's about all the info I have for now.

If you have any additional questions please feel free to contact me.

jb

-----Original Message-----

From: gstrong /unix [mailto:gstrong@dillon.ca]  
Sent: 21-Oct-02 01:57 PM  
To: John Bulmer /IN /PWS

Cc: gstrong /unix  
Subject: Tank estimates

Per our phone call, I'd appreciate knowing the construction costs for the installation of the water storage tanks in Aklavik and Fort MacPherson. Some other project details would help, such as tank size, and foundation cost, if that was separate.

Cheers

Gary Strong, P Eng

Dillon Consulting Limited

phone 867-920-4555  
fax 867-873-3328

## **APPENDIX G**

### **Microbiology Results**

PSC

ANALYTICAL SERVICES

Client: Dillon Consulting Ltd.  
895 Waverley St.  
Suite 200  
Winnipeg, MB, CANADA  
R3T 5P4  
Fax: 204-452-4412  
Attn: Angela Saranchuk

Date Received: November 13/2002  
Date Reported: December 2/2002  
Lab Ref#: G227244  
Lab Quote#: W021004  
Client PO#: 02-0602-1000  
Client Ref#: 02-0602-1000  
Sampled By: Gary Strong

Attached are your results for Microbiology

If you have any questions, please call Elaine Grant,  
your Service Manager at Philip Analytical Services Corp.

Post-It <sup>®</sup> Fax Note	7671E	Date	2-DEC-02	# of pages	7
To	GARY STRONG	From	ANGELA		
Co./Dept.		Co.	SARANCHUK		
Phone #		Phone #			
Fax #		Fax #			

RECEIVED	
DEC 02 2002	
Received by	_____
Task No.	_____
File Type	_____

---

**EPS Environmental Services**

F-1420 Clarence Avenue  
Winnipeg, MB R3T 1T6

---

---

**Total Suspended Solids Analysis  
Microscopic Identification  
Three Water Samples**

---

Job # PSC-4109  
G227244.

Prepared for: Philip Analytical Services Corp.  
5735 McAdam Road  
Mississauga, ON  
L4Z 1N9

28 November 2002

Unit 1 - 1420 Clarence Avenue  
Winnipeg, Manitoba R3T 1T6

Phone: (204) 254-1825  
Fax: (204) 477-8719

## Total Suspended Solids Analysis Microscopic Identification Three Water Samples

### Introduction

EPS Environmental Services received three 250 ml containers comprising three water samples on 18 November 2002. These samples were delivered to EPS by the client (Dillon Consulting LTD), and were received intact and in good condition. These samples were collected by the client on 3 November 2002, and have been identified as SL #1, SL #2 and WL #1. This project has been identified in the EPS internal records as Job# PSC-4109.

### Results

Each sample was tested for Total Suspended Solids as per APHA Standard Methods<sup>1</sup>. All practices followed by EPS Environmental Services are detailed in an internal Manual of Laboratory Procedures<sup>2</sup>. Tests were run on 19 November 2002, and were done by Ainslie Hildebrand.

Test results of the TSS analysis are indicated in the Table 1.

Each water sample was poured into a petria plate and was examined under a microscope for presence of microscopic organisms. Examinations were performed by Mima Wishart on 19 November 2002.

Results of the observations are detailed in Table 1.

Table 1: TSS Results and Microscopic observations for specified samples.

Sample Identification	TSS (mg/L)	Microscopic Observations
SL #1	<1	Brown colour; Has appearance of minute plant debris present; A few rotifers observed; Water clear
SL #2	<1	Brown colour; Has appearance of minute plant debris and minute fibrous organic debris present; A few free-swimming rotifers observed
WL #1	<1	Very clear; No particles observed; No organisms observed

Test results have been reviewed and validated by Nancy Fuller.

<sup>1</sup> Total Suspended Solids in *Standard Methods for the Examination of Water and Wastewater*, 18th edition, APHA 2221


<sup>2</sup> Total Suspended Solids Determination, EPS Environmental Services of Laboratory Procedures, Test Method 15, Revision 1.0 February 2000

Prepared and Approved by:



Nancy Fuller  
EPS Environmental Services

Reviewed by:



Carla Krueger  
EPS Environmental Services



Philip Analytical Services Corp

5735 McAdam Road  
Mississauga, Ontario, L4Z 1N9  
tel: (905) 890-8566 fax: (905) 890-8575  
Toll Free: 1-800-263-9040

F a x C o v e r S h e e t

Pages: 3 (including cover sheet)

Please Deliver to: Angela Saranchuk

Dillon Consulting Ltd.  
895 Waverley St.  
Suite 200  
Winnipeg MB  
R3T 5P4

Fax #: 1-204-452-4412

Service Manager: Elaine Grant

Fax #: (905) 890-8575  
Phone:

Final report will be mailed. If this fax is incomplete  
or unreadable, please call the above phone number.

REP227244INORGANIC WT

Dillon Consulting Ltd. Winnipeg, MB	
RECEIVED	
DEC 2 2002	
Proj. No.: 020602	Dis.: JDE
Task No.: 2000	65
File Type: GMS/NEC	FIVE

NOTE: The following information is confidential. If you receive this Fax  
transmission in error, please fax it back, to Nick Boulton's attention, and  
destroy the original. Thank you!

# Philip Analytical Services Corp

## Report of Analysis

Client : Dillon Consulting Ltd.  
 Contact: Angela Sarachuk

Report Date: December 2/2002  
 Lab Ref # : G227244  
 Lab Quote # : W021004  
 Client PO#: 02-0602-1000  
 Client Ref#: 02-0602-1000

### Analysis of Water

Parameter	EQL	Units	SL 1 2002/11/03	SL 1 Replicate	SL 2 2002/11/03	WT 1 2002/11/03	
Mercury	0.0005	mg/L	nd	nd	nd	nd	
Alkalinity(as CaCO <sub>3</sub> )	10	mg/L	120	116	120	107	
Nitrite(as N) and Nitrate(as N)	0.05	mg/L	nd	nd	nd	nd	
Chloride	0.5	mg/L	83.1	84.3	86.1	35.5	
Fluoride	0.1	mg/L	nd	nd	nd	0.1	
Nitrate(as N)	0.2	mg/L	nd	nd	nd	nd	
Sulphate	0.5	mg/L	8.1	7.8	7.9	22.1	
Ammonia(as N)	0.03	mg/L	0.03	0.03	0.03	nd	
Total Organic Carbon	0.2	mg/L	4.2	4.2	4.2	3.5	
Hardness(as CaCO <sub>3</sub> )	1	mg/L	141	146	139	134	
Aluminium	0.005	mg/L	0.007	0.007	0.010	0.019	
Antimony	0.0005	mg/L	nd	nd	nd	nd	
Arsenic	0.002	mg/L	nd	nd	nd	nd	
Barium	0.035	mg/L	nd	nd	nd	0.007	
Beryllium	0.001	mg/L	nd	nd	nd	nd	
Bismuth	0.001	mg/L	nd	nd	nd	nd	
Boron	0.005	mg/L	0.043	0.042	0.043	0.030	
Cadmium	0.0001	mg/L	nd	nd	0.0001	nd	
Calcium	0.5	mg/L	25.0	25.5	25.8	27.2	
Chromium	0.005	mg/L	nd	nd	nd	nd	
Cobalt	0.0001	mg/L	nd	nd	nd	nd	
Copper	0.0005	mg/L	0.0015	0.0016	0.0019	0.0016	
Iron	0.03	mg/L	nd	nd	0.03	0.04	
Lead	0.0025	mg/L	nd	nd	nd	nd	
Magnesium	0.05	mg/L	20.2	20.7	20.6	16.9	
Manganese	0.005	mg/L	nd	nd	nd	nd	
Molybdenum	0.001	mg/L	nd	nd	nd	0.003	

EQL Estimated Quantitation Limit = lowest level of the parameter that can be quantified with confidence.  
 nd parameter not detected ! = EQL higher than listed due to dilution ( ) Adjusted EQL

Philip Analytical Services Corp

# Report of Analysis

Client : Dillon Consulting Ltd.  
Contact: Angela Saranchuk

Report Date: December 2/2002  
Lab Ref # : G227244  
Lab Quote #: W021004  
Client PO#: 02-0602-1000  
Client Ref#: 02-0602-1000

## Analysis of Water

Parameter	EQL	Units	SL 1 2002/11/03	SL 1 Replicate	SL 2 2002/11/03	WL 1 2002/11/03	
Nickel	0.001	mg/L	nd	nd	nd	nd	
Phosphorus	0.05	mg/L	nd	nd	nd	nd	
Potassium	0.1	mg/L	2.7	2.8	2.7	1.9	
Selenium	0.002	mg/L	nd	nd	nd	nd	
Silver	0.0001	mg/L	nd	nd	nd	nd	
Sodium	0.1	mg/L	46.8	47.6	47.5	19.4	
Strontium	0.001	mg/L	0.041	0.042	0.041	0.335	
Thallium	0.0005	mg/L	nd	nd	nd	nd	
Tin	0.001	mg/L	nd	nd	nd	nd	
Tungsten	0.005	mg/L	nd	nd	nd	nd	
Uranium	0.0001	mg/L	0.0004	0.0004	0.0004	0.0010	
Vanadium	0.0005	mg/L	nd	nd	nd	nd	
Zinc	0.005	mg/L	nd	nd	nd	nd	
Bicarbonate(as CaCO <sub>3</sub> , calculated)	1	mg/L	115	115	115	106	
Conductivity - @25°C	1	uS/cm	493	491	502	339	
Total Dissolved Solids	2	mg/L	272	276	262	196	
Total Suspended Solids	1	mg/L	6	7	6	10	
Volatile Suspended Solids	1	mg/L	2	3	2	4	
pH	0.01	Units	8.04	8.06	8.00	7.88	
Colour	3	PCU	12	12	nd	12	
Turbidity	0.2	NTU	0.4	0.4	0.6	0.5	

EQL Estimated Quantitation Limit = lowest level of the parameter that can be quantified with confidence.  
nd parameter not detected L = EQL higher than listed due to dilution ( ) Adjusted EQL



ᓄᓇᓂᓪ: ᓄᓇᓂᓪ ᐃᓄᓪᓂᓪ ᐃᓄᓪᓂᓪ  
ᓄᓇᓂᓪ ᓄᓇᓂᓪ ᓄᓇᓂᓪ

Nunavut: Community Population Estimates

Le Nunavut: Evaluation du nombre  
d'habitants par communautés

1997/1998/1999

**Nunavut Bureau of Statistics**

Bag 800

Iqaluit, Nunavut X0A 0H0

[www.stats.gov.nu.ca](http://www.stats.gov.nu.ca)

## Nunavut: Community Population Estimates

	1997	1998	1999
Nunavut	25,947	26,429	27,039
Arctic Bay	703	709	716
Arviat	1,635	1,640	1,642
Baker Lake	1,427	1,445	1,439
Bathurst Inlet	X	X	X
Bay Chimo	53	51	X
Cambridge Bay	1,386	1,412	1,387
Cape Dorset	1,144	1,159	1,190
Chesterfield Inlet	357	363	363
Clyde River	726	733	752
Coral Harbour	794	823	822
Gjoa Haven	916	941	964
Grise Ford	149	154	145
Hall Beach	580	595	619
Igloolik	1,277	1,307	1,348
Iqaluit	4,352	4,368	4,627
Kimmirut	423	422	440
Kugaaruk	511	526	568
Kugluktuk	1,275	1,321	1,362
Nanisivik	219	243	228
Pangnirtung	1,384	1,429	1,475
Pond Inlet	1,208	1,237	1,276
Qikiqtarjuaq	499	495	508
Rankin Inlet	2,126	2,211	2,230
Repulse Bay	563	582	600
Resolute Bay	202	218	241
Sanikiluaq	680	682	680
Taloyoak	749	762	783
Whale Cove	317	317	308

**Notes:** Population estimates produced by Statistics Canada and the Nunavut Bureau of Statistics include people in the population who are residents of Nunavut and do NOT have a home elsewhere in Canada from which they are temporarily absent. Therefore, temporary residents such as construction crews, residents in mining camps, etc. are not included in the population estimates.

Data are suppressed for (a) communities with a population of 50 or less and (b) 'unorganized areas' -- but they are included in the Nunavut total.



ᓄᓇᓂᓪ: ᓄᓇᓂᓪ ᐃᓄᓪᓂᓪ ᐃᓄᓪᓂᓪᓂᓪ  
ᓇᓇᐃᓪᓂᓪᓂᓪᓂᓪᓂᓪ

Nunavut: Community Population Projections

Le Nunavut: Projections pour la population  
par communautés

2000 – 2020

**Nunavut Bureau of Statistics**

Bag 800

Iqaluit, Nunavut X0A 0H0

[www.stats.gov.nu.ca](http://www.stats.gov.nu.ca)

# Nunavut: Community Population Projections

	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010
Nunavut	27,688	28,410	29,154	29,885	30,601	31,317	32,036	32,774	33,530	34,311	35,114
Arctic Bay	730	747	763	782	801	819	837	855	876	894	916
Arviat	1,690	1,736	1,784	1,833	1,883	1,929	1,982	2,033	2,088	2,142	2,198
Baker Lake	1,470	1,501	1,534	1,563	1,594	1,624	1,655	1,683	1,712	1,745	1,777
Bathurst Inlet	X	X	X	X	X	X	X	X	X	X	X
Bay Chimo	X	X	X	X	X	X	X	X	X	X	X
Cambridge Bay	1,418	1,449	1,484	1,517	1,550	1,581	1,609	1,642	1,679	1,715	1,752
Cape Dorset	1,213	1,240	1,268	1,298	1,327	1,354	1,382	1,412	1,441	1,471	1,501
Chesterfield Inlet	372	382	391	401	409	420	431	443	452	465	476
Clyde River	771	789	812	830	848	867	890	913	937	959	982
Coral Harbour	845	865	888	911	933	955	978	1,003	1,024	1,049	1,078
Gjoa Haven	984	1,005	1,023	1,045	1,063	1,084	1,102	1,117	1,136	1,154	1,173
Grise Ford	145	146	147	146	146	147	149	151	151	153	155
Hall Beach	635	656	677	696	714	734	754	771	790	810	829
Igloolik	1,379	1,417	1,456	1,495	1,529	1,562	1,594	1,627	1,660	1,701	1,736
Iqaluit	4,762	4,930	5,108	5,278	5,438	5,606	5,768	5,936	6,108	6,289	6,477
Kimmiut	450	461	474	485	496	506	519	530	546	560	573
Kugaaruk	582	601	616	631	648	664	682	701	719	737	756
Kugluktuk	1,389	1,422	1,456	1,490	1,522	1,556	1,585	1,618	1,653	1,686	1,720
Nanisivik	230	225	224	226	225	223	222	220	221	221	220
Pangnirtung	1,506	1,539	1,575	1,613	1,651	1,687	1,722	1,756	1,792	1,831	1,870
Pond Inlet	1,314	1,361	1,405	1,443	1,489	1,532	1,574	1,624	1,668	1,714	1,761
Qikiqtarjuaq	522	537	551	566	582	599	614	629	641	654	668
Rankin Inlet	2,277	2,327	2,376	2,432	2,483	2,527	2,576	2,629	2,683	2,734	2,791
Repulse Bay	615	630	648	664	682	702	720	738	757	777	797
Resolute Bay	243	246	247	249	251	253	252	255	257	260	263
Sanikiluaq	702	722	740	758	776	796	816	834	853	873	896
Taloyoak	804	825	847	866	886	904	925	947	968	992	1,016
Whale Cove	312	321	328	336	344	351	358	367	378	388	397

**Notes:** Population projections produced by Statistics Canada and the Nunavut Bureau of Statistics include people in the population who are residents of Nunavut and do NOT have a home elsewhere in Canada from which they are temporarily absent. Therefore, temporary residents such as construction crews, residents in mining camps, etc. are not included in the population projections.

Data are suppressed for (a) communities with a population of 50 or less and (b) 'unorganized areas' -- but they are included in the Nunavut total.

**APPENDIX C – Inspection Reports**  
**INAC**  
**Health and Social Services**





**Nunavut Government**  
**Department of Health and Social Services**

**Kitikmeot Regional Office**

Box 83, Cambridge Bay, Nunavut, (NU) X0B 0C0 Tel: (867) 983-4076 Fax: (867) 983-4063

July 8, 2002

Raymond Kamookak  
Senior Administrative Officer  
Hamlet of Gjoa Haven  
Gjoa Haven, NU

**FAXED**  
July 7, 2002

**Re: Public Health Audit**

In accordance with the Public Health Act of Nunavut, inspections were conducted of Gjoa Haven's public buildings and municipal services on June 17<sup>th</sup> to 21<sup>st</sup>, 2002. The following observations and recommendations are offered to assist in rectifying conditions that might impact on public health.

**Airport Terminal Building**

Continue to service the airport washrooms, and all public washrooms on a daily basis. Clean and sanitize the plumbing fixtures, and replenish the paper towels, toilet tissue, and dispensed soap container.

**Sewage Lagoon**

A large breach was noted in the berm wall of the sewage lagoon permitting the effluent to continually discharge. It is recommended that the breach be repaired to increase the retention and treatment time. The capacity of the lagoon should be such that winter storage is possible as very little treatment takes place during this period. It takes one to two months after spring breakup to achieve the required treatment. The sewage effluent might then be discharged in the fall.

**Solid Waste Disposal**

Domestic waste is strewn over a large area instead of being confined to a smaller, more manageable cell. The waste should be bulldozed to the rear of the site, compacted and covered with available cover material.

The hazardous waste disposal area also requires your attention. Several waste drums need to be uprighted, and waste batteries need to be stacked two high on wooden pallets.

- 2 -

Community Drinking Water

The free available chlorine was measured in the water trucks on June 18<sup>th</sup> at 0.65 mg/l. Although this concentration affords good protection of the water throughout the distribution system, the Public Water Supply Regulations specify 0.2 mg/l after twenty minutes of contact time.

The Regulations also specify that all chlorination equipment must be installed in duplicate in order to provide standby units for ensuring uninterrupted operation. Only one chlorinator was noted at the time of inspection.

Dog Control

In the event of a biting incident, the Nunavut protocol is to quarantine the dog away from other animals and people for 10 days to observe it for signs of rabies. This is difficult when a dog pen is not available. It is therefore recommended that the Hamlet construct a pound to accommodate two or three dogs for this purpose. The individual pens must be constructed so that one dog does not have direct contact with another.

Swimming Pool

I understand that the pool will not be used this season and that it will eventually be relocated and housed in its own building. Once plans are underway to construct this building, the design will need to be reviewed and approved by this office in accordance with the Public Pool Regulations.

Should you have any questions or comments regarding this matter or the environmental health program, please do not hesitate to contact me at (867) 983-4086.



Robert Phillips, CPHI(C)  
Regional Environmental Health Officer



Indian and Northern  
Affairs Canada  
www.inac.gc.ca

Affaires indiennes  
et du Nord Canada  
www.ainc.gc.ca

INAC, Nunavut District Office  
P.O. Box 100  
Iqaluit, NU  
X0A 0H0

INTERNAL	
PC	JP
LA	
OM	
TA	
BS	
ST	copy
ED	
CEO	
BRD	
EXT.	

Tel.: (867) 975-4298  
Fax.: (867) 979-6445

December 29, 2002

NWB3-GJO9904

Raymond Kamootak  
Senior Administrative Officer  
Hamlet of Gjoa Haven  
General Delivery  
Gjoa Haven, NU X0B 1J0

Nunavut Water  
Board

FEB 21 2003

Public Registry

**RE: August 22, 2002 Municipal Water Use Inspection - Report**

The Water Resources Officer (WRO) appreciate the assistance provided during the tour of the Hamlet's water use and waste disposal facilities. Enclosed for your records is a copy of the Municipal Water Use Inspection Report performed on August 22, 2002. During the inspection the following observations were noted.

- ☐ **Water Supply:** The Water Lake Intake Facility requires some maintenance to the conveyance line (Photo 1 & 6). A motor boat was observed next to Water Lake Water Intake Facility (Photo 2). The filtration system at the Water Treatment Facility was not in use at the time of inspection. (Photo 3). Of major concern was the presents of Blood Worms in the potable water, given the filtration system at the Water Treatment Plant was not in use. The chlorination system located at the Water Treatment Plant was in use at the time of inspection (Photo 4 & 5). Enclosed analysis of samples taken at the Water Intake Facility (SNP) GJO-1 indicate that Nitrate + Nitrite (<0.008 mg/L vs 3.2 mg/L), pH (7.95 vs 6.5-8.5) and Colour (10 TCU vs 15 TCU) are within the *Guidelines for Canadian Drinking Water Quality*.
- ☐ **Sewage Disposal Facility:** The Sewage Lagoon had sufficient free board at the time of inspection (Photo 11). A large breach in the Sewage Lagoon berm allowed for continual sewage effluent to be discharged (Photo 12). The Lagoon effluent is discharged over land prior to entering the ocean. Enclosed analysis of samples taken from (SNP) GJO-3 the Sewage Lagoon discharge indicate that Total Suspended Solids (59 mg/L vs 120 mg/L) and pH ( 7.47 vs 6-9 ) meet the *Municipal Wastewater Effluent Quality Guidelines*. However analysis of Total Ammonia indicate that (101 mg/L vs 2.2 mg/L) is in excess of *Municipal Wastewater Effluent Quality Guidelines*.

Canada


- ☐ **Solid Waste Disposal Facility:** The Solid Waste Disposal Facility has a fence surrounding most of the dump. The dump has a large breach in the fence and the berm ( Photo 7). Staining was noted indicating a seepage path. Waste oil storage at Solid Waste Disposal Facility. Enclosed analysis of samples taken of (SNP) GJO-2 dump seepage, indicate that Total Suspended Solids (405 mg/L vs 120 mg/L) Total Ammonia concentration of (40.2 mg/L vs 2.2 mg/L) are in excess of *Municipal Wastewater Effluent Quality Guidelines* . All waste oil is drummed and stored at the Solid Waste Disposal Facility (Photo 8). The Solid Waste Disposal Facility seemed well managed with segregation of waste and signs posted at the dump.
- ☐ **Bulky Metal Dump:** The bulky metal dump was partially segregated diverting bulky waste from the general dump area (Photo 10). The creek alongside the bulky metal dump was sampled (Photo 9). Analysis of samples taken at the Bulky Metal Dump have not been received by the WRO, these sample results will be made available once received by the WRO.

**Fuel Storage:** At the time of inspection the berm surrounding the Tank Farm appeared to be in good condition with no breaches. The containment liner of the berm was not visible (Photo 14). There is a drainage hose that was left not unattended that should be removed (Photo 13).

- ☐ **Non-Compliance of Act or Licence:** The licensee has yet to provide Nunavut Water Board with Annual Reports from 1999, 2000, 2001. An Operational & Management (O&M) plan for the waste disposal facilities has yet to be submitted, so has an report detailing the Abandonment and Restoration (A&R) of municipal water and waste facilities.

If there are any concerns or questions in regards to this inspection, please contact me at (867) 975 4298 or [bodykevichc@inac.gc.ca](mailto:bodykevichc@inac.gc.ca).

Sincerely,

  
Constantine Bodykevich  
Water Resources Officer (WRO)  
INAC, Nunavut District

- cc. -Nunavut Water Board, Gjoa Haven (Jim Wall)  
-CG&T, Rankin Inlet (Don Forsyth)  
- Keewatin Health & Social Services, Rankin Inlet (Robert Phillips)  
- EC Environmental Protection, Yellowknife (Anne Wilson)  
- INAC Water Management, Iqaluit (Michelle Mc Christie)



Affaires Canada  
www.inac.gc.ca

et du Nord Canada  
www.ainc.gc.ca

## MUNICIPAL WATER USE INSPECTION REPORT

Date: August 22, 2002 Licensee Rep. (Name/Title): Rannond Kamookak/ SAO  
Licensee: Hamlet of Gjoa Haven Licence No.: NWB3-GJO9904

### WATER SUPPLY

Source(s): Water Lake / Swan Lake (source) Quantity used: recorded at truck  
Owner/Operator: Hamlet of Gjoa Haven

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected  
Intake Facilities: U Storage Structure: A Treatment Systems: U Chemical Storage: A  
Flow Meas. Device: NA Conveyance Lines: U Pumping Stations: U

Comments: Conveyance line from Water Lake Water Intake Facility to the Water Filtration Plant requires maintenance due to line damage at Water Intake Facility. Water Treatment Plant filter system presently not in use. Bloodworms present in potable water.

### WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Secondary; over land to ocean.  
Natural Water Body: Continuous Discharge (land or water): land  
Seasonal Discharge: X Wetlands Treatment: limited Trench:  
Solid Waste: Owner/Operator: Hamlet of Gjoa Haven  
Landfill: Burn & Landfill: X Other:

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected  
Discharge Quality: Sampled Decant Structure: NA Erosion: U  
Discharge Meas. Device: NIL Dyke Inspection: U Seepages: U  
Dams, Dykes: A Freeboard: A Spills: NIL  
Construction: NA O&M Plan: U A&R Plan: NIL  
Periods of Discharge: A Effluent Discharge Rate: Not Measured

Comments: There is adequate freeboard in the Sewage Lagoon. A breach in the berm is allowing considerable effluent seepage, causing accelerated erosion and exposure of the containment liner at the Sewage Lagoon discharge site. There is a large breach in the Solid Waste Disposal Facility fence and berm. Dump seepage has caused considerable staining along the discharge path. Waste oil is stored at the Solid Waste Disposal facility. Some segregation of waste is practices at the bulky metal dump. Waste batteries require spill protection in the current storage area.

### FUEL STORAGE

Owner/Operator:  
Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected  
Berms & Liners: A Water within Berms: A Evidence of Leaks: A  
Drainage Pipes: U Pump Station & Catchment Berm: NA  
Pipeline Condition: NI Not Applicable: Condition of Tanks: NI

### SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected Hamlet: NIL

INAC: GJO-1 potable water, sewage effluent GJO-3 and dump seepage GJO 2

Signs Posted SNP: NIL

Warning:

Records & Reporting: No 1999, 2000, 2001 Annual Reports or Operational Maintenance plan.

Geotechnical Inspection: Not Applicable

Non-Compliance of Act or Licence: Operational & Management plan required for municipal waste disposal facilities since 1999/07/07. Annual Reports required for 1999, 2000 & 2001.

Constantine Rodkevich

CR



Indian and Northern  
Affairs Canada  
[www.inac.gc.ca](http://www.inac.gc.ca)

Affaires indiennes  
et du Nord Canada  
[www.ainc.gc.ca](http://www.ainc.gc.ca)

## Global Positioning System Coordinates for the Municipality of Gjoa Haven

### **Gjoa Haven-01**

Gjoa Haven Pot Water 01

N68.38037 W95.52088

### **Gjoa Haven-02**

Gjoa Haven Dump-02

N68.37013 W95.50247

### **Gjoa Haven-3**

Gjoa Haven Sewage Lagoon-3

N68.37235 W95.50236

Canada

# Gjoa Haven Inspection pictures 2002



Photo # 1 Damaged section of conveyance line from Water Intake Facility




Photo # 2 Water reservoir with water intake facility in left of photo.




Photo # 3 Sand filters at Gjoa Haven Water Treatment Facility. Not in use at the time of this inspection.




Photo # 4 Chlorination system in place at Gjoa Haven Water Treatment Facility.






Photo # 5 Water Treatment Facility and truck fill station.




Photo # 6 Water Lake with Water Intake Facility and conveyance line seen to the left of the picture.



Photo # 7 Seepage from Solid Waste Disposal Facility; note a breach in the landfill berm and fencing, location of landfill seepage sample.




Photo # 8 Waste oil storage area in Solid Waste Disposal Facility.



Photo # 9 Creek by bulky metal waste dump; location of metal dump sample.




Photo # 10 Bulky metal dump showing segregation of waste streams.



Photo # 11 Sewage truck discharge structure at Sewage Treatment Facility.



Photo # 12 ewage seepage noted at partial breach in Sewage Treatment Facility berm;  
location of sewage effluent sample.



Photo # 13 Tank Farm, showing drainage hose in berm area.




Photo # 14 Drum storage area at Tank Farm.



**Taiga Environmental Laboratory**  
4601-52nd Ave., Box 1500, Yellowknife, NT, X1A 2R3

Tel: (867)-669-2788  
Fax: (867)-669-2718

## - CERTIFICATE OF ANALYSIS -

Prepared For: DIAND Nunavut District Office

Attn: Constantine Bodykevi

Sample ID: Gjoa Haven pot water 650-1

Taiga Sample ID: 222515

Client Project:

Sample Type: potable

Received Date: 26-Aug-02

Location: Gjoa Haven pot water

Sampling Date: 19-Aug-02

Report Status: Final

Approved by: \_\_\_\_\_

Test Parameter	Result	Units	Detection Limit	Analysis Date	Data Qualifier
<u>Physicals</u>					
Alkalinity	77.9	mg/L	0.3	16-Sep-02	
Colour	10		5	16-Sep-02	
Conductivity, Specific	246	µS/cm	0.3	16-Sep-02	
pH	7.95	pH units	0.05	16-Sep-02	
Solids, Total Dissolved	178	mg/L	10	16-Sep-02	
Solids, Total Suspended	<3	mg/L	3	16-Sep-02	
Turbidity		NTU	0.1	17-Sep-02	14
<u>Nutrients</u>					
Ammonia as N	0.010	mg/L	0.005	02-Sep-02	
Nitrate+Nitrite as N	<0.008	mg/L	0.008	05-Sep-02	
Organic Carbon, Total	3.4	mg/L	0.5	07-Oct-02	
Phosphorous, Dissolved	0.066	mg/L	0.004	04-Sep-02	
Phosphorous, Total	0.071	mg/L	0.004	04-Sep-02	
<u>Major Ions</u>					
Calcium	19.1	mg/L	0.05	29-Aug-02	

Report Date: Wednesday, January 22, 2003

Page 17 of 33



**Taiga Environmental Laboratory**  
1601 52nd Ave., Box 1500, Yellowknife, NT. X1A 2P3

Tel: (867)-669-2788  
Fax: (867)-669-2718

## - CERTIFICATE OF ANALYSIS -

Prepared For: DIAND Nunavut District Office

Attn: Constantine Bodykevi

Sample ID: Gjoa Haven pot water **GJO-1**

Taiga Sample ID: 222515

Chloride~	19.7	mg/L	0.2	06-Sep-02
Hardness as CaCO3	96.9	mg/L	0.17	29-Aug-02
Magnesium	12.0	mg/L	0.02	29-Aug-02
Potassium	1.50	mg/L	0.03	28-Aug-02
Sodium	11.2	mg/L	0.02	28-Aug-02
Sulphate	18	mg/L	3	04-Sep-02

### Data Qualifier Descriptions:

14 Insufficient sample to perform analysis



**Taiga Environmental Laboratory**  
4601-52nd Ave., Box 1500, Yellowknife, NT. X1A 2R3

Tel: (867)-669-2788  
Fax: (867)-669-2718

## - CERTIFICATE OF ANALYSIS -

Prepared For: DIAND Nunavut District Office

Attn: Constantine Bodykevi

Sample ID: Gjoa Haven

650-3

Taiga Sample ID: 222516

Client Project:

Sample Type: sewage

Received Date: 26-Aug-02

Location: Gjoa Haven sewage

Sampling Date: 19-Aug-02

Report Status: Final

Approved by: \_\_\_\_\_

Test Parameter	Result	Units	Detection Limit	Analysis Date	Data Qualifier
<b>Physicals</b>					
Alkalinity	777	mg/L	0.3	19-Sep-02	
Colour	300		5	16-Sep-02	
Conductivity, Specific	1950	µS/cm	0.3	16-Sep-02	
pH	7.47	pH units	0.05	16-Sep-02	
Solids, Total Dissolved	1000	mg/L	10	16-Sep-02	
Solids, Total Suspended	59	mg/L	3	16-Sep-02	
Turbidity	42.4	NTU	0.1	17-Sep-02	
<b>Nutrients</b>					
Ammonia as N	101	mg/L	0.005	02-Sep-02	
Nitrate+Nitrite as N	0.017	mg/L	0.008	05-Sep-02	
Organic Carbon, Total	84	mg/L	0.5	07-Oct-02	
Phosphorous, Dissolved	14.7	mg/L	0.001	04-Sep-02	
Phosphorous, Total	15.4	mg/L	0.004	04-Sep-02	
<b>Major Ions</b>					
Calcium	43.8	mg/L	0.05	29-Aug-02	

Report Date: Wednesday, January 22, 2003

Page 19 of 33





**Taiga Environmental Laboratory**  
4601-52nd Ave., Box 1500, Yellowknife, NT. X1A 2R9

Tel: (867)-669-2788  
Fax: (867)-669-2718

**- CERTIFICATE OF ANALYSIS -**

Prepared For: DIAND Nunavut District Office

Attn: Constantine Bodykevi

Sample ID: Gjem Haven

650-3

Taiga Sample ID: 222316

Chloride	133	mg/L	0.2	06-Sep-02
Hardness as CaCO <sub>3</sub>	262	mg/L	0.17	29-Aug-02
Magnesium	37.0	mg/L	0.02	28-Aug-02
Potassium	45.5	mg/L	0.03	28-Aug-02
Sodium	175	mg/L	0.02	28-Aug-02
Sulphate	11	mg/L	3	04-Sep-02

Data Qualifier Descriptions:

Report Date: Wednesday, January 22, 2003

Page 20 of 33



**Taiga Environmental Laboratory**  
4601-52nd Ave., Box 1500, Yellowknife, NT, X1A 2R3

Tel: (867) 669-2788  
Fax: (867) 669-2718

## - CERTIFICATE OF ANALYSIS -

Prepared For: DIAND Nunavut District Office

Attn: Constantine Bodykevi

Sample ID: GJO-2

Taiga Sample ID: 222517

Client Project:

Sample Type: dump

Received Date: 26-Aug-02

Location: Gjoa Haven

Sampling Date: 19-Aug-02

Report Status: Final

Approved by: \_\_\_\_\_

Test Parameter	Result	Units	Detection Limit	Analysis Date	Data Qualifier
<u>Physicals</u>					
Solids, Total Dissolved	2300	mg/L	10	16-Sep-02	
Solids, Total Suspended	405	mg/L	3	16-Sep-02	
Turbidity	682	NTU	0.1	17-Sep-02	
<u>Nutrients</u>					
Ammonia as N	40.2	mg/L	0.005	02-Sep-02	
Nitrate+Nitrite as N	0.036	mg/L	0.008	05-Sep-02	
Organic Carbon, Total	72	mg/L	0.5	07-Oct-02	
Phosphorous, Dissolved	0.128	mg/L	0.004	04-Sep-02	
Phosphorous, Total	1.73	mg/L	0.004	04-Sep-02	

Data Qualifier Descriptions:

Report Date: Wednesday, January 22, 2003

Page 21 of 33



## MUNICIPAL WATER USE INSPECTION FORM

Date: 2001/08/13 Licensee Rep. (Name/Title): Jacob Keanik / Foreman  
Licensee: Hamlet of Gjoa Haven Licence No.: NWB3GJO9904

### WATER SUPPLY

Source(s): Water Lake / Swan Lake (recharge) Quantity used: recorded @ truck delivery  
Owner/Operator: Hamlet

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected  
Intake Facilities: U Storage Structure: NA Treatment Systems: A Chemical Storage: A  
Flow Meas. Device: NA Convey. Lines: U Pumping Stations: U

Comments: No appreciable improvement noted in regards to the derelict status of the water intake and supply facilities; renewed conveyance line freeze up problems and bloodworm complications. Water Lake to be recharged from Swan Lake in late summer and/or early fall. Chlorination in use. Filtration system still bypassed.

### WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec./Ter.): primary; discharge overland to ocean  
Natural Water Body: Continuous Discharge (land or water):  
Seasonal Discharge: x Wetlands Treatment: limited Trench:  
Solid Waste: Owner/Operator: Hamlet

Landfill: Burn & Landfill: x Other:  
Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected  
Discharge Quality: sampled Decant Structure: U Erosion: U  
Discharge Meas. Device: none Dyke Inspection: NA Seepage: A  
Dams, Dykes: A Freeboard: U Spills: none reported  
Construction: NA O&M Plan: U A&R Plan: none  
Periods of Discharge: A Effluent Discharge Rate: not measured

Comments: Significant cleavage, and signs of erosion, of the sewage lagoon berm in the decanting area; slight flow from one of the two notches in the berm. Lack of freeboard in decanting area abridges retention time. Solid waste disposal facility is now fenced, although a gap in the section where the berm lowers creates a decant/runoff channel; no flow noted but an obviously strained path of leachate could be observed. Pooled water still lies in the middle of the wastepile. Household waste is regularly burnt and compacted towards the toe of the facility, but not covered; exposed waste covers an extensive area. Bulky metal wastes, hazardous materials and waste oil segregated; notable ground contamination in the waste oil storage area. Outstanding O&M plan.

### FUEL STORAGE

Owner/Operator:  
Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected  
Berms & Liners: Water within Berms: Evidence of Leaks:  
Drainage Pipes: Pump Station & Catchment Berm:  
Pipeline Condition: Not Applicable: x Condition of Tanks:

### SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected Hamlet: none  
INAC: raw water @ Water Lake (GJO-1); sewage discharge @ 10 m below decant  
Signs Posted SNP: no Warning: yes  
Records & Reporting: No 1999, 2000 Annual Reports; no O&M plan  
Geotechnical Inspection: not applicable

Non-Compliance of Act or Licence: 1999 and 2000 Annual Reports not submitted; respectively due by 2000/03/31 and 2001/03/31. Operation and Management (O&M) plan for the municipal waste disposal facilities overdue since 1999/07/07.

Philippe Lavallée

Inspector's Name

Inspector's Signature




figure 1. Water intake facilities at the municipal water supply; 2001/08/13.




figure 2. Sewage disposal facility, from the decant area; 2001/08/13.






figure 4. Solid waste disposal facility; 2001/08/13.



figure 5. Pooled water along the toe of the solid waste disposal facility; 2001/08/13.



figure 6. Leachate from the toe of the solid waste disposal facility; 2001/08/13.




figure 7. Path of runoff from the solid waste disposal facility; 2001/08/13.





figure 8. Bulky metal wastes disposal site; 2001/08/13.





Taiga Environmental Laboratory  
4601-52nd Ave., Box 1500, Yellowknife, NT. X1A 2R3

Tel: (867)-669-2788  
Fax: (867)-669-2718

- CERTIFICATE OF ANALYSIS -

Prepared For: Nunavut District Office

DIAND, Operations

Attn: Philippe Lavallee

Sample ID: raw water GJO-1

Taiga Sample ID: 212061

Client Project:

Sample Type: raw water

Received Date: 14-Aug-01

Location: Ghoo Haven

Sampling Date: 13-Aug-01

Report Status: Final


Approved by:

Lab Section	Test Parameter	Result	Units	Detection Limit	Analysis Date
Major Ions	Sodium	10.3	mg/L	0.02	15-Aug-01
Microbiology	Coliforms, Fecal	<1	CFU/100mL	1	14-Aug-01
Nutrients	Ammonia as N	0.013	mg/L	0.005	30-Aug-01
	Biological Oxygen Demand	<2	mg/L	2	14-Aug-01
	Nitrate+Nitrite as N	0.016	mg/L	0.008	21-Aug-01
Physicals	Colour	5		5	15-Aug-01
	Solids, Total Dissolved	139	mg/L	10	04-Sep-01
	Turbidity	1.0	NTU	0.1	15-Aug-01
Subcontract	Chloride	16.0	mg/L	0.1	30-Aug-01
	Sulphate	18.0	mg/L	0.3	30-Aug-01
Total Metals	Arsenic	<1.0	µg/L	1	07-Sep-01
	Cadmium	<0.3	µg/L	0.3	21-Aug-01
	Chromium	<3	µg/L	3	21-Aug-01
	Cobalt	<1	µg/L	1	21-Aug-01
	Copper	<2	µg/L	2	21-Aug-01
	Iron	<30	µg/L	30	20-Aug-01

Report Date: Monday, September 24, 2001

Page 1 of 2

RECEIVED  
SEP 24 2001



Taiga Environmental Laboratory  
4601-52nd Ave., Box 1500, Yellowknife, NT. X1A 2R3

Tel: (867)-669-2788  
Fax: (867)-669-2718

- CERTIFICATE OF ANALYSIS -

Prepared For: Nunavut District Office

DIAND, Operations

Attn: Philippe Lavallee

Sample ID: raw water GJO-1

Taiga Sample ID: 212061

Total Metals	Lead	<1	µg/L	1	21-Aug-01
	Manganese	10	µg/L	1	21-Aug-01
	Mercury	<0.01	µg/L	0.01	13-Sep-01
	Nickel	2	µg/L	1	21-Aug-01
	Zinc	15	µg/L	10	21-Aug-01

Field Data (01/08/13) GJO-1


Temperature: 14.5 °C

Conductivity: 245 µS/cm

pH: 8.4

Time: 13:26





Taiga Environmental Laboratory  
4601-52nd Ave., Box 1500, Yellowknife, NT. X1A 2R3

Tel: (867)-669-2788  
Fax: (867)-669-2718

## - CERTIFICATE OF ANALYSIS -

Prepared For: Nunavut District Office

DIAND, Operations

Attn: Philippe Lavallee

Sample ID: Sewage Discharge GJO-3

Taiga Sample ID: 212062

Client Project:

Sample Type: sewage

Received Date: 14-Aug-01

Location: Ghoo Havan

Sampling Date: 13-Aug-01

Report Status: Amended

Approved by:

Lab Section	Test Parameter	Result	Units	Detection Limit	Analysis Date
Microbiology	Coliforms, Fecal	3000	CFU/100mL	1	14-Aug-01
Nutrients	Ammonia as N	2.66	mg/L	0.005	30-Aug-01
	Biological Oxygen Demand	326	mg/L	2	14-Aug-01
	Nitrate+Nitrite as N	0.017	mg/L	0.008	21-Aug-01
	Phosphorous, Total	12.2	mg/L	0.004	16-Aug-01
Physicals	Solids, Total Suspended	271	mg/L	3	04-Sep-01
Subcontract	Phenols	1.0	µg/L	0.5	22-Aug-01

Field Data (01/08/13) GJO-3

Temperature: 12.5 °C

Conductivity: 838 µS/cm

pH: 10.4

Time: 13:43

Report Date: Monday, September 17,

Page 1 of 1

# REPORT OF TOXICITY USING MICROTOX

## COMPANY/LOCATION:

GJO-3 Lagoon Discharge, 212062

Sample Collected By: Philippe Lavallee

Date/Time Sampled: August 13, 2001 13:43

Date/Time Received: August 15, 2001

Date/Time Test Start: August 15, 2001

Sample Type: Elutriate  
Sampling Method: Grab

## Method:

Environment Canada Laboratories SOP#830.0 Revision 1, for Microtox Testing in Compliance with November 1992: Biological Test Method: Toxicity Test Using Luminescent Bacteria Photobacterium phosphoreum, November 1992, EPS 1/RM/24.

Environment Canada has conducted testing on the material sampled according to its own Microtox standards procedures. The data proceeding from that testing is intended as a preliminary screening tool only, and cannot be used for any other purpose. This data is provided on the condition that it not be used in any report that is intended for public or official use.

**RESULTS:** TOXIC - IC<sub>50</sub> Concentration: 53.2% (Toxic 0 to 50%)

## TEST ORGANISMS:

Species: Vibrio fischeri (Photobacterium phosphoreum)  
Test Apparatus: Model 500 Analyzer

## TEST SUBSTANCE/CONDITIONS

pH of Sample: (No pH adjustment)

Lot # of Osmotic Adjusting Solution: OAS007

Sample Appearance: no colour adjustment

Lot # of Reconstitution Solution: RSN099Y

Lot # of Diluent: DIL034L

## TEST METHODS AND CONDITIONS

Test Start Date/Time: August 15, 2001 / 02:10 PM

Test Method: Basic 45% Test, 15 minute incubation.

## QUALITY CONTROL

Reference Toxicant: Zinc Sulfate Standard

Reagent Lot #: ACV026-6

IC<sub>50</sub> - 15 minutes mg/L: 2.4 mg/L

IC<sub>50</sub> Confidence Range: 1.6 to 3.6 mg/L

TEST ANALYST: Ron Bujold

INITIAL: LB

## **APPENDIX D**

### **Geotechnical Evaluation Report**

GJOA HAVEN SEWAGE LAGOON  
AND  
SOLID WASTE DISPOSAL FACILITY  
PRELIMINARY GEOTECHNICAL EVALUATION

Submitted  
to  
STANLEY ASSOCIATES ENGINEERING LTD.

Thurber Consultants Ltd.  
Calgary, Alberta

M.C. Harris, P.Eng.  
Review Principal

A handwritten signature in dark ink, appearing to read 'L.B. Smith', is located in the lower right quadrant of the page. The signature is fluid and cursive.

April, 1985  
File: 17-308-14

L.B. Smith, P.Eng.  
Project Engineer

## TABLE OF CONTENTS

	Page
1.0 INTRODUCTION .....	1
1.1 General .....	1
1.2 Project Background .....	1
2.0 SITE CONDITIONS .....	2
3.0 SOLID WASTE DISPOSAL FACILITY .....	3
3.1 Landfill Construction .....	3
3.2 Site Drainage .....	3
4.0 SEWAGE LAGOON .....	4
4.1 Lagoon Construction .....	4
4.2 Lagoon Watertightness .....	4
4.3 Lagoon Sideslopes .....	7
4.4 Freeboard and Crest Width .....	7
4.5 Discharge Ditch .....	8
4.6 Truck Discharge .....	8
4.7 Wind Erosion .....	8
4.8 Fence Design .....	8
5.0 ROAD DESIGN AND CONSTRUCTION .....	10
6.0 GEOTECHNICAL REVIEW .....	11
APPENDIX A Test Pit Logs Grain Size Analyses	

2015A



## SECTION 1

### INTRODUCTION

#### 1.1 General

This report presents a geotechnical evaluation of a proposed sewage lagoon and solid waste disposal facility to be constructed in Gjoa Haven, N.W.T. The evaluation is based on a description of the proposed facilities as presented in the following pre-design reports, which were prepared by Stanley Associates Engineering Ltd. and submitted to the Department of Public Works, Government of the Northwest Territories:

- . Sewage Disposal Facilities, Gjoa Haven, N.W.T.
- . Design and Operation Concept Report, Gjoa Haven Solid Waste Disposal

#### 1.2 Project Background

The proposed facilities are located adjacent to one another about 1.5 km southeast of the settlement. A field investigation for the solid waste facility was carried out by project personnel from Stanley Associates in August, 1984. The site investigation included the excavation of 4 test pits at the proposed site for the waste disposal facility. The test pit logs are presented in Appendix A. Disturbed soil samples from the test pits were submitted to Thurber Consultants for grain size analyses and permeability testing.

Subsequent to the field investigation it was decided to locate the sewage lagoon adjacent to the solid waste disposal facility. It is understood that no test pits or test holes have been drilled at the location for the proposed sewage lagoon. An examination of the airphotographs indicates that the near surface soils at the lagoon site are similar to those encountered at the site for the solid waste facility.

A more complete description of the proposed sewage lagoon, solid waste disposal facility and access road is presented in the pre-design reports prepared by Stanley Associates.

## SECTION 2

### SITE CONDITIONS

The near surface soils at Gjoa Haven consist primarily of sands and gravel. These materials are underlain by limestone bedrock. The depth to bedrock at the location for the proposed sewage lagoon and solid waste disposal facility are not known.

Gjoa Haven is located within the continuous permafrost zone. The depth of the active layer ranges from 1 to 1.5 m, depending primarily on the water content of the near surface soils.

Sand and gravel and occasional cobbles were encountered in the test pits excavated at the site for the solid waste disposal facility. Permafrost was encountered at a depth of 1.2 m below grade and it was not possible to excavate below this depth with the available equipment.

In the vicinity of Gjoa Haven, groundwater is usually present within the active layer, depending on local topography. Groundwater is generally contained by the impervious permafrost below the active layer. Groundwater was encountered in two of the test pits excavated at the site for the solid waste facility at depths of 1.0 and 0.8 m below ground surface.

The near surface sands and gravels are relatively clean and therefore pervious. A permeability of  $1 \times 10^{-2}$  cm/sec was measured in a laboratory falling head test on a disturbed sample of sand taken from Test Pit 4. This value for permeability is consistent with the grain size distribution of the sample.

## SECTION 3

### SOLID WASTE DISPOSAL FACILITY

#### 3.1 Landfill Construction

It is understood that the operation of the landfill will require the excavation of a cell about 2.2 m deep, 5 m wide and 50 m long. The cells would have to be excavated progressively as the ground thaws over the summer. The excavated material would be used to bury the waste from the previous year. It is considered practical to progressively excavate the permafrost to a depth of 2.2 m over one summer, provided excavations were commenced early in each thaw season.

#### 3.2 Site Drainage

Site drainage is a major concern in the operation of the landfill site. Water will enter the landfill area through the active layer from the area upslope from the landfill. Surface runoff can also be expected to collect in the operating disposal trench. The proposed layout for the facility, as described in the pre-design report, appears to ensure that the water will be collected and drained away from the landfill. It should be recognized, however, that leachate from the solid waste disposal facility will flow into the proposed drainage system.

Annual maintenance of permanent drainage ditches may be required, depending on the volume of water which flows in the ditches. Rip rap armour protection may be required in locations where severe erosion occurs.

It is recommended that all permanent sideslopes for berms and ditches be constructed at a slope of 3 horizontal to 1 vertical in order to minimize surface erosion of the sideslopes. Temporary sideslopes for the disposal trenches could be constructed at 2 horizontal to 1 vertical, however some erosion and sloughing may occur.





## SECTION 4

### SEWAGE LAGOON

#### 4.1 Lagoon Construction

It is understood that the lagoon will be constructed using a bulldozer to excavate the material as it thaws. It should be possible to excavate the full depth of the lagoon (about 2 to 3 metres) over a single thaw season using this approach. It would be essential, however, to commence excavation in early July. The lagoon berms would be formed from the excavated sand. Care will be required to ensure that the sand is adequately drained so that it can be compacted properly as the berms are formed. It is not known what equipment will be available in the community for compaction and this aspect should be investigated further.

Water from the active layer will probably flow into the excavation as the work proceeds. This water will have to be removed either by pumping from sumps or by excavating a temporary drainage ditch through the lagoon berms.

The depth to bedrock on the lagoon site is not known. There is a risk that bedrock will be encountered within the depth of excavation. If this is the case, it may be necessary to blast the bedrock, or alternatively set the design base of excavation higher and import material for the construction of the lagoon berms. In order to reduce the risk of encountering bedrock within the excavation it is recommended that test holes or test pits be excavated at the site. If neither of these alternatives is possible, it is recommended that contingency plans be made to cover the possibility of encountering bedrock.

#### 4.2 Lagoon Watertightness

Watertightness of the lagoon is a major concern for two reasons:

- . It is important to prevent water from the surface and within the active layer from flowing into the lagoon and filling it.
- . It is important to prevent sewage effluent from leaking out of the lagoon in an uncontrolled manner.



It is understood that 3 alternatives are being considered in order to make the lagoon watertight.

- . permafrost
- . berm cutoff
- . full membrane liner

#### 4.2.1 Permafrost

If the lagoon were constructed so that the permafrost around the lagoon was higher than the maximum water level in the lagoon, then the permafrost would render the lagoon watertight. There are a number of concerns with this approach which should be addressed:

- 1) Depending on the configuration of the lagoon, water from the active layer could still flow into the lagoon during the summer months.

While permafrost will aggrade upwards into the reservoir berms, it is doubtful that the berms will become impervious. This is because the above grade portion of the berms will not be fully saturated, and will therefore be pervious. Water from the lagoon will leak through the berms and will form preferred seepage paths through the berm which will probably pipe and result in failure of the berm. It is unlikely that the seepage from the lagoon will freeze in the berms and make them impervious.

- 2) In view of the foregoing, the only feasible method of using the permafrost to make the lagoon impervious would be to make the excavation deep enough, such that full service level in the lagoon will be below the maximum depth of the active layer in the surrounding natural ground (about 1 m). This would mean that a significantly deeper excavation would be required than would be the case if the lagoon were constructed by balanced cut and fill. Moreover, depending on the configuration of the lagoon, water from the active layer could still fill the lagoon during the summer months.

- 3) There is concern that an unsaturated zone may be encountered within the natural permafrost at this site. If such a zone were present, the lagoon could leak even if the full service level were kept below the active layer of the surrounding area. The occurrence of such an unsaturated zone is unlikely but possible. Its presence would only be revealed during construction.

#### 4.2.2 Berm Cutoff

A second alternative would be to install an impervious cutoff through the berm around the entire perimeter of the lagoon as shown on Figure 3.2 of the pre-design report. There are a number of concerns with this approach:

- 1) In order to be effective, the cutoff would have to extend at least 1 m into the native soil below the berm. If the bottom of the cutoff were placed within the fill, as shown on the bottom half of Figure 3.2, it is probable that seepage underneath the cutoff would occur which could result in piping failure of the berm.
- 2) A number of construction difficulties are anticipated if the cutoff is extended into the natural permafrost below the berm. The excavation for the cutoff would be fairly deep and the trench sideslopes would have to be cut back to a slope of 1 to 1 in order to make the slopes stable. In addition, excavation of the permafrost would be required in order to anchor the cutoff into the permafrost. It is probable that the permafrost could only be excavated by blasting. Finally, there may be difficulties with water from the active layer flowing into the trench excavation.
- 3) There is a risk that sewage effluent could flow below the cutoff, either because the cutoff was installed to insufficient depth, or because of the presence of unsaturated pervious zones within the natural soil. It would be difficult to locate the exact location of such seepage zones, if they occur, so that repairs could be made.

#### 4.2.3 Full Membrane Liner

A third alternative to make the lagoon watertight would be to line the entire lagoon with a suitable membrane liner. While this alternative would be effective, it is, as pointed out in the pre-design report, extremely expensive.

If a full membrane liner is used, it is recommended that a subdrainage system be incorporated into the design in order to prevent heaving of the liner due to groundwater from the active layer flowing below the liner when the lagoon is emptied during the late summer. The installation of a subdrainage system will increase the cost of this alternative significantly. The use of weight placed on the liner can be considered further, however, a relatively substantial depth of soil cover (1 to 2 m) would be required to prevent heaving of the liner and therefore this approach may not be cost effective.

#### 4.2.4 Conclusion

It is clear that the watertightness of the lagoon will be a major concern and that there are unresolved difficulties associated with the available alternatives. This aspect of the design should be reviewed further before proceeding with the preparation of the detailed design drawings and specifications.

#### 4.3 Lagoon Sideslopes

It is proposed to construct the lagoon sideslopes at 4 horizontal to 1 vertical. Deep seated failure of the lagoon berms is not a concern in view of the granular nature of the soils to be used in construction. However, the native soils are highly susceptible to wave erosion and for this reason it is recommended that sideslopes be constructed at 4 horizontal to 1 vertical. The sideslopes could be constructed steeper than this, however, wave erosion would increase and significant annual regrading of the slopes would be required.

#### 4.4 Freeboard and Crest Width

The present design allows for 0.5 m of freeboard at full service level. It is recommended that the freeboard be increased to 1.0 m in order to account for possible



settlement of poorly compacted berms, as well as to provide an extra margin of safety in the event that wave erosion is more severe than currently anticipated.

It is also recommended that an overflow culvert be installed above full service level to prevent accidental overtopping of the lagoon berms.

A berm crest width of 5 m has been proposed. This width should be adequate to permit construction equipment to travel around the crest of the berms to carry out maintenance of the berms as required.

#### 4.5 Discharge Ditch

Erosion of the discharge ditch which carries effluent from the end of the discharge pipe to the ocean is a concern, because of the large flows which will be discharged from the outlet over a short period of time when the lagoon is emptied. This aspect should be examined in more detail during the detailed design phase. It is probable that rip rap and possibly some check structures may be required, depending on the maximum flows and gradient of the ditch. It is recommended that the design of the ditch be reviewed by a qualified hydrological engineer.

#### 4.6 Truck Discharge

A sketch of the proposed truck discharge system is shown in Figure 3.1 of the pre-design report. It is understood that the outlet from the discharge pipe will be placed below about 0.8 m of water in the fall, in order to prevent the outlet from freezing up. This depth of water may not be sufficient to prevent the outlet from freezing.

#### 4.7 Wind Erosion

The near surface soils in the vicinity of the sewage lagoon which contain more than 70 percent sand and silt size particles will be moderately susceptible to erosion, particularly when they dry out and are exposed near the top of the lagoon berms. It is recommended that a minimum thickness of 150 mm of gravel, which contains not more than 50 percent passing the #4 sieve (5 mm size) be placed on the inside and outside slopes of the lagoon berms in order to minimize possible wind erosion.

#### 4.8 Fence Design

It is understood that a chain link fence will be installed around the lagoon.

Frost jacking of the fence posts will occur as a result of annual thawing and freezing of the active layer. Frost jacking can be reduced by placing fence posts in cone shaped concrete pedestals, with the large end of the cone placed down, and the base of the cone not less than 1.5 m below finished grade. Alternatively, fence posts could be placed to a depth of 3 m below finished grade, with the upper 1 m greased to reduce adfreeze forces in the active layer. If this arrangement is selected, it is also recommended that a wide flange or bar be welded onto the bottom of the post to anchor the post into the permafrost.



## SECTION 5

### ROAD DESIGN AND CONSTRUCTION

The pre-design report recommends that the access road to the facilities be constructed in the late summer in order to prevent excessive permafrost degradation. The method of road construction and the rationale for this recommendation is not clear.

The road could be constructed by placing a minimum of 1 m of granular fill over the existing ground surface. Care should be taken not to disturb the existing surface vegetation prior to placing the fill. In poorly drained areas, additional fill may be required in order to achieve a satisfactory road surface. If this method of construction is used, it is preferable to place fill during the early summer, before the active layer reaches its maximum depth.

An alternative method of constructing the road would be to borrow native materials from the ditches in order to build up the road surface. If this approach is used, it would be preferable to construct the road in mid to late summer, when the active layer is deeper. This approach will not work where fine grained silts or clays are present near the ground surface because it will not be possible to drain such soils to the point where they will provide adequate bearing capacity.

Fill sideslopes for roads should be trimmed at 3 horizontal to 1 vertical in order to reduce erosion of the sideslopes as well as to provide a more stable shoulder.

It is recommended that past experience with road construction in the community be reviewed before a final decision is made as to the optimum method of road construction in this case.

## SECTION 6

### GEOTECHNICAL REVIEW

It is recommended that the design drawings and specifications for the access road, sewage lagoon and solid waste disposal facility be reviewed in detail by a qualified geotechnical engineer once the tender documents are 80 to 90 percent complete, and before they are submitted to prospective bidders.





APPENDIX A  
Test Pit Logs  
Grain Size Analyses



23 August 1984  
File: (2577)52-89-01-01

GJOA HAVEN SOLID WASTES SITE  
TEST PIT RECORD

Test Pit #1

0 to 0.1 m	organics with lichens	
0.1 to 0.2 m	cobbles and sand	
0.2 to 1.1	coarse sand	SAMPLE

Test Pit #2

0 to 0.7 m	coarse sand	
0.7 to 1.2 m	sand and gravel; W.T. @ 0.8; 0.75 after 20 min;	SAMPLE

Test Pit #3


0 to 0.2 m	organics	
0.2 to 1.0 m	cobbles and sand	
1.0 to 1.1 m	sand and gravel	SAMPLE

Test Pit #4

0 to 0.1 m	organics	
0.1 to 1.0 m	coarse sand	SAMPLE
1.0 to 1.2 m	sand and gravel; W.T. @ 1.0 m	

H. J. Bourque, P. Eng.

Unified Soil Classification System & N.R.C. Field Description (Modified with clay size at 0.002 mm)



CLIENT	Stanley Associates
PROJECT	Gjoa Haven Landfill
LOCATION	Test Pit #1
SAMPLE	

Gravel	0
Sand	97
Silt	3
Clay	

Classification	Clean Poorly Graded Soil (SP)
----------------	-------------------------------

The graph displays the cumulative percentage of material passing through different sieve sizes. The x-axis at the top shows sieve sizes in inches (from 3/4" to 0.075"), and the bottom shows U.S. Standard Sieve Sizes (from 3" to No. 200). The y-axis represents the percentage of material passing (0 to 100%).

The soil is classified into four regions based on sieve size:

- GRAVEL:** Sieve sizes larger than 2.0 mm (No. 10).
- SAND:** Sieve sizes between 2.0 mm (No. 10) and 75 μm (No. 200).
- SILT:** Sieve sizes between 75 μm (No. 200) and 4.75 mm (No. 40).
- CLAY:** Sieve sizes smaller than 4.75 mm (No. 40).

The curve shows that approximately 100% of the material passes through a 3/4" sieve, 90% passes through a 1/2" sieve, 75% passes through a 3/8" sieve, 50% passes through a No. 10 sieve, 25% passes through a No. 20 sieve, 10% passes through a No. 40 sieve, and 5% passes through a No. 60 sieve. The material is primarily composed of sand and silt.

%		

Clay			%
Silt	0		
Sand	75		
Gravel	25		

Clean Poorly Graded Sand (SP)

CLIENT	Stanley Associates
PROJECT	Gjoa Haven Landfill
LOCATION	Test pit #2
SAMPLE	

**THURBER CONSULTANTS LTD., Geotechnical Engineers**

TEST DATE AUG 29/84

FILE NO 17-308-14


GRAVEL		SAND			SILT		CLAY	
COARSE	FINE	COARSE	MEDIUM	FINE				
3/4"	3/8"	No. 10	No. 20	No. 40	No. 60	No. 80	No. 100	
1/2"	1/4"	No. 30	No. 40	No. 60	No. 80	No. 100	No. 120	
1/4"	1/16"	No. 60	No. 80	No. 100	No. 120	No. 140	No. 160	
1/16"	No. 10	No. 120	No. 140	No. 160	No. 180	No. 200	No. 220	

U.S. Standard Sieve Sizes

Percentage of Material Passing

100  
90  
80  
70  
60  
50  
40  
30  
20  
10  
0

3/4" 3/8" 1/2" 1/4" 1/16" No. 10 No. 20 No. 40 No. 60 No. 80 No. 100 No. 120 No. 140 No. 160 No. 180 No. 200 No. 220



			%
		3	
		46.8	
		51.1	

[illegible]

Not. Water Content	Liquid Limit	Plastic Limit	Plastic Index
--------------------	--------------	---------------	---------------

### Classification

Clean Poorly Graded Gravel (GP)

**CLIENT** Stanley Associates

PROJECT Gioa Haven Landfill

LOCATION Test Pit #3


**SAMPLE** 0.5 m

TEST DATE AUG 29/84

FILE NO

**THUBBER CONSULTANTS LTD., Geotechnical Engineering**

GRAVEL		SAND		SILT	CLAY
COARSE	FINE	COARSE	FINE		



2	97	1	%
---	----	---	---

%			

Not. Water Content
Liquid Limit
Plastic Limit
Plastic Index

## Classification

Clean Poorly Graded Sand (SP)

			%
Clay			
Silt	1		
Sand	97		
Gravel	2		

Clay  
Sill  
Sand  
Groves

**CLIENT** Stanley Associates

PROJECT Gjoa Haven Landfill

LOCATION Test Pit #4

**SAMPLE 1.0 m**

TEST DATE Aug 29/84

FILE NO 17-308-1