DIAND Nunavut District Box 100 Iqaluit, NT XOA OHO

November 30, 1998

Mr. Raymond Kamooka Senior Administrative Officer Hamlet of Gjoa Haven Gjoa Haven, NT XOE 1J0 MUNAVUT WATER BOARD

SCANNED

OCT 2 9 2001

MEF. # 9811300 Johnspectron

NWB3GJO

- 1 TAE

DEC 0 7 1998

PUBLIC REGISTRY

Dear Mr. Kamooka;

Water Management Inspection - Hamlet of Gjoa Haven; August 24, 1998 and Results from Water Samples Collected.

- Please find attached a copy of the inspection report prepared as a result of the water management inspection carried out on August 24, 1998 as well as the analytical results for water samples collected the same day.
- 2. May I first begin by thanking you for your assistance during the wrap-up meeting and for ensuring that the Hamlet has met its obligations by applying for a municipal water licence per the requirements of the NWT Waters Act and the Nunavut Land Claims Agreement.
- 3. To summarize the inspection report, there are a number of issues that will have to be addressed. Please not that some of these issues will have to be addressed once a water licence is issued.
 - Repairs have to be made to the discharge area of the sewage lagoon;
 - Waste oil storage has to be improved to prevent the further contamination of soil;
 - Warning signs at the dump, sewage lagoon and water lake should be placed.
 - Fencing is recommended along the side of the water lake that faces the community.
- 4. Please advise this office on the status of the various upgrade plans that Mr. Morash mentioned. Have the repairs to the sewage discharge chutes been completed? Have any further decisions been made with regard to the construction of a second lagoon cell? Was the solid waste disposal site covered with granular material?

.../2



MUNICIPAL WATER USE INSPECTION FORM

DATE:	24 1555		COMPANY REP.	Gram Moras	lag Rymers Frances
LICENSEE:	of age Mar	A Dec	LICENCE #: 🔀	A Sandarile	
WATER SUPPLY					
Source (s):	where English	1. W. P.	Quantity U	Jsed (to date): _	m 24, 8000 m Tyenn
Owner/Operator: 📉 🧸			(estimate	e or actual)	4
Indicate: A Acceptat		ble N/A - Not	Applicable		
Intake Facilities:	Storage Struc	ture <u>Maller</u>	Treatment Sys	stems 👫 🖰	3. Chem. Storage A
Flow Meas. Device 🚣		11 to 2	Pumping Stat	ions 🚻	
Comments: Section 1	following ?	la. V. de.	•		
WASTE DISPOSAL					A
	Treatment System (n	rimany sacondar	v or tertiana)	Same A	C = 0 * 0 0 1
	Water body				- Samuel Bersender of
					Trench
	Operator:			•	
	Buri			ner	
Indicate: A Acceptate	•		• •	Function	A. Francisco
		ant Structure _			1135. 4
Disch. Meas. Dev Dams, Dykes		e Inspection _			1 1 1 m 1 m 1
-		eboard _			Note (work or
		M Plan _			- F. J.
Periods of Discharge: Comments:	<u>а 28 м № . ६</u> — ЕПІС	ient Discharge Ri	ate: <u> </u>	My company of the	sies day washing
					f Tanks
					Leaks:

Pipeline Condition		pplicable:			
SURVEILLANCE NETW					
Samples Collected:	(Hamlet)		11.54		
	(DIAND)	at as of many		1 coch To	
Record & Reporting	4				
Geotechnical Inspection:					
Non-Compliance of Act	t or Licence: 🔼		with the same	1 6	The second of the second
the same of the					
	·	···		<u> </u>	
		·		Page 2 at	tached Yes · · No No
JAN O					miny
Licensee Representativ			Inspe	eoters Name	**** * * * * * * * * * * * * * * * * *
March & Back	r r		•	١٠ الر : ١	I want to
Licensee Representativ			Inspe	ctors Signatur	
WHITE COPY - In	spector's File YELLOW	COPY - Licensee	GREEN COPY - Fig		OPY - Water Resources

- 5. It would be worthy for the Hamlet to pursue the idea of having a separate area for the disposal/recycling of wood, and a pit for the disposal of animal carcasses and a sealift container for hazardous materials.
- 6. Also enclosed are the results of water samples I collected during the inspection. I collected two sets of samples one of raw water from the water lake and another from below the dump (leachate). With respect to the drinking water, there are no particular concerns with the raw water.
- 7. If you have any questions about the inspection report or with the analytical results, please do not hesitate to contact me at the above address or by phone at (867)-979-4405.

Sincerely,

Paul Smith

Water Resources Officer

Nunavut District

cc. - Nunavut Water Board, Gjoa Haven

- DIAND Water Resources, YK

- Kojo Kumi, MACA, Cambridge Bay

- Bob Philips, Environmental Health Officer, YK

Gjoa Haven August 24, 1998

Page 2

Note 1 and 2

Truck fill station also contains a filtration and reserve tankage for storage. When the facility was handed over from the GNWT, the Hamlet was unable to maintain the entire system and by-passed all but the chlorination aspects.

Note 3

On an annual basis, water is piped overland from Swan Lake (ca. 3.5 km away) to recharge the water lake.

Note 4

There is an earthen berm around the perimeter of the lagoon. However, at the discharge point, there is a low spot that is full of cobble stones. At the time of the inspection, there was no visible flow from the this spot. There is a great deal of erosion in this area. This area should be repaired in order to provide additional retention and to provide a more 'positive' means of controlling discharge. There is no freeboard at this point. Further, there has been a good deal of erosion around the discharge chutes. Work was to begin shortly to repair the erosion damage and install better chutes.

Note 5

The waste oil storage area is in poor condition. Many drums are leaking and the ground is heavily stained. A bermed and lined storage is recommended until the material can be properly incinerated. In the meantime, all leaky drums should be replaced, and all drums should be placed upright on pallets. Mr. Morash stated that a waste oil furnace is being considered for a 3-bay garage that is planned for 1999-2000.

General

The capacity of the water lake was increased by raising the earthen berm around the low end of the lake. The water level was nearly topping over this berm. An overflow pipe was installed, but this was right at the surface. I am concerned that this berm could wash out and significantly threaten the communities immediate supply of water.

Mr. Morash stated that a second sewage cell was in the works. He also mentioned that there were plans to have an animal pit for the disposal of carcasses as well as a wood salvage area.

The solid waste site is now being burned as wind conditions permit and work was being done to push and compact burned wastes. The area still required to be capped with granular material. The fencing around the dump is in poor condition and needs repairing. Appropriate warning signs are also required.

Due to the proximity of houses to the water lake, warning signs and fencing are required around the water lake. Fencing should be considered along the one side that borders the community. This would help reduce traffic and wind blown garbage from impact the supply.

End

TAIGA ENVIRONMENTAL LABORATORY

Dept. Indian Affairs & Northern Development

4601-52 nd Ave., Box 1500

Yellowknife, NT. X1A 2R3

Tel. (403) 669-2788

Fax: (403) 669-2718

To: NUNAVUT

WATER RESOURCES, NAP, DIAND

BOX 100

IQALUIT

NT

X0A 0H0

PAUL SMITH

Our Lab#: 971559

SEP 2 2 1997

Account No:

Your Sample ID: WATER LAKE

Sample Matrix: RAW WATER

Received Date: 20-August-1997

Collection:

Location: HAMLET OF Gjor Haven

Report Date: 08-Sep-97

Approved By:

Date: 8/14/97

By: P.SMITH

- SAMPLE ANALYSIS REPORT -

_ Lab#	Test	Result	Units	Detection Limit	Analysis Date	AnalyticalMethod
971559						
	pН	8.24	pН	0.05	8/20/97	010301
	Fluoride	0.13	mg/L	0.05	8/22/97	009105
	Conductivity	415	uS/cm	0.3	8/20/97	02041
	Colour	10.0		5.00	8/19/97	02021
	Alkalinity	91.8	mg/L	0.3	8/20/97	010101
	Calcium	27.4	mg/L	0.03	8/20/97	20103
	Chloride	44.1	mg/L	0.08	8/20/97	17206
	Potassium	2.02	mg/L	0.002	8/20/97	019106
	Sodium	29.6	mg/L	0.02	8/20/97	011102
	Magnesium	17,6	mg/L	0.005	8/20/97	012102
	Turbidity	2.6	NTU	0,1	8/19/97	002081
	Tot-Suspended-Solids	L3	mg/L	3	8/20/97	grav
	· Tot-Diss-Solids	259	mg/L	10,0	8/20/97	grav
	Tot-Mcrcury(water)	L0.01	ug/L	0.01	9/2/97	080314

TAIGA ENVIRONMENTAL LABORATORY Dept. Indian Affairs & Northern Development 4601-52 nd Ave., Box 1500 Yellowknife, NT. X1A 2R3

Tel. (403) 669-2788 Fax: (403) 669-2718 To: NUNAVUT

WATER RESOURCES, NAP, DIAND

BOX 100

IQALUIT

NT

X0A 0H0

PAUL SMITH

971559

Tot-Cadmium(ICP-MS)	L0.1	ug/L	0.1	8/20/97	ICP-MS
Tot-Cobalt(ICP-MS)	0.8	սջ/Լ	0.1	8/20/97	ICP-MS
Tot-Chromium(ICP-MS)	2.2	ug/L	2.0	8/20/97	ICP-MS
Tot-Copper(ICP/MS)	125	ug/L	0.1	8/20/97	ICP-MS
Tot-Iron(AA)	0.805	mg/L	0.012	8/28/97	ICP-MS
Tot-Manganese(ICP-MS)	10.0	ug/L	0.1	8/20/97	ICP-MS
Tot-Nickel(ICP-MS)	1.0	ug/L	0.1	8/20/97	ICP-MS
Tot-Lead(ICP-MS)	4,6	ug/L	0,2	8/20/97	ICP-MS
Tot-Zinc(ICP-MS)	108	ug/L	5.0	8/20/97	ICP-MS

TAIGA ENVIRONMENTAL LABORATORY

Dept. Indian Affairs & Northern Development

4601-52 nd Ave., Box 1500

Yellowknife, NT. X1A 2R3

Tel. (403) 669-2788

RECEIVED

Fax: (403) 669-2718

IQALUIT

BOX 100

To: NUNAVUT

NT

WATER RESOURCES, NAP, DIAND

X0A 0H0

PAUL SMITH

SEP 2 2 1997.

I A TO TO TO THE INFORMATION

Our Lab#: 971560

Account No:

Your Sample ID: DUMP LEACHATE

Sample Matrix: WATER GRAB

Collection:

Location: HAMLET OF G

Date: 8/14/97

By: P.SMITH

Received Date: 20-August-1997

Report Date: 02-Sep-97

Approved By: Wasses

- SAMPLE ANALYSIS REPORT -

Lab# 971560	Test	Result	Units 	Detection Limit	Analysis Date	Analytical Method
31.200	Ammonia-N	36.6	mg/L	0.002	8/20/97	007562
	Tot-Arsenic(water)	4.4	. ug/L	0.2	8/26/97	hydride
	Tot-Cadmium(ICP-MS)	0.8	ug/L	0.1	8/20/97	ICP-MS
	Tot-Cobalt(ICP-MS)	2.2	ug/L	0.1	8/20/97	ICP-MS
	Tot-Chromium(ICP-MS)	8,9	ug/L	2.0	8/20/97	ICP-MS
	Tot-Copper(ICP/MS)	66.7	ug/L	0.1	8/20/97	ICP-MS
	Tot-Iron(AA)	27.7	mg/L	0.012	8/28/97	ICP-MS
	Tot-Manganese(ICP-MS)	148	ug/L	0.1	8/20/97	ICP-MS
	Tot-Nickel(ICP-MS)	19.8	ug/L	0.1	8/20/97	ICP-MS
	Tot-Lead(ICP-MS)	52.9	ug/L	0.2	8/20/97	ICP-MS
	Tot-Zinc(ICP-MS)	741	ug/L	5.0	8/20/97	ICP-MS