Indian and Northern Affairs

Affaires in ulennes et du Nord

Devartment of Indian & vorthern Affairs Numbers Operations Branch

SEP 28 1388

WA' . MANAGEMENT YELLOWKNIFE, N.W.T.

Northern Affairs Program P.O. Box 100 Iqaluit, N.W.T. XOA OHO

September 14, 1988

Ms. Napatchie MacRae Secretary Manager Hamlet of Hall Beach Hall Beach, N.W.T. XOA OKO

Your file Votre reférence

B9545-5-H6 Our file Notre reférence

Dear Ms. MacRae;

Inspection - Hall Beach, N.W.T. July 4, 1988

Insp Hall Beach 1W-8

Enclosed please find the above report prepared by Mr. Jessiman following the July 4, 1988 inspection.

The inspection report identified a number of concerns that may require your attention:

- 1. the inspectors recommended that the Hamlet obtain an improved intake filter for the truck pump-out location at the water reservoir.
- 2. The sewage pit should be enlarged to accomodate the sewage discharges for Hall Beach on a yearly basis.
- 3. The garbage dump should be consolidated and a garbage pit be dug to reduce the windblown garbage.
- 4. The Hamlet should restore the abandoned waste and sewage disposal areas.
- 5. The ponds and creeks (near the dump) should be cleaned up of garbage, animal remains and scrap metal.
- 6. The Northwest Territories Power Corporation should clean-up the waste oil and diesel fuel around the generator building.
- 7. The inspectors recommended that warning signs should be posted near the sewage pit and the garbage dump perimeter in in order to prevent indiscriminate dumping.

The results of the water quality samples will be sent to you under separate cover when they are received by this office.

If you have any questions or comments on the inspection report, please contact Mr. David Jessiman, Water Resources Officer at 979-4405.

Sincerely

J.M.A. Theriault District Manager Baffin District

cc. Water Resources YK
 GNWT - MACA, Iqaluit (M. Ferris)
 GNWT - DPW, Iqaluit (S. Kennedy)
 BRHB, Iqlauit (L. Wilson)
 NWTPC, Iqaluit (W. Boyle)

INSPECTION REPORT

ON THE

HAMLET OF HALL BEACH

JULY 4, 1988

BY

DAVID JESSIMAN

INSPECTOR UNDER THE NORTHERN INLAND WATERS ACT

NORTHERN AFFAIRS PROGRAM

INDIAN AND NORTHERN AFFAIRS CANADA

IQALUIT, N.W.T.

Date: August 17, 1988 Water Register: N/A

INTRODUCTION

on July 4, 1988, David Jessiman, Water Resources Officer and Peter Kusugak, Resource Management Officer of the Baffin District conducted an inspection of the water use and the waste disposal practices of the Hamlet of Hall Beach, N.W.T.. The inspector met with Ms.Napatchie MacRae, Secretary Manager, to review and discuss the inspection.

INSPECTION

Water Supply

The Hamlet water supply is obtained from a reservoir located approximately four kilometers southeast of Hall Beach. The reservoir was originally built in 1956 by the United States Air Force as part of the Distant Early Warning network. The reservoir continues to be operated and maintained by the Fox-Main Station. The perimeter of the reservoir and the weir was inspected and no concerns were noted.

Water is trucked to the community with a 4 500 Litre Water Truck. The potable water does not receive treatment and is pumped into holding tanks. The metal tanks are gradually being replaced with plastic tanks. Ms. MacRae indicated the Hamlet was considering obtaining an improved intake hose filter for the truck. She added that turbidity of the potable water tends to be very high in the summer months which is partially caused by windblown dust from roads and the airstrip.

Sewage Disposal

Sewage is almost entirely removed by Vacuum truck to the waste disposal area northwest of the community. Three older houses continue to use honeybuckets with one of the houses being modified this year for a sewage holding tank. The honeybags are being dumped adjacent to the garbage dump.

The sewage pit measures approximately 15 metres by 25 metres with a freeboard of less than one metre. The sewage leaches through the coarse shale into a drainage area that gradually reaches the shore. The sewage pit was observed to be underdesigned to support the population of Hall Beach. Ms. MacRae mentioned that the sewage pit freezes solid in October and the raw sewage flows over the ground toward the garbage dump and the shoreline.

The old abandoned sewage pits were observed to be partially filled in and remnants of plastic bags were scattered around the area.

The sewage disposal area was not posted and was freely accessible to the public.

Solid Waste Dispos .

Domestic and commercial garbage is deposited on the ground adjacent to the sewage pit and is periodically burnt and covered with local pit-run shale. The garbage disposal area was observed to be very scattered and dumping practices of the users appear to be haphazard. It was observed that garbage is slowly migrating towards the community. A large pile of unburnt wood, insultation, and fixtures belonging to the NWT Housing Corporation was clearly outside of the dump area (towards the community).

Garbage and old 45 gallon drums were observed strewn along a small creek approximately 50 metres from the dump and approximately 400 metres from Hall Beach.

The metal waste site is located half way between the garbage dump and the community. The metal waste site considered of old vehicles, unused fuel tanks, steel pipes, and destroyed snowmobiles.

Fuel Storage

The Hamlet of Hall Beach does not own any bulk fuel storage facilities. The existing tank farms belong to the Government of the Northwest Territories, Northwest Territories Power Corporation, Ministry of Transport, Department of National Defence and the D.E.W. Line Station.

SURVEILLANCE NETWORK PROGRAM

The following water quality samples were collected:

HB-1 Water Reservoir HB-2 Potable Water - Hall Beach Hotel

Posting

The water reservoir was posted in all four corners by the DEW Line Station. The waste disposal dumpsites and the sewage pit were not posted.

Other concerns

Waste oil and diesel fuel was observed to be dumped all around Northwest Territories Power Corporation generator building. A small pond southwest of the building was heavily stained with diesel fuel. Oil globules were observed on the bottom of the pond. The fuel tank farm adjacent to the generator building was observed to have inadequate berms and lacked impermeable liners.

Scattered garbage, animal remains, and dog faeces was observed along and in the shallow pond directly west of the community (edge of housing row).

After the inspection a meeting was held with Ms. MacRae. The following points were covered:

- 1. Water Supply: The Hamlet was encouraged to obtain an improved intake filter for the truck pumpouts at the water reservoir.
- 2. Waste Disposal
- a) The Hamlet should restore the previously used waste disposal areas and establish a Garbage Pit to control and contain the windblown garbage.
- b) The waste disposal area should be clearly marked and large local organizations who use the dump should be requested to improve their dumping practices. Ms. MacRae indicated that the Hamlet picks up the domestic garbage and burns it regularly. She mentioned that the Hamlet has little control over other users and will contact local organizations to control the random dumping.
- c) The refuse belonging to the NWT Housing Corporation should be moved inside the accepted dumping area and burnt.
- d) The inspectors recommended that the Hamlet clean-out the creek bed from the road (culvert) to the shoreline. Future dumping should not be allowed within 50 metres of the creek.
- 3. Sewage Pit A new sewage lagoon should be considered to reflect the year round requirements for sewage disposal. The present sewage pit appeared to be adequate only during the summer months. After freeze-up the pit would be inoperable and the sewage would glaciate the surrounding area.

The inspectors recommended that the abandoned sewage pits and honeybag disposal areas should be totally restored. The Hamlet should consider posting warning signs to advise the public of the sewage disposal area.

4. General Clean-up - The Hamlet should strongly consider cleaning up the garbage, animal remains and scrap metal that has collected in ponds behind the community. A creek adjacent to the RCMP detachment was observed to be littered with old rusted 45 gallon drums and scrap metal.

Northwest Territories Power Corporation - The area surrounding the Diesel Generator building was observed to have large amounts of waste oil and diesel fuel spread around the site. The operators appear to be end dumping waste oil near the building. This practice is totally unacceptable. The waste oil and fuel should be contained in drums until it is removed or disposed of. The oil soaked fill should be removed and replaced with new gravel and the unacceptable dumping practices completely curtailed. The area had noticeable fuel smells and visually unaesthetic considering it is in the centre of the community.

The fuel tank farm adjacent to the generator building was observed to have inadequate berms and did not have impermeable liners.

6. General - The inspectors recognize that the Hamlet cannot correct all the noted deficiencies by themselves and additional resources must come through established government departments.

The cooperation and assistance of Ms. MacRae was greatly appreciated.

David Jessiman

Inspector Under the Northern Inland Waters Act

DEPARTMENT OF INDIAN AFFAIRS AND NORTHERN DEVELOPMENT ER RESOURCES D1 SION, YELLOWKNI. NORTHW. F TERRITORIES

RESULTS OF LABORATORY ANALYSIS

LICENSEE/ PROJECT	4amleto FHall	B	LIC	EN BE	R Ha	11	Beach		V/A	H	ION ((Bea	<u>رب</u>	4
DATE SAMPLED	July 4, 198	_				Tu	wf 11.		CO	IPI	ETED A	9.	15 188
STATION NUMBER		HBI		HBZ.							[] 18 speed		
LABORATORY NUMBER		880652		- 653		. !							
ANALYSIS REQUIRED		✓		✓	Single Strain	✓	Latin 1	✓		✓	Withing and	V	
pH (units) Conductivity (μmho/cm)		7	6.6 N3	7	7.3	-		-		-		-	
Dissolved Oxygen		٥											
Turbidity (NTU) Colour (colour U.)		1	12	2	-4	-	**	-	ļ	-		-	- 1913
Suspended Solids		2	12	v	2								
TDS, Residue		2	22	4	82	_		L					
Calcium		7	5.5	~	3.4	-		┡	ļ	-		-	<u> </u>
Magnesium Tot. Hardness (CaCO ₃)		Ž	0.84	"	59	-	 	-	<u> </u>	╁		⊢	
	linity(CaCO3)	-	.15	7	51	-		1		\vdash		╁╴	
Sodium		V	1.8.	V	6.1								
Potassium		1	0.2	~	0.8.								
Chloride		4	2.3	V	9.5	1		-		1		_	
Sulphate		4	2.0	4	5.1	-		-		-	ļ	-	
Total Coliform/count		Y		1	/	-	reid -	Pro	late	-		-	
Fecal Coli. 100		Y		1	7	┢	1200			十		\vdash	
Fecal Strep. \ ml / Std Plate Cnt (cnt/ml		5		Ť				-		1		-	
BOD ₅		-											
COD					,			L		1_	<u> </u>	L	
Carbon, IC		Ш		_		Ļ		-		┼-		_	
Carbon, TOC		Н		-	 _	-				+		-	
Ammonia Nitrogen (as)		Н		⊢		├-		-		1-		-	
Nitrate + Nitrite Notal Kjeldahl N				一		1							
Phosphorus O-P as													
Phosphorus Tot P						1		_		┼-		_	ļ
	ac.(as SiO2)			L		╄		╀		╀		┞	<u></u>
Total Cya		-		-		╢		╁~		╁		-	
Available	Cyanide	-		┝		╁		十		+	-	1	
Sulphide Oil & Gre	250	-		-		1				I			
Phenols	456					L		_		1		ļ	
			· ·	_		-	<u> </u>	┼-		╀		╀	-
Arsenic	T (ng/L)	4	LI.	1	LI.	╀╌		-		╁╴	 	1-	
	D (ug/L) T (ug/L)	u	60,5	v	Lois	\vdash		\vdash					,
Cadmium	D (Mg/L)			1	,								
	T (ug/L)	u	2.	V	84			Ŀ		-		-	ļ
Copper	D (ug/L)			L		_		┞-		+		├	
_	T (ug/L)	4	16	1	41	╁╾		╁		╁╌		┝	
Iron	D (ug/L)	\sqcup		L		╁	<u> </u>	╁		+	<u> </u>	1	
Lead	T (ug/L)	4		-	41	-	<u> </u>	✝					
	D (ug/L)	H	0.03	+-	0.05	1						1	
Mercury	T (µg/L)	۲	0.03	۲	7.00	1				1		-	
Mercury D (ug/L) T (ug/L)		L	LI	J	41	I		1		+	<u> </u>	-	
Nickel	D (ug/L)	Ť				-	<u> </u>	+		+		+	
	T (ug/L)	V	130	1	65	+		+		+-		1	
Zinc	D (ug/L)			-	LI	+		+	1			I	
	T (ug/L)	~	<u> </u>	4	1-4	+-						1	
Chromium	D (ug/L)	-		+-		-		I		_	*	_	ļ
-		-		+-	 	1		\perp		\perp		1_	

Posults are expressed in mg/L, except as indicated. T and D refer to

. 24 6...

AKSENIC			1	1014	18.17.		*,* *11.					
HEAVY METALS	2-125ml 500 ML	2 ML 1 HNO ₃		1.4		managen ing ing septim	in the same	There was not				
CVANIDE	500 ML	About 6 pellets NaOH to pH 12			1772	• • • • • • • • • • • • • • • • • • •	# 1 1 1 1 2 2 1	117				
MERCURY	250 ML	2 ML 1:1 HNO ₃ + 2 ML 5% K ₂ Cr ₂ O ₇	ic !		1.11	*						
NUTRIENTS	250 ML	NONE	10	16 K		•		. ; .: :				
BACTERIA	500 ML	NONE	.1(11-1-1	***				
OIL AND GREASE	1 LITRE (GLASS)	4 ML 1:1 H ₂ SO ₄	· · · · · · · · · · · · · · · · · · ·		7			4				
	·						r while date	in the life				
				A Assets a		one e	200	13 8 M				
Time of S	11:01	12:03	10.12	15, 11	47.5							
Air Tempe	600	6°C	119. Fig. 1	413	at pit.							
ter Ter	+3°C	16.31		Asy .	THE STATE OF	:						
Rate of I	Flow		or and a second	May United	9 TV							
Ice Thick	1 m.	143431	11 Jahr									
Depth of	Sampling	;	,	13 1	erge endedy ty h	, , , ,	TANK IN:					
рН			٠.	4.4.	4	- 🗸						
Conductiv	vity	1 1 1 1 1 1	4									
Dissolved	d Oxygen	e de la companya de l	;	Suda Si	10 to	Select Wilds	THE STATE OF	Asia di				
		and the sign of the first of the sign of t			7 178	14	Bang &	-				
	· / · .	1 L. :	: :	**************************************	fat :	٠.	** . *					
				6.1			2 - 2					
	No	Preserva	tive	A	4 40	4	,	1 6 4 1				

2 1 Thinking the same in) .

750

17

1.43.1

Preservativo added Lug 11.

•