

Photo #6
View of dolostone bedrock outcrop at south abutment.
Note the high degree of fracturing.



Photo #7
View of ground conditions in proposed spillway alignment.
Note the raised polygrounds indicative of permafrost conditions.

Note: Photos taken July 2000

SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND					SCALE: N/A DATE: February, 2002		III BOO ENGINE		Preliminary Spillway Design			
					DRAWN:	GKC	BGC	AN APPLIED EARTH SO Calgary, AB	NEERING INC. RTH SCIENCES COMPANY Phone (403) 250-5185	Selected Photos of Ground Conditions		
					DESIGNED:	GKC		Calgary, Ab				
					CHECKED:	JWC	CLIENT:	Nanisivik Mine		PROJECT No.	FIGURE. No.	REV.
RE	/. DATE	REVISION	DRAWN CHECKED	APPROVED	APPROVED:	JWC				0255-004-01	Figure 6	0.