


09-29-96 09:59 FAX 819 430 7435

NANISIVIK MINES

0002



019 P02/02 SEP 29 '95 07133

ARCTIC PLANNING STATION

403-873-6924



(Oil, Gas, Hazardous Chemicals or other Materials)

Phone/D'be DC (403) 920-8130

Fax/تلفون فاكس (403) 873-8924

HYNT 17620583



N.W.T. SPILL REPORT

(Oil, Gas, Hazardous Chemicals or other Materials)

Report date and time

Date and time of spill (if known)

Original report

Spill number

May 03/94

May 02/94

Update no.

94-089

Location and map coordinates (if known) and direction (if moving)

Nanisivik Mines Ltd. Ship loading area

Party responsible for spill

Nanisivik Mines Ltd

Product(s) spilled and estimated quantities (provide metric volumes/weights if possible)

(Powdered) Calcium hydroxide (Hydrated lime) Approx 1 tonne

Cause of spill

Broken bags during off-loading of cargo

Is spill terminated?

Yes/No

If spill is continuing, give estimated rate

Is further spillage possible?

Yes/No

Extent of contaminated area (in square metres if possible)

4 sq. metres around each bag

Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.)

Containment/natural depression, dikes, etc.)

Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials

See comments below

Do you require assistance?

Yes/No

Possible hazards to persons, property, or environment; eg: fire, drinking water, fish or wildlife

Material is caustic and should not be inhaled

Comments and/or recommendations

During off-loading of 800 one tonne bags of lime, straps on 6 bags failed during transport by fork lift. Ripped bags are set aside and will be removed by loader bucket as soon as off-loading is completed. Salvageable material will be used in the mill. The remaining material will be disposed of at West Twin Lake. This amount of Material presents no environmental hazard.

FOR SPILL LINE USE ONLY

Lead Agency

Spill significance

Lead Agency contact and time

Is this file now closed?

Reported by

R. Carneau

Position, Employer, Location

Process Technology Supervisor, Nanisivik

Telephone

819-476-7401

Reported to

Mitchell Maher

Position, Employer, Location


A.A.C.L. Ltd.

Telephone

8403-823-3117

Fax Transmission

Page 1 of 1

DIAND NWT Region
PO Box 100
Iqaluit, NT
XOA OHOFax: (819)-979-6445
Voice: (819)-979-4405To: Spill Line403-873-6924Date: November 1, 1994File: B9545-S-N563-0159B5555-1-94 NMLTransmittal Notes:Updates for Spills 94-008, -074, -089 - Nanisivik Mine.1. The licensee has advised the inspector that these
spills have been cleaned up.2. During the next inspection (not as yet scheduled)
the spill sites will be inspected. If clean-up has
been done to the satisfaction of the inspector, these
spills will be closed and you will be notified.

Number of pages to follow

0 Short0 LongIndian and Northern
Affairs CanadaAtkins (National)
of the North CanadaPaul Smith
Wild Resources Officer
DIAND NWT Region
P.O. Box 100
Iqaluit, N.W.T.
XOA OHOFax: (819) 979-4405
Fax: (819) 979-7140
Fax: (819) 979-7140

Canada

Fax Transmission

Page 1 of 2

DIAND NWT Region
PO Box 100
Iqaluit, NT
X0A 0H0

Fax: (819)-979-6445
Voice: (819)-979-4405

To: Spill Line

(403)-873-6924

Date: May 10, 1994

File: B5555-1-Nanisivik

Transmittal Note:

UPDATE ON SPILLS 94-074 & 94-075.

1. Spoke to Bob Carreau (NML) on May 6, 1994 regarding
the above noted spills.
2. Spill 94-074 (tailings material) is frozen in place
and will be cleaned up by hand when temperature permits.
This spill was well contained by natural depressions.
3. Spill 94-075 (reclaim water) was not contained. Water
started flooding the mill and was diverted by the
digging of a large trench. Water flowed through certain
portions of the building and down the hill towards the
temporary chemical storage area and into Twin Lakes

Number of pages to follow:

1 Short
0 Long



Indian and Northern
Affairs Canada

Attiéres Indiennes
et du Nord Canada

Paul Smith
Water Resources Officer
DIAND NWT Region

P.O. Box 100
Iqaluit, N.W.T.
X0A 0H0

Bus. (819) 979-4001
Fax (819) 979-8649
Fax (819) 979-8441

Canada

2/2

creeks area.

4. Metal levels in the recalin water were of acceptable
levels (within water licence limits).

5. Ground around mill was saturated with water.

6. I will be travelling to Nanisivik at the end of May.
I will inspect the spill areas at that time.

PCAL



N.W.T. SPILL REPORT

(Oil, Gas, Hazardous Chemicals or other Materials)

24-66 Δ6'9'6 Δ0'6'ΔΔ'Δ'Δ'Δ'Δ' Δ'6'6'6'
Phone/Δ'6'Δ'Δ' (403) 920-8130
Fax/Δ'6'Δ'Δ' (403) 873-8824

A Report date and time 27 JAN 94 07:14		B Date and time of spill (if known) 18 JAN 94 12:45		C Original report ☒ Update no. 1		Spill number 94-008	
D Location and map coordinates (if known) and direction (if moving) NANISIVIK NT							
E Party responsible for spill NANISIVIK MINES LTD							
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible)							
G Cause of spill							
H Is spill terminated? ☐ yes/Δ ☐ no/Δ6		I If spill is continuing, give estimated rate		J Is further spillage possible? ☐ yes/Δ ☐ no/Δ6		K Extent of contaminated area (in square metres if possible)	
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.)				M Containment (natural depression, dykes, etc.)			
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials							
O Do you require assistance? ☐ no ☐ yes, describe				P Possible hazards to persons, property, or environment; eg: fire, drinking water, fish or wildlife			
Q Comments and/or recommendations 1) PROBLEMS WITH ANIK E2 SATELLITE PREVENTED UPDATE PRIOR TO NOW. 2) LOCATION OF SPILL WAS APPROX 300m BEYOND THE "DOCK POND". AFTER THE DOCK POND, THE ROAD NOT A LINES LINE TURN RIGHT NOT LENDS SOUTH TOWARDS WEST TWIN LAKE (TWIN LAKES CONTAINMENT AREA). THE VALVE FAILURE TOOK PLACE ALONG THIS STRETCH OF ROAD. TWIN LAKES CREEK IS APPROX. 500m TO THE EAST OF THE SPILL SITE. 3) CLEAN UP WILL BE COMPLETE WITHIN A WEEK. THE MINNE WILL SUBMIT A DETAILED REPORT WITH MONTHLY SNP REPORT.						FOR SPILL LINE USE ONLY INAC Lead Agency Spill significance Lead Agency contact and time GREG COOK Is this file now closed? C's D's H's P's L's X's	
Reported by PAUL SMITH		Position, Employer, Location INAC NORTHERN AFFAIRS PROGRAM - IQUALUIT				Telephone (819) 979-4405	
Reported to DON CHATFIELD		Position, Employer, Location ARCTIC ALERT - SPILL LINE - YELLOWKNIFE				Telephone (403) 873-3317	




N.W.T. SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

24-Hour Report Line
24-05 Δ6565 D-05ΔD5-059 Δ56D5

Phone/Δ56D5 (403) 820-8130

Fax/Δ56D5 (403) 873-8924

A Report date and time Oct 15/93 13:06		B Date and time of spill (if known) Oct 8/93 17:00 est		C Original report ☒ Update no. 1		D Spill number 93-167	
P Location and map coordinates (if known) and direction (if moving) Nanisivik Mine at the Concentration Bldg.							
E Party responsible for spill Nanisivik Mines Ltd.							
F Products spilled and estimated quantities (provide metric volumes/weights if possible) Mill Tailings 10,000 l							
G Causes of spill N/A							
H Is spill terminated? ☒ yes ☐ no		I If spill is continuing, give estimated rate N/A		J Is further spillage possible? ☐ yes ☒ no		K Extent of contaminated area (in square metres if possible) N/A	
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) N/A				M Containment (natural depression, dykes, etc.) N/A			
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials N/A							
O Do you require assistance? ☐ no ☒ yes, describe: N/A				P Possible hazards to persons, property, or environment, eg: fire, drinking water, fish or wildlife N/A			
Q Comments and/or recommendations 1 page to follow						FOR SPILL LINE USE ONLY INAC Lead Agency Spill significance Lead Agency contact and time Is this sig now closed? N/A	
Reported by Paul Smith		Position, Employer, Location Water Res. Officer, Northern Affairs Program				Telephone (891)-979-6445	
Reported to Bob Kinnaird		Position, Employer, Location Station Manager, AACL Y.K.				Telephone (403)-873-3117	



DIAND IQUALUIT

ID:819-979-6445

OCT 15 '93 14:56 No.007 P.01

Fax Transmission

Page 1 of 1

Northern Affairs Program
PO Box 100
Iqaluit, NT
X0A 0H0

Fax: (819)-979-6445
Voice: (819)-979-4405

To: Spill LineDate: 15 October 93File: B9546-6-N5L3-0159Transmittal Notes:UPDATE OF SPILL 22-167

1. Line failure occurred just outside the mill and was acted upon immediately. Mill shut down and heavy equipment made bays to contain the material. Most material has since been placed in the tailings disposal area. Some material remains frozen on a roadbank, but will be cleaned up by next week. No tailings slurry made it into Twin Lakes Creek.

2. Area will be inspected during next inspection.

Number of pages to follow:

0 Short0 Long

Indian and Northern
Affairs Canada

Affaires Indiennes
et du Nord Canada

Paul Smith

Water Resources Officer
Northern Affairs Program

P.O. Box 100
Iqaluit, N.W.T.
X0A 0H0

Doc. (819) 979-4405
Fax (819) 979-4405
Fax (819) 979-6445

Canada

N.W.T. SPILL REPORT

(Oil, Gas, Hazardous Chemicals or other substances)


Northwest Territories

SPILL DATE: 08/09/93

SPILL TIME: 17:00

SPILL NUMBER: 93-167

A Report date and time OCT 8/93 15:50		B Date and time of spill (if known) OCT 8/93 17:00 (EDT)		C ☒ Original report ☐ Update no. 93-167	
D Location and map coordinates (if known) and direction of moving NANISIVIK MINE AT THE CONCENTRATOR BUILDING					
E Party responsible for spill NANISIVIK MINES LTD					
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) MILL TAILINGS 10,000 L					
G Cause of spill BROKEN TAILINGS LINE					
H Is spill terminated? ☒ yes / ☐ no		I If spill is continuing, give estimated rate NONE		J Is further spillage possible? ☐ yes / ☒ no	
K Extent of contaminated area (in square metres if possible) ABOUT 300 sq. metres					
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) NONE			M Containment method (dike, depression, dyke, etc.) DYKE BUILT WITH LOADERS		
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials WHEN FREEZING OCCURS WILL CLEAN UP WITH LOADERS AND REMOVE TO TAILINGS LAKE					
O Do you require assistance? ☒ no / ☐ yes, describe			P Possible hazards to persons, property, or environment (e.g. fire, drinking water, fish or wildlife) HIGH pH. CAUSTIC		
Q Comments and/or recommendations TO BE CONFIRMED - GREG COOK.			FOR SPILL LINE USE ONLY INAC Lead Agency Spill significance Lead Agency contact and time INAC - Greg Cook 16:27 Is this file now closed? C. D. B. 12/93		
Reported By ROBERT CARREAU		Position, Employer, Location PROCESS TECHNOLOGY SUPERVISOR NANISIVIK MINE		Telephone (819) 436-7401	
Reported to Y. Green		Position, Employer, Location STATION OPERATOR, AALL YK.		Telephone (403) 873-3117	





N.W.T. SPILL REPORT

(Oil, Gas, Hazardous Chemicals or other Materials)

212 102/82 DEC 20 '94 11:07
24-Hour Report Line
24-00 06:00 00:00 00:00 00:00
Phone 0600 (403) 920-8130
Fax 0600 (403) 873-8924

A Report date and time 20 December 1994 09:00h		B Date and time of spill (if known) 8 October 1993 17:0000		C Original report Update no. 93-167	
D Location and map coordinates (if known) and direction (if moving) Nahisivik Mine at the Concentration Bldg					
E Party responsible for spill Nahisivik Mines Ltd					
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) Mine Tailings 10,000 L					
G Cause of spill At 09:00					
H Is spill terminated? ☐ yes ☐ no		I If spill is continuing, give estimated rate At 09:00		J Is further spillage possible? ☐ yes ☐ no	
K Extent of contaminated area (in square metres if possible) 0.000000					
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) At 09:00			M Containment (natural depression, dykes, etc.) 0.000000		
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials 0.000000					
O Do you require assistance? ☐ no ☐ yes, describe:		P Possible hazards to persons, property, or environment; eg. fire, drinking water, fish or wildlife 0.000000			
Q Comments and/or recommendations 1. An inspection conducted during the summer of 1994 (31 May - 1 June) concluded that Spill 93-167 had been cleaned up. No further concerns noted. 2. This office considers this spill file closed.					
Reported by Paul Smith		Position, Employer, Location Water Resources Officer, Northern Affairs Program		Telephone (819) 979-4405	
Reported to Alex Bertin		Position, Employer, Location Station Operator, N.A.C.L. (Spill Line), YK		Telephone (403) 873-6724	



N.W.T. SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

24-Hour Report Line
Phone (403) 873 8130
Fax (403) 873 8924

A Report date and time JAN 28/93 8:34		B Date and time of spill (if known) JAN 27/93 14:00		C ☒ Original report ☐ Update no. 93-010	
D Location and map coordinates (if known) and direction (if moving) NANISIVIK MINE UNDERGROUND COMPRESSOR ROOM 17N					
E Party responsible for spill NANISIVIK MINE LTD.					
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) 2 litres of ASKAREL OIL (PCB'S)					
G Cause of spill TRANSFORMER FAILED DURING MAINTENANCE - INSULATOR CRACKED CAUSING SPILLAGE INTO CONTAINMENT SPILL PANS					
H Is spill terminated? ☒ yes ☐ no		I If spill is continuing, give estimated rate		J Is further spillage possible? ☐ yes ☒ no	
K Extent of contaminated area (in square metres if possible) SPILL PANS ONLY					
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) N				M Containment (natural depression, dykes, etc.) SPILL PAN	
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials TIPPED TRANSFORMER ONTO ITS SIDE TO STOP LEAKING. WILL BE ENCASED AND WELDED INTO A METAL CONTAINER AND STORED IN AN UNUSED AREA OF THE MINE UNDERGROUND.					
O Do you require assistance? ☒ no ☐ yes, describe:		P Possible hazards to persons, property, or environment eg. fire, drinking water, fish or wildlife N			
Q Comments and/or recommendations A FULL REPORT WILL FOLLOW				FOR SPILL LINE USE ONLY INAC Lead Agency MINOR Spill significance Lead Agency contact and time MIKE LOOGE JAN 28/93 09:40 Is this file now closed?	
Reported by BIB CARRELL		Position, Employer, Location PROCESS TECHNOLOGY SUPERVISOR		Telephone 436-7401	
Reported to R. CHIPMAN		Position, Employer, Location AACL		Telephone 873-3117	

92-135

Fax Transmission

Page 1 of 1

Northern Affairs Program
PO Box 100
Iqaluit, NWT
XCA OHQ

Fax: 1-819-979-6445
Office: 1-819-979-4405

To: Ken Hall
Pollution Control Div.
Renewable Resources
(403)-873-0221

Date: 8 July 92
File: B3555-1-92-135
N5L3-0159

Transmittal Note:

Update on spill 92-135:

I talked to Mr. Bob Carreau on 3 July 92.

Mr. Carreau said that they would be sampling on a

daily basis for the 14 day period after the spill,

then weekly after that, as per licence requirements.

Mr. Carreau stated that the results of this testing

would be included in the next monthly report.

Regards,

P. O. Smith

Number of pages to follow:

0 Short

0 Long

Paul Smith
WRO - Trainee
Baffin District



SPILL REPORT (Oil, Gas or Other Materials, i.e. Hazardous Chemicals, etc.)

24-Hour Report Line
Phone (403) 845-1301

92-135

update #1

A	Report Date June 25, 92	Date and Time of Spill if Known June 24th/92 at 17:00 B.S.T															
B	Location and Map Coordinates (if known) and Direction of Flowing Nanisivik Mine Property, East Side Water Treatment Plant																
C	Party-Responsible Nanisivik Mines Ltd																
D	Product Spilled and Estimated Quantity (provide name, volume/weight if possible) 660 M3 of untreated run-off water.																
E	Cause of Spill Catchment pond overflowed.																
F	Spill Terminated or Contained Spill terminated at 07:00 June 25th, 1992.																
G	Extent of Contaminated Area Spill followed drainage route South to Strathcona Sound.																
H	Factors Affecting Spill or Release - Temperature, Wind, Snow, Ice, Terrain, Buildings, etc. Temperature recorded at Mine-site was unusually high for this time of year (14 degree celsius). This accelerated melting of snowcover and run-off volumes were too large to contain at catchment pond. Spill not contained.																
J	Action, if any, Taken or Proposed to Contain, Remove, Clean-up or Dispose No action possible to stop spill on this occasion.																
K	Do You Require Assistance NO	If so, What Part -															
L	Hazard to Persons or Property or Environment - Fire, Drinking Water, Threat to Fish or Wildlife See analysis below.																
M	Comments and/or Recommendations Larger capacity discharge pipe will be installed to handle more volume should similar circumstances occur again.																
	<table border="1"> <thead> <tr> <th></th> <th>PH</th> <th>Zn</th> <th>Pb</th> <th>Kd</th> </tr> </thead> <tbody> <tr> <td>Samples collected at 19:00 June 24th, 1992.</td> <td>6.06</td> <td>2.29</td> <td>0.039</td> <td>0.007</td> </tr> <tr> <td>8:00 June 25th, 1992.</td> <td>6.32</td> <td>2.95</td> <td>0.028</td> <td>0.005</td> </tr> </tbody> </table> (analysis done in ug/l)			PH	Zn	Pb	Kd	Samples collected at 19:00 June 24th, 1992.	6.06	2.29	0.039	0.007	8:00 June 25th, 1992.	6.32	2.95	0.028	0.005
	PH	Zn	Pb	Kd													
Samples collected at 19:00 June 24th, 1992.	6.06	2.29	0.039	0.007													
8:00 June 25th, 1992.	6.32	2.95	0.028	0.005													
Reported by R. CARRISON	Position, Employer, Location Acting Mill Superintendent	Telephone 819-436-7472															
Reported to J.M.A Theriault	Position, Employer, Location District Manager, D.I.A.N.D	Telephone 819-979-4405															



SPILL REPORT

(Oil, Gas or Other Materials, i.e. Hazardous Chemicals, etc.)

24-Hour Report Line
Phone (403) 920-8130

A	Report Date <i>June 24/92</i>	Date and Time of Spill if Known <i>June 24 17:00 hrs.</i>	92-135
B	Location and Map Coordinates (if known) and Direction if Moving <i>Nanisivik Mines Ltd 73°N on Baffin Island</i>		
C	Party Responsible <i>Nanisivik Mines Ltd.</i>		
D	Product Spilled and Estimated Quantities (Provide Metric Volumes/Weights if Possible) <i>acid mine drainage quantity unknown</i>		
E	Cause of Spill <i>quickness of run-off</i>		
F	Is Spill Terminated or Continuing <i>continuing</i>		
G	Extent of Contaminated Area <i>flowing in creek area (called adit)</i>		
H	Factors Affecting Spill or Recovery - Temperature, Wind, Snow, Ice, Terrain, Buildings, etc. <i>temperature</i>		
I	Containment - Naturally, Booms, Dykes or Other, No Containment <i>none</i>		
J	Action, if any, Taken or Proposed to Contain, Recover, Clean-up or Dispose <i>none</i>		
K	Do You Require Assistance <i>No.</i>	If so, What Form	
L	Hazard to Persons or Property or Environment - Fire, Drinking Water, Threat to Fish or Wildlife <i>environment</i>		
M	Comments and/or Recommendations <i>significance: lead agency: NAC Baffin Region NAD office E. PARVIN (ENVT Renewable Resource) contacted at 18:35 hrs. GREG COOK (NAD/WAC) contacted at 18:40 hours. ED COLLINS (ENVT Canada) contacted at 19:00 hours.</i>		
Reported by <i>Robert Arrau</i>		Position, Employer, Location <i>Environmental Technician, Nanisivik</i>	Telephone <i>(844) 436-7472</i>
Reported to <i>Pam (Arctic Admin.)</i>		Position, Employer, Location	Telephone <i>920-8130</i>

Archives
Nanisivik
Northwest Territories

4/5

SPILL REPORT

(Oil, Gas or Other Materials, i.e. Hazardous Chemicals, etc.)

24-Hour Report Line
Phone (403) 620-8190

91-123

A Report Date July 28/91	Date and Time of Spill if Known - July 7/91 18:30	
B Location and Map Coordinates (if known) and Direction if Moving - EAST ADIT CATCHMENT POND - BARTIN ISLAND NANISIVIK		
C Party Responsible - MINERAL PROCESSING DEPT.		
D Product Spilled and Estimated Quantities (Prefer Metric Volumes/Weights if Possible) - 400 LITRES / MIN. ADV. EST. = 120 m³		
E Cause of Spill - 25 min of rain		
F Is Spill Terminated or Continuing - started treatment system, pumped through line treatment down to 20 Ltr/min by 8:00. ceases overflow by 10:00 AM. - TERMINATED		
G Extent of Contaminated Area - SPILL FOLLOWED NATURAL DRAINAGE ROUTE TO STREATHONA SOUND.		
H Factors Affecting Spill or Recovery - Temperature, Wind, Snow, Ice, Terrain, Buildings, etc. - NO RECOVERY		
I Containment - Naturally, Booms, Dikes or Other, No Containment - no containment		
J Action, if any, Taken or Proposed to Contain, Recover, Clean-up or Dispose - no action taken - water was gone		
K Do You Require Assistance - no	If so, What Form -	
L Hazards to Persons or Property or Environment - Fire, Drinking Water, Threat to Fish or Wildlife		
M Comments and/or Recommendations LEAKED FROM D DISTRICT IGAAHIT Analysis of 2 water samples: July 8 1 at 200 am - PH 8.2, Zinc 1.5 mg, Lead 0.050, SILICIF: Minor 1 at 8:30 - PH 9.2, Zinc 1.03 mg, Lead 0.021 CADMIUM FOR BOTH WAS .005. Called Andy Thurnquist and passed spill 16:20		
Reported by KEN RAWLING Reported to LAURIE	Position, Employer, Location ACTING MILL SUP'T. Position, Employer, Location SPILL LINE	Telephone 819-436-7472 Telephone 403-920-8130

Government of the Northwest Territories
SPILL REPORT
(Oil, Gas or Other Materials, i.e. Hazardous Chemicals, etc.)

GNWT 2/16
90-114
90/07/11

A	Report Date July 16, 1990	Date and Time of Spill or Release Morning of June 25, 1990 through to morning of June 27, 1990.
B	Location and Map Coordinates (if known) and Direction of Flowing East Adit Catchment Pond - Naniisivik	
C	Party Responsible Mineral Processing Department	
D	Product Spilled and Estimated Quantities (Provide Name, Volume/Weight if known) Eighteen litres/min or approx. 50 m3 of untreated run-off water.	
E	Cause of Spill Instrumentation problem with treatment system causing pond to fill up and overflow.	
F	Is Spill Terminated or Containing? Terminated on June 27, 1990.	
G	Extent of Contaminated Area Spill followed natural drainage route to Strathcona Sound.	
H	Factors Affecting Spill or Recovery: Temperature, Wind Speed, Ice Cover, Buildings etc. Catchment pond full making recovery impossible.	
I	Containment: Methods, Success, Delay or Other: See Containment No containment.	
J	Action, if any: Taken or Proposed to Contain, Recover, Clean-up or Dispose Instrumentation problem with treatment system corrected.	
K	Do you Require Assistance No	Is Spill: Harmful No
L	Hazard to Persons or Property or Environment: Fire, Draining Water, Threat to Fish or Wildlife No	
M	Comments and Recommendations Water Resource Officer made aware of this discharge on June 26 followed by a formal letter with analysis. Book: T.N.R.C. - N.A.S. Incident Signed: [Signature] K(1)	
Reported By		Person Employed Locally