



Photo 18 Looking south along crest of slope where tank farm was located. The slope to the right needs to be flattened and re-contoured.



Photo 19 Looking north along crest of slope below tank farm area. Slope needs to be flattened.





Photo 20 Looking north across former product storage building foundation.



Photo 21 View of cover over product storage area, towards reclaimed slope above.





Photo 22 View of shoreline area in front of product storage building area.



Photo 23 View towards former dock cell area, from product storage building.





Photo 24 Looking south towards bench which contained tank farm. Note steepness of slope below tank farm bench compared with reclaimed and re-contoured slope above.



Photo 25 Looking south along former dock cell area.





Photo 26 Shoreline to north of former dock cell area.



Roll 5 Photo 1 View of former barge area.





Photo 2 Main portal area backfilled.



Photo 3 Looking south towards Main Portal area from road to LRD Quarry.





Photo 4 Looking south from road to LRD Quarry, along shoreline north of dock area.



Photo 5 Looking north along road to LRD Quarry. Note reclaimed slopes.





Photo 6 LRD Quarry with thermistors inside barrels.




Photo 7 View of steel casing to house thermistors inside barrels.





Photo 8 View to northwest across LRD Quarry Landfill cover. Note notch cut out of rock at far end for drainage.



Photo 9 Edge of cover along south side of quarry.





Photo 10 Edge of cover along east side of quarry.




Photo 11 South side slopes of quarry. Mound at the top of the slope is the north end of the Polaris runway.





Photo 12 Close-up view of LRD Landfill cover material, composed of limestone obtained from LRD Quarry.



Photo 13 Reclaimed slopes in former open pit area, located above the North Portal.





Photo 14 Reclaimed slope above the North Portal.



Photo 15 Looking east along re-contoured slopes east of North Portal area.





Photo 16 Backfilled North Portal.



Photo 17 Reclaimed shoreline area in front of North Portal.





Photo 18 View of temporary trailer camp set up in vicinity of former CRF Plant area.



Photo 19 View to south of airstrip area.





Photo 20 Looking north from end of runway across LRD Quarry.



Photo 21 Benches along east side of LRD Quarry.





Photo 22 View along runway in vicinity of accommodation complex.



Photo 23 Reclaimed site of former accommodation complex.





Photo 24 Looking north along west side of runway towards area to the north of the accommodation complex.



Photo 25 Runway, looking south.





Photo 26 Miscellaneous equipment left on site at the trailer camp for ongoing remedial repairs.