

## WATER LICENCE INSPECTION FORM

Original	
Follow-Up	Report

Licensee			epresentat	ive					
Mosher Engineering Ltd Marc Losier									
Licence No. / Expiry		•	ative's Title						
1BH-RFS0910	Project Manager								
Land / Other Authorizations Land / Other Authorizations									
Date of Inspection Inspector									
04/07/2014	Justin HACK								
Activities Inspected									
☐ Camp	☐ Drilling								
Roads/Hauling Conditions: A -	Other: Records  Acceptable	C - Concern U - Unaccep		NA –	Not Applicable	NI – Not Ins	pected		
Water Use	Condition Comment		Condition	Comment	Haz/Mat Manage		Comment		
Intake/Screen	NA	Water Management Structures	NA		Storage	NA			
Flow Measure. Device		Culverts / Bridges	NA		Spills	NA			
Source:	NA	Drainage	NA		Spill Plan	NA			
Water Use:	NA	Erosion / Sediment	NA		·				
Recirculation ( y /n)	NA	Mitigation Measures	NA		Administrative				
		Reclamation Activities	Α	1	Records	Α			
		Materials Storage	NA		Reports	А			
Waste Disposal		Signage	NA		Plans	NA			
Waste Water	NA				Notifications	NA			
Solid Waste	NA	Monitoring			Other				
Hazardous Waste	NA	Sample Collection / Analysis	NA						
,	*The number in the	comments field will correspond	with spec	ific comn	nents provided belo	W.			
	Comments	Non-Compliance w	ith Act o	r Licence	Act	ion Required			
<u>Background</u>									
Water discharge and waste disposal activities took place in August 2010 by Mosher Construction as part of the Hydrometric Testing									
of the Rankin Inlet Fuel Storage Facility. Approximately 3064m³ of salt water was used from Hudson Bay to check the integrity of six									
tanks. A water sample was taken by the Licensee from the tanks before discharge and the Licensee was given approval to discharge									
by the Nunavut Water Board (NWB).									
<u>Inspectors Statement</u>									
_	•	n was conducted at the Rankin Ir				•			
activities associated with this licence have ceased and the licence is expired, the inspection was focused on determining whether all									
relevant terms and conditions of the NWB Licence No. 1BH-RFS0910 were met prior to the expiration of the licence.									
Observations on Site									
1. An inspection of the effluent discharge location was conducted to determine if the activity was effectively remediated.									
Photos taken by the Licensee of the effluent discharge activity and observations from this on-site inspection confirm that									
the licensee has completed all restoration work as required by the water licence.  2. The licensee has indicated through correspondences that the sludge was put in the sludge tank at the fuel storage facility.									
		· .		<u> </u>			omry.		
SECTION 2	Comments	Non-Compliance w	ith Act o	r Licence	Act	ion Required			
Inspector's Name  Justin Hack									
Signature Signature									
Justin favor									
Date									
August 20, 2014									

