



P.O. Box 119
GJOA HAVEN, NU X0B 1J0
TEL: (867) 360-6338
FAX: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᑎᓕᓂᓪ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYINGI
OFFICE DES EAUX DU NUNAVUT

File No.: 1BR-CAM0520/TR/B1

January 13, 2011

Douglas Craig, Environmental Officer
DEW Line Clean Up
Defence Construction Canada
Constitution Square, Suite 1720, 350 Albert Street
Ottawa ON K1A 0K3
E-mail: Douglas.Craig@dcc-cdc.gc.ca

RE: Submission of 2007 Landfill Monitoring Report, Licence No. 1BR – CAM0520, CAM-M Cambridge Bay Site

Dear Mr. Craig:

The Nunavut Water Board (“NWB”) received on August 1, 2008, from Defence Construction Canada (DCC), the document entitled “The Collection of Landfill Monitoring Data at the CAM-M Cambridge Bay Site – 2007 Report,” dated January 2008. On October 23, 2008, the Board acknowledge receipt and distribute the document to interested parties and persons for information purposes. No comments have been received to date. The report was reviewed and determined to be partly consistent with the reporting requirements in the licence: Part B, Item 1 of the terms and conditions in the Licence requires that the monitoring report be a subset of the annual report as opposed to superseding the annual reporting requirement. To completely satisfy the annual reporting requirements, future reports should be submitted to the Board on or before March 31st following the calendar year being reported and should also address the items listed below:

- *Part B, Item Iiii* – a summary of any abandonment and restoration work undertaken during the year and an outline of any work anticipated for the next year;
- *Part B, Items Ivi* – a public consultation/participation report describing consultation with local organizations and the residents of the nearby communities; and
- *Part B, Item Iviii* – an executive summary in English and Inuktitut of all plans, reports, or studies conducted under this Licence.

In addition, the Licensee is advised to provide the Board with written confirmation, by March 31, 2011, of the measures implemented to address the following issues that were identified in the 2007 Monitoring Report for the CAM-M Cambridge Bay Site:

- Main Landfill, North – Ponding;
- Main landfill, South – Limited erosion
- South Shore Landfill – Minor depressions, ponding and seepage;
- Airport Landfill – Exposed metal debris; and
- Tier II Soil Disposal Facility – cracks and exposed geotextile material.

The Board reminds the Licensee that the 2006, 2008, and 2009 Annual Reports remain outstanding and should be submitted together with the 2010 Annual Report. The Licensee is encouraged to provide the Board with the results of reviews and recommendations made by the Environmental Working Group (EWG) subsequent to the submission of the 2007 Monitoring Report.

Should you have any question please feel free to contact the undersigned at 867-360-6338 ext. 25 or by email at sjoseph@nunavutwaterboard.org.

Yours truly,

Original Signed By:

Sean Joseph
Technical Advisor

Cc: Distribution List –Kitikmeot Region