

APPENDIX A

Site Photographs



Project Photographs

Long Term Monitoring, 2017
PIN-B, Clifton Point, Nunavut



Photo: 1

Date:

August 3, 2017

Description:

Northwest side of the NHL.
Monitoring Well MW1 in
middle of photo, on right
hand side.

Location:

Viewpoint 42 (Figure 2)

Direction Taken:

SE



Photo: 2

Date:

August 3, 2017

Description:

Southwest side of the NHL.

Location:

Viewpoint 30 (Figure 2)

Direction Taken:

NE

Project Photographs

Long Term Monitoring, 2017
PIN-B, Clifton Point, Nunavut



Photo: 3

Date:

August 3, 2017

Description:

Southeast side of the NHWL.
Monitoring Well MW3 in
foreground at red stakes.

Location:

Viewpoint 19 (Figure 2)

Direction Taken:

NW



Photo: 4

Date:

August 3, 2017

Description:

Northeast side of the NHWL.
Monitoring Well MW4 in
foreground.

Location:

Viewpoint 17 (Figure 2)

Direction Taken:

SW

Project Photographs

Long Term Monitoring, 2017
PIN-B, Clifton Point, Nunavut



Photo: 5

Date:

August 3, 2017

Description:

View of grading on surface of
NHWL.

Location:

Viewpoint 25 (Figure 2)

Direction Taken:

N



Photo: 6

Date:

August 3, 2017

Description:

View of grading of slope on
northwest side of NHWL.
Typical of all sides.

Location:

Viewpoint 37 (Figure 2)

Direction Taken:

E

Project Photographs

Long Term Monitoring, 2017
PIN-B, Clifton Point, Nunavut



Photo: 7

Date:

August 3, 2017

Description:

View of an animal burrow near the north corner of the NHWL (Feature A).

Location:

Viewpoint 45 (Figure 2)

Direction Taken:

W



Photo: 8

Date:

August 3, 2017

Description:

View of attempted animal burrow, since filled in. Previously-noted animal burrow (Feature A) seen at right of photo.

Location:

Viewpoint 51 (Figure 2)

Direction Taken:

W

Project Photographs

Long Term Monitoring, 2017
PIN-B, Clifton Point, Nunavut



Photo: 9

Date:

August 3, 2017

Description:

View of droppings at animal burrow near the north corner of the NHWL (Feature A).

Location:

Viewpoint 45 (Figure 2)

Direction Taken:

W



Photo: 10

Date:

August 3, 2017

Description:

One of four concrete pads at Main Station Area.

Location:

Viewpoint 49 (Figure 2)

Direction Taken:

N

Project Photographs

Long Term Monitoring, 2017
PIN-B, Clifton Point, Nunavut



Photo: 11

Date:

August 3, 2017

Description:

View of natural drainage on the southwest side of NHWL (Feature B).

Location:

Viewpoint 46 (Figure 2)

Direction Taken:

E



Photo: 12

Date:

August 3, 2017

Description:

View of drainage pathway on the southeast side of NHWL (Feature C).

Location:

Viewpoint 47 (Figure 2)

Direction Taken:

N

Project Photographs

Long Term Monitoring, 2017
PIN-B, Clifton Point, Nunavut



Photo: 13

Date:

August 3, 2017

Description:

View of previously identified settlement along the eastern side of the NHL (Feature D).

Location:

Viewpoint 58 (Figure 2)

Direction Taken:

NE



Photo: 14

Date:

August 3, 2017

Description:

View of newly identified settlement at the southeast corner of the NHL (Feature G)

Location:

Viewpoint 54 (Figure 2)

Direction Taken:

E

Project Photographs

Long Term Monitoring, 2017
PIN-B, Clifton Point, Nunavut



Photo: 15

Date:

August 3, 2017

Description:

View of newly identified settlement along the western side of the NHL (Feature I).

Location:

Viewpoint 56 (Figure 2)

Direction Taken:

W



Photo: 16

Date:

August 3, 2017

Description:

View of newly identified settlement along the northwest side of the NHL (Feature H).

Location:

Viewpoint 55 (Figure 2)

Direction Taken:

NW