Appendix E – Photographs



APPENDIX E

Photographs



Photo 1: Clyde River from the bridge in July 2011; east aspect



Photo 2: Clyde River from the bridge in July 2011; west aspect.




Photo 3: Aerial photograph depicting locations of the four drainage channels and pond located at the Old Town Site in August 2010; west aspect.



Photo 4: Drainage channel #1 from ATV trail location in July 2011; east aspect.



Photo 5: ATV crossing location at drainage channel #1 in July 2011; south aspect.



Photo 6: Drainage channel #1 from ATV trail location in July 2011; west aspect.



Photo 7: Drainage channel #2 from ATV trail location in July 2011; east aspect.



Photo 8: ATV crossing location at drainage channel #2 in July 2011; north aspect.



Photo 9: Drainage channel #2 from ATV trail location in July 2011; west aspect.



Photo 10: Drainage channel #3 in August 2010; east aspect.



Photo 11: Drainage channel #3 from ATV trail location in July 2011; east aspect.




Photo 12: ATV crossing location at drainage channel #2 in July 2011; southeast aspect.




Photo 13: Drainage channel #3 in July 2011; west aspect.



Photo 14: ATV crossing location at drainage channel #4 in July 2011; east aspect.



Photo 15: Drainage channel #4 from ATV trail location in July 2011; west aspect.



Photo 16: Watercourse adjacent to potential borrow sources deposits 1, 2 and 3 in July 2011; east aspect.



Photo 17: Watercourse adjacent to potential borrow sources deposits 1, 2 and 3 in July 2011; southwest aspect with Clyde River in the background.



Photo 18: Watercourses near borrow source deposits 4 and 6 in July 2011; southeast aspect.



Photo 19: Nearshore area at the Old Town Site in August 2010; south aspect.



Photo 20: Ponded surface water at the Site Dump located at the Old Town Site; north aspect.

Remediation of the Old Town Site, Clyde River, Nunavut
Environmental Screening
Final
Appendix E – Photographs

THIS PAGE LEFT BLANK INTENTIONALLY