

October 29th, 2020

Ms. Stephanie Autut
Executive Director,
Nunavut Water Board
P. O. Box 119
Gjoa Haven, Nunavut
X0B 1J0

Dear Ms. Autut:

Pursuant to Part E, Article 6(c) and (d) of Water Licence 1BR-CUL1828, please find appended an e-copy of a report by **exp** Services Inc. entitled "2020 Tailings Facility Examination, Cullaton Lake Gold Mine".

Summarized, the consultant recommends:

- Continued visual surveillance of the Tailings Pond No. 1 spillway for erosion.
- Water levels are monitored for how they serve as cover for the tailings.
- Wet spots down stream of the dam continue to be monitored.
- Surficial cracking noted in 2017 is monitored during subsequent visits.
- As per past recommendations, the frequency of geotechnical inspections be reduced to once every 3 years (note - this frequency has been adjusted to every 2 years starting in 2020 to coincide with the frequency outlined in the new water license issue October 15th 2018).

Should you have any questions regarding this report or any other Cullaton Lake matter, please don't hesitate to contact the undersigned.

Sincerely,



Paul Brugger, P. Eng.
Closed Properties Manager, Eastern Canada Sites
Tel: (705) 632-1871
Cell: (807) 631-4895
E mail: pbrugger@barrick.com

Cc Godwin Okonkwo, Manager, Water Resources, Crown Indigenous Relations and Northern Affairs Canada
Allison Brown, Canadian Closed Properties Manager, Barrick Gold Corp.

Attachment: As stated