



Photo 17: Looking west over backfilled and re-graded APEC 8.2 (centre) and APEC 1 (lower right corner) (August 15, 2014).



Photo 18: Overlooking the main site. Tanks right to left: APEC 9 (Tank 1), APEC 10 (Tank 2), APEC 11 (Tank 3), APEC 12 (Tank 4). Buildings left to right: APEC 16 (Building 3), APEC 14 (Building 1), APEC 17 (Building 4), and APEC 15 (Building 2) (June 5, 2014).





Photo 19: Looking south up at APECs (from left to right): APEC 9 (Tank 1), APEC 10 (Tank 2), APEC 11 (Tank 3), and APEC 12 (Tank 4). The stakes mark out APEC 12 excavation. APEC 13, overhead pipeline, is visible on the left (June 7, 2014).



Photo 20: Looking northwest over APEC 12 excavation to survey limits (June 24, 2014).





Photo 21: Looking southwest at additional excavation of the south and southwest walls of APEC 12 excavation. APEC 12 areas 2 and 3 are backfilled in the top right corner (July 28, 2014).



Photo 22: Looking south at backfilled and re-graded APEC 12 excavation (August 13, 2014).





Photo 23: Looking north at APEC 13, overhead pipeline, and buildings (left to right): APEC 16 (Building 3), APEC 14 (Building 1), APEC 17 (Building 4) and APEC 15 (Building 2).



Photo 24: Looking south at APEC 13.1 the stained soil to be excavated between APEC 16 (Building 3) on the right, and APEC 14 (not shown) (June 5, 2014).





Photo 25: Looking south over APEC 13.1 excavated to survey limits. Note square on left hand side indicating sample exceedance that was further excavated (July 25, 20114).



Photo 26: Looking north at former locations of APEC 18 (Building 5), APEC 16 (Building 3) and APEC 13.1 excavation.





Photo 27: Looking northeast at APEC 13.2 excavation indicated by survey stakes (June 28, 2014).



Photo 28: Looking south at APEC 13.2 excavation to survey limits (June 30, 2014).





Photo 29: Looking south at additional excavation of APEC 13.2 to the north and south (under the basement floor of APEC 14(Building 1)) (July 28, 2014).



Photo 30: Looking south at backfilled APEC 13.2, APEC 14 (Building 1) and APEC 17 (Building 4) (August 30, 2014).





Photo 31: Looking east at the southwest side of APEC 14 (Building 1) (June 8, 2014).



Photo 32: Demolition of APEC 14 (Building 1) (July 24, 2014). See Photo 30 for backfilled APEC 14 (Building 1).





Photo 33: Looking northeast at the southwest face of APEC 15 (Building 2) (June 26, 2014).



Photo 34: Excavations of metal impacted soil (APEC 15.Met) and APEC 15.1 to the southwest of APEC 15 (Building 2) (June 27, 2014).





Photo 35: Looking southeast at APEC 15.2 excavation west of APEC 15 (Building 2) (June 26, 2014).





Photo 36: APEC 15.3 unidentified soil excavation along the southwest side of APEC 15 (Building 2) and expanding under the northwest corner of APEC 15 (Building 2) (August 24, 2014).



Photo 37: APEC 15 (Building 2) and APEC 15.3 excavation backfilled and re-graded (August 30, 2014).





Photo 38: Looking northwest at the south side of APEC 16 (Building 3) (July 2, 2014).



Photo 39: Looking southwest at the northeast side of APEC 17 (Building 4), with asbestos wrapped material in front, and APEC 14 (Building 1) to the right (July 5, 2014). See Photo 29 for post demolition photo.





Photo 40: Looking northwest at the demolition of APEC 16 (Building 3) on the left and APEC 17 (Building 4) on the right and APEC 14 (Building 1) in the center (July 7, 2014).



Photo 41: APEC 18 (Building 5) prior to demolition (June 26, 2014).





Photo 42: Looking southwest at former location of APEC 18 (Building 5) (August 13, 2014).



Photo 43: Looking northeast APEC 19 (Building 6) and APEC 20 (June 3, 2014).





Photo 44: Footprint of former APEC 19 (Building 6) post demolition. APEC 20 (Building 7) is visible in the background (June 18, 2014).