



Photo 45: Looking southeast at APEC 20 (Building 7) and APEC 21 (Building 8) (June 3, 2014).



Photo 46: APEC 20 (Building 7) post demolition (June 25, 2014).



Photo 47 APEC 20.1 excavation completed to survey limits (July 2, 2014).



Photo 48: Looking northeast at APEC 20.2 excavation completed to survey limit (June 30, 2014).



Photo 49: Looking northeast at backfilled APEC 20.1 and APEC 20.2 (July 24, 2014).



Photo 50: Building 9 at APEC 22 prior to demolition (July 3, 2014).



Photo 51: Backfilled excavations and re-graded area at APEC 22 (August 1, 2014).



Photo 52: Looking southwest at APEC 23 (barrel walls) north of APEC 14 (Building 1). See Photo 25 for re-graded area of APEC 23.



Photo 53: Baseline sampling of barrel processing area, APEC 24, with APECs 25 to 27 in the background to the left (June 9, 2014).



Photo 54: Looking northwest at APEC 27, with APEC 26 and APEC 25 to the right (August 13, 2014).



Photo 55: Looking north over re-graded APEC 24 (September 17, 2014).



Photo 56: Looking north over APEC 28, buried debris area and former landfill (June 6, 2014).



Photo 57: Looking south, at re-graded APEC 28, as the east side of the current landfill (July 31, 2014).



Photo 58: Looking southwest at Building 10 (June 6, 2014).



Photo 59: Looking north at re-graded area of former Building 10 (July 21, 2014).



Photo 60: Overview of the Site before remediation (June 3, 2014).



Photo 61: Overview of Site during remediation (July 12, 2014)



Photo 62: Overview of the Site during demolition (July 18, 2014).



Photo 63: Overview of Site during demolition and additional excavations (August 12, 2014).



Photo 61: Overview of the Site after remediation (September 28, 2014)

REMEDIATION OF THE ENNADAI LAKE FORMER WEATHER STATION, NU

Appendix E LU/WL Inspection
March 31, 2016

Appendix E LU/WL INSPECTION

Date: July 8th, 2015

Project: Ennadai Lake Remediation

Water Licence No.: 1BR-ELR1419

Licensee: Contaminated Site, AANDC

Inspector: WRO C Wilson

Representative: Dele Morankinyo



Observation: Erosion to hill side near old fuel tank locations (61° 7' 52.82"N, 100° 53' 20.8"W), Ennadia Lake Remediation Project,

Date: July 8th, 2015
Project: Ennadai Lake Remediation

Water Licence No.: 1BR-ELR1419
Licensee: Contaminated Site, AANDC

Inspector: WRO C Wilson
Representative: Dele Morankinyo



Observations: Erosion (61° 7' 52.82"N, 100° 53' 20.8"W) sedimentation observed in water around lakefront near activity (61° 7' 54"N, 100° 53' 25"W).

Date: July 8th, 2015
Project: Ennadai Lake Remediation

Water Licence No.: 1BR-ELR1419
Licensee: Contaminated Site, AANDC

Inspector: WRO C Wilson
Representative: Dele Morankinyo



Observations: 20 fuel drums, unlabeled, suspected owner GN-DOE (61° 8' 1.78"N, 100° 52' 26"W)

Date: July 8th, 2015
Project: Ennadai Lake Remediation

Water Licence No.: 1BR-ELR1419
Licensee: Contaminated Site, AANDC

Inspector: WRO C Wilson
Representative: Dele Morankinyo



Observations: 7 drums of fuel with public works labels and 20 unknown drums at airstrip (61° 8' 1.78"N, 100° 52' 26"W)

Date: July 8th, 2015

Project: Ennadai Lake Remediation

Water Licence No.: 1BR-ELR1419

Licensee: Contaminated Site, AANDC

Inspector: WRO C Wilson

Representative: Dele Morankinyo



Observations: A number of locations had little pieces of garbage near old main building area (61° 7' 53.89"N, 100° 53' 25.68"W)