| NWB Annual Report | Year being reported: 2020 |
|-------------------------|----------------------------|
| | |
| icansa No: 1DD EL D1920 | Issued Date: June 28, 2018 |

Expiry Date: June 27, 2029

Project Name: Ennadai Lake Long Term Monitoring

Licensee: Crown-Indigenous Relations and Northern Affairs Canada

(CIRNAC) Contaminated Sites

Mailing Address: PO Box 2200

Iqaluit NU X0A 0H0

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

The Ennadai Lake site was a former weather station, located approximately 370 km west of Arviat (the nearest community) and 500 km southwest of Rankin Inlet, Nunavut, at approximately 61° 07' 51" N latitude and 100° 53' 14" W longitude. The site was developed in the 1950s and was operated both as a manned and unmanned station, at different times since its construction and was abandoned in the late 1980s to early 1990s.

Remediation activities at the site were undertaken between 2014-2015, and included the construction of a non-hazardous waste landfill (NHWL), demolition and disposal of onsite structures, and clean-up of hazardous materials and contaminated soil.

As per departmental commitments to monitor the NHWL post-closure, a 25-year long term monitoring (LTM) program was initiated at Ennadai Lake in 2016 and includes visual inspection, groundwater sampling, soil sampling (as required), and natural environment monitoring. Refer to the *Ennadai Lake Long Term Monitoring Plan* (2016) for more details.

Year 1, 3 and 5 of the LTM Plan took place in 2016, 2018, and 2020 respectively. Future events are scheduled for 2022, 2025, 2030, 2035, and 2040.

| Part B | m 1 ▼ |
|--|--|
| the state of the s | d waste disposal activities, including, but not limited to: methods of water management; drill waste management; solid and hazardous |
| Water Source(s): | Monitoring Wells at the NHWL (See GPS Coordinates Page) |
| Water Quantity: | 1/day Quantity Allowable Domestic (cu.m) <0.05 |
| duplicate were colle (with no duplicate) of the sample taken would during the site used/collected was the center of the Nh Monitoring activities of Rankin Inlet, NU paper towels, pape were collected and activities. Refer to the Ennada Ennadai Lake 2020 | e on August 27th, 2020. A groundwater sample and a ected from monitoring well (MWLF-3), and a sample was collected from MWLF-1. MWLF-1 was not dry, but ras purge water as groundwater did not recharge in the visit. MWLF-2 was dry. The total volume of water less than 10 litres. Excess purge water was disposed in HWL. So were conducted within a single day and were based out so no camp was required. Solid wastes (packaging, r, kimwipes, filters, Teflon tubing) generated (< 0.5 m3) removed from the site at the completion of monitoring at Lake Lake Long Term Monitoring Plan (2016) and OLTM Report for details. |
| A list of unauthorized discharges a Spill No.: No spills | and a summary of follow-up actions taken. (as reported to the Spill Hot-line) |
| Date of Spill: N/A Date of Notification to | |
| Revisions to the Spill Contingency | / Plan |
| No Spill Contingency Plan (| |
| Additional Details: | |
| N/A | |

Licence Requirements: the licensee must provide the following information in accordance

with

| Revisions to | the Abandonment and Restoration Plan | |
|---------------------|--------------------------------------|---|
| | N/A - not applicable ▼ | |
| | Additional Details: | _ |
| | N/A | |
| | | |

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No progessive reclamation work was undertaken in 2020.

Year 5 of LTM occurred on August 27, 2020. A visual inspection of the NHWL and surrounding area was conducted in accordance with the Abandoned Military Site Remediation Protocol (AMSRP) and the site-specific LTM Plan. The NHWL was found to be in acceptable condition. No new staining, seepage points or settlements were observed, and all other features previously identified have either decreased in size and extent, or have remained relatively stable. None of the features noted in the report are considered to affect the physical integrity of the NHWL. Significant erosion was observed along the access road to the airstrip during the site visit. This area of erosion does not appear to impact the integrity of the NHWL but could impact access to both the NHWL and the weather station.

A total of 3 groundwater samples were collected (1 samples and 1 blind duplicate from MWLF-3, 1 purge water sample from MWLF-1). The samples were submitted for analysis and detailed results can be found in the *Ennadai Lake 2020 LTM Report*. Soil samples were not collected because there was no indication of new seepage or staining.

As per the *Ennadai Lake Lake Long Term Monitoring Plan* (2016), future LTM events are scheduled for 2022, 2025, 2030, 2035, and 2040 (Years 7, 10, 15, 20, and 25 respectively).

Results of the Monitoring Program including:

Details attached

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized:

| Additional Details: | |
|--|--|
| Additional details regarding water sources can be found in the <i>Ennadai</i> Lake Long Term Monitoring Plan (2016). | |

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

Remediation was completed in 2015 and the only structure remaining at the site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated is removed from the site at the completion of LTM activities.

Results of any additional sampling and/or analysis that was requested by an Inspector

| | No additional sampling requested by an Inspector or the Board | | |
|--|--|--|--|
| | Additional Details: (date of request, analysis of results, data attached, etc) | | |
| | N/A | | |
| Any other de being report | etails on water use or waste disposal requested by the Board by November 1 of the year ed. | | |
| | No additional sampling requested by an Inspector or the Board | | |
| | Additional Details: (Attached or provided below) | | |
| | N/A | | |
| Any resnons | es or follow-up actions on inspection/compliance reports | | |
| Any respons | No inspection and/or compliance report issued by INAC | | |
| | Additional Details: (Dates of Report, Follow-up by the Licensee) | | |
| | The last inspection conducted at Ennadai Lake was in 2015. The 2015 Inspection Report is available on the NWB ftp site. The majority of issues were identified during remediation and no issues remain applicable to post-remediation monitoring activities. | | |
| Any addition | al comments or information for the Board to consider | | |
| Any addition | Physical observations of the NHWL conducted during the 2020 LTM event indicate that the NHWL at Ennadai Lake is in acceptable condition, is performing as designed, and is containing the enclosed waste. | | |
| | | | |
| Date Submit Submitted/P Contact Info | repared by: Selma Al-Soweydawi, CIRNAC | | |