



Photo G41: Landfarm 2, looking southeast.



Photo G42: Landfarm 2, looking west.



Photo H-1: APEC 3 – Stain 3 – Organic content remaining in the pipeline



Photo H-2: APEC 4 - Tank 5 (42000L) - Organic content remaining in Tank 5



Photo H-3: APEC 5 - Drums (Located on the shore of Ennadai Lake) - Total and leachable lead painted drums



Photo H-4: APEC 6 - Medium Cabin - Asbestos black felt, total lead and leachable lead painted wood exterior and drums and lubricants

Photo H-5: APEC 7 - Small Cabin - Asbestos black felt and panels, and total and leachable painted wood



Photo H-6: APEC 8 - Pipeline - View from Tanks 1-4, looking toward the Small Cabin and esker



Photo H-7: APEC 9 - 12 - Close up of Tanks 1-4, Tank 1 on the far right and Tank 4 is on the far left



Photo H-8: APEC 9 - 12 - Tanks 1-4 - View looking west, Tank 1 on the far right and Tank 4 is on the far left; asbestos gaskets on all tanks and organic content in all tanks, except for Tank 3



Photo H-9: APEC 9 - Tank 1 - Close-up of asbestos gasket



Photo H-10: APEC 13 - Overhead piping from tanks to Buildings - View of overhead piping towards Building 3; total and leachable lead painted concrete and organic content in pipeline



Photo H-11: APEC 13 - Overhead piping from tanks to Building - View of overhead piping towards Building 2; total and leachable lead painted concrete and organic content in pipeline



Photo H-12: APEC 14 - Building 1 - Asbestos black felt, asbestos window caulking, total and leachable lead painted wood



Photo H-13: APEC 14 - Building 1 - Basement total lead and leachable lead painted concrete walls, miscellaneous chemicals, ODS in freezer, mould on wood beams and concrete



Photo H-14: APEC 14 - Building 1 - Basement northwest wall



Photo H-15: APEC 14 - Building 1 - Basement unknown crystallized white material (possibly a cleaning product)



Photo H-16: APEC 14 - Building 1 - Basement two drums and jerry cans, assumed to be full of diesel, new, labelled: Paul Anowtalik and Tony V's property

Photo H-17: APEC 14 - Building 1 - Leachable lead seals on cast iron piping and tanks behind



Photo H-18: APEC 14 - Building 1 - Main floor hallway, viewing northeast; asbestos flooring wall panels and ceiling, total lead and leachable lead painted asbestos panels on walls and second layer of ceiling particulate board



Photo H-19: APEC 14 - Building 1 - Main floor kitchen; asbestos flooring, wall panels and ceiling, total lead and leachable lead painted wood shelves, mercury vapor in lights and PCBs in light ballasts



Photo H-20: APEC 14 - Building 1 - Main floor living room and bedrooms; asbestos flooring, wall panels and ceiling



Photo H-21: APEC 14 - Building 1 - Main floor control desk; asbestos walls and ceiling, PCBs, mercury and lead solder in electrical parts



Photo H-22: APEC 14 - Building 1 - Main floor electrical box. Asbestos walls and ceiling, PCBs, mercury and lead solder in electrical parts.



Photo H-23: APEC 14 - Building 1 -
Asbestos attic insulation



Photo H-24: APEC 15 - Building 2 - Asbestos black felt, asbestos window caulking, total and leachable lead painted wood, organic content in the AST and drum



Photo H-25: APEC 15 - Building 2 - Northwest half of building; total lead and leachable lead painted metal walls, ceiling and concrete floor, mercury in lights and PCBs in light ballasts



Photo H-26: APEC 15 - Building 2 - Total lead, leachable lead and PCBs painted generators, total lead, leachable lead and PCBs painted plastic over fiberglass insulation, ceiling and concrete floor miscellaneous fluids in generators and lead acid batteries



Photo H-27: APEC 15 - Building 2 - Miscellaneous chemicals, total lead and leachable lead painted metal walls, ceiling and concrete floor



Photo H-28: APEC 16 - Building 3 - Asbestos black felt, attic insulation, window caulking and total lead and leachable lead painted wood



Photo H-29: APEC 16 - Building 3 - Total lead and leachable lead painted wood and compressed gas cylinder



Photo H-30: APEC 16 - Building 3 - Total lead and leachable lead painted wood and miscellaneous containers of oil/lubricants/fuel



Photo H-31: APEC 17 - Building 4 - Asbestos black felt, attic insulation, window caulking, walls panels and total lead and leachable lead painted wood



Photo H-32: APEC 17 - Building 4 - Asbestos chimney tile and ceiling tile, and total lead and leachable lead painted wood



Photo H-33: APEC 17 - Building 4 - Asbestos insulation, and total lead and leachable lead painted wood



Photo H-34: APEC 18 - Building 5 - Asbestos exterior panels, black felt, attic insulation, window caulking, and total lead and leachable lead painted wood



Photo H-35: APEC 18 - Building 5 - Total lead and leachable lead painted wood and equipment, lead acid batteries and miscellaneous containers of oil/lubricants



Photo H-36: APEC 18 - Building 5 - Total lead and leachable lead painted wood, AST organic contents and miscellaneous containers of oil/lubricants