



Photo H-37: APEC 18 - Building 5 - Total lead and leachable lead painted caterpillar



Photo H-38: APEC 18 - Building 5 - Fibre glass insulation (not containing asbestos)



Photo H-39: APEC 19 - Building 6 - Total lead and leachable lead painted wood



Photo H-40: APEC 20 - Building 7 - Asbestos exterior asphalt shingles and total lead and leachable lead painted wood



Photo H-41: APEC 20 - Building 7 - Asbestos flooring, asbestos white piping, asbestos black felt, total and leachable lead painted wood and metal, miscellaneous containers of oil/lubricants, drum content (clear, flammable) and PCBs in light ballasts and electrical equipment



Photo H-42: APEC 21 - Building 8 - Asbestos exterior asphalt shingles and black felt



Photo H-43: APEC 21 - Building 8 - Miscellaneous containers of oil/lubricants



Photo H-44: APEC 21 - Cement mixer, painted with total lead and leachable lead paint



Photo H-45: APEC 21 - Organic content in 205L and 20L drums between Building 7 and Building 8



Photo H-46: APEC 22 - Building 9 - Metal exterior and total lead and leachable lead painted metal tower and drums, and drum content (organic)



Photo H-47: APEC 22 - Building 9 - Interior asbestos panels and fire extinguisher



Photo H-48: APEC 23 - Drum Cache 1 - Total lead and leachable lead painted drums welded together and drum content (organic)



Photo H-49: APEC 24 – Drum Cache 2 - Total lead and leachable lead painted drums and drum content (organic)



Photo H-50: APEC 24 – Drum Cache 2 - Total lead and leachable lead painted drum and some organic drum content



Photo H-51: APEC 25 - Drum Cache 3 - Total lead and leachable lead painted drums and drum content (organic)



Photo H-52: APEC 26 - Drum Cache 4 - Total lead and leachable lead painted drums



Photo H-53: APEC 27 - Drum Cache 5 - Total lead and leachable lead painted drums



Photo H-54: APEC 25-27 - Drum Cache 3 on the right, Drum Cache 4 in the center and Drum Cache 5 on the left - Total lead and leachable lead painted drum and drum content (organic)



Photo H-55: APEC 28 - Main Debris Area - Metal debris



Photo H-56: APEC 28 - Main Debris Area - Partially buried total and leachable lead paint wood, metal and drums, electrical parts and lead acid batteries



Photo H-57: APEC 29 - Shoreline Debris Area and Pumphouse (in background) - Various metal and wood debris



Photo H-58: APEC 29 - Pumphouse - Asbestos black felt, total lead and leachable lead painted equipment and wood

Photo H-59: APEC 29 - Total lead and leachable lead painted drum with blue, flammable content



Photo H-60: APEC N/A - Building 10 - Total and leachable lead painted metal tower and Building 10 in background



Photo H-61: APEC N/A - Building 10 -
Antenna Tuning Unit Shelter,
Total lead and leachable lead
painted wood and asbestos
panel



Photo H-62: APEC N/A - Building 10 - Antenna Tuning Unit Shelter interior



Photo H-63: APEC N/A - Scattered debris throughout and adjacent to the site - metal cans and debris west of the main building cluster on the hill



Photo H-64: APEC N/A - Scattered debris throughout and adjacent to the site - Two total lead and leachable lead painted metal towers west of the main building cluster, on the top of the hill



Photo H-65: APEC N/A - Scattered debris throughout and adjacent to the site; new drums and organic drum content by the airstrip