

South Beach - East Side

SBE-1 st Panoramic 408840/7596434
 looking N 6 Photos L to R
 sta-0066 to sta-0071

SBE-2 0408842/7596429 looking E
 img-0072 Wet spot @ toe

SBE-3 st 0408873/7596432 looking N
 along eastern toe
 sta-0073
 & sta-0074

SBE-4 Close-up of rust staining NE corner
 img-0075 @ 408883/7596478

SBE-5 408882/7596474 Looking NW
 img-0076 along toe

SBE-6 408865/7596493 looking W
 img-0077

SBE-7 st 408827/7596515 looking SW 2 photos
 sta-0078
 & sta-0079

SBE-8 408305/7596499 looking S
 img-0080 Note granular displacing soft material

Aug 16

SBE-9 Possible seepage from toe ~~with~~ middle west side
 img-0081 408799/7596473
 already tag orange on nail 12978

also seepage at 408803/7596463

st
 SBE-10 408802/7596471 looking S
 sta-0082
 & sta-0083 Note displaced part

^{SW}
 SBE-11 Wet spot along toe 408819/7596454
 img-0084 looking 230°
 SBE-12 - adjacent displaced part (10m N)
 img-0085 Same point looking 260°

* SBE-13 looking 115° 408798/7596450
 NO PHOTO
 over seepage? NO PHOTO

now SBE-13
 SBE-13 st Seepage from SE corner of landfill
 408852/7596432
 sta-0086 & sta-0087

END OF SOUTH BEACH EAST
 LANDFILL

10 60725

South Beach ~~West~~ Landfill

s - small (underscored)
l - large
s in filename

SBW-s-1ST 408712/7596427 looking N
to smaller south landfill

sta-0089
img-0090

SBW-s-2 408716/7596441 looking 310°
img-0091

SBW-s-3 408729/7596465 looking W
img-0092

No signs of seepage or moisture

SBW-s-4 408690/7596464 look S
img-0093

SBW-1ST 408651/7596500 looking E

Note ponded water along N and SBE in background
img-0094 3 shot panoramic
to img-0096

SBW-2 408723/7596464 SE corner looking N

note area of staining and possible seepage
img-0097 tag 12954 (took photo) in seepage stain
SBW-2a img-0098

SBW-3 408729/7596482 looking N

Note depression and ponded water
img-0099

Aug 16/2006 11

SBW-4ST 408723/7596492 looking E
sta-0100 ponded water
sta-0101

SBW-5 408736/7596496 looking N

img-0102 Seepage (v minor) along toe

SBW-6ST 408737/7596509 looking W
sta-0103 water ponded water along toe (can't tell if seeping)
sta-0104

SBW-7 408716/7596512 looking WNW
img-105 Close up of ponded water and tire ruts

SBW-8 408708/7596521 looking SW
img-106

SBW-9 wet spot at toe of landfill (cleanup)
img-0107 408665/7596508

SBW-10 408667/7596511 looking SSW
img-0108 Ponded water / seepage?

SBW-11 408668/7596497 looking SE
sta-0109 towards SBW-5 from NW corner
sta-0110

Aug 16/2006

SBW-12 408677/7596464 looking E
img-0111

DONE Spn

6:40 p.m.

NON HAZARDOUS WASTE LANDFILL

NHWL-1 Panoramic Looking 220°
img-0112 408885 7597653 (North slope)
img-0113 - looks good

NHWL-2 408867/7597632 looking W
img-0114 Viewed from mid-slope

NHWL-3 408773/7597638 looking E
towards PCB containers viewed from near toe
img-0115 of NW corner

NHWL-4 408775/7597631 looking E
img-0116 from crest of corner

5 photos st.
NHWL-5 from NW corner
img-0117 408783/7597625
to
img-0121

Aug 16/2006 13

2 photos st.
NHWL-6 408771 7597634 looking S
no cracking on crest, looks good slope
img-0122 - toe appears damp but intermingled w
img-0123 organics

2 photos st.
NHWL-7 408771 7597598 looking S
img-0124 mid-slope
img-0125

NHWL-8 403759 7597574 looking N
to solar ball along western toe of dam
img-0126 outside toe appears darker and damp w
increased organic content → no seepage observed

NHWL-9 403762 7597559 looking E
img-0128 along toe → note darker more organic rich
soil adjacent to toe → no seepage

NHWL-10 408778/7597566 looking E from
img-0129 crest

NHWL-11 408814/7597569 looking E
from mid-slope to SE corner
img-0131