

Aug 16/2006

SBW-12 408677 / 7596464 looking E
img-0111

DONE Spn

6:40 p.m.

NON HAZARDOUS WASTE LANDFILL

NHWL-1 Panoramic Looking 220°
img-0112 408885 7597653 (North slope)
img-0113 - looks good

NHWL-2 408867 / 7597632 looking W
img-0114 Viewed from mid-slope

NHWL-3 408773 / 7597638 looking E
towards PCB containers viewed from near toe
img-0115 of NW corner

NHWL-4 408775 / 7597631 looking E
img-0116 from crest of corner

5 photos st.
NHWL-5 from NW corner
img-0117 408783 / 7597625
to
img-0121

Aug 16/2006 13

2 photos st.
NHWL-6 408771 7597634 looking S
no cracking on crest, looks good slope
img-0122 - toe appears damp but intermingled w
img-0123 organics

2 photos st.
NHWL-7 408771 7597598 looking S
img-0124 mid-slope
img-0125

NHWL-8 403759 7597574 looking N
to solar ball along western toe of dam
img-0126 outside toe appears darker and damp w
increased organic content → no seepage observed

NHWL-9 403762 7597559 looking E
img-0128 along toe → note darker more organic rich
soil adjacent to toe → no seepage

NHWL-10 408778 / 7597566 looking E from
img-0129 crest

NHWL-11 408814 / 7597569 looking E
from mid-slope to SE corner
img-0131

3 shot panoramic
 NHWL-12 408862/7597571
 looking NW from SE corner

sta-0132

to sta-0134

end of inspection for the day - East
 slope in complete shadow - take photos
 in the morning

Photos 135 to 138 Old radar balls viewed from camp

Sunny 6°C 8am

Aug 17th

Back @ NHWL

NHWL-13 408872/7597561 looking N
 from SE corner (Dennis for scale)

img-0139

NHWL-14 408864/7597572 looking
 N

img-0140

NHWL-15 408868/7597600 looking N
 to camp

img-0141

NHWL-16 408872/7597615 organics
 along toe NE edge of landfill between
 slope and road -> dump but no noticeable
 seepage baseball cap for scale

img-0142

Aug 17/2006 15

8:30am TIER II Site

- starting in gravel walk over
- slopes have been tracted perpendicular to
 crest -> increasing potential for channelized flow
- no obvious erosion, but numerous deep track
 marks
- surface is rough and undulating
- some deep ruts along crest - SW corner
 and near VT-7
- > ruts make it difficult to observe changes
- noticeable depression along crest just East of VT-6
 -> appears related to repeated traffic

T2-1 409614/7597447 looking 230°
 to NE corner panoramic East N slopes
 sta-0143 to sta-0146 L to R

T2-2 SW corner crest 409476/7597353
 Area of depression - no signs of recent
 movement -> construction remnant?

(img-0148 deleted)

T2-3 409478/7597351 looking East
 to VT-7

img-0149

T2-4 Rattings @ VT-7 409503/7597350

img-0150