

**July 14, 2015**



Photo #1: View looking east, accumulated snowmelt and rainfall in the FTA LTU.

**July 21, 2015**



Photo #2: View looking north, importing backfill for FTA excavation.

July 22, 2015



Photo #3: Flow meters to be used for FTA LTU de-watering.

July 23, 2015



Photo #4: Heavy rain in Cambridge Bay.



Photo #5: View looking south, de-watering FTA LTU.

**July 25, 2015**



Photo #6: View looking south east, de-watering FTA LTU.



**July 28, 2015**



Photo #7: View looking north, importing backfill for FTA LTU excavation.

**July 30, 2015**



Photo #8: View looking south, importing demarcation material/crush.

**August 2, 2015**



Photo #9: View looking north, dewatering FTA LTU.



Photo #10: View looking east, dewatering FTA LTU.



**August 4, 2015**



Photo #11: View looking east, de-watered FTA-LTU.

**August 5, 2015**



Photo #12: View looking east, constructing ramp to access the interior FTA LTU.

**August 6, 2015**



Photo #13: View looking northwest, placing demarcation material/crush along eastern berm.

**August 8, 2015**



Photo #14: Looking at the south eastern sump prior to installation.

**August 9, 2015**



Photo #15: View looking west, spreading demarcation material.

**August 11, 2015**



Photo #16: View looking north, spreading and surveying demarcation material.



**August 12, 2015**



Photo #17: View looking north, spreading demarcation material.

**August 13, 2015**



Photo #18: View looking east, spreading demarcation material.

**August 14, 2015**



Photo #19: View looking south, FTA remedial excavation.



Photo #20: View looking north east, spreading impacted soil in the FTA LTU.



**August 15, 2015**



Photo #21: View looking south, FTA remedial excavation



Photo #22: View looking north east, spreading impacted soil in the FTA LTU.



August 16, 2015



Photo #23: View looking south, FTA remedial excavation



Photo #24: View looking north east, spreading impacted soil in the FTA LTU.

**August 17, 2015**



Photo #25: View looking south, FTA remedial excavation.



Photo #26: View looking north east, spreading impacted soil in the FTA LTU.



**August 18, 2015**



Photo #27: View looking south, FTA remedial excavation.



Photo #28: View looking north east, spreading impacted soil in the FTA LTU.



**August 19, 2015**



Photo #29: View looking north, monitor well installation.

**August 20, 2015**



Photo #30: View looking south, additional impacted soil removed.

**August 21, 2015**



Photo #31: View looking north, backfilling excavation.

**August 22, 2015**



Photo 32: View of FTA Excavation backfill facing south.

**August 24, 2015**



Photo 33: View of FTA excavation backfill facing northwest.

**August 25, 2015**



Photo 34: View of FTA backfill process facing east.



**August 26, 2015**



Photo 35: View of west side of FTA excavation backfill facing north.

**August 27, 2015**



Photo 36: View of low area of water on the north side of the FTA LTU facing east.



**August 28, 2015**



Photo 37: View of low area on the south side of FTA LTU facing southeast.

**August 29, 2015**



Photo 38: View of instillation of MW15-9.

**August 30, 2015**



Photo 39: View corrected low area to the north of FTA LTU facing east.

**August 31, 2015**



Photo 40: View of corrected low area to the south of FTA LTU facing west.



**September 1, 2015**



Photo 41: View of water accumulation to the southeast of the FTA facing south.

**September 2, 2015**



Photo 42: View of the west side of the FTA LTU facing northwest.