


## **ANNEX 2: Electronic photographs of the landfarm during construction**



Photograph 1: Cell 3 during construction (2003)



Photograph 2: Cell 3 surface smoothness and geomembrane deployment



Photograph 3: 30 mil HDPE geomembrane over contour berms



Photograph 4: Agricultural tilling tool used to aerate the soil during treatment