



Water Licence Inspection Report

Original
 Follow-Up Report

Authorization	Representative
Nunatta Environmental Services	Jim Wilson
Authorization No. / Expiry	Representative's Title
1BR-NUN1828	Vice President
Activities Inspected	
<input type="checkbox"/> Camp, Commercial <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Winter Hauling <input type="checkbox"/> Camp, Private <input checked="" type="checkbox"/> Other	

Section 1 Comments

On June 17, 2025 I, Sean Naullaq, Inspector with Crown-Indigenous Relations and Northern Affairs Canada (CIRNAC) completed an inspection of the site named above for the purpose of verifying compliance with the terms and conditions of which this water license was issued upon. The inspector was accompanied by Jim Wilson (Vice President, Nunatta Environmental).

This license allows for the disposal of waste during the operation of a commercial Hydrocarbon Impacted Soil Facility (Landfarm). Nunatta Environmental Services receives Waste such as soil and water that has been contaminated then treats the materials within the Landfarm. The Landfarm consists of 4 separate cells which contains and treats impacted material in order to remediate and occasionally re-use the material for other projects. Water use is not authorized in this license.

During the inspection, Nunatta Environmental was in the middle of sorting hazardous waste throughout the facility. While there was no evidence of water leaking/overflowing from the first cell, the Inspector was concerned about the amount of water that has accumulated within the cell and the amount of freeboard left.

Section 2 Non-Compliance with Acts or License

No non-compliance issues were observed during the inspection.

Section 3 Action Required

The Licensee must monitor the water levels in Cell #1 and ensure that no water exits the cell prior to being treated.

Licensee or Representative	Inspector's Name
Jim Wilson	Sean Naullaq
Signature	Signature
	<i>Sean Naullaq</i>
Date	Date
	July 14, 2025

Office Use Only: Follow-up report to be issued by Inspector Yes No



PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
Tuesday, June 17, 2025	1BR-NUN1828	Samsung S23	Sean Naullaq

Photo No. 1	
Photo	Click or tap here to enter text.



Description: Photo of cell with melt water along the edge of the cell being contained within the berm. Photo facing West towards the main road.

Photo No. 2	
Photo	Click or tap here to enter text.



Description: Photo of same cell with water being contained. Sheening in the water was observed during the inspection.

Photo No. 3

Photo

Click or tap here to enter text.



Description:

Photo of the other end of the cell, more seen observed during the inspection.

Photo No. 4

Photo



Description:

Photo of first cell where hazardous waste is received and sorted.



Photo No. 5

Photo



Description:

Contaminated soil is received at the landfarm where it will be treated prior to being used for a variety of projects.

Photo No. 6

Photo

Click or tap here to enter text.



Description:

Used oil from the Iqaluit Power Plant is being stored at the landfarm prior to being sent South to a disposal facility.



Photo No. 7

Photo

Click or tap here to enter text.



Description:

Used oil from the Iqaluit Power Plant is being stored at the landfarm prior to being sent South to a disposal facility.

Photo No. 8

Photo

Click or tap here to enter text.



Description:

Used oil from the Iqaluit Power Plant is being stored at the landfarm prior to being sent South to a disposal facility.



Photo No. 9

Photo

Click or tap here to enter text.



Description:

Used oil from the Iqaluit Power Plant is being stored at the landfarm prior to being sent South to a disposal facility.

Photo No. 10

Photo

Click or tap here to enter text.



Description:

Empty fuel drums were observed within the landfarm facility.



Photo No. 11

Photo

Click or tap here to enter text.



Description:

Empty fuel drums were observed within the landfarm facility.