APPENDIX II

PHOTOS

PHOTOGRAPHIC RECORDS



Photo 1: Landfarm berm.



Photo 2: Lower Site Non-Hazardous Waste Landfill.

PHOTOGRAPHIC RECORDS



Photo 3: Upper Site Non-Hazardous Waste Landfill.



Photo 4: Contaminated soil excavation.

PHOTOGRAPHIC RECORDS



Photo 5: Upper Site Landfill excavation.



Photo 6: Liner and cover at the Upper Site Landfill.