


privileged and confidential



**Photograph TII-1A.** Northwest corner of landfill facing east along crest. ↑



**Photograph TII-1B.** Northwest corner of landfill facing south along crest. ↑

privileged and confidential



**Photograph TII-2A.** Northeast corner of landfill facing west. ↑



**Photograph TII-2B.** Northeast corner of landfill facing southwest. ↑



privileged and confidential



**Photograph TII-2C.** Northeast corner of landfill facing south. ↑



**Photograph TII-3.** Panoramic photo of the north slope. ↑



privileged and confidential



**Photograph TII-4A.** At the northeast toe. Some seepage with orange staining. Some water drainage along the road at the toe. ↑



**Photograph TII-4B.** Northeast corner and toe. ↑



privileged and confidential



**Photograph TII-5A.** Southeast crest facing north. ↑



**Photograph TII-5B.** Southeast crest facing west. Some coarse rockfill along crest edge but there does not appear to be tension cracks. ↑



privileged and confidential



**Photograph TII-6.** Panoramic photo of the southeast slope. Some water seeping out of slope face. No staining. ↑




**Photograph TII-7.** South slope from southeast toe facing west. Some seepage from south slope and minor ponding at toe. No staining. ↑

privileged and confidential



**Photograph TII-8.** South slope from southwest toe facing east. ↑



**Photograph TII-9A.** Facing east along crest from the southwest corner of the landfill. ↑



privileged and confidential



**Photograph TII-9B.** Facing north along crest from the southwest corner of the landfill. Some ponded water along toe. No staining. ↑



**Photograph TII-10.** Panoramic photo of Tier II landfill facing east from raised gravel pad. ↑