

**Visual Inspection Checklist
Inspection Report – Page 1 of 2**

SITE NAME:	CAM-4 - Pelly Bay
LANDFILL/AREA DESIGNATION:	Upper Site Landfill
DATE OF INSPECTION:	August 14, 2008
DATE OF PREVIOUS INSPECTION:	August 24 - 26, 2007
INSPECTED BY:	Darrin Johnson, P.Eng.
REPORT PREPARED BY:	Darrin Johnson, P.Eng.

The preparer represents to the best of the preparer's knowledge, the following statements and observations are true and correct and to the best of the preparer's actual knowledge, no material facts have been suppressed or misstated.

Preliminary Stability Assessment

Feature	Severity Rating	Extent
Settlement	Not observed	None
Erosion	Not observed	None
Frost Action	Not observed	None
Animal Burrows	Not observed	None
Vegetation	Not observed	None
Staining	Not observed	None
Vegetation Stress	Not observed	None
Seepage Points	Not observed	None
Debris Exposed	Not observed	None
Tension Crack	Not observed	None
Overall Landfill Performance	Acceptable	

Upper Site Landfill - Inspection Report - Page 2 of 2

Checklist Item	Present Yes/No	Location	Dimensions (L x W) (m)	Depth (m)	Extent (%)	Description	Photographic Records (Photos referenced in photolog and in figures)	Additional Comments/ Preliminary Stability Assessment
Settlement	No							
Erosion	No							
Frost Action	No							
Animal Burrows	No							
Vegetation	No							
Staining	No							
Vegetation Stress	No							
Seepage Points	No							
Debris Exposed	No							
Presence/ Condition of Monitoring Instruments	Good							
Other Features of Note.	No							
Additional Photos						General	USL-1, 2A, 2B, 2C, 3, 4, 5, 6, 7, 8, 9A, 9B, 10A, 10B, 11A, 11B, 12, 13	