

privileged and confidential




**Photograph USL-1.** Panoramic photo facing southeast towards west slope of Upper Site Landfill. ↑



**Photograph USL-2A.** Facing southeast along crest. ↑

privileged and confidential



**Photograph USL-2B.** Facing east along line of thermistors. ↑



**Photograph USL-2C.** Facing north along west crest. ↑



privileged and confidential



**Photograph USL-3.** Facing south slope. ↑



**Photograph USL-4.** Facing west along south slope. ↑

privileged and confidential



**Photograph USL-5.** Panoramic photo from the southwest corner of south lobe. ↑




**Photograph USL-6.** Facing south along the south slope of the south lobe from the southeast corner. ↑



privileged and confidential



**Photograph USL-7.** Facing north from the southeast corner of the rip-rap. ↑



**Photograph USL-8.** Toe of rip-rap below thermistors. ↑

privileged and confidential



**Photograph USL-9A.** Facing north along crest from southeast corner. ↑



**Photograph USL-9B.** Facing west along south crest from the southeast corner. ↑



privileged and confidential



**Photograph USL-10A.**

Panoramic photo of the top of the landfill facing west. ↑



**Photograph USL-10B.** Facing north along crest. ↑

privileged and confidential



Photograph USL-11A.

Facing southeast. ↑



Photograph USL-11B.

Facing northwest. ↑



privileged and confidential



**Photograph USL-12.** North gravel slope. ↑



**Photograph USL-13.** Panoramic photo of the landfill top from the northwest corner. ↑