

**Visual Inspection Checklist**  
**Inspection Report – Page 1 of 2**

SITE NAME:	CAM-4 - Pelly Bay
LANDFILL/AREA DESIGNATION:	Lower Site Non-Hazardous Waste Landfill
DATE OF INSPECTION:	August 15, 2008
DATE OF PREVIOUS INSPECTION:	August 24 - 26, 2007
INSPECTED BY:	Darrin Johnson, P.Eng.
REPORT PREPARED BY:	Darrin Johnson, P.Eng.

The preparer represents to the best of the preparer's knowledge, the following statements and observations are true and correct and to the best of the preparer's actual knowledge, no material facts have been suppressed or misstated.

**Preliminary Stability Assessment**

<b>Feature</b>	<b>Severity Rating</b>	<b>Extent</b>
Settlement	Not observed	None
Erosion	Not observed	None
Frost Action	Not observed	None
Animal Burrows	Not observed	None
Vegetation	Not observed	None
Staining	Not observed	None
Vegetation Stress	Not observed	None
Seepage Points	Not observed	None
Debris Exposed	Not observed	None
Tension Crack	Not observed	None
<b>Overall Landfill Performance</b>	Acceptable	

**Lower Site Non-Hazardous Waste Landfill - Inspection Report - Page 2 of 2**

<b>Checklist Item</b>	<b>Present Yes/No</b>	<b>Location</b>	<b>Dimensions (L x W) (m)</b>	<b>Depth (m)</b>	<b>Extent (%)</b>	<b>Description</b>	<b>Photographic Records (Photos referenced in photolog and in figures)</b>	<b>Additional Comments/ Preliminary Stability Assessment</b>
<b>Settlement</b>	No							
<b>Erosion</b>	No							
<b>Frost Action</b>	No							
<b>Animal Burrows</b>	No							
<b>Vegetation</b>	No							
<b>Staining</b>	No							
<b>Vegetation Stress</b>	No							
<b>Seepage Points</b>	No							
<b>Debris Exposed</b>	No							
<b>Presence/ Condition of Monitoring Instruments</b>	Good							
<b>Other Features of Note.</b>	No							
<b>Additional Photos</b>						General	LNH-1, 2A, 2B, 2C, 3A, 3B, 4, 5A, 5B, 5C, 6A, 6B, 7A, 7B	