

- Aug. 15/08
- LOWER SITE NON-HAZ LF (LSNH)
 - STARTED INSPECTION AT 10AM
 - LSNH PHOTO LOC. 1 (WAYPOINT 34)
 - FROM NW-20 (NORTH SLOPE)
 - PHOTOS 68, 69 & 70 (PANORAMIC)
 - COARSE ROCKFILL ON SLOPE WITH NO EROSION OR CRACKS OBSERVED, NO SEEPAGE AT TOP
 - LSNH PHOTO LOC. 2 (WP 35)
 - CENTRE OF NORTH CRIST ABOVE PHOTO LOC. 1
 - PHOTO 71 (CRIST FACING EAST)
 - PHOTO 72 (TOP OF LF FACING SOUTH)
 - PHOTO 73 (CRIST FACING WEST)
 - NO CRACKS OBSERVED ALONG CRIST
 - NO SIGNIFICANT SETTLEMENT OF CONCRETE ON TOP OF LF
 - SOME TIRE TRACKS VISIBLE BUT NO DAMAGE OR RUINING

LSNH LF (PAGE 2)

- LSNH PHOTO LOC. 3 (WP 36)
 - CENTRE OF EAST CREST
 - PHOTO 74 (FACING NORTH)
 - PHOTO 75 (FACING SOUTH)
- LSNH PHOTO LOC. 4 (WP 37)
 - EAST SLOPE FACING NORTHWEST
 - PHOTO 76 (FACING SLOPE)
- LSNH PHOTO LOC. 5 (WP 38)
 - CENTRE OF SOUTH CREST
 - PHOTO 77 (FACING WEST) CREST
 - PHOTO 78 (FACING NORTH)
 - PHOTO 79 (FACING EAST ALONG CREST)
 - NO CRACKING OR SETTLEMENT OBSERVED
- LSNH PHOTO LOC. 6 (WP 39)
 - CENTRE OF WEST CREST
 - PHOTO 80 (FACING NORTH)
 - PHOTO 81 (FACING SOUTH)

AUG. 15/08

LSNH LF (PAGE 3)

- LSNH PHOTO LOC. 7 (WP 40)
 - WEST SLOPE OF LF
 - PHOTO 82 (FACING NE)
 - PHOTO 83 (FACING SE)
- OVERALL LANDFILL APPEARS TO BE STABLE, WITH NO EROSION OR CRACKING OBSERVED.
- NO SERPENTS FROM TOES.
- NO VEGETATION.