NWB Annual Report Year being reported: 2018

License No: 1BR-ROS1727 Issued Date: September 11, 2017

Expiry Date: September 10, 2027

Project Name: PIN-D Ross Point Long Term Monitoring

Licensee: Crown-Indigenous Relations and Northern Affairs Canada

(CIRNAC) Contaminated Sites

Mailing Address: PO Box 2200

Iqaluit NU X0A 0H0

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

N/A

## General Background Information on the Project (\*optional):

The PIN-D Ross Point Intermediate Distant Early Warning (DEW) Line Site was constructed in 1959, and subsequently deactivated in 1963. The nearest communities are Kugluktuk, located approximately 185 kilometres to the southwest, and Cambridge Bay, located approximately 250 kilometres to the east.

The remediation of the PIN-D Ross Point Remediation Project was successfully completed in 2012. A non-hazardous waste landfill (NHWL) was constructed to contain non-hazardous waste and is the only structure remaining on site.

As per departmental commitments to monitor the NHWL post-closure, a 25-year long term monitoring (LTM) program was initiated at PIN-D in August 2013 and includes visual inspection, groundwater sampling, soil sampling (as required), and natural environment monitoring. Refer to the PIN-D Ross Point Long Term Monitoring Plan (2013) for additional information.

Years 1, 3, and 5 of the LTM Plan took place in 2013, 2015, and 2017 respectively. Future LTM events are scheduled for 2019 (or 2020), 2022,

IQALUIT#1138882 - v1 1/5

| Licence Requirem | ents: the | lice | nsee mus | t pr | ovide the following information in accodance |
|------------------|-----------|------|----------|------|--|
| with             |           |      |          |      |  |
|                  | Part B    | •    | Item 1   | •    |  |

| Water Source(s):  | Monitoring Wells at NHWL (See GPS Coordinates Page)  |
|---|--|
| Water Quantity:   | 1/dayQuantity Allowable Domestic (cu.m)0Actual Quantity Used Domestic (cu.m)0Quantity Allowable Drilling (cu.m)0Total Quantity Used Drilling (cu.m)  |
| PIN-D Ross Poi  | I-D Ross Point Long Term Monitoring Plan (2013) and the nt 2017 LTM Report for details.  |
|   | of the orbit of th |
| uthorized discharg  | es and a summary of follow-up actions taken.   |
| Spill No.: No some spill No.: No some spill: Date of Notification | (as reported to the Spill Hot-line)  |
|   |  |
| the Spill Conting   | ency Plan  |
| Other: (see additional  | details)   |
| Additional Details:   |  |

A General LTM Spill Plan was submitted to the Nunavut Water Board on

2/5 IQALUIT#1138882 - v1

November 2, 2018 for their consideration.

| each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.   | Davisiana  | to the Abandanment and Destaustion Dlan   |
|--|------------|---|
| Additional Details:  **Reclamation Work Undertaken** Additional Details (i.e., work completed and future works proposed)  No progessive reclamation work was undertaken in 2018.  As per the **PIN-D Ross Point Long Term Monitoring Plan (2013), future long term monitoring events are scheduled for 2019, 2022, 2027, and 2037.  **esults of the Monitoring Program including:**  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where sources of water are utilized;  Details attached  Additional Details:  Additional Details:  Additional details regarding water sources can be found in the **PIN-D Ross Point Long Term Monitoring Plan (2013).**  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insector or the Board  Additional Details: (date of request, analysis of results, data attached, etc) | Revisions  |   |
| rogressive Reclamation Work Undertaken Additional Details (i.e., work completed and future works proposed)  No progessive reclamation work was undertaken in 2018.  As per the PIN-D Ross Point Long Term Monitoring Plan (2013), future long term monitoring events are scheduled for 2019, 2022, 2027, and 2037.  esults of the Monitoring Program including:  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where sources of water are utilized;  Details attached  Additional Details:  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insectional Details: (date of request, analysis of results, data attached, etc)   |            |   |
| Additional Details (i.e., work completed and future works proposed)  No progessive reclamation work was undertaken in 2018.  As per the PIN-D Ross Point Long Term Monitoring Plan (2013), future long term monitoring events are scheduled for 2019, 2022, 2027, and 2037.  esults of the Monitoring Program including:  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insective of the Board  Additional Details: (date of request, analysis of results, data attached, etc)  |            | Additional Details:   |
| Additional Details (i.e., work completed and future works proposed)  No progessive reclamation work was undertaken in 2018.  As per the PIN-D Ross Point Long Term Monitoring Plan (2013), future long term monitoring events are scheduled for 2019, 2022, 2027, and 2037.  esults of the Monitoring Program including:  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insective of the Board  Additional Details: (date of request, analysis of results, data attached, etc)  |            |   |
| Additional Details (i.e., work completed and future works proposed)  No progessive reclamation work was undertaken in 2018.  As per the PIN-D Ross Point Long Term Monitoring Plan (2013), future long term monitoring events are scheduled for 2019, 2022, 2027, and 2037.  esults of the Monitoring Program including:  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insective of the Board  Additional Details: (date of request, analysis of results, data attached, etc)  |            |   |
| Additional Details (i.e., work completed and future works proposed)  No progessive reclamation work was undertaken in 2018.  As per the PIN-D Ross Point Long Term Monitoring Plan (2013), future long term monitoring events are scheduled for 2019, 2022, 2027, and 2037.  esults of the Monitoring Program including:  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insective of the Board  Additional Details: (date of request, analysis of results, data attached, etc)  | Progressiv | ve Reclamation Work Undertaken  |
| As per the PIN-D Ross Point Long Term Monitoring Plan (2013), future long term monitoring events are scheduled for 2019, 2022, 2027, and 2037.  **Esults of the Monitoring Program including:**  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insertic Monitoring requested by an Insertic Monitoring Reditional Details: (date of request, analysis of results, data attached, etc)   |            |   |
| long term monitoring events are scheduled for 2019, 2022, 2027, and 2037.  esults of the Monitoring Program including:  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insector or the Board  Additional Details: (date of request, analysis of results, data attached, etc)   |            | No progessive reclamation work was undertaken in 2018.  |
| The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insector or the Board  Additional Details: (date of request, analysis of results, data attached, etc)   |            | long term monitoring events are scheduled for 2019, 2022, 2027, and   |
| The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insector or the Board  Additional Details: (date of request, analysis of results, data attached, etc)   |            |   |
| each location where sources of water are utilized;  Details attached  Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longiture each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Instantional Details: (date of request, analysis of results, data attached, etc)  | esults of  | the Monitoring Program including:   |
| Additional Details:  Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitue each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Institutional Details: (date of request, analysis of results, data attached, etc)  |            | The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where sources of water are utilized;        |
| Additional details regarding water sources can be found in the PIN-D Ross Point Long Term Monitoring Plan (2013).  The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longiture each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Institutional Details: (date of request, analysis of results, data attached, etc)  |            | Details attached  |
| The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longiture each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insulational Details: (date of request, analysis of results, data attached, etc)  |            | Additional Details:   |
| each location where wastes associated with the licence are deposited;  Not Applicable (N/A)  Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Insulational sampling requested by an Insulational Details: (date of request, analysis of results, data attached, etc)  |            |   |
| Additional Details:  Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Ins  No additional sampling requested by an Inspector or the Board  Additional Details: (date of request, analysis of results, data attached, etc)   |            |   |
| Remediation was completed in 2012 and the only structure remaining on site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Instantian No additional sampling requested by an Inspector or the Board  Additional Details: (date of request, analysis of results, data attached, etc)  |            | Not Applicable (N/A)  |
| site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring activities.  Results of any additional sampling and/or analysis that was requested by an Ins  No additional sampling requested by an Inspector or the Board  Additional Details: (date of request, analysis of results, data attached, etc)  |            | Additional Details:   |
| No additional sampling requested by an Inspector or the Board  Additional Details: (date of request, analysis of results, data attached, etc)  |            | site is the NHWL. No waste was deposited on site in 2018. Any solid waste generated was removed from site at the completion of monitoring |
| Additional Details: (date of request, analysis of results, data attached, etc)   |            | Results of any additional sampling and/or analysis that was requested by an Ins   |
| · · · · · · · · · · · · · · · · · · ·  |            | No additional sampling requested by an Inspector or the Board   |
| N/A  |            | Additional Details: (date of request, analysis of results, data attached, etc)  |
|  |            | N/A   |
|  |            |   |

IQALUIT#1138882 - v1 3/5

| Any other de<br>being report               |                          | r use or               | waste disposal  | requested by    | the Board by Nove   | mber 1 of the year |
|--|--------------------------|------------------------|---|-----------------|---|--------------------|
|  | No additional sa         | mpling req             | uested by an Inspect  | or or the Board |   | •                  |
|  | Additional De            | tails: (Att            | ached or provide  | d below)        |   |                    |
|  | N/A                      |                        |   |                 |   |                    |
| Any respons                                | es or follow-            | up actior              | ns on inspection  | n/compliance    | reports   |                    |
|  | No inspection ar         | nd/or comp             | liance report issued  | by INAC         |   | •                  |
|  | Additional De            | tails: (Da             | tes of Report, Fo   | llow-up by the  | Licensee)   |                    |
|  | N/A                      |                        |   |                 |   |                    |
| Any addition                               | al comments              | or infor               | mation for the E  | oard to consi   | der   |                    |
|  | analysis co<br>NHWL at P | nducted<br>IN-D is i   | during the last   | LTM event (2    | of groundwater che<br>2017) indicate that erforming as design | the                |
|  |                          |                        |   |                 |   |                    |
| Date Submit<br>Submitted/P<br>Contact Info | repared by:              | Jean A<br>Tel:<br>Fax: | ber 20, 2018<br>llen, Contamina<br>867-975-4732<br>867-975-4560<br>jean allen@car |                 | t, CIRNAC   |                    |

IQALUIT#1138882 - v1 4/5

## **GPS** Coordinates for water sources utilized

|   | L     | Longitude |       |       |     |       |
|---|-------|-----------|-------|-------|-----|-------|
| Source Description                                | o Deg | Min       | , Sec | o Deg | Min | Sec.  |
| Non-Hazardous Landfill<br>Monitoring Wells (MW) : |       |           |       |       |     |       |
| MW1   | 68    | 35        | 43.45 | 111   | 6   | 53.11 |
| MW2   | 68    | 35        | 39.77 | 111   | 6   | 41.92 |
| MW3   | 68    | 35        | 44.19 | 111   | 6   | 46.43 |
| MW4   | 68    | 35        | 44.78 | 111   | 6   | 42.71 |
|   |       |           |       |       |     |       |
|   |       |           |       |       |     |       |

## **GPS** Locations of areas of waste disposal

| Location Description (type) | Latitude |          |       | Longitude |          |       |  |
|-----------------------------|----------|----------|-------|-----------|----------|-------|--|
|                             | o Deg    | ,<br>Min | , Sec | o Deg     | ,<br>Min | , Sec |  |
| N/A                         |          |          |       |           |          |       |  |
|                             |          |          |       |           |          |       |  |
|                             |          |          |       |           |          |       |  |
|                             |          |          |       |           |          |       |  |
|                             |          |          |       |           |          |       |  |
|                             |          |          |       |           |          |       |  |
|                             |          |          |       |           |          |       |  |
|                             |          |          |       |           |          |       |  |
|                             |          |          |       |           |          |       |  |
|                             |          | •        | _     |           |          |       |  |