

Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 5

Date:

August 19, 2017

Description:

View of ponded water surrounding MW0604. SSDF northern edge.

Location:

SSDF, Viewpoint 40 (Figure 2)

Direction Taken:

SW



Photo: 6

Date:

August 19, 2017

Description:

Landfill cap view of SSDF. Thermistor Number 3 in background.

Location:

SSDF, Viewpoint 43 (Figure 2)

Direction Taken:

Ε



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 7

Date:

August 19, 2017

Description:

Northeast side of the SSDF. Monitoring Well MW0604 in top right corner or photo.

Location:

SSDF, Viewpoint 54 (Figure 2)

Direction Taken:

SE



Photo: 8

Date:

August 19, 2017

Description:

Northwest corner of landfill, Settlement Feature B.

Location:

SSDF, Viewpoint 55 (Figure 2)

Direction Taken:

SE



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 9

Date:

August 19, 2017

Description:

West side of the SSDF. Feature E.

Location:

SSDF, Viewpoint 60 (Figure 2)

Direction Taken:

Ε



Photo: 10

Date:

August 19, 2017

Description:

Western side of SSDF. Thermistor Number 1 in top left corner of photo.

Location:

SSDF, Viewpoint 62 (Figure 2)

Direction Taken:

SW



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 11

Date:

August 19, 2017

Description:

Western side of SSDF. View of Feature G in middle of photo (line feature)

Location:

SSDF, Viewpoint 65 (Figure 2)

Direction Taken:

SE



Photo: 12

Date:

August 19, 2017

Description:

View out from landfill southwest corner. Feature I in photo.

Location:

SSDF, Viewpoint 75 (Figure 2)

Direction Taken:

SW



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 13

Date:

August 19, 2017

Description:

View of SSDF southeastern corner in background, Feature Q in foreground.

Location:

SSDF, Viewpoint 84 (Figure 2)

Direction Taken:

NE



Photo: 14

Date:

August 19, 2017

Description:

Southern edge of the SSDF in background, Feature N in foreground.

Location:

SSDF, Viewpoint 80 (Figure 2)

Direction Taken:

Ν



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 15

Date:

August 3, 2017

Description:

View of Feature T, SSDF eastern side.

Location:

SSDF, Viewpoint 86 (Figure 2)

Direction Taken:

W



Photo: 16

Date:

August 3, 2017

Description:

View of revegetated area on landfill cap.

Location:

SSDF, Viewpoint 91 (Figure 2)

8

Direction Taken:

SW



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 17

Date:

August 19, 2017

Description:

View of revegetated area (Feature J), southwest corner of SSDF.

Location:

SSDF, Viewpoint 95/96 (Figure 2)

Direction Taken:

W



Photo: 18

Date:

August 19, 2017

Description:

Aerial view of SSDF.

Location:

SSDF

Direction Taken:

_

APPENDIX A-2

Site Photographs - NHWL



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 1

Date:

August 20, 2017

Description:

Western corner of the landfill. Feature C can be seen in the foreground.

Location:

NHWL, Viewpoint 2 (Figure 2)

Direction Taken:

Ε



Photo: 2

Date:

August 20, 2017

Description:

Southern corner of the NHWL.

Location:

NHWL, Viewpoint 10 (Figure 2)

Direction Taken:

Ν



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 3

Date:

August 20, 2017

Description:

Eastern corner of the NHWL.

Location:

NHWL, Viewpoint 20 (Figure

2)

Direction Taken:

W



Photo: 4

Date:

August 20, 2017

Description:

Northern corner of the NHWL. Feature E in the

foreground.

Location:

NHWL, Viewpoint 27 (Figure

2

Direction Taken:

S



Long Term Monitoring, 2017 CAM-F Sarcpa Lake, Nunavut



Photo: 5

Date:

August 20, 2017

Description:

View of northern corner of NHWL.

Location:

NHWL, Viewpoint 28 (Figure 2)

Direction Taken:

Ν



Photo: 6

Date:

August 20, 2017

Description:

View of grading of cap on south side of NHWL.

Location:

NHWL, Viewpoint 39 (Figure 2)

3

Direction Taken:

Ν