LANDFILL VISUAL INSPECTION

Site Name: CAM-3 Shepherd Bay

Landfill:NWS LandfillDate Inspected:August 5, 2008Inspected By:Anwar Majid, P.Eng.

Signature:



Checklist Item	Present Yes/No	Location	Length (m)	Width (m)	Depth (m)	Extent	Description	Photographic Records (Pictures Provided on Data CD	Severity Rating	Additional Comments
Settlement	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Erosion	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Frost Action	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Animal Burrows	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Vegetation	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Staining	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Vegetation Stress	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Seepage Points	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Debris Exposed	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Presence/ Condition of Monitoring Instruments	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Other Features of Note.	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not observed	N/A
Overall Landfill Performance:	Acceptab	ole			<u>I</u>		ı	1	1	