

LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
 Landfill: Beach Landfill
 Date Inspected: August 14, 2009
 Inspected by: Andrew Passalis, P.Eng.

Photo (BLF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
1		C309_3655	2,619 KB	14/08/2009	49684	39736	Panoramic view N to W from southwest of landfill. Note ponding along south and west sides.
		C309_3656	2,408 KB	14/08/2009			
		C309_3657	2,082 KB	14/08/2009			
		C309_3658	1,702 KB	14/08/2009			
2		C309_3659	3,043 KB	14/08/2009	49678	39744	Panoramic view N to W from southwest corner of landfill. Note ponding along south and west sides
		C309_3661	3,072 KB	14/08/2009			
		C309_3662	2,664 KB	14/08/2009			
		C309_3663	2,289 KB	14/08/2009			
3		C309_3664	3,220 KB	14/08/2009	49696	39774	Panoramic view SW to NW from southeast corner of landfill. Note hummocky surface along south cover.
		C309_3665	2,542 KB	14/08/2009			
		C309_3666	2,198 KB	14/08/2009			
		C309_3667	2,966 KB	14/08/2009			
4		C309_3668	5,069 KB	14/08/2009	49689	39765	View of minor depression on southeast corner of landfill
5		C309_3669	2,372 KB	14/08/2009	49692	39769	View SW along south side of landfill. Note localized ponding along adjacent roadway.
6		C309_3670	3,342 KB	14/08/2009	49703	39777	View N along drainage feature extending east of landfill
7		C309_3671	2,317 KB	14/08/2009	49703	39777	View NW along east side of landfill
8		C309_3672	2,897 KB	14/08/2009	49670	39897	Panoramic view SE to NW from northeast corner of landfill
		C309_3673	3,144 KB	14/08/2009			
		C309_3674	3,139 KB	14/08/2009			
		C309_3675	2,966 KB	14/08/2009			
		C309_3676	2,475 KB	14/08/2009			
		C309_3677	2,041 KB	14/08/2009			
9		C309_3678	2,716 KB	14/08/2009	49662	39799	View NW at ponded water and drainage north of landfill toe
		C309_3679	3,777 KB	14/08/2009			
10		C309_3680	2,036 KB	14/08/2009	49656	39808	Panoramic view SW to SE from east end of boulder wave break
		C309_3681	2,366 KB	14/08/2009			
		C309_3682	3,020 KB	14/08/2009			
		C309_3683	3,066 KB	14/08/2009			
		C309_3684	2,654 KB	14/08/2009			
11		C309_3685	2,465 KB	14/08/2009	49620	39781	Panoramic view NE to SE from west end of boulder wave break. Note ponding on northwest toe.
		C309_3686	2,638 KB	14/08/2009			
		C309_3687	2,776 KB	14/08/2009			
		C309_3688	2,955 KB	14/08/2009			
		C309_3689	3,191 KB	14/08/2009			
12		C309_3690	2,691 KB	14/08/2009	49632	39771	Panoramic view NE to SE from northwest corner of landfill
		C309_3691	2,585 KB	14/08/2009			
		C309_3692	2,786 KB	14/08/2009			
		C309_3693	2,842 KB	14/08/2009			
13		C309_3694	3,468 KB	14/08/2009	49652	39769	View SW at minor depression on northwest corner of landfill
14		C309_3695	3,065 KB	14/08/2009	49650	39762	View NW at minor depression on northwest corner of landfill
15		C309_3696	4,749 KB	14/08/2009	49674	39768	View NE at minor depression on southeast area of landfill
16		C309_3697	3,240 KB	14/08/2009	49657	39786	View SW at minor depressions along north side of landfill at top of armouring.
17		C309_3698	3,488 KB	14/08/2009	49678	39774	View SE at minor erosion on southeast corner of landfill
18		C309_3699	2,606 KB	14/08/2009	49687	39764	View NW at minor erosion on southeast corner of landfill
19		C309_3700	3,921 KB	14/08/2009	49682	39781	View SE at minor settlement on east side of landfill cover