


LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
 Landfill: Northeast Landfill
 Date Inspected: August 14, 2009
 Inspected by: Andrew Passalis, P.Eng.

Photo (NELF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
Lobe A							
1		C309_3838	2,635 KB	15/08/2009	10744	11913	Panoramic view N to E from gravel pile located south of Lobe A
		C309_3839	2,924 KB	15/08/2009			
		C309_3840	3,004 KB	15/08/2009			
		C309_3841	2,974 KB	15/08/2009			
		C309_3842	2,841 KB	15/08/2009	10752	11894	View E along south side of Lobe A
2					10755	11877	View NE along east side of Lobe A
3		C309_3843	2,787 KB	15/08/2009	10771	11855	Panoramic view SW to NW from east side of Lobe A
		C309_3844	2,916 KB	15/08/2009			
		C309_3845	2,836 KB	15/08/2009			
		C309_3846	2,495 KB	15/08/2009			
		C309_3847	2,438 KB	15/08/2009			
4					10795	11855	View SE at ponded area on northeast toe of Lobe A
		C309_3848	2,953 KB	15/08/2009			
5					10813	11862	View W along north side of Lobe A
		C309_3849	2,915 KB	15/08/2009			
6		C309_3850	3,097 KB	15/08/2009	10819	11867	Panoramic view E to S from northwest corner of Lobe A
		C309_3851	2,913 KB	15/08/2009			
		C309_3852	2,837 KB	15/08/2009			
		C309_3853	3,115 KB	15/08/2009			
7					10819	11885	View NW at minor erosion on west side of Lobe A
		C309_3854	4,286 KB	15/08/2009			
8					10811	11883	View SE at minor erosion on west side of Lobe A
		C309_3855	4,628 KB	15/08/2009			
9					10820	11904	View SE to S at west side of Lobe A. Note several locations of erosion along side slope.
		C309_3856	2,824 KB	15/08/2009			
		C309_3857	2,835 KB	15/08/2009			
		C309_3858	2,720 KB	15/08/2009			
10					10785	11889	View NW at minor erosion on west side of Lobe A
		C309_3859	4,260 KB	15/08/2009			
11					10792	11910	View SE at minor erosion on west side of Lobe A
		C309_3860	2,796 KB	15/08/2009			
12					10816	11875	View NNE at minor depression on northwest surface of Lobe A
		C309_3861	3,793 KB	15/08/2009			
Lobe B							
13		C309_3862	2,552 KB	15/08/2009	10826	11896	Panoramic view W to N from southeast corner of Lobe B
		C309_3863	2,254 KB	15/08/2009			
		C309_3864	2,267 KB	15/08/2009			
		C309_3865	3,363 KB	15/08/2009			
		C309_3866	2,953 KB	15/08/2009	10831	11926	Panoramic view W to N to E from mid south side of Lobe B
		C309_3867	2,873 KB	15/08/2009			
		C309_3868	3,194 KB	15/08/2009			
		C309_3869	3,381 KB	15/08/2009			
		C309_3870	3,311 KB	15/08/2009			
		C309_3871	3,241 KB	15/08/2009			
14					10846	11938	View N at minor depression on southeast cover of Lobe B
		C309_3872	3,270 KB	15/08/2009			
15					10851	11945	View NW at existing drainage channel extending west of Lobe B
		C309_3873	2,761 KB	15/08/2009			
16		C309_3874	2,751 KB	15/08/2009	10843	11962	Panoramic view SE to NE from southeast of Lobe B
		C309_3875	2,602 KB	15/08/2009			
		C309_3876	2,545 KB	15/08/2009			
17					10858	11954	View W at minor erosion on west slope of Lobe B
		C309_3877	3,147 KB	15/08/2009			
18		C309_3878	2,569 KB	15/08/2009	10888	11962	Panoramic view E to S from northwest of Lobe B
		C309_3879	2,348 KB	15/08/2009			
		C309_3880	2,112 KB	15/08/2009			
19					10874	11937	View NW at minor erosion on northwest side of Lobe B
		C309_3881	3,875 KB	15/08/2009			
20					10875	11928	View N at minor erosion on northwest side of Lobe B
		C309_3882	3,554 KB	15/08/2009			
21					10890	11926	View S at minor erosion on northwest side of Lobe B
		C309_3883	3,546 KB	15/08/2009			
22					10874	11894	View NW at minor erosion extending along north toe of Lobe B
		C309_3884	3,343 KB	15/08/2009			
		C309_3885	2,303 KB	15/08/2009	10897	11894	Panoramic view SE to W from northeast of Lobe B
		C309_3886	2,591 KB	15/08/2009			
		C309_3887	2,740 KB	15/08/2009			
		C309_3888	2,820 KB	15/08/2009			

LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
 Landfill: Northeast Landfill
 Date Inspected: August 14, 2009
 Inspected by: Andrew Passalis, P.Eng.

Photo (NELF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
Lobe C							
23		C309_3889	2,564 KB	15/08/2009	10912	11890	Panoramic view W to N from southeast of Lobe C
		C309_3890	2,393 KB	15/08/2009			
		C309_3891	2,446 KB	15/08/2009			
24		C309_3892	3,181 KB	15/08/2009	10927	11899	View W along south side of Lobe C
25		C309_3893	2,469 KB	15/08/2009	10932	11894	View N along east side of Lobe C
26		C309_3894	2,607 KB	15/08/2009	10930	11935	View E along south side of Lobe C. Note ponding at southeast toe.
27		C309_3895	2,841 KB	15/08/2009	10929	11951	Panoramic view E to N from southeast of Lobe C. Note low lying wet area southeast of lobe.
		C309_3896	2,828 KB	15/08/2009			
		C309_3897	2,728 KB	15/08/2009			
28		C309_3898	3,578 KB	15/08/2009	10955	11937	View N at tension crack on west side of Lobe C.
29		C309_3900	3,147 KB	15/08/2009	10965	11937	Close up of tension crack on west side of Lobe C
30		C309_3901	2,697 KB	15/08/2009	10979	11936	View S along west side of Lobe C
31		C309_3902	2,972 KB	15/08/2009	10987	11933	View NE along northwest side of Lobe C. Note ponding and rust coloured staining on northwest corner.
32		C309_3903	4,224 KB	15/08/2009	10994	11927	Ponded water and rust coloured staining on northwest toe of Lobe C
		C309_3904	3,311 KB	15/08/2009	10988	11923	Panoramic view SW to E from northwest corner of Lobe C
		C309_3905	2,960 KB	15/08/2009			
		C309_3906	2,590 KB	15/08/2009			
		C309_3907	2,768 KB	15/08/2009			
		C309_3908	3,265 KB	15/08/2009			
33		C309_3909	2,641 KB	15/08/2009	10985	11901	View S along east side of Lobe C. Note minor erosion along toe.
34		C309_3910	3,558 KB	15/08/2009	10991	11905	View W along north side of Lobe C
		C309_3911	3,327 KB	15/08/2009	10935	11901	View N at minor depression on southeast cover of landfill
		C309_3912	4,441 KB	15/08/2009	10953	11903	View S at minor depression on southeast side of landfill
35		C309_3913	4,898 KB	15/08/2009	10945	11901	View S at minor depression on southeast side of landfill
Lobe D							
36		C309_3914	3,152 KB	15/08/2009	10932	11887	View E at west side of Lobe D
		C309_3916	2,855 KB	15/08/2009	10950	11890	View E at west side of Lobe D
37		C309_3917	2,893 KB	15/08/2009	10962	11892	View E at west side of Lobe D
		C309_3918	2,931 KB	15/08/2009	10978	11891	View E at west side of Lobe D
38		C309_3919	2,961 KB	15/08/2009	10995	11890	View E at west side of Lobe D
		C309_3920	2,855 KB	15/08/2009	11011	11888	View E at west side of Lobe D
39		C309_3921	2,830 KB	15/08/2009	11021	11886	View E at west side of Lobe D
40		C309_3922	2,222 KB	15/08/2009	11040	11861	Panoramic view SE to SW from north of Lobe D
		C309_3923	2,123 KB	15/08/2009			
		C309_3924	2,209 KB	15/08/2009			
		C309_3925	2,506 KB	15/08/2009			
41		C309_3926	3,860 KB	15/08/2009	11012	11838	View E at minor depression on northeast corner of Lobe D
42		C309_3927	3,004 KB	15/08/2009	10966	11847	Panoramic view S to W to N from mid east side of Lobe D.
		C309_3928	3,319 KB	15/08/2009			
		C309_3929	3,541 KB	15/08/2009			
		C309_3930	3,436 KB	15/08/2009			
		C309_3931	2,929 KB	15/08/2009			
		C309_3932	2,801 KB	15/08/2009			
		C309_3933	2,908 KB	15/08/2009			
		C309_3934	3,353 KB	15/08/2009			

LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
 Landfill: Northeast Landfill
 Date Inspected: August 14, 2009
 Inspected by: Andrew Passalis, P.Eng.

Photo (NELF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
Lobe E							
43		C309_3935	3,237 KB	15/08/2009	10920	11834	View E to N from southeast corner of Lobe E
		C309_3936	3,197 KB	15/08/2009			
		C309_3937	2,939 KB	15/08/2009			
		C309_3938	2,604 KB	15/08/2009			
44		C309_3939	4,239 KB	15/08/2009	10927	11825	View SE at linear depression on southeast corner of Lobe E
45		C309_3940	2,992 KB	15/08/2009	10909	11823	View N at linear depression on southeast corner of Lobe E
46		C309_3941	2,653 KB	15/08/2009	10911	11786	Panoramic view SW to NW at ponded water and depression on south side of Lobe E. Minor erosion noted on side of lobe.
		C309_3942	3,139 KB	15/08/2009			
		C309_3943	3,248 KB	15/08/2009			
		C309_3944	3,070 KB	15/08/2009			
47		C309_3945	2,614 KB	15/08/2009	10902	11742	Panoramic view W to NW from northeast of Lobe E
		C309_3946	2,559 KB	15/08/2009			
		C309_3947	2,496 KB	15/08/2009			
48		C309_3948	3,043 KB	15/08/2009	10937	11759	View W along north side of Lobe E
49		C309_3949	2,853 KB	15/08/2009	10950	11783	View N along east side of Lobe E
50		C309_3950	2,840 KB	15/08/2009	10943	11793	View S at large depression on south side of Lobe E. Ponding extends beyond toe in background.
51		C309_3951	4,532 KB	15/08/2009	10962	11790	View E at minor erosion on east side of Lobe E
52		C309_3952	3,669 KB	15/08/2009	10960	11775	View W at minor erosion on east side of Lobe E
53		C309_3953	3,367 KB	15/08/2009	11002	11779	View S along east side of Lobe E
54		C309_3954	3,513 KB	15/08/2009	11009	11782	View W along north side of Lobe E
		C309_3955	2,783 KB	15/08/2009	11014	11773	View SW at north side of Lobe E
55		C309_3956	2,126 KB	15/08/2009	11019	11787	View S at north side of Lobe E
56		C309_3957	2,190 KB	15/08/2009	11020	11804	View S at north side of Lobe E
		C309_3958	2,360 KB	15/08/2009	11015	11817	View SE at north side of Lobe E
57		C309_3959	2,690 KB	15/08/2009	11000	11810	View S along west side of Lobe E
Lobe F							
58		C309_3961	2,723 KB	15/08/2009	11029	11808	Panoramic view N to E from southeast of Lobe F
		C309_3962	2,971 KB	15/08/2009			
		C309_3963	3,101 KB	15/08/2009			
		C309_3964	3,132 KB	15/08/2009			
59		C309_3965	3,197 KB	15/08/2009	11023	11764	View NE along southeast side of Lobe F
60		C309_3966	2,924 KB	15/08/2009	11023	11772	View NW along south side of Lobe F
61		C309_3967	2,871 KB	15/08/2009	11036	11753	Panoramic view NW to SW from southeast corner of Lobe F
		C309_3968	3,068 KB	15/08/2009			
		C309_3969	3,114 KB	15/08/2009			
		C309_3970	3,115 KB	15/08/2009			
62		C309_3971	2,582 KB	15/08/2009	11088	11760	View S along east side of Lobe F. Note ponding along northeast toe.
63		C309_3972	3,280 KB	15/08/2009	11094	11765	View W along north side of Lobe F. Note ponding along northeast toe.
64		C309_3973	2,631 KB	15/08/2009	11066	11784	View NE at ponding northeast of Lobe F
		C309_3974	2,796 KB	15/08/2009			
65		C309_3975	3,323 KB	15/08/2009	11082	11808	View NE along north side of Lobe F
66		C309_3976	2,927 KB	15/08/2009	11075	11809	View SE along west side of Lobe F
67		C309_3977	2,775 KB	15/08/2009	11118	11797	Panoramic view SE to SW from northwest of Lobe F. Note significant ponding northeast of lobe.
		C309_3978	2,319 KB	15/08/2009			
		C309_3979	2,309 KB	15/08/2009			




LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
 Landfill: Northeast Landfill
 Date Inspected: August 14, 2009
 Inspected by: Andrew Passalis, P.Eng.

Photo (NELF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
Lobe G							
68		C309_3981	3,360 KB	15/08/2009	11083	11825	View SW along southeast side of Lobe G
69		C309_3982	3,002 KB	15/08/2009	11089	11820	View ESE along east side of Lobe G
		C309_3983	2,719 KB	15/08/2009	11091	11828	View N across cover of Lobe G
70		C309_3984	2,593 KB	15/08/2009	11092	11836	View N across cover of Lobe G
		C309_3985	2,478 KB	15/08/2009	11093	11844	View N across cover of Lobe G
71		C309_3986	2,440 KB	15/08/2009	11096	11855	View N across cover of Lobe G
		C309_3987	2,593 KB	15/08/2009	11098	11867	View N across cover of Lobe G
72		C309_3988	2,538 KB	15/08/2009	11101	11880	View N across cover of Lobe G
		C309_3989	2,521 KB	15/08/2009	11103	11891	View N across cover of Lobe G
73		C309_3990	2,816 KB	15/08/2009	11134	11893	View SW at southeast corner of Lobe G
74		C309_3991	3,044 KB	15/08/2009	11197	11884	View WNW along west side of Lobe G. Note isolated ponding at toe.
75		C309_3992	3,419 KB	15/08/2009	11205	11883	View NW at drainage feature located west of Lobe G
76		C309_3993	2,522 KB	15/08/2009	11228	11865	View S across cover of Lobe G
		C309_3994	2,194 KB	15/08/2009	11225	11858	View S across cover of Lobe G
		C309_3995	2,135 KB	15/08/2009	11221	11851	View S across cover of Lobe G
77		C309_3996	1,938 KB	15/08/2009	11217	11845	View S across cover of Lobe G
		C309_3997	2,668 KB	15/08/2009	11204	11840	View S across cover of Lobe G
78		C309_3998	2,143 KB	15/08/2009	11198	11833	View S across cover of Lobe G
		C309_3999	2,048 KB	15/08/2009	11195	11824	View S across cover of Lobe G
79		C309_4000	1,857 KB	15/08/2009	11192	11818	View S across cover of Lobe G
		C309_4001	2,381 KB	15/08/2009	11189	11809	View S across cover of Lobe G
80		C309_4002	2,411 KB	15/08/2009	11186	11801	View S along east side of Lobe G
81		C309_4003	3,253 KB	15/08/2009	11192	11799	View W along north side of Lobe G
82		C309_4004	3,641 KB	15/08/2009	11202	11809	View S at minor erosion on northeast side of Lobe G
		C309_4005	2,573 KB	15/08/2009	11252	11856	Panoramic view SW to SE from northwest of Lobe G
		C309_4006	2,639 KB	15/08/2009			
		C309_4007	2,833 KB	15/08/2009			
83		C309_4008	2,292 KB	15/08/2009	11265	11870	View SE from northwest of Lobe G
		C309_4009	1,987 KB	15/08/2009			

LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
Landfill: Northeast Landfill
Date Inspected: August 14, 2009
Inspected by: Andrew Passalis, P.Eng.

Photo (NELF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
Lobe H							
85		C309_4010	2,832 KB	15/08/2009	11267	11860	View NE to E from southeast of Lobe H
		C309_4011	2,923 KB	15/08/2009			
		C309_4012	2,808 KB	15/08/2009	11259	11837	View N to NW from southeast of Lobe H
		C309_4013	2,879 KB	15/08/2009			
86		C309_4014	2,796 KB	15/08/2009	11269	11828	View NE along east side of Lobe H
		C309_4015	3,344 KB	15/08/2009	11310	11810	View SW along east side of Lobe H
87		C309_4016	2,327 KB	15/08/2009	11330	11809	View S to SW from northeast of Lobe H
		C309_4017	2,714 KB	15/08/2009			
88		C309_4018	2,657 KB	15/08/2009	11324	11830	View SW along west side of Lobe H
89		C309_4019	4,563 KB	15/08/2009	11302	11831	View NW at minor erosion on west side of Lobe H