


LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
 Landfill: USAF Landfill
 Date Inspected: August 14, 2009
 Inspected by: Andrew Passalis, P.Eng.

Photo (USAF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
		C309_3438	1,976	14/08/2009	12223	11450	VT-1
1		C309_3439	2,112	14/08/2009	12228	11451	View S at VT-1
2		C309_3440	2,300	14/08/2009	12221	11419	View S at VT-2
		C309_3441	1,819	14/08/2009	12215	11415	View SW at VT-2
3		C309_3442	4,441	14/08/2009	12193	11502	C309-12W
4		C309_3444	2,296	14/08/2009	12184	11503	View E at MW-12
5		C309_3445	4,267	14/08/2009	12265	11370	C309-13W
6		C309_3446	2,607	14/08/2009	12270	11363	View NW at MW-13
7		C309_3447	4,324	14/08/2009	12347	11370	C309-14W
8		C309_3448	2,124	14/08/2009	12353	11362	View NW at MW-14
9		C309_3449	3,979	14/08/2009	12320	11452	C309-15W
10		C309_3450	2,119	14/08/2009	12331	11448	View NW at MW-15
11		C309_3451	2,384	14/08/2009	12296	11413	View NW at VT-3
		C309_3452	2,237	14/08/2009	12287	11420	View SW at VT-3
12		C309_3453	2,251	14/08/2009	12308	11421	View E at VT-4
13		C309_3454	2,402	14/08/2009	12176	11458	Panoramic view N to NE along west side of landfill
		C309_3455	2,319	14/08/2009			
		C309_3456	2,222	14/08/2009			
14		C309_3457	2,283	14/08/2009	12167	11471	View SE at west side of landfill
15		C309_3458	2,553	14/08/2009	12172	11482	View SE at west side of landfill
16		C309_3459	2,457	14/08/2009	12180	11493	View SE at west side of landfill
		C309_3460	2,187	14/08/2009	12195	11502	View SE at west side of landfill
17		C309_3461	2,155	14/08/2009	12183	11514	Panoramic view E to S from west side of landfill
		C309_3462	2,136	14/08/2009			
		C309_3463	2,021	14/08/2009			
18		C309_3464	2,293	14/08/2009	12205	11508	View SE at east side of landfill
19		C309_3465	2,324	14/08/2009	12219	11518	View SE at east side of landfill
20		C309_3466	2,507	14/08/2009	12246	11522	Panoramic view SE to SW from northwest of landfill
		C309_3467	2,394	14/08/2009			
		C309_3468	2,353	14/08/2009			
21		C309_3471	2,000	14/08/2009	12259	11506	Panoramic view SE to SW from access road on northwest side of landfill
		C309_3472	2,354	14/08/2009			
		C309_3473	2,478	14/08/2009			
		C309_3474	2,462	14/08/2009			
22		C309_3476	2,123	14/08/2009	12284	11497	View SW at east side of landfill
		C309_3477	2,003	14/08/2009	12293	11487	View SW at east side of landfill

LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
 Landfill: USAF Landfill
 Date Inspected: August 14, 2009
 Inspected by: Andrew Passalis, P.Eng.

Photo (USAF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
23		C309_3478	2,178	14/08/2009	12305	11475	View SW at east side of landfill
		C309_3479	2,057	14/08/2009	12313	11468	View SW at east side of landfill
24		C309_3480	1,966	14/08/2009	12323	11462	View SW at east side of landfill
		C309_3481	1,826	14/08/2009	12333	11455	View SW at east side of landfill
25		C309_3482	1,841	14/08/2009	12342	11447	View W at east side of landfill
		C309_3483	1,810	14/08/2009	12349	11439	View W at east side of landfill
26		C309_3484	1,846	14/08/2009	12355	11429	View W at east side of landfill
		C309_3485	1,883	14/08/2009	12361	11416	View W at east side of landfill
27		C309_3486	1,818	14/08/2009	12361	11406	Panoramic view NW to SW from southeast of landfill
		C309_3487	1,928	14/08/2009			
		C309_3488	1,829	14/08/2009			
		C309_3489	2,075	14/08/2009	12361	11390	View W at east side of landfill
28		C309_3490	2,148	14/08/2009	12359	11375	View W at east side of landfill
29		C309_3491	1,731	14/08/2009	12359	11353	Panoramic view W to N from southeast of landfill. MW-14 in view.
		C309_3492	2,010	14/08/2009			
		C309_3493	2,054	14/08/2009			
		C309_3494	2,169	14/08/2009	12334	11357	View NW at south side of landfill
30		C309_3495	2,112	14/08/2009	12318	11352	Panoramic view N to W along south side of landfill
		C309_3496	2,086	14/08/2009			
		C309_3497	1,919	14/08/2009			
		C309_3498	2,120	14/08/2009	12302	11352	View N at south side of landfill
31		C309_3499	2,080	14/08/2009	12290	11352	View N at south side of landfill
		C309_3500	2,109	14/08/2009	12274	11356	View NE at south side of landfill
32		C309_3501	2,159	14/08/2009	12259	11362	View NE at south side of landfill
		C309_3502	2,164	14/08/2009	12245	11366	View NE at south side of landfill
33		C309_3503	2,157	14/08/2009	12232	11371	View NE at south side of landfill
		C309_3504	2,157	14/08/2009	12221	11375	View NE at south side of landfill
34		C309_3505	2,242	14/08/2009	12203	11379	View NE at south side of landfill
		C309_3506	2,292	14/08/2009	12185	11386	View NE at south side of landfill
35		C309_3507	2,229	14/08/2009	12173	11398	View NE at south side of landfill
		C309_3508	2,221	14/08/2009	12161	11420	Panoramic view N to E at west end of landfill. VT-2 visible on right.
		C309_3509	2,113	14/08/2009			
		C309_3510	2,137	14/08/2009			
36		C309_3511	2,505	14/08/2009	12189	11446	Panoramic view NE to S from access road on southwest corner of landfill
		C309_3512	2,609	14/08/2009			
		C309_3513	2,704	14/08/2009			
		C309_3514	2,903	14/08/2009			
		C309_3515	2,935	14/08/2009			
		C309_3516	2,614	14/08/2009	12189	11446	Panoramic view S to SW from access road on southwest corner of landfill
		C309_3517	2,512	14/08/2009			

LANDFILL VISUAL INSPECTION PHOTO LOG

Site Name: CAM-3, Shepherd Bay
 Landfill: USAF Landfill
 Date Inspected: August 14, 2009
 Inspected by: Andrew Passalis, P.Eng.

Photo (USAF-)	Thumbnail	Filename	Size (KB)	Date	Vantage Point		Caption
					Easting	Northing	
37		C309_3518	3,274	14/08/2009	12188	11431	View SE at tension crack on west corner of landfill, VT-2 in left background.
38		C309_3519	3,651	14/08/2009	12196	11424	Close up view of tension crack on west corner of landfill
39		C309_3520	3,961	14/08/2009	12203	11413	View NW at tension crack on west corner of landfill
40		C309_3521	3,825	14/08/2009	12245	11399	View SE at tension cracks extending along west side of landfill.
41		C309_3522	4,084	14/08/2009	12262	11394	Close up view of tension crack on west corner of landfill
42		C309_3523	3,102	14/08/2009	12275	11385	View NW at tension crack on west corner of landfill, VT-2 in left background.
43		C309_3524	4,086	14/08/2009	12280	11381	View SE at tension crack on west corner of landfill
44		C309_3525	2,701	14/08/2009	12287	11377	Close up view of tension cracks extending along west side of landfill
45		C309_3526	4,097	14/08/2009	12293	11376	Close up view of tension cracks extending along west side of landfill
46		C309_3527	4,062	14/08/2009	12298	11373	Close up view of tension cracks extending along west side of landfill
47		C309_3528	4,195	14/08/2009	12321	11372	View NE at tension crack on west corner of landfill
48		C309_3529	4,287	14/08/2009	12326	11375	Close up view of tension crack on southeast corner of landfill
49		C309_3530	4,284	14/08/2009	12332	11379	View SW at tension crack on west corner of landfill
50		C309_3531	4,195	14/08/2009	12327	11395	View SE at minor erosion on east slope of landfill
51		C309_3532	3,803	14/08/2009	12349	11388	View NW at minor erosion on east slope of landfill
52		C309_3533	2,645	14/08/2009	12323	11396	Panoramic view W to NE from east end of landfill. VT-1 and 3 visible in centre back and VT-4 on right.
		C309_3534	2,477	14/08/2009			
		C309_3535	2,408	14/08/2009			
		C309_3536	2,456	14/08/2009			
53		C309_3537	2,503	14/08/2009	12329	11407	View E at minor erosion on east end of landfill
54		C309_3538	3,677	14/08/2009	12344	11412	View W at minor erosion on east end of landfill
55		C309_3539	3,045	14/08/2009	12333	11422	Partially exposed crushed drum on northeast slope of landfill
56		C309_3540	4,216	14/08/2009	12340	11425	View W at partially exposed drum on northeast slope of landfill
57		C309_3541	2,465	14/08/2009	12312	11450	Ponding at northeast toe of landfill. Bacterial sheen noted on surface of water.
58		C309_3542	3,584	14/08/2009	12269	11462	View N-NW at ponded water along northeast toe of landfill
		C309_3543	2,850	14/08/2009			
		C309_3544	3,023	14/08/2009	12269	11462	Panoramic view E to S to W from east side of landfill. Note ponded water along northeast toe (left side of photo).
		C309_3545	2,740	14/08/2009			
		C309_3546	2,929	14/08/2009			
		C309_3547	2,757	14/08/2009			
		C309_3548	2,706	14/08/2009			
		C309_3549	2,513	14/08/2009			
59		C309_3550	2,537	14/08/2009	12285	11478	View SE at ponded water along northeast toe of landfill