

WATER USE INSPECTION REPORT

Date: July 29th,2008	Licensee Rep. (Name/Title): Mark Kolebaba , W.E Brereton
Licensee: Uranium North / MPH Consulting	Licence No: 2BE-AME0712

WATER SUPPLY

Source(s): Amer Lake	Quantity used: Unknown – Unknown
Owner:/Operator: Uranium North.	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Intake Facilities: NI	Storage Structure: A	Treatment Sys: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: Water for the exploration camp is currently not being treated at the Exploration Camp. Inspector provided advice on installation of a filter system to prevent build up of sediment in tanks. Water intake is not metered; this must be addressed by the period of the next inspection.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Latrine pit system.

Natural Water Body: NA	Continuous Discharge (land or water):NA		
Seasonal Discharge: NA	Wetlands Treatment: NA	Trench: NA	

Comments: If camp expands next year a different system of dealing with human wastes will be required.

Solid Waste:

Landfill: NA	Burn & Landfill: NA	Other: Incinerator & backhaul
--------------	---------------------	-------------------------------

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: A
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: A
Dams, Dykes: NI	Freeboard: A	Spills: NA
Construction: NI	O&M Plan: NI	A&R Plan: NI
Periods of Discharge: NA.	Effluent Discharge Rate: NA	

Comments: An Incinerator is currently on order for the camp. Waste is being back hauled to Baker Lake until it arrives. No hazardous materials have been shipped off site.

FUEL STORAGE:

Waste Oil Storage: None noted

Owner/Operator: Uranium North

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NA	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

Comments: Secondary Containment is strongly recommended at both the camp and drill sites.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator: Uranium North resources Ltd.
1		INAC: Potable water
Signs Posted	SNP: None	Warning: U
Records & Reporting: Annual reporting is required		
Geotechnical Inspection: N/A		

Non-Compliance of Act or Licence: The Camp is well laid out and clean. The Kitchen sump should have a screen or other system to remove food particles before deposit to environment. Waste was noted piling up in designated area and should be backhauled more often until an incinerator is installed. The need for secondary containment at refuelling station and drill was noted.