




Water Licence: 2BE-MSX0712 Silvermet Inc.; Land Use Permit: 2007J0012 (Valley Lake)

Inspection photographs –July 28, 2010 for “Site 1” at coordinates N66° 45’ 11.5” W115° 11’ 29.8” (NAD 83)
(taken by Water Resource Officer M. Joy)

Photograph 1: Aerial view “Site 1” drill laydown area -core boxes, fuel cache, scattered insulation and unreported fuel spill visible.





CIDM#516254

Water Licence: 2BE-MSX0712 Silvermet Inc.; Land Use Permit: 2007J0012 (Valley Lake)

Photographs 2 & 3: View of spill site –hydrocarbon stained substrate and used spill absorbant pads left behind.

Photograph 2.



Photograph 3.





Indian and Northern
Affairs Canada

Affaires indiennes
et du Nord Canada

CIDM#516254

Water Licence: 2BE-MSX0712 Silvermet Inc.; Land Use Permit: 2007J0012 (Valley Lake)

Photograph 4: Fuel drum marked as “AGL/SYP”



Photograph 5: View of charred timbers, coreboxes and several fuel drums





CIDM#516254

Water Licence: 2BE-MSX0712 Silvermet Inc.; Land Use Permit: 2007J0012 (Valley Lake)

Photograph 6: Insulation was scattered throughout the immediate area at the site.



Photograph 7: Close-up view of insulation.

