

## NWB Annual Report

Year being reported: 2005 ▼

License No: NWB2REP0305 Issued Date: May 12, 2003  
 Expiry Date: May 31, 2005

Project Name: Qilalugaq

Licensee: BHP Billiton Diamonds inc

Mailing Address: PO Box 49223  
 Van Stn Bentall Centre  
 Vancouver, BC  
 V7X 1L2

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

## General Background Information on the Project (\*optional):

This report covers camp and drilling activities that occurred over a period of about 2 months to the end of May 2005 (the expiry of the permit) by which time all activities on the site had ceased. There had been no work in the summer of that year owing to

Licence Requirements: the licensee must provide the following information in accordance with

Select ▼ Select ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.


Water Source(s):	domestic: unnamed lake adjacent camp drill: see map	
Water Quantity:	10 per day	Quantity Allowable Domestic (cu.m)
	1 per day	Actual Quantity Used Domestic (cu.m)
	25 per day	Quantity Allowable Drilling (cu.m)
	4 per day	Total Quantity Used Drilling (cu.m)

## Waste Management and/or Disposal

- ☒ Solid Waste Disposal  
☒ Sewage  
☒ Drill Waste  
☒ Greywater  
☒ Hazardous  
☐ Other:

## Additional Details:

Solid waste: Incinerated and/or assembled in 45 gal drums for disposal in Churchill  
 Sewage: treated in RBC unit. By permission of Repulse Bay Hamlet, sludge was disposed of in the hamlet sewage system.



A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:  May 7, 2004

Date of Notification to an Inspector:  June 8, 2004

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Follow-up of a leak of kimberlite cuttings from a containment sump in 2004 has shown it has been effectively mitigated by measures implemented that year. The site showed continuing stability on examination in the summer of 2005 and will be

#### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

#### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Progressive reclamation was confined to the backhaul of empty drums and scrap metal during a few flights that brought in drummed jet fuel to support the spring 05 drilling. The primary demobilisation will take place in the April/May of 2006 and a

#### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details attached ▼

Additional Details:

Water sources were lakes adjacent the drills. No GPS co-ordinates other than the drill collars were obtained.

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details described below ▼

Additional Details:

Drill Holes:	LONG	LAT
2005-8-01	85° 54' 46.4761	66° 33' 30.2400"
2005-8-02	85° 57' 39.6000	66° 33' 40.6800
2005-8-03	85° 45' 5.6880"	66° 41' 5.4960"

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

The period of activity covered by this report did not involve open water season. As a result, no samples were required (Amendment No. 1, Part D Insert Item 5)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

Select ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

This permit expired May 31st - after the cessation of exploration activities at the site. It has been succeeded by a new permit NWB2REP0507 under which no water use has been undertaken nor is planned as it has been decided to abandon the project. As required, a full description of site reclamation will be included in the Annual Report for that permit before March 31, 2007.

**Date Submitted:**

March 28, 2006

**Submitted/Prepared by:**

Jeremy Howe

**Contact Information:**

**Tel:** 604 632-1451

**Fax:** 604 683-4125

**email:** [jeremy.j.howe@bhpbilliton.com](mailto:jeremy.j.howe@bhpbilliton.com)

