Licones Mar		Year being reported: 2007 ▼
LICEUSE NO:	2BE-PER0610	Issued Date: May 24, 2006
		Expiry Date: December 10, 2010
	Project Name:	Peregrine Property
	Licensee: Diamo	ondex Resources Ltd.
	Mailing Address:	P.O. Box 11584 1410 - 650 West Georgia Street Vancouver, BC V6B 4N8
	• •	filing Annual Report (if different from Name of Licensee please clarify e two entities, if applicable):
	Same as Licensee	
General Bac	kground Information	n on the Project (*optional):
	•	was not occupied during 2007. No work was conducted, therefore nd no waste deposited.
Licence Req with		see must provide the following information in accodance
	Part B I	item 2
obtaining wa	report of water use a ater; sewage and gre	and waste disposal activities, including, but not limited to: methods of eywater management; drill waste management; solid and hazardous
	report of water use a ater; sewage and gre gement.	and waste disposal activities, including, but not limited to: methods of eywater management; drill waste management; solid and hazardous
obtaining wa	report of water use a ater; sewage and gre	and waste disposal activities, including, but not limited to: methods of

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: No spills (as reported to the Spill Hot-line)
	Date of Spill: Not applicable Date of Notification to an Inspector: Not applicable
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
	There were no spills.
Revisions	s to the Spill Contingency Plan
	Other: (see additional details)
	Additional Details:
	A revised Spill Contingency Plan Spill Contingency Plan was submitted with the
	Water License Renewal Application, granted in 2006.
Revisions	s to the Abandonment and Restoration Plan
	Other: (see additional details)
	Additional Dataila
	Additional Details: A revised Abandonment and Restoration Plan was submitted with the Water License
	Renewal Application, granted in 2006.
Progressi	ive Reclamation Work Undertaken
	Additional Details (i.e., work completed and future works proposed)
	To date there has been no reclamation work undertaken.
Results o	f the Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
	each location where sources of water are utilized;
	Details described below ▼
	Additional Details:
	Peregrine camp is located at: 113 degrees 35 minutes 35 seconds West Longitude,
	67 degrees, 8 minutes, 28 seconds North Latitude.
	No work was conducted, therefore no water was used in 2007
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of
	each location where wastes associated with the licence are deposited; Details described below
	Details described below
	Additional Details:
	No work was conducted, therefore no waste was deposited in 2007

Results of any additional sampling and/or analysis that was requested by an Inspector

	No additional sampling requested by an Inspector or the Board			
	Additional Details: (date of request, analysis of results, data attached, etc) Not applicable			
Any other de being reporte	tails on water use or waste disposal requested by the Board by November 1 of the year			
	No additional sampling requested by an Inspector or the Board			
	Additional Details: (Attached or provided below)			
Any respons	es or follow-up actions on inspection/compliance reports			
	No inspection and/or compliance report issued by INAC ▼			
	Additional Details: (Dates of Report, Follow-up by the Licensee)			
Any additional comments or information for the Board to consider				
Date Submitt Submitted/Pr Contact Info	David Ritcey, Senior Project Geologist, Diamondex Resources Ltd.			