



AANDC, Nunavut District Office
Box 100
Iqaluit, NU, X0A 0H0

November 14, 2013

Ken Armstrong
Strongbow Exploration Inc.
1103-475 Howe St.
Vancouver, BC V6C 2B3
Email: karmstrong@strongbowexploration.com

RE: Inspection of Water Licence 2BE-TRE0608, September 15 2013

Please find attached the report on the Water License Inspection conducted at the Tree River Project. Included at the end of the report is a summary of observations made during the inspection with respect to issues of non-compliance or non-conformity with the issued Water License or the Nunavut Water and Nunavut Surface Rights Tribunal Act, and the actions required of Strongbow Exploration Inc. as a result. Please note that this licence is a renewal of 2BE-TRE0406, responsibilities under which carry over into the newer licence.

Please do not hesitate to contact me at the coordinates listed below. I look forward to continuing to work with you and your staff.

Sincerely,

Eva Paul
Water Resources Officer
Aboriginal Affairs and Northern Development Canada
Nunavut Regional Office
Building 918, PO Box 100
Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548

Cell | Mobile: 867-222-6490

Fax | Téléc. : 867-979-6445

Eva.Paul@aandc-aadnc.gc.ca

CC: Phyllis Beaulieu, Manager of Licensing – Nunavut Water Board
Erik Allain, Manager of Field Operations – Aboriginal Affairs and Northern Development Canada
David Gale, Strongbow Exploration Inc.
Nicole Westcott, Strongbow Exploration, Licensing – WestcottNicole@gmail.com



WATER LICENCE INSPECTION REPORT

Date: September 15, 2013	Licensee Rep. (Name/Title): N/A
Licensee: Strongbow Exploration Inc.	Licence No.: 2BE-TRE0608

The original Tree River Project licence was issued in 2004. Most activity on this licence was conducted in 2004. Only two days of work were reported for 2005 and supported out of the Rush Lake Camp (2BE-ANI0406). 2BE-TRE0406 was renewed in 2006 as 2BE-TRE0608, however, no further activity was reported for 2006, 2007 or 2008.

Six locations were visited in relation to this project.

- 1) 2004 Licence coordinate: N67°00'38.0" W112°09'30.0" or (NAD83 N67°00'39.9" W112°09'24.7")
- 2) 2004 Annual Report (NAD83 N67°08'30.0" W112°12'49.8") Camp 3
- 3) 2004 Annual Report (NAD83 N67°08'52.8" W112°10'15.0") Camp 1
- 4) 2004 Annual Report (NAD83 N67°10'40.2" W112°09'58.8") Camp 2
- 5) Coordinate listed in new licence NAD83 N67°11'59.1" W112°08'11.9")
- 6) Trench CS-CH-9 (2004 Trenching) (NAD83 N67°19'19.1" W111°43'06.8")

No sign of use was found at any of the above locations. The trench was not located.

It appears that all materials in relation to this project were removed.

Non-Compliance with the Act or the Licence:

None

Action Required:

None

I am satisfied that Strongbow's abandonment and reclamation activities in relation to this licence have been completed.

Eva Paul
Water Resources Officer

November 14, 2013

Date